

RECAPP Facility Evaluation Report

Lethbridge School Dist #51



Allan Watson School

B3680A
Lethbridge

Facility Details

Building Name: Allan Watson School
Address: 429 - 15 Street S.
Location: Lethbridge

Building Id: B3680A
Gross Area (sq. m): 0.00
Replacement Cost: \$13,618,210
Construction Year: 0

Evaluation Details

Evaluation Company: J. A. Matthew Architect
Evaluation Date: December 1 2004
Evaluator Name: Mr. John Matthew

Total Maintenance Events Next 5 years: **\$830,501**
5 year Facility Condition Index (FCI): **6.10%**

General Summary:

The original building was constructed in 1928 with an addition later going on in 1958, in which the later was taken over by Allen Watson School. No major modernizations have taken place in this building.

The current school consists of three areas that include the 1958 (3488 sq. m.), 1972 (80.26 sq. m.) and 1985 modernization (315.28 sq. m.). Currently the school is made up of three floors of classrooms, wood shop, and an administration office. The student capacity of the school is approximately 110 from various grade levels of 8-12.

Structural Summary:

1928 - The structural condition of the school is good. No serious cracks were detected.

The original school 1928 structure is structural masonry with wood joist floors and roof framing. The 1958 addition is also masonry with a cast in place foundation system. The structural integrity of the school appears to be in good condition as determined by visual inspection. There are some signs of cracks along the foundation walls on the east side of the school along the administration area as indicated by the damage of the exterior parking. A canopy could be installed at the rear of the school where parking is generally accessed. In general the school is in adequate condition and is well maintained given the age of the school structure. The current rating of the school is acceptable.

Envelope Summary:

1928 - Pre-cast concrete wall details are in need of paint and the brick face requires cleaning. The aluminum framed windows have failed and will require replacement. The roofing was replaced in 1999 and is in good condition. Exterior doors are in poor condition and require replacement. Overall the envelope is in reasonable condition, with only wall finishes in need of repair or replacement.

The exterior of the school is made up of masonry brick, stucco, and concrete foundation wall with parking. The windows are adequate and are still operable from the interior. Some parking has separated from the concrete walls along the east side of the school that need to be refinished. The brick facade does not show any visible damage however the masonry block wall finish at the north entry needs to be refinished. The current rating of the envelope is acceptable.

Interior Summary:

1928 - Overall the interior of the school is in poor shape, the hardwood flooring will need to be taken out and reinstalled, in order to lessen the amount of noise. Doors, lockers, visual display boards, and floor finishes are all in need of replacement. The walls all require new paint, and will also need some patching work.

The interior of the school is generally in good condition with recent upgrades to the flooring and wall finishes. The classrooms are well maintained and do not appear to be in need of immediate repairs. White board could be added to replace the current green boards that are original to the school. There are not enough washrooms in the school and the current Boys and Girls washrooms are in need of upgrading to properly accommodate the student capacity. There are also no adequate change rooms as the current ones are in poor condition and not being used for their purpose. Given there has been modernization the current rating of the school is good.

Mechanical Summary:

1928 - Mechanical plumbing, sanitary and domestic water, requires replacement. The replacement of all plumbing fixtures in the basement is also required.

The hot water heating system is in good condition, except that the pneumatic thermostats and radiation valves require replacement.

The building currently has no ventilation. A system of air-handling units and ductwork is required to provide ventilation in accordance with current codes.

The building is not equipped with an energy management control system.

The building is heated primarily by a glycol heating system. Most of the building has no ventilation. The plumbing facilities are generally in poor condition. The heating control system is in poor condition.

A significant mechanical upgrade is recommended to resolve the deficiencies. This would include providing ventilation throughout, upgrading the controls, and replacing plumbing fixtures.

Generally the building mechanical systems are in poor condition.

Electrical Summary:

1928 - Overall condition of the school is average.

The branch circuit panels are full and need to be replaced. Lighting consists of inefficient T-12 fluorescents, and this should be upgraded to T-8 fluorescents. The fire alarm system is past its life span and should be upgraded to an addressable system. Exit lights are not connected to emergency circuits and should be rewired to accommodate this.

The main service is large enough to accommodate ventilation upgrade, the telephone, security, and data systems are adequate for any usage.

Fire alarm system requires an upgrade, the power distribution system needs to be upgraded for additional branch circuits, and the lighting should be upgraded to energy efficient lighting. The electrical systems are generally in marginal condition.

Rating Guide	
Condition Rating	Performance
1 - Critical	Unsafe, high risk of injury or critical system failure.
2 - Poor	Does not meet requirements, has significant deficiencies. May have high operating/maintenance costs.
3 - Marginal	Meets minimum requirements, has significant deficiencies. May have above average operating maintenance costs.
4 - Acceptable	Meets present requirements, minor deficiencies. Average operating/maintenance costs.
5 - Good	Meets all present requirements. No deficiencies.
6 - Excellent	As new/state of the art, meets present and foreseeable requirements.

S1 STRUCTURAL

A1010 Standard Foundations*

1928, 1958, 1985 - Concrete foundation with footings.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	100	MAY-06

A1030 Slab on Grade*

1928 and 1958 - Concrete slab on grade
1985 - Cast in place concrete with a basement

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	100	MAY-06

A2020 Basement Walls (& Crawl Space)*

1928 - Concrete basement wall in the storage room and ancillary room.
1958 - Concrete basement wall.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	100	MAY-06

A2020 Basement Walls* 1928 Section

1928 - Concrete

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	100	MAY-06

B1010.01 Floor Structural Frame*(Building Frame)

1928, 1958, 1985 - Concrete foundation with concrete masonry block walls

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	100	MAY-06

B1010.01 Floor Structural Frame*(Building Frame) 1928 Section

1928 - Wood floor structure

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	100	MAY-06

B1010.02 Structural Interior Walls Supporting Floors*

1928, 1958,1985 - Load bearing masonry walls with wood joist framing throughout.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	100	MAY-06

B1010.02 Structural Interior Walls Supporting Floors* 1928 Section

1928 - Wood framed walls

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	100	MAY-06

B1010.07 Exterior Stairs 1928 Section**

1928 - Concrete exterior stairs

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	40	MAY-06

B1020.01 Roof Structural Frame* 1928 Section

1928 - Wood roof structure

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	100	MAY-06

B1020.04 Canopies*

1928,1958,1985 - Rear Entry Canopy Required

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
2 - Poor	0	50	MAY-06

Event: Install rear entry canopy**Concern:**

The rear entry to the school from the parking lot does not have a canopy to protect people from the elements and makes delivery into the school for supplies and for general use difficult in times of rain and snow.

Recommendation:

Install a canopy cover over the entry to protect people from the elements for safer use.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Operating Efficiency Upgrade	2007	\$5,700	Low

Updated: JUN-06

S2 ENVELOPE**B2010.01.01 Precast Concrete: Exterior Wall Skin* 1928 Section**

1928 - Precast concrete details

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	75	MAY-06

Event: Patch and paint concrete detailing**Concern:**

Pre-cast concrete detailing is very weathered, some chipped areas, paint is peeling.

Recommendation:

Repair chipped areas, and paint precast concrete details. (also includes painting fascia)

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2006	\$1,231	Low

Updated: MAR-06**B2010.01.02.01 Brick Masonry: Ext. Wall Skin***

1928,1958,1985 - The building skin is composed of concrete masonry block and bricks.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	75	MAY-06

B2010.01.02.01 Brick Masonry: Ext. Wall Skin* 1928 Section

1928 - Brick face

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	75	MAY-06

Event: Clean brick face**Concern:**

Brick face is weathered and is discolored.

Recommendation:

Clean brick face.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Preventative Maintenance	2006	\$4,309	Low

Updated: MAR-06

B2010.01.02.02 Concrete Block: Ext. Wall Skin*

1972 - Small portion of the rear addition to the parking lot is painted concrete block wall.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	75	MAY-06

B2010.01.08 Cement Plaster (Stucco): Ext. Wall*

1928,1958, 1985 - The lower portion of the elevation around the perimeter of the building is stucco. The 1958 addition is mostly stucco as the wall skin with some brick infill.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	75	MAY-06

B2010.01.09 Expansion Control: Exterior Wall Skin*

1928,1958, 1985 - The expansion control joint between materials does not appear to be a problem with the envelope.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	75	MAY-06

B2010.01.11 Joint Sealers (caulking): Ext. Wall**

The 1958 addition building on the east side, caulking is badly deteriorated around window frames.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	20	MAY-06

Event: **Caulking has deteriorated along windows on the east portion of the school.**

Concern:

The building seal is no longer maintained around the window frames.

Recommendation:

Re-caulk the window frames so the seal is maintained. (Approximately 30 m2)

Consequences of Deferral:

Water will penetrate into the building and become worse.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2006	\$5,700	High

Updated: MAR-06

B2010.01.13 Paints (& Stains): Exterior Wall**

The 1972 addition concrete wall paint is cracked and peeling off. Needs to be repainted.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	15	MAY-06

Event: Paint concrete block wall at rear of building**Concern:**

The finish is flaking off the wall

Recommendation:

Refinish the concrete block wall at the north portion of the building.

Consequences of Deferral:

Further deterioration of the paint and possibly damage to the structural integrity of the concrete block wall.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Preventative Maintenance	2007	\$2,280	High

Updated: FEB-06

B2010.01.99 Other Exterior Wall Skin*

The parging around the perimeter of the building is cracked and falling off the wall in many areas of the building.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	MAY-06

Event: Exterior parging of the concrete wall failing**Concern:**

The further deterioration of the parging is exposing the concrete wall without protection

Recommendation:

Refinish the exposed concrete wall areas or remove existing parging and finish with exterior paint. (Approximately 140 m²)

Consequences of Deferral:

Further damage to the wall will increase the deterioration of the wall system

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2006	\$11,400	Medium

Updated: MAR-06

B2010.02.01 Cast-in-place Concrete:Ext.Wall Const*

Small area of the exterior is cast in place concrete.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	100	MAY-06

B2010.02.03 Masonry Units: Ext. Wall Const.*

Masonry wall skin makes up 90% of the building exterior finish

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	MAY-06

B2010.06 Exterior Louvers, Grilles, and Screens*

Painted metal and aluminum Louvre and grilles are in good condition throughout the perimeter.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	MAY-06

B2010.06 Exterior Louvers, Grilles, and Screens* 1928 Section

Install date unknown - Exterior grilles and louvres

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	20	MAY-06

B2020.01.01.02 Aluminum Windows (Glass & Frame)**

Prefinished aluminum windows are in adequate condition throughout the perimeter of the elevation.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	35	MAY-06

B2020.01.01.02 Aluminum Windows 1928 Section**

1980 - Window replacement

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	35	MAY-06

Event: Replace windows**Concern:**

Windows have significant air and moisture leakage.

Recommendation:

Replace windows throughout 1928 section. 75 m2

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2006	\$36,935	Low

Updated: MAR-06

B2030.01.10 Wood Entrance Door 1928 Section**

1928 - Wood entrance doors

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	MAY-06

Event: Replace entrance doors**Concern:**

Wood doors are very worn and are in poor condition.

Recommendation:

Replace wood entrance doors with new metal doors. (Cost for Approx. 6 doors, includes hardware and installation.)

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2006	\$8,003	Low

Updated: MAR-06**B2030.03 Large Exterior Special Doors***

Shop Garage Overhead Door. There is an insulated metal garage door at the shop of the school.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	20	MAY-06

B3010.04.01 Built-up Bituminous Roofing (Asphalt & Gravel)**

Asphalt Gravel Roof

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	25	MAY-06

B3010.04.04 Modified Bituminous Membrane Roofing (SBS) 1928 Section**

1999 - 2ply SBS roofing system

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	25	MAY-06

B3010.07 Sheet Metal Roofing**

Pre-finished metal flashing are in good condition around the canopies and roof parapets.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	40	MAY-06

B3010.08.02 Metal Gutters and Downspouts**

Aluminum painted downspouts are in adequate condition around the building.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	MAY-06

B3010.08.02 Metal Gutters and Downspouts 1928 Section**

Install date unknown - Metal downspouts

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	MAY-06

Event: Replace metal downspouts

Concern:

Downspouts are in poor condition, and damaged causing them to not function properly.

Recommendation:

Replace downspouts.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2006	\$1,231	Low

Updated: MAR-06

B3020.02 Other Roofing Openings (Hatch,Vent, etc)*

All the roof openings and hatches are in good condition and do not appear to have any visible deterioration at this time.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	MAY-06

S3 INTERIOR**C1010.01 Interior Fixed Partitions***

Painted brick masonry and drywall partitions make up most of the interior walls.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	50	MAY-06

C1010.01 Interior Fixed Partitions* 1928 Section

1928 - Frame construction, reinforced concrete, concrete block

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	MAY-06

C1010.04 Interior Balustrades and Screens, Interior Railings*

Painted steel balustrades and railings at stair locations throughout.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	40	MAY-06

C1010.05 Interior Windows*

Prefinished interior windows in the administration room with wire mesh in the shop area between the offices.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	40	MAY-06

C1020.01 Interior Swinging Doors**

Wood

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	MAY-06

C1020.01 Interior Swinging Doors 1928 Section**

1928 - Hollow metal

1928 - Solid core wood doors

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	50	MAY-06

Event: Replace damaged wood doors**Concern:**

Doors located throughout school are damaged and splintering at the edges.

Recommendation:

Replace wood doors. Estimated cost for 40 wood doors and hardware.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2006	\$46,785	Low

Updated: MAR-06**C1020.02 Interior Entrance Doors* 1928 Section**

1928 - Wood entrance doors

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	50	MAY-06

Event: Replace doors**Concern:**

Doors located at entrances are damaged, and in some cases splintering at the edges.

Recommendation:

Replace doors at entrances. Estimated cost for approx. 20 metal doors and hardware.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2006	\$19,699	Low

Updated: MAR-06**C1020.03 Interior Fire Doors***

Solid core painted steel fire doors at the main lobby near the entry of the school.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	MAY-06

C1020.07 Other Interior Doors* 1928 Section

1928 - Storefront doors

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	MAY-06

C1030.01 Visual Display Boards**

Green Boards

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	10	MAY-06

Event: Greenboards need to be updagraded to white boards

Concern:

Some green boards are in need of replacement as they are shadowing

Recommendation:

Replace green boards to white boards. Approximately 20 white boards

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Program Functional Upgrade	2007	\$5,700	Low

Updated: MAY-06

C1030.01 Visual Display Boards 1928 Section**

1928 - Blackboards, tack boards

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	MAY-06

Event: Replace blackboards

Concern:

Blackboards are chipped and ghosting.

Recommendation:

Replace blackboards with whiteboards. Estimated cost for approx. 34 whiteboards.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2006	\$11,081	Low

Updated: MAR-06

C1030.02 Fabricated Compartments(Toilets>Showers)**

Painted steel toilet partitions are in good shape. Shower partitions are not in use as room is being used for storage.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	20	MAY-06

C1030.02 Fabricated Compartments(Toilets>Showers) 1928 Section**

1928 - Wood partitions

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
N/A	0	0	MAY-06

Event: Replace wood toilet partitions

Concern:

Doors to compartments are damaged and are not functioning properly.

Recommendation:

Replace wood compartments with new metal partitions. Estimated cost for 10.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2006	\$8,618	Low

Updated: MAR-06

C1030.06 Handrails*

Steel Painted Handrails at all the stairs.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	MAY-06

C1030.08 Interior Identifying Devices*

Signs throughout the school are visible and well placed.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	10	MAY-06

C1030.10 Lockers**

Full length lockers are in good condition throughout in the basement hallways

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	MAY-06

C1030.10 Lockers 1928 Section**

1928 - Metal built in lockers

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	MAY-06

Event: Replace metal lockers**Concern:**

Metal lockers built into framed wall are in poor condition. Many doors do not close properly.

Recommendation:

Replace metal lockers in corridors. Estimated cost for approx. 300

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2006	\$48,016	Low

Updated: MAR-06**C1030.14 Toilet, Bath, and Laundry Accessories***

Washroom accessories are in poor shape in the boys and girls washrooms in the school.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	20	MAY-06

Event: Replace washroom Accessories**Concern:**

All washroom accessories need to be replaced or upgraded in both the Boys and Girls washrooms

Recommendation:

All washroom accessories need to be replaced or upgraded in both the Boys and Girls washrooms

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Program Functional Upgrade	2007	\$5,700	Low

Updated: MAY-06

C1030.14 Toilet, Bath, and Laundry Accessories* 1928 Section

1928 - Soap, toilet paper, and paper towel dispensers

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	20	MAY-06

Event: Replace existing dispensers.**Concern:**

Existing dispensers have been unused for quite sometime and have fallen into disrepair.

Recommendation:

Replace dispensers through out all washrooms.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2006	\$1,847	Low

Updated: MAR-06**C2010 Stair Construction* 1928 Section**

1928 - Reinforced concrete stairs

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	100	MAY-06

C2020.05 Resilient Stair Finishes**

The resilient stair finishes are still in good condition with the modernization in 1985.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	20	MAY-06

C2020.05 Resilient Stair Finishes 1928 Section**

1928 - Vinyl composite stair finishes

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	20	MAY-06

C2020.08 Stair Railings and Balustrades*

Painted Steel Stair railings and balustrades at stair locations.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	MAY-06

C2020.08 Stair Railings and Balustrades* 1928 Section

1928 - Wood railings Balustrades

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	MAY-06

C3010.01 Concrete Wall Finishes* 1928 Section

1928 - Paint

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	100	MAY-06

Event: Re-paint concrete walls**Concern:**

Much of the paint on the concrete walls has peeled and chipped away.

Recommendation:

Repaint conc. walls. Approx. 650 m2

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2006	\$4,925	Low

Updated: MAR-06**C3010.02 Wall Paneling** 1928 Section**

1928 - Gymnasium (wood paneling)

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	MAY-06

C3010.03 Plaster Wall Finishes* 1928 Section

1928 - Painted plaster

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	40	MAY-06

Event: Patch, and repair plaster. Repaint**Concern:**

Plaster walls are in poor condition. Many holes and cracks.

Recommendation:

Patch holes and cracks in walls and repaint. Approx. 1620 m2

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2006	\$18,468	Low

Updated: MAR-06

C3010.04 Gypsum Board Wall Finishes*

Painted drywall finish throughout.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	40	MAY-06

C3010.04 Gypsum Board Wall Finishes* 1928 Section

1928 - Painted Gyp. Bd.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	40	MAY-06

Event: Paint gyp. bd. walls**Concern:**

Paint is peeled off drywall, some places require patching.

Recommendation:

Paint and patch gypsum board partitions. Approx. 530 m2

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2006	\$4,925	Low

Updated: MAR-06

C3010.06 Tile Wall Finishes**

Boys and Girls Washrooms have tile finish on the walls throughout.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	MAY-06

Event: Boys and Girls washrooms need to be upgraded.**Concern:**

Boys and Girls Washrooms are in poor condition. All finishes in the washroom are dated, worn. They appear to be original finishes. There is constant odor in the washroom from old materials.

Recommendation:

Upgrade all the finishes in the Boys and Girls washrooms. (Approximately 125 m2 of tile surface for Boys and Girls Washrooms).

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2010	\$11,400	Low

Updated: MAY-06

C3010.06 Tile Wall Finishes 1928 Section**

1928 - Boys washroom tiled dado

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	MAY-06

C3010.09 Acoustical Wall Treatment 1928 Section**

1928 - Gymnasium

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	20	MAY-06

Event: Replace Acoustical paneling in gym.**Concern:**

Acoustical tiles in gym are damaged.

Recommendation:

Replace existing acoustical panels with new.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2006	\$4,925	Low

Updated: MAR-06**C3010.11 Interior Wall Painting****

Repaint the Boys and Girls Washrooms. Approximately 130 m2 of area, cost under \$1,000.00

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	5	MAY-06

C3010.11 Interior Wall Painting (1950/1954 Original Building)**

Remedial painting required to most areas, excluding the areas upgraded in 2002. Overall wall paint is peeling, cracking and wearing off.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	5	JAN-06

Event: Interior wall painting throughout the school.

Concern:

Interior paint is peeling, cracking, and fading.

Recommendation:

Repaint all interior walls throughout the school for aesthetic purposes.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2006	\$22,800	Low

Updated: JAN-06

C3020.01 Concrete Floor Finishes (Paint)*

Painted concrete floor in the storage and mechanical rooms.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	20	MAY-06

C3020.01 Concrete Floor Finishes* 1928 Section

1928 - Painted conc. floors

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	75	MAY-06

Event: Repaint conc. floors.

Concern:

Paint has worn away exposing conc. floors.

Recommendation:

Re-paint concrete floors. Approx. 550 m2

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2006	\$4,063	Low

Updated: MAR-06

C3020.02 Tile Floor Finishes**

There are missing floor tiles and visible cracks are evident throughout both rooms.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	MAY-06

Event: **Replace the floor tile finish in both Boys and Girls Washrooms.**

Concern:

The Tile finish in the Boys and Girls Washroom are in need of replacement as they are dated. The emission of odor is very evident in both washrooms from years of use. There are visible cracks and missing tiles in some areas of the floor throughout the girls and boys washroom.

Recommendation:

Replace the floor tile finish in both Boys and Girls Washrooms.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2007	\$11,400	Low

Updated: MAY-06

C3020.04 Wood Flooring**

The gym floor has just been refinished and is in good condition.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	10	MAY-06

C3020.04 Wood Flooring 1928 Section**

1928 - Classrooms, gymnasium

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	25	MAY-06

Event: **Hardwood flooring is uneven and very worn**

Concern:

Hardwood floors is very worn, uneven and very noisy.

Recommendation:

Level and finish flooring. Approx. 1020 m2

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2006	\$41,244	Low

Updated: MAR-06

C3020.07 Resilient Flooring**

Resilient flooring throughout both sheet vinyl composite and vinyl asbestos tiles.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	20	MAY-06

C3020.07 Resilient Flooring 1928 Section**

1928 - Corridors, Classrooms - Sheet vinyl

1928 - Washrooms - Vinyl Composite Tile

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	20	MAY-06

Event: Replace VCT flooring**Concern:**

Much of the VCT flooring in the washrooms is missing,

Recommendation:

Replace existing VCT with vinyl sheet flooring. Approx. 120 m2

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2006	\$6,771	Low

Updated: MAR-06

Event: Replace vinyl sheet flooring**Concern:**

Sheet flooring is in poor condition, curling at edges ripped in some areas.

Recommendation:

Replace sheet vinyl flooring with new. Approx. 600 m2

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2006	\$32,011	Low

Updated: JUN-06

C3020.08 Carpet Flooring**

New carpet in the administration office area and in the offices throughout.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	10	MAY-06

C3020.08 Carpet Flooring 1928 Section**

1990 - Library, admin. areas

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	10	MAY-06

Event: Replace carpeting**Concern:**

Carpet is worn, stained and damaged.

Recommendation:

Replace carpet in Library and administration areas. Approx. 450 m2

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2006	\$17,236	Low

Updated: MAR-06**C3020.11 Floor Painting**

The mechanical room and the storage room below the stairs have exposed concrete painted floors. Could use repainting in the storage room.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	MAY-06

C3020.14 Other Floor Finishes**

Aggregate concrete floor finish

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	MAY-06

C3030.04 Gypsum Board Ceiling Finishes*

Boys and Girls Washrooms

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	50	MAY-06

Event: Boys and Girls Washrrom ceiling gypsum board in poor shape**Concern:**

Refinish the Gypsum Wall Board on the ceiling. There are large holes cut for access without proper access panels to cover.

Recommendation:

Replace and refinish the Gypsum Wall Board ceiling on both Boys and Girls Washrooms.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2007	\$11,400	Low

Updated: MAY-06

C3030.04 Gypsum Board Ceiling Finishes* 1928 Section

1928 - Painted Gyp. Bd. ceiling

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	50	MAY-06

Event: Patch, and refinish gypsum board ceiling.**Concern:**

Gyp. Bd. has holes, and is in need of paint and patchwork.

Recommendation:

Patch holes, in gyp. bd. ceiling and repaint. Approx. 700 m2

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2006	\$8,618	Low

Updated: JUN-06

C3030.06 Acoustic Ceiling Treatment (Susp.T-Bar)**

Suspended T-bar ceilings are in good condition throughout the building with no staining or damage in the areas taht were observed in this evaluation.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	15	MAY-06

C3030.07 Interior Ceiling Painting**

Boys and Girls Washrooms

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	10	MAY-06

Event: Boys and Girls Washrooms ceiling needs to be refinished

Concern:

The ceiling finish is chipping and peeling off the ceiling

Recommendation:

Repaint the ceiling in both the Boys and Girls Washrooms

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Preventative Maintenance	2006	\$1,710	Low

Updated: MAR-06

C3030.09 Other Ceiling Finishes*

Miniral Fibre Ceiling Tiles

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	MAY-06

S4 MECHANICAL**D2010.01 Water Closets****

Fixtures are original, components wearing out, and require frequent maintenance.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	MAY-06

Event: Replace original water closets.

Concern:

The washroom water closets are original and components are wearing out. The fixtures require frequent maintenance.

Recommendation:

Replace original water closets.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Operating Efficiency Upgrade	2006	\$17,100	Low

Updated: FEB-06

D2010.01 Water Closets 1928 Section basement**

Flushvalve water closets.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	MAY-06

Event: Replace water closets in basement.

Concern:

The water closets in the basement are stained and some are leaking.

Recommendation:

Replace 8 water closets and provide new flushvalves. This work should be done in conjunction with the plumbing pipe replacement in D2020.01.01.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2006	\$11,081	Low

Updated: MAR-06

D2010.01 Water Closets 1928 Section Upper Section**

Tank flush vitreous china water closets in individual washrooms throughout.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	MAY-06

D2010.02 Urinals**

Fixtures are original, components wearing out, and require frequent maintenance.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	MAY-06

Event: Replace Original Urinals**Concern:**

Existing Urinals are wearing out and require frequent maintenance.

Recommendation:

Replace Original Urinals.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Operating Efficiency Upgrade	2006	\$5,700	Low

Updated: FEB-06

D2010.02 Urinals 1928 Section**

Original stall type urinals in basement with trickle tank flush system.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	MAY-06

Event: Replace urinals.**Concern:**

The existing urinals are original and pose a sanitary hazard. The flushing system is also inefficient.

Recommendation:

Install three new wall hung urinals. Either use waterless urinals, or flushvalves.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2006	\$3,694	Low

Updated: MAR-06

D2010.03 Lavatories**

Fixtures are original, components wearing out, and require frequent maintenance.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	MAY-06

Event: Replace Original Lavatories**Concern:**

Original Lavatories are in poor condition and require additional maintenance.

Recommendation:

Replace original lavatory units.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Operating Efficiency Upgrade	2006	\$5,700	Medium

Updated: MAY-06

D2010.03 Lavatories 1928 Section Basement**

Lavatories in basement are vitreous china with separate hot and cold faucets.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	MAY-06

Event: Replace lavatories in basement washrooms.**Concern:**

The existing lavatories in the basement washrooms are original and employ separate hot and cold faucets which are difficult to operate and are not barrier free.

Recommendation:

Replace 6 lavatories with new countertop lavatories with new faucets.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2006	\$4,925	Low

Updated: MAR-06

D2010.03 Lavatories 1928 Section Upper Floors**

Vitreous china lavatories located in individual washrooms throughout.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	MAY-06

D2010.04 Sinks**

Installed in upgrade

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	MAY-06

D2010.04 Sinks 1928 Section**

Mixture of single, double and triple bowl stainless steel sinks throughout.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	MAY-06

D2010.05 Showers**

Installed in upgrade and are not functioning properly.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	MAY-06

Event: Replace Shower Mixing Valves

Concern:

Existing shower mixing valves are not operating properly .

Recommendation:

The Shower mixing valves should be replaced

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Operating Efficiency Upgrade	2006	\$2,280	Low

Updated: FEB-06

D2010.05 Showers 1928 Section**

One shower stall in basement.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	MAY-06

Event: Remove and dispose shower.

Concern:

The shower in the basement does not meet code.

Recommendation:

Replace shower in basement with new barrier free type.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Code Upgrade	2006	\$3,078	Low

Updated: MAR-06

D2010.08 Drinking Fountains / Coolers**

Installed in upgrade

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	MAY-06

D2010.08 Drinking Fountains / Coolers 1928 Section**

Vitreous china non-refrigerated drinking fountains. Drinking fountain drains connected to storm drainage piping.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	MAY-06

Event: **Connect new drinking fountains to new sanitary drain piping.**

Concern:

The drinking fountains are directly connected to the storm drainage system.

Recommendation:

Replace the drinking fountains and connect them to the new sanitary drain piping. See D2020.01.01.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Code Repair	2006	\$6,771	Low

Updated: MAR-06

D2020.01.01 Pipes and Tubes: Domestic Water*

(2002) Recently replaced.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	40	MAY-06

D2020.01.01 Pipes and Tubes: Domestic Water* 1928 Section

Mixture of copper and galvanized piping.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	40	MAY-06

Event: Replace domestic water distribution piping.**Concern:**

The domestic water piping is original and is galvanized in some areas. The piping also appears to be undersized and not insulated. No recirculation system in place.

Recommendation:

Replace the domestic water distribution piping, add recirculation system, and insulate. Coordinate this with the replacement of the waste and vent piping.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2006	\$196,988	Low

Updated: MAR-06

D2020.01.02 Valves: Domestic Water**

2 shower mixing valves are not working properly. Event and cost included in D2010.01.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	40	FEB-06

D2020.01.03 Piping Specialties (Backflow Preventors)**

Provided in water service upgrade.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	30	MAY-06

D2020.02.02 Plumbing Pumps: Domestic Water**

Copper piping

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	20	MAY-06

D2020.02.06 Domestic Water Heaters**

State Sandblaster, 19kW input, 284 L. Does not provide adequate hot water.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	20	MAY-06

Event: Replace domestic water heater.**Concern:**

Problems have been reported with the capacity of the domestic water heater.

Recommendation:

Replace the domestic water heater.

Consequences of Deferral:

Capacity problems will continue.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Operating Efficiency Upgrade	2006	\$2,280	Low

Updated: FEB-06

D2020.02.06 Domestic Water Heaters 1928 Section**

(1995 Approx.) - Bradford white 189 L, 13 kW domestic water heater with no recirculation.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	20	MAY-06

D2020.03 Water Supply Insulation*: Domestic 1928 Section

Piping observed not insulated. Event and cost included in D2020.01.01.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	MAY-06

D2030.01 Waste and Vent Piping*

No problems reported despite age of plumbing.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	MAY-06

D2030.01 Waste and Vent Piping* 1928 Section

Original waste and vent piping cast iron and copper. Piping is likely corroded, event and cost included in D2020.01.01.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	50	MAY-06

D2040.01 Rain Water Drainage Piping Systems*

Interior rainwater leaders connected to municipal storm.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	MAY-06

D2040.01 Rain Water Drainage Piping Systems* 1928 Section

Roof drains collect storm drainage and conveys water to interior cast iron leaders and underground storm sewer. Event and cost included in D2020.01.01.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	50	MAY-06

D2040.02.04 Roof Drains**

Roof drains convey storm water to interior rainwater leaders.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	40	FEB-06

D2090.01 Compressed Air Systems**

Compresses air lines for industrial arts shop run in cold spaces and experience condensation.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	FEB-06

Event: Re-route compressed air lines.**Concern:**

The compressed air lines run in cold spaces and experience condensation problems.

Recommendation:

Re-route the compressed air lines in warm spaces, and install air dryer.

Consequences of Deferral:

Problems with condensation will continue.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Preventative Maintenance	2006	\$2,850	Low

Updated: FEB-06

D3010.02 Gas Supply Systems*

1972 original service adequate capacity

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	50	MAY-06

D3010.02 Gas Supply Systems* 1928 Section

Municipal gas supply.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	MAY-06

D3020.02.01 Heating Boilers and Accessories: H.W.**

(2004) 2 Weil McLain LGB-19W, 685 kW input each.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
6 - Excellent	0	30	FEB-06

D3020.02.01 Heating Boilers and Accessories: H.W. 1928 Section**

(1987) - 4 hot water boilers heat entire building. Boilers are Weil McLain HG-9 640 MBH input, 445 MBH output.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	MAY-06

D3020.02.02 Chimneys (&Comb. Air): H.W. Boiler**

(2004) New chimney and combustion air ducting installed as part of boiler replacement.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
6 - Excellent	0	30	MAY-06

D3020.02.02 Chimneys (&Comb. Air): H.W. Boiler 1928 Section**

Chimney not lined. Fan-assisted combustion air provided.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	MAY-06

Event: Line existing chimney.**Concern:**

The existing chimney is not lined. The flue gases may deteriorate the mortar in the chimney.

Recommendation:

Provide stainless steel liner for chimney.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Code Upgrade	2006	\$9,849	Low

Updated: MAR-06

D3020.02.03 Water Treatment: H. W. Boiler*

(2004) Installed as part of boiler replacement.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	FEB-06

D3020.03.01 Furnaces**

Flamemaster furnace for shower room in poor condition. Event and cost included in ventilation upgrade, D3040.01.01.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	25	FEB-06

D3020.03.02 Chimneys (&Comb. Air): Furnace*

Significant corrosion. Replace as part of furnace replacement in ventilation upgrade, D3040.01.01.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	FEB-06

D3040.01.01 Air Handling Units: Air Distribution**

No ventilation provided except for science room.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	MAY-06

Event: Provide ventilation throughout.**Concern:**

Only the science room portion of the building is ventilated.

Recommendation:

Provide air-handling units and ductwork throughout to provide ventilation to all areas. Exhaust fans, the shower room furnace, and the science room air-handling unit should be replaced at the same time. It would be beneficial to perform this upgrade along with the heating controls upgrade to incorporate all HVAC system in to the DDC automation system. Pricing provided is for ventilation upgrade only.

Consequences of Deferral:

Poor indoor air quality will persist. Science room air-handling unit and exhaust fans will continue to require frequent maintenance.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Indoor Air Quality Upgrade	2008	\$387,593	Low

Updated: FEB-06

D3040.01.01 Air Handling Units: I.A. Make-up Air**

Engineered-Air make-up unit for industrial arts dust collection system.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	FEB-06

D3040.01.01 Air Handling Units: I.A. Shop**

Buffalo roof top unit heats shop area.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	FEB-06

D3040.01.01 Air Handling Units: Science Lab**

I.C.G air handling unit for science lab requires frequent maintenance and does not function reliably. Event and cost included in ventilation upgrade, D3040.04.01.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	FEB-06

D3040.01.04 Ducts: Air Distribution*

Original Equipment

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	MAY-06

D3040.01.07 Air Outlets & Inlets:Air Distribution*

Original Equipment

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	MAY-06

D3040.03.01 Heating Distribution Systems Glycol**

(2004) New primary and secondary loop distribution pumps provided in boiler upgrade.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	40	MAY-06

D3040.03.01 Hot Water Distribution Systems 1928 Section**

(1987) - Insulated hot water heating distribution system. Primary/secondary loop arrangement. Primary distribution pump replaced during site visit, secondary pumps relatively new.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	40	MAY-06

D3040.03.01 Hot Water Distribution Systems Piping and Insulation**

Main heating lines poorly insulated. Pipe fitting insulation contains asbestos.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	FEB-06

D3040.04 Special Exhaust Systems

Dust collection unit in shop area with partial recirculation. Current codes forbid recirculation units, however this unit operates properly.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	FEB-06

Event: Replace dust collection unit.

Concern:

The dust collection unit recirculates air into the shop which is not allowed by current codes.

Recommendation:

Replace the dust collection unit with one that exhausts 100% of the filtered air.

Consequences of Deferral:

Indoor air quality may not be satisfactory.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Indoor Air Quality Upgrade	2006	\$19,380	Low

Updated: FEB-06

D3040.04.01 Fans: Exhaust 1928 Section**

Local exhaust fans serve washroom areas.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	MAY-06

D3040.04.01 Fans: Exhaust 1928 Section Central**

1928 - Main exhaust fan serving entire building in mechanical penthouse. No longer used.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	MAY-06

Event: Remove and dispose central exhaust fan.

Concern:

The existing central exhaust fan is no longer used.

Recommendation:

Remove and dispose of central exhaust fan.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Program Functional Upgrade	2006	\$3,078	Low

Updated: MAR-06

D3040.04.01 Fans: Exhaust**

Original Equipment

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	MAY-06

D3040.04.01 Fans: Washroom Exhaust**

Capacity issues reported for washroom exhaust fans. Event and cost included in ventilation upgrade, D3040.01.01.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	FEB-06

D3040.04.05 Air Outlets and Inlets*: Exhaust 1928 Section

Original exhaust air grilles throughout.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	MAY-06

D3050.01.01 Computer Room Air Conditioning Units**

No cooling provided.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	FEB-06

Event: Provide cooling in computer room.**Concern:**

The computer room has no air conditioning and becomes excessively warm.

Recommendation:

Provide a cooling roof top unit with economizer section and ductwork to cool the computer room. This could be done in conjunction with the main ventilation upgrade.

Consequences of Deferral:

Room will continue to be excessively hot in spring and fall.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Program Functional Upgrade	2006	\$22,800	Low

Updated: FEB-06

D3050.01.02 Packaged Rooftop Air Conditioning Units (& Heating Units)**

Air condition unit provided only for administration areas.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	FEB-06

D3050.03 Humidifiers**

No humidification.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	25	MAR-06

D3050.05.03 Finned Tube Radiation 1928 Section**

(1987) - Finned tube radiation cabinets throughout.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	MAY-06

D3050.05.06 Unit Heaters**

1988 - Replaced in Upgrade

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	MAR-06

D3050.05.06 Unit Heaters 1928 Section**

(1987) Force flow unit heaters.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	MAY-06

D3060.02.01 Electric and Electronic Controls**

DDC controls in boiler room and administration areas only.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	30	FEB-06

D3060.02.02 Pneumatic Controls**

Pneumatic zone valves are leaking and require constant maintenance.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	40	FEB-06

Event: Replace pneumatic system.

Concern:

The pneumatic zone valves are leaking and require frequent maintenance. They have also been configured poorly for comfort control. The pneumatic system itself is in poor condition and requires frequent maintenance.

Recommendation:

Replace the pneumatic zone valves with new replacements

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2007	\$22,800	Low

Updated: FEB-06

D3060.02.03 Pneumatic and Electric Controls* 1928 Section

Pneumatic perimeter radiation zone valves and thermostats throughout. Event and cost included in D3060.02.05.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	40	MAY-06

D3060.02.05 Building Systems Controls(BMCS, EMCS)**

DDC system controls boiler plant and radiation valves in the administration areas.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	30	MAY-06

D3060.02.05 Building Systems Controls(BMCS, EMCS) 1928 Section**

No building control system provided. Minor controls provided for central heating plant.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	MAY-06

Event: Install Energy Management and Control System (EMCS)**Concern:**

The aging pneumatic thermostats and control valves require replacement. The building has no EMCS.

Recommendation:

Remove and dispose all existing pneumatic controls and perimeter radiation zone valves. Install new valves and EMCS devices throughout. Coordinate this upgrade with the ventilation upgrade in D3040.01. New EMCS shall control hot water heating system and new air-handling system.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Operating Efficiency Upgrade	2006	\$123,118	Low

Updated: MAR-06

D4010 Sprinklers: Fire Protection*

Provided in shop paint booth.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	FEB-06

D4010.01 Wet-Pipe Fire Sprinkler Systems 1928 Section

No system installed.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	MAY-06

Event: Install fire sprinkler system.**Concern:**

The building requires a fire sprinkler system to meet current codes.

Recommendation:

Install a wet pipe fire sprinkler system throughout.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Code Upgrade	2006	\$135,429	Low

Updated: MAR-06

D4020 Standpipes*

1988 - Installed in Upgrade

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	FEB-06

D4020 Standpipes* 1928 Section

Standpipe system throughout.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	MAY-06

D4030.01 Fire Extinguisher, Cabinets and Accessories**

1988 - Installed Throughout

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	FEB-06

D4030.01 Fire Extinguisher, Cabinets and Accessories 1928 Section**

Fire extinguishers throughout.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	MAY-06

S5 ELECTRICAL**D5010.01 Main Electrical Transformers****

1995 - Pad mount transformer c/w adequate blast wall.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	40	FEB-06

D5010.01 Main Electrical Transformers 1928 Section**

1995 - Main utility service transformer is a 225 KVA pad mount transformer.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	40	MAY-06

D5010.03 Main Electrical Switchboards (Main Distribution)**

1995 - Main electrical service is a Siemens 1200A main and CDP. Main breaker and feeders were upgraded from a 800A to a 1200A in 2005. CDP is 75% full.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	40	FEB-06

D5010.03 Main Electrical Switchboards (Main Distribution) 1928 Section**

1995 - 1200 A 120/208 V Siemens service, shared with Allen Watson High School, located in Allen Watson Electrical Room, and the Main CDP feeds both Allen Watson and Hamilton CPDs. Service size is insufficient for any additional ventilation and branch circuit wiring, for the size of Hamilton and Allen Watson combined.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	40	MAY-06

Event: Upgrade Main Service**Concern:**

Existing service cannot support a ventilation upgrade or a additional branch circuit devices.

Recommendation:

Upgrade the electrical service to a 2000 A

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Indoor Air Quality Upgrade	2006	\$30,779	Low

Updated: MAR-06

D5010.03.01 Low-Voltage Distribution 1928 Section

1995 - Main CDP in Allen Watson Electrical Room feeds a 400 A local in Hamilton CDP, which feeds Hamilton panels and the Wood Shop in Allen Watson. Additional ventilation should be fed off the main CDP to allow new panels to be fed off of this CDP.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	MAY-06

D5010.05 Electrical Branch Circuit Panelboards (Secondary Distribution) - 1972**

1928 Section - Panels are primarily Square D panels and are all full or 95% full.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	25	MAY-06

Event: Upgrade Branch Circuit Panels

Concern:

Existing panels are full and existing panel feeders are nearing capacity, any additional branch circuits will over tax distribution panels.

Recommendation:

Install new and additional panels, for additional branch circuit capacity, and new feeders to increase ampacity.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2006	\$98,494	Low

Updated: MAR-06

D5010.05 Electrical Branch Circuit Panelboards (Secondary Distribution) - 1998**

1928 Section - Panels for the computer outlets in the LAN room and the concession stands in the gymnasium, both panels are 95% full, Federal Pioneer Stablok Panels. There is no TVSS unit to protect the main service or the computer panel.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	MAY-06

Event: Install TVSS protection on main CDP and computer sub panel

Concern:

Existing distribution system has not protection for transient voltage, and this lack of protection can result in computers and other equipment being damaged.

Recommendation:

Install TVSS units on the main CDP and on the computer branch circuit panel.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Preventative Maintenance	2006	\$10,465	Low

Updated: MAR-06

D5010.05 Electrical Branch Circuit Panelboards (Secondary Distribution) 1972**

Branch circuit panels are all 90 to 100% full. Panels are antiquated and several parts are hard to find.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	FEB-06

Event: Add Panels for Additional Circuits.

Concern:

Existing panels are antiquated, parts are hard to find and the majority of panels are full.

Recommendation:

Add additional circuit capacity by replacing panels with new panels and add panels where necessary.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Program Functional Upgrade	2006	\$170,997	Low

Updated: FEB-06

D5010.05 Electrical Branch Circuit Panelboards (Secondary Distribution) 1995**

Secondary CDP located in adjacent board office and feeds the wood shop, CDP is 75% full. Branch circuit panels installed with this CDP are also 50% to 75% full.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	30	MAY-06

D5010.07.02 Motor Starters and Accessories**

1988 - Motor starters are in good working order.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	FEB-06

D5010.07.02 Motor Starters and Accessories 1928 Section**

1987 - Motor starters are individual motor starters, mounted in close proximity to the individual motors.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	MAY-06

D5020.01 Electrical Branch Wiring*

1970 - Branch circuit wiring is adequate in the classrooms, and several receptables were added in 1995 and 1997, but there are still very few receptables in the classrooms.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	50	MAY-06

Event: Add Receptacles and Circuits to Classrooms**Concern:**

Existing classrooms have minimal receptacles and the wiring has too many receptacles on each circuit.

Recommendation:

Add 2 to 3 receptacles per class depending on the size of room add 1 circuit for every 2 classrooms.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Program Functional Upgrade	2009	\$45,599	Low

Updated: FEB-06

D5020.01 Electrical Branch Wiring* 1928 Section - 1972

Wiring and conduits are all mounted on surface.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	MAY-06

D5020.01 Electrical Branch Wiring* 1928 Section - 1998

Wiring is primarily on the surface, and where there are new walls and suspended ceilings the wiring is concealed.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	MAY-06

D5020.01.03 Wiring Devices 1928 Section - 1972

Devices are very old but functional, devices are being replaced on failure. Devices are minimal and insufficient for general usage.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	MAY-06

Event: Add Receptacles through out the school

Concern:

Receptacles are sparcly located and existing circuits are taxed for the amount of receptacles on them.

Recommendation:

Add 2 to 3 receptacles in each classroom, and add general use receptacles in the gymnasium, library and hallways and circuits to power them.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Program Functional Upgrade	2006	\$30,779	Low

Updated: MAR-06

D5020.01.03 Wiring Devices 1928 Section - 1998

The wiring devices are in good condition, there was a receptacle added in each classroom for a computer outlet.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	MAY-06

D5020.02.01 Lighting Accessories (Lighting Controls)*

1970 - Lighting control is all line voltage switching.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	MAY-06

D5020.02.01 Lighting Accessories (Lighting Controls)* 1928 Section

Lighting controls are all line voltage switches.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	MAY-06

D5020.02.02.01 Interior Incandescent Fixtures*

1970 - Lighting is primarily incandescent fixtures in all small mechanical rooms and closets.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	FEB-06

D5020.02.02.01 Interior Incandescent Fixtures* 1928 Section

1972 - Fixtures in basement mechanical spaces, and storage rooms are keyless fixtures with 100 W bulbs.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	MAY-06

D5020.02.02.02 Interior Florescent Fixtures**

1970 - Fluorescent fixtures are T-12, 4' lamp fixtures. The lighting levels are adequate but the fixtures are inefficient and ballasts are failing regularly.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	FEB-06

Event: Upgrade Lights to Energy Efficient Fixtures.**Concern:**

Existing fixtures are not very energy efficient, and have out lived their life span, which means the maintenance cost is significantly higher that it should be.

Recommendation:

Install new T-8 fluorescent fixtures with electronic ballasts everywhere but in the gym install T-5 high bay fluorescents.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Energy Efficiency Upgrade	2007	\$427,492	Medium

Updated: FEB-06

D5020.02.02.02 Interior Florescent Fixtures 1928 Section**

1972 - Fluorescent fixtures in classrooms and hallways, are T-12 pendent and surface mount 4' wraps.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	MAY-06

Event: Upgrade Fluorescent Lights to T-8 Fluorescents**Concern:**

Existing fluorescents are very inefficient and nearing the end of there life span.

Recommendation:

Replace existing T-12 fluorescents with energy efficient T-8 fixtures.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Energy Efficiency Upgrade	2006	\$221,612	Low

Updated: MAR-06

D5020.02.03 Emergency Lighting*

1988 - Emergency lighting is provided by hall lighting circuits that are powered by the emergency generator. Exit lights are also on the generator, but they have been retrofitted with LED bulbs.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	MAY-06

D5020.02.03 Emergency Lighting* 1928 Section

1982 - Emergency lighting consists of fluorescent fixtures powered by an emergency generator. Exit lights are inefficient incandescent exit lights, which are not connected to the emergency circuits on the emergency generator.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	MAY-06

Event: **Exit lighting circuits changed over to emergency circuits, and exit lights to be replaced.**

Concern:

Existing exit lights will not operate in emergency, and existing emergency lights are at the end of their life span.

Recommendation:

Replace emergency circuits and emergency exit lights.

Consequences of Deferral:

Higher cost of operation and currently there is a loss of the exit lights during a power failure.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Code Repair	2006	\$14,774	Medium

Updated: MAR-06

D5020.02.05 Special Purpose Lighting* 1928 Section

1985 - Track lighting is mounted in old music room for performance lighting.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	MAY-06

D5020.03.01.04 Exterior H.P. Sodium Fixtures*

1988 - 150 W HPS wall mount area lights have been installed above the entrance doors and the parking lot.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	FEB-06

D5020.03.01.04 Exterior H.P. Sodium Fixtures* 1928 Section

1985 - 150 W HPS fixtures for perimeter lighting, dusk-til-dawn fixture over main entrance, and flood fixture over north parking lot.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	MAY-06

D5020.03.02 Lighting Accessories (Lighting Controls)* 1928 Section

1985 - Exterior lighting control consists of local photocells on each exterior fixture.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	25	MAY-06

D5030.01 Detection and Fire Alarm**

1988 - Edwards 6500 Conventional fire alarm system, old technology with no strobe devices with bell devices.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	25	MAY-06

Event: Replace Fire Alarm System

Concern:

Existing system is missing strobe devices and parts are becoming hard to find for these systems.

Recommendation:

Install new addressable fire alarm system with horn-strobe devices.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Code Upgrade	2008	\$39,899	Low

Updated: FEB-06

D5030.02.02 Intrusion Detection**

1988 -Security system is a Magnum Alert 1000 with motion detectors and door contact. System has good coverage.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	25	MAY-06

D5030.02.02 Intrusion Detection 1928 Section**

1985 - Security system is a Magnum Alert 1000 security panel, with motion sensors in the halls, this system is becoming outdated.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	25	MAY-06

Event: Replace Security System**Concern:**

Existing security system is becoming out dated and lacks several features which the school board now requires in each school.

Recommendation:

Install new computer based security system in the school.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2006	\$22,161	Low

Updated: MAR-06

D5030.02.03 Security Access 1928 Section**

1995 - Key card system allows staff to enter the building to deactivate the security system.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	25	MAY-06

D5030.04.01 Telephone Systems**

1997 Nortel Meridian Phone system, handles paging and functions well.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	25	MAY-06

D5030.04.01 Telephone Systems 1928 Section**

1998 - Telephone system was upgraded in 1998. Telephone switch is a Nortel Norstar MOX16, with a 25 pair phone line coming into the building. The main service enters in the NE side of the building and is routed to the switch in the SW basement.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	25	MAY-06

D5030.04.02 Paging Systems*

1997 - Handled through phone system

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	15	FEB-06

D5030.04.02 Paging Systems* 1928 Section

1985 - Sound system installed through out the building, based in Allen Watson school, however the system can be controlled from the office in Hamilton.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	25	MAY-06

D5030.04.03 Call Systems 1928 Section**

1985 - Call buttons are located in each classroom, to connect to the office through the paging system.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	MAY-06

D5030.04.04 Data Systems**

1998 - Data is centralized in the LAN room above the stage. CAT 5 cabling is run in suspended ceilings free air and in conduits and surface raceway in exposed areas. Fibre optics connect the secondary data reac in the attached School Board Administration Office.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	25	MAY-06

D5030.04.04 Data Systems 1928 Section**

1998 - Computer system is based on the top floor in the LAN room, cabling is primarily CAT 5. Data link to main server in Allen Watson is a CAT 6 cable. Supernet, Telus, and WAN fiber has not been run into Hamilton school. There are 5 drops per classroom and one in every office, however there is no computer lab and there is no space in the existing patch panel for additional data runs.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	MAY-06

Event: Add Conduit and Wiring for Computer Lab**Concern:**

Existing school does not have any area to be used as a computer lab.

Recommendation:

Add conduit, wiring and data drops for a computer classroom, conduit and wire to be surface wiring

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Program Functional Upgrade	2006	\$20,930	Low

Updated: MAR-06

D5030.05 Public Address and Music Systems**

1997 - Dukane MCS 350 PA system that controls the change bells.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	FEB-06

D5030.05 Public Address and Music Systems 1928 Section**

1985 - Public Address system based in Allen Watson School. Separate gymnasium sound system. This system is becoming out dated and is missing functional features that the school requires.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	MAY-06

Event: Upgrade Public Address / Phone system

Concern:

Existing public address system is extremely limited in the functions it can perform, and additional speakers and controls are needed.

Recommendation:

Add additional speakers and controls, and replace existing PA system with a new system.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Program Functional Upgrade	2006	\$55,403	Low

Updated: MAR-06

D5030.06 Television Systems*

1988 - CAT has been brought into the building but there is no distribution through out the school.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	FEB-06

Event: Add CATV distribution to the school.

Concern:

Existing school has no CATV distribution through the school. There is no where for TV's to be utilized in the school.

Recommendation:

Add CATV drops in all classes, library, weight room, shop and gym.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Program Functional Upgrade	2007	\$8,550	Low

Updated: FEB-06

D5090.02 Packaged Engine Generator Systems (Emergency Power System)**

1988 - Emergency generator is a 10 kW Toshiba Genset which is powered from a diesel tank that is attached.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	40	MAY-06

D5090.02 Packaged Engine Generator Systems (Emergency Power System) 1928 Section**

1985 - Kohler Diesel 10 kW Gen set powers emergency lighting circuits in both schools.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	35	MAY-06

S6 EQUIPMENT, FURNISHINGS AND SPECIAL CONSTRUCTION**E1090.07 Athletic, Recreational, and Therapeutic Equipment***

The athletic, recreational and therapeutic equipment are all in good condition. Basketball backboards, nets and other accessories are all functional.

Retractable and stationary basketball nets as well as standard portable hockey and volleyball nets, hockey sticks, balls, pucks, etc. Workout room on lower level.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	15	MAY-06

E1090.07 Athletic, Recreational, and Therapeutic Equipment* 1928 Section

1928 - Gymnasium

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	MAY-06

E2010.02.05 Educational Facility Casework*

The millwork is old with stains and missing countertop in the boys washroom.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	35	MAY-06

Event: **Millwork in the Boys and Girls Washrooms in poor condition**

Concern:

There is only one girls and boys washroom for the entire student population. What is there is not acceptable as there is millwork missing, and the existing is not in good condition.

Recommendation:

Replace and add missing millwork in the Boys and Girls Washroom.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Program Functional Upgrade	2007	\$8,550	Low

Updated: NOV-06

E2010.02.05 Educational Facility Casework* 1928 Section

1928 - Cabinets, built in shelving units

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	MAY-06

Event: Replace original millwork throughout**Concern:**

Millwork is very worn and damaged.

Recommendation:

Replace millwork throughout. Approx. 35m

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2006	\$20,314	Low

Updated: JUN-06**E2010.02.07 Kitchen Casework***

Millwork in the kitchen are in good condition with no deterioration as they are fairly new. Cabinets and cupboards are in working order.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	MAY-06

E2010.02.09 Library Casework* 1928 Section

1928 - Library reception desk, book storage

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	MAY-06

Event: Replace library reception desk**Concern:**

Librarians reception desk is in poor condition. Very little millwork in library.

Recommendation:

Replace librarians desk, and add more book storage to library.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2006	\$6,156	Low

Updated: OCT-06

E2020 Moveable Furnishings* 1928 Section

1928 - Desks, chairs

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	MAY-06

F1010.02.05 Grandstands and Bleachers**

Wood bleachers in the gym are in good condition and well kept. They are still functional and look as if they have recently been refinished.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	MAY-06

S8 FUNCTIONAL ASSESSMENT**K4010.01 Barrier Free Route: Parking to Entrance**

Parking to entrance accessible from the rear of the school.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	MAY-06

K4010.01 Barrier Free Route: Parking to Entrance 1928 Section

1928 - Barrier free entrance on northside

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	MAY-06

K4010.02 Barrier Free Entrances

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
2 - Poor	0	0	MAY-06

Event: Provide power door operator at designated entrance

Concern:

There are no automatic door operator at either the front or rear entry of the school.

Recommendation:

Install automatic door operator at the rear entry door of the school which is accessible for handicap parking.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Barrier Free Access Upgrade	2007	\$11,400	Low

Updated: FEB-06

K4010.02 Barrier Free Entrances 1928 Section

1928 - North entrance at grade

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	MAY-06

K4010.03 Barrier Free Interior Circulation

Barrier free circulation throughout the school is made difficult, due to the different levels and stairs in the school.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
2 - Poor	0	0	MAY-06

Event: Provide lifts or ramps to accomodate barrier free access

Concern:

Barrier Free Circulation is poor in the school

Recommendation:

Install lifts and or ramps to accomodate for barrier free access where possible.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Barrier Free Access Upgrade	2007	\$22,800	Low

Updated: FEB-06

K4010.03 Barrier Free Interior Circulation 1928 Section

1928 - No barrier free access inside building

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	MAY-06

Event: Install chair lifts for barrier free access

Concern:

There is no barrier free access to any of the floors in existing school

Recommendation:

Install chair lifts in stair well.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Barrier Free Access Upgrade	2006	\$29,548	Low

Updated: MAR-06

K4010.04 Barrier Free Washrooms**Barrier Free Washroom**

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
2 - Poor	0	0	MAY-06

Event: Barrier Free Washroom not provided**Recommendation:**

Make provisions to upgrade the current washrooms to accommodate a barrier free washroom or provide a new washroom located central to the classrooms.

Consequences of Deferral:

Students and staff with physical disability can not be accommodated in the school given the current condition and layout of the interior circulation.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Barrier Free Access Upgrade	2007	\$11,400	Low

Updated: FEB-06

K4010.04 Barrier Free Washrooms 1928 Section**1928 - No barrier free washrooms**

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	MAY-06

Event: Install barrier free washroom**Concern:**

No barrier free washrooms available in school.

Recommendation:

Install at least one barrier free washroom on main floor.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Barrier Free Access Upgrade	2006	\$4,309	Low

Updated: MAR-06

Facility Details

Building Name: Allan Watson School
Address:
Location: Lethbridge

Building Id: S3680
Gross Area (sq. m): 0.00
Replacement Cost: \$0
Construction Year: 0

Evaluation Details

Evaluation Company:
Evaluation Date:
Evaluator Name:

Total Maintenance Events Next 5 years: \$41,746
5 year Facility Condition Index (FCI): 0%

General Summary:

North asphalt parking lot and athletic fields are shared with Allen Watson School. Landscaping is well maintained. There are some drainage issues but overall site is in good condition.

The school site is bound by two streets on the south and west side where access to the school is accommodated. The playing fields are to the north and the east side of the school is landscaped. The main entry to the school is by the street on the south side with a paved concrete pathway leading to the main level of the school, which is approximately three to four meters above street level.

The site for the school is large however the main entry to the school is hampered by the lack barrier free access from the street level. There is adequate space to accommodate for ramps if found suitable for the school. The north end of the school from the parking lot is adequate for barrier free access given the upgrade to the doors and the addition of a canopy cover. The parking lot is in need of resurfacing and new lines painted throughout. Overall the rating of the site is acceptable.

Structural Summary:

Envelope Summary:

Interior Summary:

Mechanical Summary:

Electrical Summary:

Rating Guide

Condition Rating	Performance
1 - Critical	Unsafe, high risk of injury or critical system failure.
2 - Poor	Does not meet requirements, has significant deficiencies. May have high operating/maintenance costs.
3 - Marginal	Meets minimum requirements, has significant deficiencies. May have above average operating maintenance costs.
4 - Acceptable	Meets present requirements, minor deficiencies. Average operating/maintenance costs.
5 - Good	Meets all present requirements. No deficiencies.
6 - Excellent	As new/state of the art, meets present and foreseeable requirements.

S7 SITE**G2010.02.02 Flexible Pavement Roadway (Asphalt)****

Asphalt roadway to parking lot. The roadway to the school is paved asphalt. There are catch basins throughout and there are no visible holes on the roadway.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	MAY-06

G2020.02.02 Flexible Paving Parking Lots(Asphalt)**

Paving Parking Lot-Asphalt

There are visible signs that the parking lot asphalt has been deteriorating over time. There are many areas where the asphalt is crumbling and cracks are distributed throughout.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	MAY-06

Event: Resurface the paving in the parking lot**Concern:**

Cracks and holes are evident throughout the parking lot area

Recommendation:

Resurface the parking lot and provide new parking lines in addition to designation of handicap parking stall (Approximately 800 sq. m. area).

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2007	\$34,199	Medium

Updated: JUN-06

G2020.02.02 Flexible Paving Parking Lots(Asphalt) 1928 Section**

Asphalt parking area

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	MAY-06

G2020.05 Parking Lot Curbs and Gutters*

Asphalt curbs have been incorporated with the parking lot around the perimeter of the paved areas.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	MAY-06

G2020.06.02 Parking Bumpers*

Concrete tire bumpers are provided for the parking areas.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	MAY-06

G2020.06.03 Parking Lot Signs*

Parking Lot Signs

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	MAY-06

G2020.06.04 Pavement Markings*

Pavement markings are in need of repainting as they have worn out.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	MAY-06

Event: Pavement markings are worn

Concern:

Pavement markings are worn

Recommendation:

Repaint the pavement marking in the parking lot and add handicap stall area.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2007	\$5,700	Low

Updated: MAY-06

G2030.04 Rigid Pedestrian Pavement (Concrete)**

Concrete sidewalks. Concrete stairs and pavement is provided at the front of the school from the street. They are in good condition throughout.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	MAY-06

G2030.06 Exterior Steps and Ramps*

Concrete steps. Exterior concrete stairs leading to the school are in good shape. There are no visible signs of heaving.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	MAY-06

G2040.02 Fences and Gates**

Fenced athletic fields and parking lot. There is a fenced area in the north side of the school that separates the school from the maintenance building.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	MAY-06

G2040.03 Athletic and Recreational Surfaces**

Shared athletic field with Allen Watson School. The playing fields are in good shape with grass throughout. There are no exterior basketball courts or other hard playing surfaces around the school.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	MAY-06

G2040.06 Exterior Signs*

The school sign is located on top of the front entry of the school. There are also signs in the parking areas to designate handicap stalls.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	MAY-06

G2040.06 Exterior Signs* 1928 Section

Metal lettering

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	MAY-06

Event: Replace metal signage

Concern:

Metal letters in poor condition, should be replaced

Recommendation:

Replace metal lettering with new sign.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2006	\$1,847	Low

Updated: MAR-06

G2040.08 Flagpoles*

There is a flagpole located directly in front of the front entry of the school.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	MAY-06

G2040.11 Retaining Walls*

Retaining walls at the front entry of the school are in good shape and there are no visible cracks.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	40	MAY-06

G2050.01 Irrigation Systems*

Underground sprinkler system provided.

Irrigation provided on west side. South side and field partially irrigated by City.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	MAY-06

G2050.04 Lawns and Grasses*

The school site has grassed fields and trees throughout. The site is mostly grassed around the perimeter except for the front entry, which has a concrete paved surface.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	MAY-06

G2050.05 Trees, Plants and Ground Covers*

Trees, Plants, and Ground Covers

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	MAY-06

G3010.02 Site Domestic Water Distribution* 1928 Section

Municipal service serves domestic water, irrigation water, and standpipe system.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	MAY-06

G3030.01 Storm Water Collection* 1928 Section

Storm water retained in underground tank located at front of school.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	MAY-06

Event: Replace storm retention tank.

Concern:

The exiting underground storm retention tank is undersized and has backed up into the school in the past.

Recommendation:

Replace the underground tank with an appropriately sized tank.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Code Upgrade	2006	\$61,559	Low

Updated: MAR-06

G3060.01 Gas Distribution* 1928 Section

Municipal gas supply.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	MAY-06

G4010.03 Electrical Power Distribution Equipment*

The main service transformer is a padmount 225KVA, 120/208V transformer.

Pad mount transformer adjacent to building has adequate blast wall protection.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	MAY-06

G4010.04 Car Plugs-ins*

There are car plugs on Allen Watson school parking.

Car plug-ins along building and fence, 15 in total.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	MAY-06

G4020.01 Area Lighting*

The exterior fixtures consist of one dusk-til-dawn 150 W HPS, and one 150W HPS flood light.

Area lighting is provided by wall mounted 150W HPS fixtures.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	MAY-06