Sub Total

5535

| S | chool Name: | Dr. Glady | ys McKel | vie Egbert Scho | pol | School Code: | 9650 |
|------------------------|--------------|-------------------|---------------|----------------------------|--|--|-------------------|
| Lo | ocation: | 6033 Ma | digan Dr | ive. N.E., Calga | ry | Facility Code: | 1557 |
| | | | | | | | |
| R | tegion: | Calgary | | | | Superindendent: | Dr Donna Michaels |
| Jı | urisdiction: | School D | istrict No | o. 19 | | Contact Person: | Leanne Soligo |
| | | | | | | Telephone: | (403) 214-1123 |
| | | | | | | | |
| G | Grades: | 7-9 | | | | School Capacity: | 705 |
| | | | | | | | |
| Building S | Section | Year of Compl. | No. of Floors | Gross Bldg Area (Sq.M.) | Type of Construction (i.e., structure, roof, cladding) | Description of Mechanical Systems (incl. major upgrades) | Comments/Notes |
| Original | | | | | Masonry, steel columns, beams and joists, flat roof asphalt and gravel, and clay brick/metal siding exterior cladding. | terminal radiation units, reheat coils and preheat coils in airhandling units. Two central airhandling units supply ventilation and cooling for the classrooms. | |
| Addition: Expansion | | 1981 | | 1616.3 | joists, flat roof asphalt and gravel, and clay brick/metal siding exterior | Hot water boilers from two boiler rooms supply heating media for the terminal radiation units, reheat coils and preheat coils in airhandling units. Two central airhandling units supply ventilation and cooling for the classrooms. | |

School Facility Evaluation Project Part I - Facility Profile and Summary

| Evaluation Components | Summary Assessment | | | | | | | |
|--|---|--------------|--|--|--|--|--|--|
| Site Conditions | Overall site size is good and has an adjacent community center on north side. Parking lot is asphalt need to lower the storm drain and reslope paving to allow for proper drainage. There is a problem with ice buildup on north entrance to school causing ponding and large areas of ice at sidewalk. Needs some resloping and pouring of new slab. | | | | | | | |
| Building Exterior | Clay brick and stucco mostly around building lower walls and vertical metal siding and mansard roof at upper walls. Vertical metal mansard roof around perimeter of building including roof of gymnasium. Weatherstripping is in poor condition and needs to be replaced. | \$8,000.00 | | | | | | |
| Building Interior | VCT in corridors and interior rooms. Carpet in classrooms, library, staff areas and all exterior rooms at south and west of building. Carpet in poor condition and needs to be replaced. | \$150,000.00 | | | | | | |
| Mechanical Systems | Primary concern is the lack of outdoor air supply and circulation of dust from woodworking area and floor diffusers. Other concerns are continual maintenance requirement for blocked sanitary drainage lines plus boiler room maintenance items.Replace existing heat and vent system and dust collector for industrial arts room and generally upgrade central control system. Replace sanitary sewer line which is continuously causing plugged drain. | \$394,000.00 | | | | | | |
| Electrical Systems | Underground power feed. 208VAC, 3 phase feed to main switch in electrical room. Main service is 1400 amps Fire alarm system is in need of upgrading should install visual devices as required by code. Main service requires surge protection. Replace breakers in distribution panels. | | | | | | | |
| 6 Portable Buildings | Electrical systems in portable are suitable for intended use with sub-panels located in each. Ventilation for relocatables is supplied from floor diffusers from central air handling units. Air supply appears inadequate and is also creating dust. Replace ventilation system with separate roof top HVAC system. | \$76,000.00 | | | | | | |
| Space Adequacy: | | | | | | | | |
| 7.1 Classrooms | -14.57% deficient | | | | | | | |
| 7.2 Science Rooms/Labs | -0.82% deficient | | | | | | | |
| 7.3 Ancillary Areas | -11.34% deficient | | | | | | | |
| 7.4 Gymnasium | -45.48% deficient Gym is very small for High School especially for this schools capacity. | | | | | | | |
| 7.5 Library/Resource Areas | 6.71% surplus | | | | | | | |
| 7.6 Administration/Staff Areas | 2.44% surplus | | | | | | | |
| 7.7 CTS Areas | -38.04% deficient Program includes fewer CTS functions than allowed for on equivalent new facility. | | | | | | | |
| 7.8 Other Non-Instructional Areas (inc gross-up) | . 29.51% surplus | | | | | | | |
| Overall School Conditions & Estim. Co | -7.57% deficient over total area. | \$724.000.00 | | | | | | |

| Section 1 | Site Conditions | Rating | Comments/Concerns | Estim. Cost |
|-----------|---|--------|---|-------------|
| 1.1 | General Site Condions | | | |
| 1.1.1 | Overall site size. | 4 | Overall site size is good with an adjacent community center on north side. | |
| 1.1.2 | Outdoor athletic areas. | 4 | Large flat area for play fields, softball etc. No problems reported or evident. | |
| | Outdoor playground areas, including condition of equipment and base. | 4 | Large playing fields with goal posts, back stops etc. | |
| 1.1.4 | Site landscaping. | 4 | Mostly grass with minimal perimeter planting primarily at North entrance to school. | |
| | Site accessories (i.e., perimeter and other fencing, guard rails, bike stands, flag poles). | 4 | Good condition some metal link fencing on part of noth east lot between lot and school. | |
| | Surface drainage conditions (i.e., drains away from building, signs of ponding). | 4 | General site condition allows adequate drainage. | |
| 1.1.7 | Evidence of sub-soil problems. | 4 | None reported or evident. Appears good. | |
| 1.1.8 | Safety and security concerns due to site conditions. | 4 | None reported or evident. Appears good. | |
| Other | | | | |
| | | | | |

| Section 1 | Site Conditions | Rating | Comments/Concerns | Estim. Cost |
|-----------|--|--------|---|-------------|
| 1.2 | Access/Drop-Off Areas/Roadways/Bus Lanes | | | |
| | Vehicular and pedestrian access points (i.e., size, number, visibility, safety). | 4 | Parking lot on north side of school accessed from Madigan Drive on East side of school. Minimal but sufficient parking. | |
| | Surfacing of on-site road network (note whether asphalt or gravel). | 4 | Asphalt paved on north side adjacent to main entrance. | |
| | Bus lanes/drop-off areas (note whether on-site or off site). | | Buses drop-off on Madigan Drive and from north parking area adjacent to north entrance. Works well according to on site personnell. | |
| 1.2.4 | Fire vehicle access. | 4 | Good access to school. | |
| 1.2.5 | Signage. | | School identification on North face of building of good scale but difficult to read because it is clear aluminum finish and blends with color of brick. | |
| Other | | | | |
| | | | | |

| Section 1 | Site Conditions | Rating | Comments/Concerns | Estim. Cost |
|-----------|--|--------|---|-------------|
| 1.3 | Parking Lots and Sidewalks | | | |
| 1.3.1 | Number of parking spaces for staff, students and visitors (including stalls for disabled persons). | 4 | Adequate number of stalls on north side of school. Also adjacent community center on north side acts as drive through for drop off etc. | |
| 1.3.2 | Layout and safety of parking lots. | 4 | Appears to work well . | |
| 1.3.3 | Surfacing and drainage of parking lots (note whether asphalt or gravel). | 3 | Lot is asphalt. Need to lower storm drain and reslope paving to allow for better drainage. Refer to 1.3.5 re ponding. | \$25,000.00 |
| 1.3.4 | Layout and safety of sidewalks. | 4 | The sidewalk layout is quite extensive and works well. Tied into city sidewalk system. | |
| 1.3.5 | Surfacing and drainage of sidewalks (note type of material). | 3 | Problem with ice buildup on north side of school causing ponding and large areas of ice at sidewalk. Needs some regrading at walkway/entrance plaza. To drain towards parking lot/driveway. | \$15,000.00 |
| 1.3.6 | Curb cuts and ramps for barrier free access. | 4 | Appears adequate no problems noted or reported by staff. | |
| Other | | | | |
| | | | | \$40,000.00 |
| | Overall Site Conditions & Estimated Costs | | | \$40,00 |

| Section 2 | Building Exterior | Rating | | Comments/Concerns | Estim. Cost |
|-----------|---|--------|---------|--|-------------|
| 2.1 | Overall Structure | | Bldg. | | |
| | Floor structure and beams (i.e., signs of bending, cracking, heaving, settlement, voids, rust, stains). | 4 | Section | Description/Condition Cast in place concrete slab on grade no problems evident or reported. | |
| 2.1.2 | Wall structure and columns (i.e., signs of bending, cracking, settlement, voids, rust, stains). | 4 | | Loadbearing concrete block perimeter walls, steel columns, beams and open web steel joists and steel roof deck. All in good condition. | |
| 2.1.3 | Roof structure (i.e., signs of bending, cracking, voids, rust, stains). | 4 | | Open web steel joists and steel roof deck. | |
| Other | | | | | |

| Section 2 | Building Exterior | Rating | | Comments/Concerns | Estim. Cost |
|-----------|--|----------------|----------------|---|-------------|
| | Roofing and Skylights | | Bldg. | Description/Condition/Age | |
| | Identify the availability of an up-to-date | | Section or | | |
| | inspection report or roofing program. Note if roof | | Roof | | |
| | sections are of different ages and/or in varying | | <u>Section</u> | | |
| | Based on the inspection report (and to the extent | F/I | | Asphalt and gravel approximately 50% has been replaced in past 5 years remainder | |
| | possible, direct observation), assess and rate roof conditions and estimate costs for required | | | seems to be performing reasonably well but needs to be inspected and likely replaced in | |
| | improvements (i.e., covering materials, membrane, | | | next 5 years. No roofing report available. | |
| | insulation, other components). | | | | |
| | modation, other compensions). | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | Roof accessories (i.e., ladders, stairs, hatches, | 4 | | Adequate. | |
| | masts, exhaust hoods, chimneys, gutters, | | | | |
| | downspouts, splashpads). | | | | |
| | | | | | |
| 2.2.3 | Control of ice and snow falling from roof. | F.I. | | Snow and ice falls from mansard roof around building, however no solutions to the | |
| | | | | problem appears to be evident. | |
| | | | | | |
| | | | | | |
| 2.2.4 | Skylights (i.e., signs of distress, leaks, ice build-up, | 4 | | Some lighting tubes installed in interior rooms. | |
| | condensation, deteriorated materials/seals). | l [*] | | | |
| | , | | | | |
| | | | | | |
| Othor | | | | | |
| Other | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| 1 | | | | | l |

| | Building Exterior | Rating | | Comments/Concerns | Estim. Cost |
|-------|--|--------|----------------|---|-------------|
| 2.3 | Exterior Walls/Building Envelope | | Bldg. | <u>Description/Condition</u> | |
| 2.3.1 | Exterior wall finishes (i.e., signs of deterioration, cracks, brick spalling, effluorescence, water stains). | 4 | <u>Section</u> | Clay brick and stucco mostly around building lower walls and vertical metal siding and mansard roof at upper walls. | |
| | Fascias, soffits, parapets (i.e., signs of looseness, stains, rust, peeling paint). | 4 | | Vertical metal mansard roof around perimeter of building including roof of gymnasium. All in good condition. | |
| | Building envelope (i.e., evidence of air infiltration/ exfiltration through the exterior wall or ice build up on wall, eaves, canopy). | 4 | | None noted or reported. | |
| | Interface of roof drainage and ground drainage systems. | N/A | | | |
| | Inside faces of exterior walls (i.e., signs of cracks, water stains, dust spots). | 4 | | None evident. | |
| Other | | | | | |
| | | | | | |

| Section 2 | Building Exterior | Rating | | Comments/Concerns | Estim. Cost |
|-----------|---|--------|-----|--|-------------|
| 2.4 | Exterior Doors and Windows | | | | |
| | Doors (i.e., signs of deterioration, rusting metal, glass cracks, peeling paint, damaged seals, sealed unit failure). | 4 | | Painted solid core wood doors in pressed steel frames. Good condition. | |
| | Door accessories (i.e., latches, hardware, screens, locks, alarms, holders, closers, security devices). | 3 | All | Latches, closers, door retention chains In good condition. Weatherstripping in poor condition and needs to be replaced. | \$8,000.00 |
| | Exit door hardware (i.e., safety and/or code concerns). | 4 | | Push panel type good condition. | |
| | Windows (i.e., signs of deterioration, rusting metal, glass cracks, peeling paint, damaged seals, sealed unit failure). | 4 | | Prepainted aluminum with sealed double glazing, no vents. Good condition some double glazed single panel units in aluminum frames. | |
| | Window accessories (i.e., latches, hardware, screens, locks, alarms, holders, closers, security devices). | 4 | | Non opening windows in good condition. | |
| | Building envelope (i.e., signs of heavy condensation on doors or windows). | 4 | | None evident. | |
| Other | | | | | |
| | | | | | |
| | Overall Bldg Exterior Condition & Estim Costs | | | | \$8,000.00 |

| Section 3 | Building Interior - Overall Conditions | Rating | | Comments/Concerns | Estim. Cos |
|-----------|---|--------|-----------------------|---|-------------|
| 3.1 | Interior Structure | | Bldg. Section | Description/Condition | |
| 3.1.1 | Interior walls and partitions (i.e., signs of cracks, spalling, paint peeling). | 4 | | Painted concrete block generally throughout with some painted drywall. All in good condition. | |
| 3.1.2 | Floors (i.e., signs of cracks, heaving, settlement). | 4 | | Concrete slab on grade no sign of distress. | |
| Other | | | | | |
| 3.2 | Materials and Finishes | | Bldg. | | |
| 3.2.1 | Floor materials and finishes. | 2 | <u>Section</u> All | <u>Description/Condition</u> VCT in corridors and interior rooms. Carpet in classrooms, library, staff areas and all exterior rooms at south and west of building. Carpet in poor condition and needs to be replaced. | \$150,000.0 |
| 3.2.2 | Wall materials and finishes. | 4 | | Painted concrete block generally throughout with some painted drywall and some vinyl covered drywall. Good condition. | |
| 3.2.3 | Ceiling materials and finishes. | | | | |
| | | | | | |

| Section 3 | Building Interior - Overall Conditions | Rating | | Comments/Concerns | Estim. Cost |
|-----------|---|--------|------------------|---|-------------|
| 3.2 | Materials and Finishes (cont'd) | | Bldg. Section | Description/Condition | |
| 3.2.4 | Interior doors and hardware. | 4 | | Wood doors in pressed steel frames. Good condition. | |
| | | | | | |
| 3.2.5 | Millwork | 4 | | Painted plywood with plastic laminate tops. Clear finish plywood in science labs. | |
| 3.2.6 | Fixed/wall mounted equipment (i.e., writing boards, tackboards, display boards, signs). | 4 | | Blackboards, vinyl tackboards throughout in good condition. | |
| 3.2.7 | Any other fixed/mounted specialty items (i.e., CTS equipment, gymnasium equipment). | 4 | | Basketball backstops/hoop (folding type) good condition. | |
| 3.2.8 | Washroom materials and finishes. | 4 | | Ceramic floor tile and tile at urinals, painted concrete block walls and painted drywall ceiling, prepainted metal toilet partitions. Good condition. | |
| Other | | | | | |
| | | | | | |

| Section 3 | Building Interior - Overall Conditions | Rating | | Comments/Concerns | Estim. Cost |
|-----------|---|--------|------------------|--|--------------|
| | Health and Safety Concerns Intent is to identify renovations considered necessary to meet applicable codes, primarily due to safety concerns. Basis of evaluation should be an up-to-date inspection report from the authority having jurisdiction together with direct observations as appropriate. Evaluator should note if in his opinion a comprehensive code evaluation is required. | | Bldg. Section | <u>Description/Condition</u> | |
| | Building construction type - combustible or non- combustible, sprinklered or non-sprinklered. | 4 | | Non combustible, non sprinklered. | |
| | Fire separations (i.e., between buildings, wings, zones if non-sprinklered). | 4 | | Adequate. | |
| | Fire resistance rating of materials (i.e., corridor walls and doors). | 4 | | Adequate. | |
| 3.3.4 | Exiting distances and access to exits. | 4 | | Adequate. | |
| 3.3.5 | Barrier-free access. | 4 | | Fully accessible including portables. | |
| | Availability of hazardous materials audit (i.e., evidence of safety concerns with respect to asbestos, PCB's, chemicals). | 4 | | No evidence of any problems or concerns. | |
| | Other health and safety concerns (i.e., evidence of excessive noise conditions, air quality problems) | F.I. | | Air quality poor after hours due to fresh air intake shutdown. Makes it difficult to use school after hours. | |
| Other | | | | | |
| | Overall Bldg Interior Condition & Estim Costs | | | | \$150,000.00 |

| | Mechanical Systems | Rating | | Comments/Concerns | Estim. Cost |
|-------|--|--------|--------------|---|-------------|
| 4.1 | Mechanical Site Services | | | | |
| | Site drainage systems (i.e., surface and underground systems, catch basins). | 4 | | Catch basin provided in parking lot. Refer also to 1.3.3. | |
| 4.1.2 | Exterior plumbing systems (i.e., irrigation systems, hose bibs). | 4 | | Has exterior frostproof hose bibs. Has provisions for irrigation system. | |
| 4.1.3 | Outside storage tanks. | N/A | | | |
| Other | | | | | |
| 4.2 | Fire Suppression Systems | | Bldg. | Description/Condition | |
| | | | Section | | |
| 4.2.1 | Fire hydrants and siamese connections. | 3 | 1975 1981 | Fire hydrant is available. Install siamese connection. Includes allowance for architectural work. | \$10,000.00 |
| | Fire suppression systems (i.e., pumps, sprinklers, piping, reservoirs, hoses, stand pipes, CO2 systems). | 4 | | Stand pipe and hose system existing. Fire extinguisher is installed in hose cabinet. | |
| | Hand extinguishers, blankets and showers (i.e., in CTS areas). | 4 | | Fire extinguishers are provided in boiler room, storage, I.A. Shop, etc. | |
| 4.2.4 | Other special situations (e.g., flammable storage areas, science labs, CTS areas). | N/A | | | |
| Other | | | | | |
| | | | | | |
| | | | | | |

| Section 4 | Mechanical Systems | Rating | | Comments/Concerns | Estim. Cost |
|-----------|---|--------|------------------|--|-------------|
| | Water Supply and Plumbing Systems | | Bldg. Section | <u>Description/Condition</u> | |
| 4.3.1 | Domestic water supply (i.e., pressure, volume, quality - note whether municipal or well supply). | 4 | <u> </u> | Water pressure and volume is satisfactory. Connected to city water system. | |
| 4.3.2 | Water treatment system(s). | N/A | | | |
| 4.3.3 | Pumps and valves (including backflow prevention valves). | 4 | | Appears satisfactory. | |
| 4.3.4 | Piping and fittings. | 4 | | No known problem. | |
| 4.3.5 | Plumbing fixtures (i.e., toilets, urinals, sinks) | 4 | | Water closets have flush valves. Urinals are tank operated and energized when lights are on. Wall hung enamel cast iron lavatory. All in good condition. | |
| | Domestic hot water system (i.e., heater, storage tanks, failure alarms, pressure, volume, recirculation). | 3 | 1975 1981 | Original 1975 building has 2 STATE SBT-70-360 hot water tanks, 324.0 MBH input and 70 gallon storage tank which are satisfactory. 1981 addition has 2 RUUD GL67-120-5A gas fired tanks and heaters. Replace one damaged tank and heater. Both systems have domestic hot water recirc. pumps. | \$4,000.00 |
| | Sanitary and storm sewers, including sumps and pits (note whether sewage system is municipal or septic). | 3 | 1975 1981 | Sanitary sewer is connected to city system. Rain water leader is connected to city storm sewer system. Replace and/or clean sanitary sewer lines inside and outside building. | \$30,000.00 |
| Other | | | | | |
| | | | | | |

| Section 4 | Mechanical Systems | Rating | | Comments/Concerns | Estim. Cost |
|-----------|---|--------|------------------|--|-------------|
| 4.4 | Heating Systems | | Bldg. Section | Description/Condition | |
| 4.4.1 | Heating capacity and reliability (including backup capacity). | 3 | 1975 1981 | 1975 building has 2 Bryan 1-36W boilers with 2,350.0 MBH input system complete with 3 base mounted pumps. 1981 addition has 2 Bryan CL-120W boilers with 1,080.0 input. System is complete with 3 base mounted pumps. Replace circulation pumps, some leaky control valves, check and if necessary replace one boiler installed in 1975. Includes allowance for architectural and electrical work. | \$80,000.00 |
| 4.4.2 | Heating controls (including use of current energy management technology. | 4 | | JOHNSON pneumatic control system is installed . Consider installation of energy management system. | |
| 4.4.3 | Fresh air for combustion and condition of the combustion chimney. | 4 | | Direct gas fired Eng 'A' units (2) installed to provide CA for boiler room in 1975 building. | |
| 4.4.4 | Treatment of water used in heating systems. | 4 | | Water treatment equipment is provided. | |
| 4.4.5 | Low water cutoff/pressure relief valves and failure alarms (i.e., hot water heating). | 4 | | Appears to be operating satisfactorily. | |
| 4.4.6 | Heating air filtration systems and filters. | N/A | | | |
| 4.4.7 | Heating humidification systems and components. | N/A | | | |

| Section 4 | Mechanical Systems | Rating | | Comments/Concerns | Estim. Cost |
|-----------|---|--------|------------------|--|-------------|
| 4.4 | Heating Systems (cont'd) | | Bldg. Section | Description/Condition | |
| 4.4.8 | Heating distribution systems (i.e., piping, ductwork) and associated components (i.e., diffusers, radiators). | 4 | | Piping distribution, reheat coil, preheat coil for interior zone and perimeter radiation are satisfactory. | |
| 4.4.9 | Heating piping, valve and/or duct insulation. | 4 | | Pipe and insulation appear satisfactory. | |
| 4.4.10 | Heat exchangers. | N/A | | | |
| 4.4.11 | Heating mixing boxes, dampers and linkages. | 4 | | Reheat coils satisfactory. | |
| 4.4.12 | Heating distribution/circulation in larger spaces (i.e., user comfort, temperature of outside wall surfaces). | F.I. | 1975 | Erratic control system requires further detailed investigation. | |
| 4.4.13 | Zone/unit heaters and controls. | 4 | 1975 1981 | Unit heaters provided in fan room. Fan coil units at entrance. Units controled with electric thermostat. | |
| Other | | | | | |
| | | | | | |

| Section 4 | Mechanical Systems | Rating | | Comments/Concerns | Estim. Cost |
|-----------|--|--------|--------------------------------|--|--------------|
| 4.5 | Ventilation Systems | | Bldg. | Description/Condition | |
| 4.5.1 | Air handling units capacity and condition. | 3 | <u>Section</u> 1975 1981 | 1975 building central air handling unit system consists of: supply fan, centrifugal return fam, mixing section, filter section, preheat coil, DX cooling and humidifier. Recommend gym and portables have separate heat/vent. 1981 addition: Trane central air handling unit consists of:a return fan, mixing section, filter, heating coil, DX cooling and humidifier.Includes allowance for architectural and electrical work. | \$114,000.00 |
| 4.5.2 | Outside air for the occupant load (if possible, reference CFM/occupant). | 4 | | Complaint of lack of outdoor air supply. Addition of separate air handling system for gym and portables will increase O.A. supply to classrooms. Replace damaged louver and modify plenum.Refer to 4.5.1 | |
| 4.5.3 | Air distribution system (if possible, reference number of air changes/hour). | 4 | | Air distribution to gym and portables from central air handling system. Supply air from floor creates dust condition. Recommend air be supplied from side wall or ceiling.Refer to 4.5.1 | |
| 4.5.4 | Exhaust systems capacity and condition. | 4 | | Recirculation fans for both central system appear to be working satisfactorily. | |
| 4.5.5 | Separation of out flow from air intakes. | 3 | 1981 | Exhaust air is blowing down toward intake. Modify exhaust hood. | \$3,000.00 |
| 4.5.6 | Special/dedicated ventilation and/or exhaust systems (i.e., kitchen, labs, CTS areas). | 3 | 1975 1981 | Dust collector supply for woodworking shop is too small. Replace non-operational exhaust systems existing for washrooms, dark room, welding, paint hood, arts, etc. Provide cooling system for food preparation area. Note: Woodworking shop does not have any operable windows.Includes allowance for architectural and electrical work. | \$70,000.00 |
| Other | | 3 | 1975 1981 | Industrial arts supply unit near end of its usefulness. Replace with new roof top gas fired indirect fired heat and vent unit, and duct supply and return to ceiling. Balance entire system. Clean ducts. Includes allowance for architectural and electrical work. | \$55,000.00 |

| Section 4 | Mechanical Systems | | | Estim. Cost | |
|-----------|--|-----|------------------|--|--|
| | Ventilation Systems (cont'd) | | Bldg. Section | Description/Condition | |
| | Note: Only complete the following items if there are separate ventilation and heating systems. | | | | |
| | Ventilation controls (including use of current energy management technology). | 4 | | JOHNSON and BARBER COLMAN pneumatic control system installed. Consider energy management system. Refer to 4.7.1 | |
| 4.5.8 | Air filtration systems and filters. | 4 | | Flat filters provided. | |
| 4.5.9 | Humidification system and components. | 4 | | 1975 Building has wet cell humidifier. 1981 addition has spray humidifier. | |
| 4.5.10 | Heat exchangers. | N/A | | | |
| | Ventilation distribution system and components (i.e., ductwork, diffusers, mixing boxes, dampers, linkages). | 4 | | Duct distribution and diffusers are satisfactory. Should consider abandoning below slab air distribution system.Refer to 4.5.1 | |
| Other | | | | | |
| | | | | | |

| Section 4 | Mechanical Systems | Rating | | Comments/Concerns | Estim. Cost |
|-----------|---|--------|--------------------------------|---|--------------|
| 4.6 | Cooling Systems | | Bldg. Section | <u>Description/Condition</u> | |
| | Cooling system capacity and condition (i.e., chillers, cooling towers, condensers). | 4 | 1975 1981 | Separate air cooled condensing units for 1975 and 1981 central air handling units. | |
| 4.6.2 | Cooling distribution system and components (i.e., ductwork, diffusers, mixing boxes, dampers, linkages) | 4 | | Refer to 4.5.11 | |
| | Cooling system controls (including use of current energy management technology). | 4 | | Interlocked to operate with air handling units. | |
| 4.6.4 | Special/dedicated cooling systems (i.e., labs, CTS areas). | N/A | | | |
| Other | | | | | |
| 4.7 | Building Control Systems | | Bldg. | Description/Condition | |
| | Building wide/system wide control systems and/or energy management systems. | 3 | <u>Section</u> 1975 1981 | JOHNSON and BARBER COLMAN pneumatic control systems provided. Consider providing energy management system. Includes allowance for architectural work. | \$28,000.00 |
| | Overall Mech Systems Condition & Estim. Costs | | | | \$394,000.00 |

| Section 5 | Electrical Systems | Rating | | Comments/Concerns | Estim. Cost |
|-----------|--|--------|----------------|--|-------------|
| 5.1 | Site Services | | | | |
| 5.1.1 | Primary service capacity and reliability (i.e., access, location, components, installation, bus sizes - note whether overhead or underground). | 4 | | Underground power feed. 208VAC, 3 phase feed to main switch in electrical room. Main service is 1400 amps | |
| 5.1.2 | Site and building exterior lighting (i.e., safety concerns). | 4 | | Exterior site lighting is adequate. | |
| 5.1.3 | Vehicle plug-ins (i.e., number, capacity, condition). | 4 | | Existing system is adequate for intended use. System is controlled by time clock or temperature controller. | |
| Other | | | | | |
| 5.2 | Life Safety Systems | | Bldg. | | |
| | | | <u>Section</u> | <u>Description/Condition</u> | |
| 5.2.1 | Fire and smoke alarm systems (i.e., safety concerns, up-to-date technology, regularly tested). | 2 | All | Fire alarm system is an Edwards 6616 in good condition. System is tested annually as required by code. System is well maintained. Install visual devices as required by code. | \$8,000.00 |
| 5.2.2 | Emergency lighting systems (i.e., safety concerns, condition). | 4 | | Existing system is in good condition. System is well maintained. | |
| 5.2.3 | Exit lighting and signage (i.e., safety concerns, condition). | 4 | | Existing system is in good condition. System is well maintained. | |
| Other | | | | | |
| | | | | | |

| Section 5 | Electrical Systems | Rating | | Comments/Concerns | Estim. Cost |
|-----------|--|--------|------------------|--|-------------|
| 5.3 | Power Supply and Distribution | | Bldg. Section | Description/Condition | |
| 5.3.1 | Power service surge protection. | 3 | All | No power surge protection install on the system. Minimum recommendation is to install on main service. | \$13,000.00 |
| 5.3.2 | Panels and wireways capacity and condition. | 3 | All | Panels are all in good condition. Most are at capacity with little or no spare circuits available. Wireways are also at capacity. Breakers are aging and continually tripping. Replace breakers. | \$10,000.00 |
| 5.3.3 | Emergency generator capacity and condition and/or UPS (if applicable). | N/A | | N/A | |
| 5.3.4 | General wiring devices and methods. | 3 | All | Devices are generally in good condition. Most are adequate for intended use. Some are damaged and cracked. Replace 20% of devices. | \$2,500.00 |
| 5.3.5 | Motor controls. | 4 | | Motor controls are in good condition. Most are adequate for the intended job. | |
| Other | | | | | |
| | | | | | |

| Electrical Systems | Rating | | Comments/Concerns | Estim. Cost |
|---|--|---|---|--|
| | | Bldg. Section | Description/Condition | |
| Interior lighting systems and components (i.e., illumination levels, conditions, controls). | 3 | AII | | \$2,500.00 |
| Replacement of ballasts (i.e., health and safety concerns). | 4 | | No evidence of ballasts containing PCB's. | |
| Implementation of energy efficiency measures and recommendations. | 3 | All | exterior lights). Motion sensors for washrooms and other non- | |
| | | | | |
| | Interior lighting systems and components (i.e., illumination levels, conditions, controls). Replacement of ballasts (i.e., health and safety concerns). | Interior lighting systems and components (i.e., illumination levels, conditions, controls). Replacement of ballasts (i.e., health and safety concerns). Implementation of energy efficiency measures and recommendations. | Bldg. Section 3 | Interior lighting systems and components (i.e., illumination levels, conditions, controls). All Interior lighting system consists of various fluorescent systems. Classrooms are 2'x4' recessed lighting. Hallway has 1'x4' recessed lighting. Gym consists of metal halide high bay fixtures. Fixtures are typically from original construction. Lighting levels are as follows: Classroom - 45fc; Hallways - 35fc; Gym - 45fc; Offices - 50fc; Library - 40fc; Portables - 45fc. Some metal halide fixtures in need of relamping. Implementation of energy efficiency measures and recommendations. All Some energy efficient systems are in place (time clocks for exterior lights). Motion sensors for washrooms and other non-critical areas are to be installed. (Future recommendation is to install light fixtures with T-8 lamps c/w electronic ballasts). |

| Section 5 | Electrical Systems | Rating | | Comments/Concerns | Estim. Cost |
|-----------|--|--------|------------------|---|-------------|
| 5.5 | Network and Communication Systems | | Bldg. Section | Description/Condition | |
| 5.5.1 | Telephone system and components (i.e., capacity, reliability, condition). | 4 | | Existing system is a Meridian Northstar. System is adequate for intended use. | |
| 5.5.2 | Other communication systems (i.e., public address, intercom, CCTV, satellite or cable TV). | 4 | | Public Address system is a Sony. System is adequate for intended use. No other systems are installed. Fibre optic computer link in place. | |
| 5.5.3 | Network cabling (if available, should be category 5 or better). | 4 | | Cat. 5 cabling is installed for all Computers on site. Outlets are typically installed in every classroom with provisions for future. | |
| 5.5.4 | Network cabling installation (i.e., in conduit, secured to walls or tables). | 4 | | All network cabling is installed in wireways and run free-air in the ceiling space. | |
| 5.5.5 | Wiring and telecommunication closets (i.e., size, security, ventilation/cooling, capacity for growth). | 4 | | Network server installed in closet in separate room. Installation is neat and clearly labeled. | |
| 5.5.6 | Provision for dedicated circuits for network equipment (i.e., hubs, switches, computers). | 3 | All | Network server and computers in computer room are wired on dedicated circuits. All others in classrooms are not. Add dedicated circuits to classrooms | \$12,000.00 |
| Other | | | | | |

| Section 5 | Electrical Systems | Rating | | Comments/Concerns | Estim. Cost |
|-----------|--|--------|------------------|--|-------------|
| 5.6 | Miscellaneous Systems | | Bldg. Section | Description/Condition | |
| 5.6.1 | Site and building surveillance system (if applicable). | N/A | <u> </u> | | |
| 5.6.2 | Intrusion alarms (if applicable). | 4 | | Existing system is a Regency. System is in good condition with door contacts and motion detectors operating as intended. | |
| 5.6.3 | Master clock system (if applicable). | 3 | All | Master timer in place. Master clock system installed for some clocks. Upgrade clock system to include all clocks | \$3,000.00 |
| Other | | | | | |
| 5.7 | Elevators/Disabled Lifts (If applicable) | | | | |
| 5.7.1 | | N/A | | | |
| 5.7.2 | Condition of elevators/lifts. | N/A | | | |
| 5.7.3 | Lighting and ventilation of elevators/lifts. | N/A | | | |
| Other | | | | | |
| | Overall Elect. Systems Condition & Estim Costs | | | | \$56,000.00 |

| Section 6 | Portable Buildings | Rating | Comments/Concerns | Estim. Cost |
|-----------|--|--------|--|-------------|
| | Note: Separate sheets can be completed, if necessary, for portable buildings of different ages and/or conditions. | | | |
| | Foundation and structure (i.e., signs of bending, cracking, settlement, rust, voids, stains). | 4 | Timber support with plywood skirting at modular portables Steel floor beams with metal deck supported by concrete posts at permanent portables. | |
| 6.1.2 | Roof materials and components (i.e., signs of deterioration, leaks, ice build-up). | F/I | Asphalt and gravel with some leakage. | |
| 6.1.3 | Exterior wall finishes (i.e., signs of deterioration, cracks, water stains). | 3 | Vertical metal siding and horizontal wood upper wall fascia badly deteriorated. (rm 152/153) Vertical metal siding and vertical upper wall facia siding on all others. | \$6,000.00 |
| | Doors and windows (i.e., signs of deterioration, rusting hardware, glass cracks, peeling paint, damaged seals). | 4 | Aluminum in solid core doors and frames, Aluminum sliding panel double glazed single pane windows/screens. Solid core wood painted in steel frames. | |
| 6.1.5 | Interior finishes (i.e., floors, walls, ceiling). | 4 | Painted drywall walls, vinyl panel ceilings, carpet floors. Vinyl finished drywall panels, acoustic panel tee bar ceiling, carpet floors. Painted drywall, acoustic panel tee bar, carpet floor. | |
| 6.1.6 | Millwork (i.e., counters, shelving, vanities, cabinets). | N/A | | |
| | Fixed/wall mounted equipment (i.e., writing boards, tackboards, display boards, signs) | 4 | Green chalkboards, vinyl covered tackboards in aluminum frames. | |
| 6.1.8 | Heating system. | 3 | Ventilation for relocatables are supplied from floor diffusers from central air handling units. Air supply appears inadequate and also is creating dust. Replace ventilation system with separate roof top HVAC system. Estimated cost \$70,000.00 | |
| 6.1.9 | Ventilation system. | 4 | See 6.1.8 | |
| 6.1.10 | Electrical, communication and data network systems. | 4 | Electrical systems in portable are suitable for intended used. Sub-panels are located in each. | |
| | Health and safety concerns (i.e., fire and smoke alarms, fire protection systems, exiting, fire resistance rating of materials). | 4 | None noted or reported. | |
| 6.1.12 | Barrier-free access. | 4 | Adequate works well. | |
| | Overall Portable Bldgs Condition & Estim Costs | | | \$76,000.00 |

| | | | This Fa | cility | Ec | quiv. Nev | w Facility | Surplus/ | |
|-----------|--|-----|---------|------------|-----|-----------|------------|------------|-------------------|
| Section 7 | Space Adequacy | No. | Size | Total Area | No. | Size | Total Area | Deficiency | Comments/Concerns |
| 7.1 | Classrooms K-6 | 15 | 72.9 | 1093.5 | 16 | 80 | 1280.0 | -186.5 | |
| 7.2 | Science Rooms/Labs | 3 | 158.69 | 476.07 | 4 | 120 | 480.0 | -3.9 | |
| | Ancillary Areas (i.e., Art, Computer Labs, Drama, Music,) | 4 | 117.47 | 469.88 | 2 3 | 130 90 | 530.0 | -60.1 | |
| 7.4 | Gymnasium (incl. gym storage) | 1 | | 489 | 1 | 897 | 897.0 | -408.0 | |
| 7.5 | Library/Resource Areas | 1 | | 330.8 | 1 | 310 | 310.0 | 20.8 | |
| | Administration/Staff, Physical Education, Storage Areas | | | 779.58 | | | 761.0 | 18.6 | |
| 7.7 | CTS Areas | | | | | | | | |
| | 7.7.1 Business Education | 1 | 68.7 | 68.7 | 3 | 115 | 345.0 | -276.3 | |
| | 7.7.2 Home Economics | 2 | | 220.1 | 2 | | 256.0 | -35.9 | |
| | 7.7.3 Industrial Arts | 2 | | 364.73 | 2 | | 456.0 | -91.3 | |
| | 7.7.4 Other CTS Programs | | | | | | 0.0 | 0.0 | |
| | Other Non-Instructional Areas (i.e., circulation, wall area, crush space, wc area) | | | 2166.84 | | | 1673.0 | 493.8 | |
| | Overall Space Adequacy Assessment | 29 | | 6459.2 | 34 | | 6988.0 | -528.8 | |

| Evaluation Component/ | |
|--|-------------------------------|
| Evaluation Component/ Sub-Component | Additional Notes and Comments |
| 8.1.1 | |
| | |
| | |
| 8.1.2 | |
| 6.1.2 | |
| | |
| | |
| 8.1.3 | |
| | |
| | |
| | |
| 8.1.4 | |
| | |
| | |
| 8.1.5 | |
| | |
| | |
| | |
| | |
| 8.1.6 | |
| | |
| | |
| | |
| | |
| 8.1.7 | |
| | |
| | |
| | |
| | |
| 8.1.8 | |
| | |
| | |
| | |
| 8.1.9 | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

| Evaluation Component/ Sub-Component | Additional Notes and Comments |
|--|-------------------------------|
| Sub-Component | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

| Sub-Component Additional Notes and Comments Additional Notes and Comments | Evaluation Component/ Sub-Component | Additional Notes and Comments |
|--|--|-------------------------------|
| | Sub-Component | Additional Notes and Comments |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| 1 | | |
| 1 | | |
| | | |
| | | |
| | | |
| | | |
| | | |

| Sub-Component Additional Notes and Comments Additional Notes and Comments | Evaluation Component/ Sub-Component | Additional Notes and Comments |
|--|--|-------------------------------|
| | Sub-Component | Additional Notes and Comments |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| 1 | | |
| 1 | | |
| | | |
| | | |
| | | |
| | | |
| | | |

| Evaluation Component/ | Additional Natas and Comments |
|--|-------------------------------|
| Evaluation Component/ Sub-Component | Additional Notes and Comments |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |