School Facility Evaluation Project Part I - Facility Profile and Summary

School Name:	Eaglesham School	School Code:		1306
Location:	Eaglesham, Alberta	Facility Code:		1836
Region:	North	Superintendent	Mr. Gerry Mazer	
Jurisdiction:	Peace Wapiti Regional Division No. 33	Contact Person:	Mr. Al McEwan	
		Telephone:	(780) 532-8133	
Grades:	K - XII	School Capacity:		365

Year of Compl.	No. of Floors	Gross Bldg Area (Sq.M.)	Type of Construction (i.e., structure, roof, cladding)	Description of Mechanical Systems (incl. major upgrades)	Comments/Notes
1953	1	194.5	Wood structure on crawl space	School heat and ventilation by furnaces. Municipal services.	Poor indoor air quality.
1954	1	193.6	Wood structure on crawl space	School heat and ventilation by furnaces.	Ductwork in crawlspaces (and below grade at gymnasium) have been
1955	1	239.2	and ar	subject to excessive moisture/humidity and are extremely rotted with concerns of mildew/mold in ducts. Poor indoor	
1957	1	312	Wood structure on crawl space		air quality.
1958	1	715	Slab on grade.		
1959	1	900.7	Slab on grade.		
1963	1	577.3	Wood structure on crawl space		Exterior walls and windows deteriorated especially at science labs.
	1953 1953 1954 1955 1957 1958 1959		Compl. Floors (Sq.M.) 1953 1 194.5 1954 1 193.6 1955 1 239.2 1957 1 312 1958 1 715 1959 1 900.7	Compl. Floors (Sq.M.) roof, cladding) 1953 1 194.5 Wood structure on crawl space 1954 1 193.6 Wood structure on crawl space 1955 1 239.2 Wood structure on crawl space 1957 1 312 Wood structure on crawl space 1958 1 715 Slab on grade. 1959 1 900.7 Slab on grade.	Compl.Floors(Sq.M.)roof, cladding)(incl. major upgrades)19531194.5Wood structure on crawl spaceSchool heat and ventilation by furnaces. Municipal services.19541193.6Wood structure on crawl spaceSchool heat and ventilation by furnaces.19551239.2Wood structure on crawl space19571312Wood structure on crawl space19581715Slab on grade.19591900.7Slab on grade.

Evaluator's Name: & Company:

Vivian Manasc, MRAIC, MBA

pany: Manasc Isaac Architects Ltd.

Part I - Facility Profile and Summary

(identify whether minor or major)		3407	modernization.	past few years. New crawlspace sumps added recently to reduce water/moisture.	quality. Recommend adding crawlspace ventilation currently not in place. Other systems may need adjustment to suit.
	1999		Flooring replacement (selective).		
Portable Struct. (identify whether attached/perman. or free-standing/ relocatable)	1			N/A	

List of Reports/	Roof inspection report August 1995. Re-roof tender 1997.
Supplementary	
Information	

11/23/2000

School Facility Evaluation Project Part I - Facility Profile and Summary

Evaluation Components	Summary Assessment	Estim. Cost
1 Site Conditions	Poor drainage/wet crawlspace. Not much can be done, as there is a general drainage problem in the area.	\$ -
2 Building Exterior	Partial re-roof 1997. Some new insulated metal cladding.	\$ 98,000.0
3 Building Interior	Significant moisture and mold problems in some areas. Many of the finishes are aging and worn. A modernization is required in this school.	\$ 138,000.0
4 Mechanical Systems	New heating and ventilation systems recommended for improved indoor air quality cost reflected). Plumbing fixtures ok. Plumbing original and should be replaced (cost reflected). School is not sprinklered and controls should be upgraded with heating and ventilation. Need crawlspace ventilation and ductwork requires replacement. Building services appear ok. Building is not sprinklered and could be with associated upgrades to incoming water supply (cost not shown in overall estimate).	\$ 510,000.00
5 Electrical Systems	Aging systems with limited branch wire circuiting. Energy retrofit and improved lighting needed.	\$ 61,000.0
6 Portable Buildings	N/A	
7 Space Adequacy:		
7.1 Classrooms	Classroom space is in somewhat short supply. Because this is a K-12 school, more classrooms may be warranted.	
7.2 Science Rooms/Labs	There is only one science room in this school.	
7.3 Ancillary Areas	Ancillary space is limited, but appears to be adequate.	
7.4 Gymnasium	Gym is small for a K-12 school. However, it seems to meet community and educational needs.	
7.5 Library/Resource Areas	Library is reasonably sized for the school.	
7.6 Administration/Staff Areas	There is a shortage of administrative space. There is also a lack of student gathering space, especially for the older students. Classrooms and corridors are crowded.	
7.7 CTS Areas	CTS areas are generally somewhat small, but adequate for the needs of the school.	
7.8 Other Non-Instructional Areas (incl. gross-up)		
Overall School Conditions & Estim. Costs		\$ 807,000.0

Section 1	Site Conditions	Rating	Comments/Concerns	Estim. Cost
1.1	General Site Condions			
1.1.1	Overall site size.	4	Okay	
1.1.2	Outdoor athletic areas.	3	Okay, muddy when rainy.	
1.1.3	Outdoor playground areas, including condition of equipment and base.	3	Adequate.	
1.1.4	Site landscaping.	4	Adequate.	
1.1.5	Site accessories (i.e., perimeter and other fencing, guard rails, bike stands, flag poles).	4	Adequate.	
1.1.6	Surface drainage conditions (i.e., drains away from building, signs of ponding).	3	Poor drainage - generally in the region.	
1.1.7	Evidence of sub-soil problems.		N/A	
1.1.8	Safety and security concerns due to site conditions.		N/A	
Other				
1.2	Access/Drop-Off Areas/Roadways/Bus Lanes			
	Vehicular and pedestrian access points (i.e., size, number, visibility, safety).	4	Adequate.	

	Site Conditions	Rating		Estim. Cost
1.2.2	Surfacing of on-site road network (note whether asphalt or gravel).	4	Gravel.	
1.2.3	Bus lanes/drop-off areas (note whether on-site or offsite).	4	On-site	
1.2.4	Fire vehicle access.	4	Okay.	
1.2.5	Signage.	3	Could be clearer.	
Other				

	Site Conditions	Rating	Comments/Concerns	Estim. Cost
1.3	Parking Lots and Sidewalks			
1.3.1	Number of parking spaces for staff, students and visitors (including stalls for disabled persons).	4	Okay.	
1.3.2	Layout and safety of parking lots.	4	Okay.	
1.3.3	Surfacing and drainage of parking lots (note whether asphalt or gravel).	4	Gravel - poor drainage.	
1.3.4	Layout and safety of sidewalks.	4	Okay.	
1.3.5	Surfacing and drainage of sidewalks (note type of material).	4	Concrete.	
1.3.6	Curb cuts and ramps for barrier free access.	4	N/A	
Other				
	Overall Site Conditions & Estimated Costs	4		\$ -

Section 2	Building Exterior	Rating		Comments/Concerns	Estim. Cost
2.1	Overall Structure		Bldg. Section	Description/Condition	
2.1.1	Floor structure and beams (i.e., signs of bending, cracking, heaving, settlement, voids, rust, stains).	1	53 to 57	Wood structure on crawl space/slightly sagging floor in corridor. Foundation walls badly damaged due to moisture in mechanical crawlspace. Wood columns and beams damaged. Rest of crawlspace dry and clean.	\$ 25,000.00
		4	58	Slab on grade.	
		FI	59/63	Wood floor on crawlspace - uneven floor. Very wet crawlspace - new sump recently installed. Performance of this new sump should be monitored.	
2.1.2	Wall structure and columns (i.e., signs of bending, cracking, settlement, voids, rust, stains).	4	53 to 57	Wood frame walls, insulated.	
2.1.3	Roof structure (i.e., signs of bending, cracking, voids, rust, stains).	4	53 to 57	Wood frame roof structure.	
			59	Cracks noted at U/S of GWB U/S of structure.	
			59	Glulam at gym - no problems evident.	
2.1.4	Control/expansion joints.				
Other					

Section 2	Building Exterior	Rating		Comments/Concerns	Estim. Cost
2.2	Roofing and Skylights Identify the availability of an up-to-date inspection report or roofing program. Note if roof sections are of different ages and/or in varying		Bldg. Section or Roof Section	Description/Condition/Age	
	Based on the inspection report (and to the extent possible, direct observation), assess and rate roof conditions and estimate costs for required improvements (i.e., covering materials, membrane, insulation, other components).	4		Evidence of roof leaks throughout. Partial re-roof 1997.	
		2	All	Remainder of roof requires replacement.	\$ 25,000.00
	Roof accessories (i.e., ladders, stairs, hatches, masts, exhaust hoods, chimneys, gutters, downspouts, splashpads).			N/A	
2.2.3	Control of ice and snow falling from roof.			N/A	
	Skylights (i.e., signs of distress, leaks, ice build-up, condensation, deteriorated materials/seals).			N/A	
Other					

ompleted as part of modernization.
ompleted as part of modernization.
4.6
4

Section 2	Building Exterior	Rating	Comments/Concerns	Estim. Cost
2.4.2	Door accessories (i.e., latches, hardware, screens, locks, alarms, holders, closers, security devices).	4	All Good condition.	
2.4.3	Exit door hardware (i.e., safety and/or code concerns).	3	All Good condition panic devices - hinges and closers poor. All weatherstripping poor. Rated doors w/o closers at exit vestibule.	
2.4.4	Windows (i.e., signs of deterioration, rusting metal, glass cracks, peeling paint, damaged seals, sealed unit failure).	1	throughout. Especially bad condensation at all windows, some deterioration noted. New windows recommended in 1968 building, in conjunction with envelope repairs.	\$ 18,000.00
		4	All Rest of the windows appear to be in good condition.	
2.4.5	Window accessories (i.e., latches, hardware, screens, locks, alarms, holders, closers, security devices).			
2.4.6	Building envelope (i.e., signs of heavy condensation on doors or windows).	1	1963 Significant moisture at east wall - mold evident behind and inside millwork, under windows.	\$ 30,000.00
		4	All The rest of the building appears to be in good condition.	
Other				
	Overall Bldg Exterior Condition & Estim Costs	3		\$ 98,000.00

Section 3	Building Interior - Overall Conditions	Rating		Comments/Concerns	Estim. Cost
	Interior Structure	_	Bldg.		
	Interior walls and partitions (i.e., signs of cracks, spalling, paint peeling).	3	Section All	<u>Description/Condition</u> Stud walls/vinyl covered GWB - good condition except in 1963 wing where significant water and moisture damage is evident. Finishes require repair.	\$10,000.00
3.1.2	Floors (i.e., signs of cracks, heaving, settlement).	4 2	55 to 57 58 59	Some movement noted - mostly level floors with undulations. Significant ramped level changes. Not much can be done about the movement noted. Minor cracks in slab on grade. Slab settlement evident - floor wall junctions open; movement. Mudjack relevant sections especially at change rooms, and repair	\$10,000.00
Other				flooring.	
3.2	Materials and Finishes		Bldg.		
3.2.1	Floor materials and finishes.	3	Section All	Description/Condition Flolex carpet in corridors. Should be replaced.	\$60,000.00
3.2.2	Wall materials and finishes.	3 4 4 4	AII AII AII	Regular carpet in classroom. Should be replaced. Quarry tile in vestibules and industrial arts, in reasonable condition. Corlon in some classrooms, hardwood floor at gym. All in good condition. Vinyl covered GWB/battens throughout - well maintained.	Incl.
		3	All All	Acoustic wall fabric at gym - good shape. Spray on acoustic material at gym ceiling. Material falls off when hit by balls. It will require replacement with a more durable finish. Painted GWB at gym storage. Exterior wall to be patched and repaired.	\$ 13,000.00 \$5,000.00
3.2.3	Ceiling materials and finishes.	4	All	T-bar ceiling in classroom. GWB ceiling in IA. Exposed structure at gym/acoustic material. All in good condition.	¥3,33333
3.2	Materials and Finishes (cont'd)		Bldg. Section	Description/Condition	
3.2.4	Interior doors and hardware.	4	All	Good condition wood doors - 1984 hardware.	

	Building Interior - Overall Conditions	Rating	Comments/Concerns	Estim. Cost
3.2.5	Millwork	4	Most of the millwork is in good condition, as it was upgraded in the 1984	
		2	modernization Science labs and prep room - cabinets damaged due to moisture. Remove millwork and replace portions.	\$10,000.00
		2	Home ec room - hinges at millwork need replacing.	\$10,000.00
3.2.6	Fixed/wall mounted equipment (i.e., writing boards, tackboards, display boards, signs).	4	New chalkboards in classrooms.	
3.2.7	Any other fixed/mounted specialty items (i.e., CTS equipment, gymnasium equipment).	4	I.A. equipment - metal work/welding/woodwork. Fumehood at science lab not in use.	
328	Washroom materials and finishes.	4	Ceramic tile walls and floors (1984).	
0.2.0	Washioon materials and misres.	4	Ceramic the waits and moors (1904).	
		3	1959 Some cracks where slab is settling (minor). Repair.	
				\$5,000.00
Other				φο,σσσ.σσ
3.3	Health and Safety Concerns Intent is to identify renovations considered necessary to		Bldg. Section Description/Condition	
	meet applicable codes, primarily due to safety concerns. Basis of evaluation should be an up-to-			
	date inspection report from the authority having			
	jurisdiction together with direct observations as appropriate. Evaluator should note if in his			
	opinion a comprehensive code evaluation is			
3.3.1	Building construction type - combustible or non- combustible, sprinklered or non-sprinklered.	4	Wood frame not sprinklered.	
000				
3.3.2	Fire separations (i.e., between buildings, wings, zones if non-sprinklered).	4		
		<u> </u>		

Section 3	Building Interior - Overall Conditions	Rating		Comments/Concerns	Estim. Cost
3.3.3	Fire resistance rating of materials (i.e., corridor walls and doors).	4			
3.3.4	Exiting distances and access to exits.	4			
3.3.5	Barrier-free access.	4	All	Barrier-free access throughout the school. Some significan ramps in corridors.	
3.3.6	Availability of hazardous materials audit (i.e., evidence of safety concerns with respect to asbestos, PCB's, chemicals).				
3.3.7	Other health and safety concerns (i.e., evidence of excessive noise conditions, air quality problems)	2	1963	Moisture and mold in parts of crawlspace. Very humid/stuffy at 63 wing. Very poor air quality.	\$15,000.00
Other					
	Overall Bldg Interior Condition & Estim Costs	3			\$138,000.00

ction 4	Mechanical Systems	Rating	Comme		Estim. Cost
4.1	Mechanical Site Services				
4.1.1	Site drainage systems (i.e., surface and underground systems, catch basins).	4	All	A. Rain water leaders splash to grade. B. No site drainage.	-
4.1.2	Exterior plumbing systems (i.e., irrigation systems, hose bibs).	4	All	A. Exterior hose bibbs. Conditions noted ok by maintenance.	-
4.1.3	Outside storage tanks.	-		A. Two abandoned septic tanks and one abandoned cistern tank in crawlspace below elementary Rooms 102/109/110.	-
Other					
4.2	Fire Suppression Systems		Bldg. Section	Description/Condition	
4.2.1	Fire hydrants and siamese connections.	4		A. One hydrant across street to south (across from 1959 addition). B. No siamese.	-
4.2.2	Fire suppression systems (i.e., pumps, sprinklers, piping, reservoirs, hoses, stand pipes, CO2 systems).		All	A. No fire suppression systems.	-
4.2.3	Hand extinguishers, blankets and showers (i.e., in CTS areas).	3	All	A. Hand extinguisher in corridors, mechanical rooms, business education, home economics, industrial arts, and science rooms. No cabinets. Some extinguishers are dated and may need replacement.	\$ 1,500.00
4.2.4	Other special situations (e.g., flammable storage areas, science labs, CTS areas).	3	1963	A. Flammable storage cabinets in Room 137 and industrial arts paint room. No fire suppressions except for nearby fire extinguisher cabinet. No fire extinguisher cabinet in Room 137 noted. B. Water bottle eyewash in Science Room 136	\$ 2,500.00
Other				Consideration should be given to adding a building wide sprinkler system with any major upgrades at an estimated cost of \$50,000 (not carried in over-all cost estimates).	-

Section 4	Mechanical Systems	Rating	Comme		Estim. Cost
4.3	Water Supply and Plumbing Systems		Bldg.	Description/Condition	
4.3.1	Domestic water supply (i.e., pressure, volume, quality - note whether municipal or well supply).	4	Section All	A. Municipal water supply. B. Pressure and volume reasonable as noted by staff.	-
4.3.2	Water treatment system(s).	-	All	None	N/A
4.3.3	Pumps and valves (including backflow prevention valves).	-	All	A. No backflow prevention.	-
4.3.4	Piping and fittings.	3	All	A. Copper domestic pipe is original and may contain lead at fittings and calcium build-up on pipe walls. No leaks evident. Should replace. B. Cast iron sanitary original. Some pipe replaced with ABS/PVC. No leaks evident. C. Gas supply with main manual shut-off valve and gas turrets in Sci Room 136.	See Below
4.3.5	Plumbing fixtures (i.e., toilets, urinals, sinks)	3	All	A. No handicapped fixtures noted. B. Plumbing fixtures generally in good condition. Fixtures in 109/110 are marginal condition and should be replaced. Shower trim and closets in change rooms have been abused and should be replaced. C. Bottle traps on science sink drains.	See Below
4.3.6	Domestic hot water system (i.e., heater, storage tanks, failure alarms, pressure, volume, recirculation).	4	1959	A. One 500 MBH, 80 USGAL gas domestic hot water tank complete with recirculation pump in Room 125 serving entire school.	-
4.3.7	Sanitary and storm sewers, including sumps and pits (note whether sewage system is municipal or septic).	4	All	A. Municipal sanitary sewer. No storm sewer. B. Five recently upgraded crawlspace sumps to control ground water seepage. Pump into sanitary system.	-
Other				Plumbing System Upgrade Estimate	\$191,000.00

Section 4	Mechanical Systems	Rating	Comme		Estim. Cost
4.4	Heating Systems		Bldg.	Description/Condition	
4.4.1	Heating capacity and reliability (including backup capacity).	3	Section All	A. Entire school heated by furnaces. No back-up. B. Reliability varies. Furnaces range in age from 2 to 10+ years. Some replacement may be required soon. Approximately 2/3 of the furnaces are 10+ years old. C. Classroom furnaces range from 80 to 90 MBH. Furnaces ranging 120 to 180 MBH serve larger areas. D. Furnaces are Lennox or American Standard.	See Below
4.4.2	Heating controls (including use of current energy management technology.	2	All	A. Approximately 50% of furnaces controlled by programmable thermostat. Remainder of thermostats are not programmable. Working condition is good. B. Noted that all furnace fans do not operate continuously during occupied hours. Unacceptable. Furnace fans operate intermittently as dictated by thermostats. Currently fans appear on only when a call for heat.	See Below
4.4.3	Fresh air for combustion and condition of the combustion chimney.	4	All	A. Combustion air duct provided for each furnace and conditions are good. B. Combustion flues on furnaces in good condition.	-
4.4.4	Treatment of water used in heating systems.	-		N/A	N/A
4.4.5	Low water cutoff/pressure relief valves and failure alarms (i.e., hot water heating).	-		N/A	N/A
4.4.6	Heating air filtration systems and filters.	4	All	A. 1" flat filter either in furnace or in return air duct to furnace.	-
4.4.7	Heating humidification systems and components.	2	All	A. None. B. Drum humidifiers on gymnasium furnace system long removed. Recommend humidification be re-introduced with gymnasium hardwood floors.	See Below

Section 4	Mechanical Systems	Rating	Comme		Estim. Cost
4.4	Heating Systems (cont'd)		Bldg.	Description/Condition	
4.4.8	Heating distribution systems (i.e., piping, ductwork) and associated components (i.e., diffusers, radiators).	1	All	A. All crawlspace ductwork is rotting and may contain mold/mildew due to excess crawlspace moisture. Below grade ductwork serving gymnasium is rotting due to excessive ground water. Ductwork replacement required. B. All other ducts appear ok.	See Below
4.4.9	Heating piping, valve and/or duct insulation.	4	All	A. No ductwork insulation except some internal lining on outdoor air ducts to furnaces.	-
4.4.10	Heat exchangers.	3	All	A. Gas heat exchangers on furnaces 10+ years old may be faulty or have leaks. No evident signs of problems.	See Below
4.4.11	Heating mixing boxes, dampers and linkages.	4	All	A. Most furnaces have fixed outdoor air. B. Dampers and linkage condition of furnaces serving library and gymnasium area unknown. Limited access. Assume ok since no complaints. Used for free cooling on warm days.	-
4.4.12	Heating distribution/circulation in larger spaces (i.e., user comfort, temperature of outside wall surfaces).	3	All	A. General comfort ok. B. Cool in industrial arts shop area. Noted that comfort usually ok. C. Muggy and humid in science room. Probably due to moisture from crawlspace.	See Below
4.4.13	Zone/unit heaters and controls.	-	All	None	N/A
Other				Heating System Upgrade Estimate	\$150,000.00

Section 4	Mechanical Systems	Rating	Comme		Estim. Cost
4.5	Ventilation Systems		Bldg.	Description/Condition	
4.5.1	Air handling units capacity and condition.	4	Section All	A. Furnaces throughout school. See heating. B. One make-up air unit for industrial arts shop, rooftop. Inaccessible during visit. Noted by staff as good condition.	-
4.5.2	Outside air for the occupant load (if possible, reference CFM/occupant).	2	All	A. Furnace outdoor air unknown. B. Most furnaces have 6" fixed outdoor air duct. C. Library and gymnasium furnaces capable of 100% outdoor air for free cooling only. Assume 10% outdoor air otherwise.	See Below
4.5.3	Air distribution system (if possible, reference number of air changes/hour).		All	A. AC/H unknown.	-
4.5.4	Exhaust systems capacity and condition.	3	All	A. Exhaust fans generally provide ample exhaust as noted by maintenance. B. Poor exhaust in Change Rooms 113 and 114. Needs upgrade. C. Washroom exhaust fan for Rooms 124 and 125 not functioning. D. Capacity/condition of fans unknown.	See Below
4.5.5	Separation of out flow from air intakes.	FI	All	Some concerns regarding poor proximity of furnace flues near combustion air and outdoor air intakes.	-
4.5.6	Special/dedicated ventilation and/or exhaust systems (i.e., kitchen, labs, CTS areas).	2	1963	A. Science Room 137 storage has exhaust fan that appears inoperable.	See Below
Other		4	1963	A. Industrial arts shop woodwork area exhaust to outdoor dust collection unit. Gas fired rooftop unit make-up air unit on roof interlocked. Conditions appear ok and no problems indicated by maintenance. B. Industrial arts shop welding and paint booth exhaust appear adequate. C. Crawlspace ductwork in all areas excluding administration (1958) and gymnasium (1959) noted by maintenance.	-
4.5	Ventilation Systems (cont'd)		Bldg. Section	Description/Condition	
	Note: Only complete the following items if there are separate ventilation and heating systems.				

Section 4	Mechanical Systems	Rating	Comme		Estim. Cost
	Ventilation controls (including use of current energy management technology).	4	All	A. Furnace thermostats. See heating.	-
4.5.8	Air filtration systems and filters.	4	All	A. 1" furnace filters. See heating.	-
4.5.9	Humidification system and components.	-	All	None	N/A
4.5.10	Heat exchangers.	3	All	A. Gas heat exchangers on furnaces. See heating.	-
	Ventilation distribution system and components (i.e., ductwork, diffusers, mixing boxes, dampers, linkages).	1	All	A. Ductwork in crawlspace and below slab needs replacement. See heating. B. Floor grilles and crawlspace ductwork in industrial arts shop do fill up with wood shavings and dust in woodwork area. Unacceptable. New air/heat distribution required for this area. C. Floor grilles in "wet" change room areas	See Below
Other				are improperly located and should be relocated with ductwork. Ventilation System Upgrade Estimate	\$165,000.00

Section 4	Mechanical Systems	Rating	Comme		Estim. Cost
4.6	Cooling Systems		Bldg.	<u>Description/Condition</u>	
404	5 1 15 C 15		Section		21/4
4.6.1	Cooling system capacity and condition (i.e., chillers, cooling towers, condensers).	-	All	None	N/A
	cooming towers, condensers).				
4.6.2	Cooling distribution system and components (i.e., ductwork, diffusers, mixing boxes, dampers, linkages)	-	All	None	N/A
	ductwork, director, mixing boxes, dampers, mixages/				
4.6.3	Cooling system controls (including use of current energy management technology).	-	All	None	N/A
	onergy management teamining, y.				
404	On a significant and a soliton assertance (i.e. labor OTO		A.II	N.	21/2
4.6.4	Special/dedicated cooling systems (i.e., labs, CTS areas).	-	All	None	N/A
Other					
Other					
4.7	Building Control Systems		Bldg. Section	<u>Description/Condition</u>	
4.7.1	Building wide/system wide control systems and/or	_		A. None. School on manual systems. B. Consideration should be given to	_
	energy management systems.		7 (11	building/system wide control system with heating and ventilation upgrades, with an	
				estimated cost of \$95,000 (not carried in over-all cost estimates).	
				,	
	Overall Mech Systems Condition & Estim. Costs	3			\$ 510,000.00

Section 5	Electrical Systems	Rating	Comments/Concerns	Estim. Cost
5.1	Site Services			
5.1.1	Primary service capacity and reliability (i.e., access, location, components, installation, bus sizes - note whether overhead or underground).	4	600A, 2P, 120 - 24V Service (250 A demand) fused main switch - FPE CDP Distribution Centre - good condition, spare capacity.	
5.1.2	Site and building exterior lighting (i.e., safety concerns).	3	HID/incandescent luminaires at exits/entrances 3 HID "yard" lights in bus parking. Poor lighting - staff parking.	\$ 4,000.00
5.1.3	Vehicle plug-ins (i.e., number, capacity, condition).	4	12 Vehicle plug-ins mounted on 2" pipe rail good condition.	
Other				
5.2	Life Safety Systems		Bldg. Section Description/Condition	
5.2.1	Fire and smoke alarm systems (i.e., safety concerns, up-to-date technology, regularly tested).	4	System up-graded 1985 - Chubb 3000 panel with some Edwards equipment - meets all code requiremetns with exception of "strobes"	
5.2.2	Emergency lighting systems (i.e., safety concerns, condition).	4	Recessed Dual-Lite battery operated units - meet code requirements.E16	
5.2.3	Exit lighting and signage (i.e., safety concerns, condition).	4	Exit signage provided at all exits meet code requirements.	
Other				

	Electrical Systems	Rating		Comments/Concerns	Estim. Cost
5.3	Power Supply and Distribution		Bldg.	<u>Description/Condition</u>	
531	Power service surge protection.	2	Section	None	\$ 2,000.00
3.3.1	i ower service surge protection.			Notie	\$ 2,000.00
5.3.2	Panels and wireways capacity and condition.	4		FPE Panelboards good condition up-graded 1985 limited spares available.	
	, , , , , , , , , , , , , , , , , , , ,			The Franciscator good condition up graded 1000 illinited spared available.	
	Emergency generator capacity and condition and/or			None	
	UPS (if applicable).				
5.3.4	General wiring devices and methods.	4		Specification grade receptacles, stainless steel coverplates, copper wiring x-link	
				insulation in conduit.	
5.2.5	Motor controls.	_		L. P. C. L. LAHLE, D. H. L.	
5.3.5	imotor controls.	4		Individual Allen Bradley automatic and manual motor starters in good condition.	
Other					

Section 5	Electrical Systems	Rating		Comments/Concerns	Estim. Cost
5.4	Lighting Systems		Bldg.		
5.4.1	Interior lighting systems and components (i.e., illumination levels, conditions, controls).	3	Section	<u>Description/Condition</u> Lighting generally florescent, recessed 4 lamp 2 x 4s, T12 lamps, electromagnetic ballasts. Classroom and administration areas 750 lux, Corridors 300 lux Over lit in Computer Workstation Lab 700 lux	\$ 2,000.00
				Over it in computer workstation Lab 700 tax	
5.4.2	Replacement of ballasts (i.e., health and safety concerns).	4		Replacement on failure, no PCB Ballasts reported or noted.	
5.4.3	Implementation of energy efficiency measures and recommendations.	2		School Division plans on energy retrofit similar to other schools in District. i.e.: Upgraded lighting, motion sensors, exit sign retrofits.	\$26,000.00
Other					

Section 5	Electrical Systems	Rating		Comments/Concerns	Estim. Cost
5.5	Network and Communication Systems		Bldg. Section	Description/Condition	
5.5.1	Telephone system and components (i.e., capacity, reliability, condition).	4		Meridian Norstar - 2 line system. Dedicated lines fax, distance learning, student union.	
5.5.2	Other communication systems (i.e., public address, intercom, CCTV, satellite or cable TV).	3		Dukane 3200 manual school intercom/paging system older technology but in good condition.	\$10,000.00
5.5.3	Network cabling (if available, should be category 5 or better).	3		Data cabling run to all classrooms and administration areas does not meet category 5 standards.	\$ 2,000.00
	Network cabling installation (i.e., in conduit, secured to walls or tables).	3		Cable run in free air in ceiling and walls no conduit or raceway system.	\$ 4,000.00
5.5.5	Wiring and telecommunication closets (i.e., size, security, ventilation/cooling, capacity for growth).	3		No designated closets or communication rooms cabinets and backboards located in service rooms.	\$ 1,000.00
5.5.6	Provision for dedicated circuits for network equipment (i.e., hubs, switches, computers).	3		Inadequate branch circuit wiring available to meet current needs.	\$10,000.00
Other					

		Rating		Comments/Concerns	Estim. Cost
5.6	Miscellaneous Systems		Bldg.		
504			Section		
5.6.1	Site and building surveillance system (if applicable).			None	
5.6.2	Intrusion alarms (if applicable).	4		Magnum Alart 1000 security system keypad, motion sensors, door interlocks.	
		-		,	
5.6.3	Master clock system (if applicable).	3		120 Volt standalone clocks.	
Other				School Division plans on energy retrofit similar to other schools in District. i.e.: Up-	
				graded lighting, motion sensors, exit sign retrofits.	
				graded high mings, meners conserve, each edge, remained	
5.7	Elevators/Disabled Lifts (If applicable)				
	Elevator/lift size, access and operating features (i.e.,				
	sensing devices, buttons, phones, detectors).				
	0 100				
5.7.2	Condition of elevators/lifts.				
5.7.3	Lighting and ventilation of elevators/lifts.				
Other					
	Overall Elect. Systems Condition & Estim Costs	3			\$ 61,000.00

Section 6	Portable Buildings	Rating	Comments/Concerns	Estim. Cost
	Note: Separate sheets can be completed, if necessary, for portable buildings of different ages and/or conditions.			
	Foundation and structure (i.e., signs of bending, cracking, settlement, rust, voids, stains).			
	Roof materials and components (i.e., signs of deterioration, leaks, ice build-up).			
	Exterior wall finishes (i.e., signs of deterioration, cracks, water stains).			
	Doors and windows (i.e., signs of deterioration, rusting hardware, glass cracks, peeling paint, damaged seals).			
6.1.5	Interior finishes (i.e., floors, walls, ceiling).			
6.1.6	Millwork (i.e., counters, shelving, vanities, cabinets).			
	Fixed/wall mounted equipment (i.e., writing boards, tackboards, display boards, signs)			
6.1.8	Heating system.		N/A	
6.1.9	Ventilation system.		N/A	
6.1.10	Electrical, communication and data network systems.			
	Health and safety concerns (i.e., fire and smoke alarms, fire protection systems, exiting, fire resistance rating of materials).		N/A	
6.1.12	Barrier-free access.			
	Overall Portable Bldgs Condition & Estim Costs			

04: 7	Space Adequacy		This Fa	cility	Equiv. New Facility			Surplus/	0	
Section /	Space Adequacy	No.	Size	Total Area	No.	Size	Total Area	Deficiency	Comments/Concerns	
7.1	Classrooms	3	75.84							
		3	76.73						Classroom space is in somewhat short supply. Because	
		1	75.45	589.39	9	80	720	-130.61	this is a K-12 school, more classrooms may be warranted.	
		1	56.23					4	inis is a N-12 school, more diassioonis may be warranted.	
7.2	Science Rooms/Labs									
7.2	Colonica Nooms/Edb3	1	100.8	115	2	120	240	-125	There is only one science room in this school.	
		1	14.2	113	-	120	240	-125	There is only one science room in this school.	
7.3	Ancillary Areas (i.e., Art, Computer Labs,	1	98.07		1	130				
	Drama, Music,)	1	75.1	249.55	2	90	310	-60.45	Ancillary space is limited, but appears to be adequate.	
7.4	Gymnasium (incl. gym storage)	1	76.38 461.1		.					
7	Cymnasiam (mor. gym storage)	1	37	498.07	1	595	655	-156.93	Gym is small for a K-12 school. However, it seems to meet	
				430.07	1	60	033	-130.93	community and educational needs.	
7.5	Library/Resource Areas									
		1	156.5	156.5	1	190	190	-33.5	Library is reasonably sized for the school.	
									,	
7.6	Administration/Staff, Physical Education,	1	34.4						There is a shortage of administrative space. There is also a	
		1	14.4 11.1	107.3	1	377	377	-269.7	lack of student gathering space, especially for the older	
		1	29	107.3	┪ '	311	311	-203.7	students. Classrooms and corridors are crowded.	
		2	9.2						students. Classiconts and comucis are crowded.	
7.7	CTS Areas 7.7.1 Business Education									
	7.7.1 Business Education		77.54	77.54		445	445	07.40	CTS areas are generally somewhat small, but adequate for	
		1	77.54	77.54	1	115	115	-37.46	the needs of the school.	
	7.7.2 Home Economics									
		1	143.4	143.4	1	115	115	28.4		
	7.7.3 Industrial Arts									
		1	163.5	163.5	1	300	300	-136.5		
	7.7.4 Other CTS Programs									
70	Other Non-Instructional Areas (i.e.,	-			1			1		
7.0	circulation, wall area, crush space, wc									
	area)			1345.93	1	800	800	545.93		
	Overall Space Adequacy Assessment			3446.18			3822	-375.82	Overall, there is a significant shortage of student gathering	
	, ,,								spaces and administrative space.	

Evaluation Component/	
Evaluation Component/ Sub-Component	Additional Notes and Comments
ous-component	
	II

Evaluation Component/	П
Sub-Component	Additional Notes and Comments
ous component	
	11

Evaluation Component/ Sub-Component	Additional Notes and Comments
i .	

Evaluation Component/ Sub-Component	Additional Notes and Comments
Sub-Component	

Evaluation Component	П
Evaluation Component/ Sub-Component	Additional Notes and Comments
Sub-Component	

Eaglesham School November 17, 1999

Evaluation Component/ Sub-Component	Additional Notes and Comments