

RECAPP Facility Evaluation Report



Kildare Elementary School

B3182A
Edmonton

Facility Details

Building Name: Kildare Elementary School
Address: 7525 - 144 Avenue
Location: Edmonton

Building Id: B3182A
Gross Area (sq. m): 0.00
Replacement Cost: \$7,071,642
Construction Year: 0

Evaluation Details

Evaluation Company: Lotus Architecture
Evaluation Date: December 1 2004
Evaluator Name: Mr. Tonu Mitra

Total Maintenance Events Next 5 years: **\$390,960**
5 year Facility Condition Index (FCI): **5.53%**

General Summary:

Kildare Elementary School is one story building with flat roof and dark brown brick exterior. The building is comprised of three distinct sections: the central portion (housing classrooms, administration and a Library) is circular. The west portion (containing a Gymnasium, Boiler Room and various ancillary spaces) is basically rectangular with curved front wall. The two sections are separated by the main entrance vestibule. The east section (with four classrooms) follows the curved profile of the circular building and is separated by a corridor. The building structure is made of concrete piles and grade beam foundations, load bearing concrete block walls and steel columns, steel roof joists and steel roof deck.

The original building, comprising of circular building and the west Gymnasium portion was built in 1968. The four classrooms were added on the east in 2002. Two portables are located to the SW of the school building. They were built in 1992 and 1994.

The total area is 3,357.90 sq. m. It is based on Edmonton Public Schools' 2004 Room Data figures and includes 4 new classrooms built in 2002 @ 79.50 sq.m. each. With two portables @ 84 sq.m. each, the Total Area would be: 3,525.90 sq.m.

Capacity: 570

Current enrolment: 535

The roof was replaced in 2002 together with complete interior upgrading. Several outstanding issues, however, still need to be addressed. These include replacement of exterior entrance doors, windows, provision of a handicap entrance and new vestibules. Ceiling and floor tiles containing asbestos were not replaced completely. The ones, that are left, are in good condition. Furnaces need to be replaced in portables, otherwise the two portables are in good condition.

The overall rating is 'good' (5).

Structural Summary:

Concrete piles and grade beam foundations. Concrete slab on grade floors. Concrete block load bearing walls, interior steel columns, steel roof joists and steel roof deck.

Minor hair line cracks in concrete block walls, otherwise building structure is in good condition.

Overall rating: 'Good' (5).

Envelope Summary:

Exterior walls are cavity wall system, consisting of exterior brick and interior load bearing concrete block back up walls. The original roof was replaced in 2002 with 2 ply SBS system. Original aluminum windows and exterior doors with sidelites.

All aluminum windows and exterior entrance doors should be replaced. A handicap entrance should be incorporated in to the north secondary entrance.

Overall rating: 'Acceptable' (4).

Interior Summary:

Interior walls include, painted concrete block walls, steel studs and painted gypsum board walls and demountable walls with tack able vinyl surfaces. Interior doors are mostly solid core wood and hollow metal doors on steel frames. New carpet and linoleum flooring and original vinyl asbestos tiles. Majority of ceilings incorporate suspended T-Bar and painted drywall. New or upgraded casework throughout.

The building interior was completely upgraded in 2002. Majority of interior materials and finishes are new. Materials that

have been reused , are in good condition. Asbestos containing ceiling and floor tiles have been replaced in the central portion.

Music Room should incorporate sound abatement.

Overall rating: 'Good' (5).

Mechanical Summary:

The heating system in the school is in acceptable condition as is the plumbing system. The plumbing fixtures are flush tank fixtures but are in acceptable condition. The ventilation system should be replaced to allow for increased outdoor air quantities. Overall the school is in acceptable condition (4).

Electrical Summary:

The school is in fair condition and is well maintained. The lighting levels are adequate in all areas. All original fixtures have been replaced with energy efficient ballasts and T8 Lamps, as well as exit lights have been upgraded to LED type. The exterior lighting requires upgrading for security purposes. (Rating 5).

Rating Guide	
Condition Rating	Performance
1 - Critical	Unsafe, high risk of injury or critical system failure.
2 - Poor	Does not meet requirements, has significant deficiencies. May have high operating/maintenance costs.
3 - Marginal	Meets minimum requirements, has significant deficiencies. May have above average operating maintenance costs.
4 - Acceptable	Meets present requirements, minor deficiencies. Average operating/maintenance costs.
5 - Good	Meets all present requirements. No deficiencies.
6 - Excellent	As new/state of the art, meets present and foreseeable requirements.

S1 STRUCTURAL

A1010 Standard Foundations*

(1968)(2002) Concrete grade beams and piles.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	100	DEC-04

A1030 Slab on Grade*

(1968)(2002) Concrete slab on grade throughout. Minor hair line cracks in Boiler Room slab. Slabs should be extended to incorporate two new vestibules - see K40 Code Issues.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	100	DEC-04

B1010.01 Floor Structural Frame*(Building Frame)

(1968)(2002) Combination of steel frame structure and load bearing concrete block walls.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	100	DEC-04

B1010.02 Structural Interior Walls Supporting Floors*

(1968) Load bearing concrete block walls.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	100	DEC-04

B1010.05 Mezzanine Construction*

(1968) Mezzanine adjacent to the stage structural concrete slab supported by load bearing concrete block walls.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	100	DEC-04

B1010.06 Ramps: Exterior*

(1968) A sidewalk raised like ramp to the handicap entrance in the middle of the round section of the building. A temporary asphalt stoop like short ramp at south doors of the main entrance Foyer.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	40	DEC-04

B1010.09 Floor Construction Fireproofing*

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	DEC-04

B1010.10 Floor Construction Firestopping*

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	DEC-04

B1020.01 Roof Structural Frame*

(1968)(2002) Open web steel joist and steel roof decks, bearing on steel internal columns, concrete block walls and exterior load bearing concrete block walls.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	100	DEC-04

B1020.04 Canopies*

(1968)(2002) Recessed canopies at roof level, framed with steel extended roof structure framing.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	100	DEC-04

B1020.06 Roof Construction Fireproofing*

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	100	DEC-04

S2 ENVELOPE**B2010.01.02.01 Brick Masonry: Ext. Wall Skin***

(1968)(2002) 90 mm dark brown brick exterior skin as part of the cavity wall system.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	75	DEC-04

B2010.01.06.03 Metal Siding*

(2002) New metal cladding on the upper portions of gymnasium.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
6 - Excellent	0	40	DEC-04

B2010.01.09 Expansion Control: Exterior Wall Skin*

(1968)(2002)

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

B2010.01.11 Joint Sealers (caulking): Ext. Wall*

(1968)(2002) In older portion caulking around windows have shrunk. They should be recaulked with new window installation in the future - B2020.01.01.02 - Aluminum Windows.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

B2010.01.99 Other Exterior Wall Skin*

(1968) Transite panels under windows in original building may contain asbestos and should be replaced with new window installation - see 2020.01.01.02 Aluminum Windows.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

B2010.02.03 Masonry Units: Ext. Wall Const.*

(1968)(2002) 200 mm concrete block load bearing back up walls, as part of the cavity wall system.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	100	DEC-04

B2010.03 Exterior Wall Vapor Retarders, Air Barriers, and Insulation*

(1968)(2002)

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	20	DEC-04

B2010.06 Exterior Louvers, Grilles, and Screens*

(1968)(2002) Paint on vertical wood louvres, in front of windows of the original building, have started to deteriorate. Should be sanded and repainted as regular maintenance.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	20	DEC-04

B2010.09 Exterior Soffits*

(1968)(2002) Perforated prefinished metal soffits.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	20	DEC-04

B2020.01.01.02 Aluminum Windows*

(2002) New aluminum windows in addition. Anodized aluminum frame, thermally broken with sealed double glazing.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
6 - Excellent	0	35	DEC-04

B2020.01.01.02 Aluminum Windows*

(1968) Original aluminum windows, consisting of two separated aluminum sections with field glazing. Wood framing sections in between. Bottom slider sections. Painted wood sills.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	35	DEC-04

Event: Replace original windows.**Concern:**

Original windows are not energy efficient, there is no effective weather seal. Wood sections between panes have rotted due to condensation and cannot be repaired. Interior surfaces of frames also condensate. Painted wood sills have cracked and starting to rot.

Recommendation:

Replace existing windows with new windows, similar to the ones used in the new addition, complete with new sills. (16 windows). Includes cost of demolition of transite panel walls below 14 windows and rebuilding of exterior walls.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Operating Efficiency Upgrade	2008	\$32,400	Low

Updated: March 4 2005



B2030.01 Exterior Entrance Doors

(1968) Single leaf aluminum doors at the main entrance and double leaf doors at other entrances fully or upper half glazed, on aluminum frames, complete with transoms and sidelites (georgian wired glass) and weather stripping. Aluminum and wood thresholds. Other hardware includes closers, lock sets, pull bars and push plates and panic sets. One rear door at the main entrance has automatic opener - see also K4010.02 Barrier Free Entrances.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	DEC-04

Event: Replace all original exterior doors.

Concern:

Original exterior doors are not insulated. Frost build up on door surfaces reported. Wood threshold at the rear entrance doors is rotting. Old hardware and not compatible with the remaining upgraded areas.

Recommendation:

Exterior entrance doors, frames and sidelites should be replaced with new insulated steel doors and frames with new hardware and sealed glazing. Two additional entrance doors with sidelites have been included in the new vestibule costs - see K40 Code Issues.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Operating Efficiency Upgrade	2007	\$75,600	Low

Updated: March 4 2005

B2030.01 Exterior Entrance Doors

(2002) Double leaf insulated steel doors on steel frames, complete with panic sets, closers, kick plates and weather stripping, at the end of corridors between the new addition and existing building.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
6 - Excellent	0	30	DEC-04

B2030.02 Exterior Utility Doors*

(1968) Single leaf steel doors and frames, complete with weather stripping, thresholds, locksets. Exterior Gymnasium doors have panics - see also K40 Code Issues. Roof access door is insulated steel on steel frame of custom size (1500 x 900 mm).

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

B3010.01 Deck Vapor Retarder and Insulation*

(2002) New roof assembly components on original steel deck consists of exterior gypsum board sheathing, vapour barrier, EPS insulation tapered to internal drains, fibre board. Roofing assembly would be required for new vestibules - see K40 Code Issues.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
6 - Excellent	0	0	DEC-04

B3010.04.04 Modified Bituminous Membrane Roofing (SBS)*

(2002) 2 ply SBS roofing with internal drains. Ponding noted. Large sections of the roof have one internal drain. Additional drains incorporated in Mechanical evaluation. Roof expansion joints. Roofing will have to be extended to new vestibules - see K40 Code Issues.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	25	DEC-04

B3010.09 Roof Specialties and Accessories*

(2002) Painted steel ladder added to the higher Gymnasium roof. Precast pavers and pressure treated wood blocking under gas lines.

Roof access is provided via a steel ladder to the mezzanine concrete slab near Stage / Arts Room. From this mezzanine a wooden ladder complete with intermediate landing leads to a steel man door to access the roof area.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	25	DEC-04

B3020.02.03 Roof Windows (Clearstory)

(1968) Aluminum frame clearstory windows above Library.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

S3 INTERIOR

C1010.01 Interior Fixed Partitions*

(1968) Concrete block walls (stack bond), and steel stud and gypsum board partitions. Some hairline cracks in block walls.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	DEC-04

C1010.02 Interior Demountable Partitions*

(1968) Demountable partitions in Classrooms and in hallways in the circular portion of the original building.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	30	DEC-04

C1010.03 Interior Operable Folding Panel Partitions*

(1968) A large folding accordion partition divider curtain in Gymnasium. Vinyl fabric covered sound attenuating folding partition in Stage / Arts Room - manual operation.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	30	DEC-04

C1010.04 Interior Balustrades and Screens, Interior Railings*

(1968) Painted metal rails with vinyl cap at interior steps in Gymnasium area hallway.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	40	DEC-04

C1010.05 Interior Windows*

(1968) A steel frame on the corridor wall near Gymnasium area; does not have georgian wired glass. Steel frame windows between Computer Room and Library / corridor.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	40	DEC-04

C1010.06 Interior Glazed Partitions and Storefronts*

(2002) Painted steel frame glazed partitions in Principals' office, Administration entrance and in Library.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
6 - Excellent	0	40	DEC-04

C1010.07 Interior Partition Firestopping*

(1968)(2002) Concrete block walls in fire separations extend to underside of deck. All other partitions extend to ceilings.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	DEC-04

C1020.01 Interior Swinging Doors*

(1968)(2002) Except in corridors and door to Gymnasium, all doors are single leaf, solid core wood on steel frames (some with upper glazed portions and sidelites). Hardware includes aluminum or plastic kick plates, chrome door knobs with locks and except Classrooms, most doors have closers.

Corridor and Gymnasium doors are double leaf, solid core wood (glazed upper half), on steel frames. Corridor doors have removable mullions. Hardware includes Door stops, kick plates, closers push plates and pull bars.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	50	DEC-04

C1020.02 Interior Entrance Doors*

(1968) Two doors at the main entrance Foyer, separating Classroom and Gymnasium areas. Hollow metal doors, on steel frames with central removable mullions, one pair with upper half glazed. Hardware include panics, closers, kick plates and magnetic hold open devices.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	50	DEC-04

Event: **Provide interior entrance doors at secondary entrances.**

Concern:

The north and south corridors (in the middle of circular building) have no vestibules. Exterior aluminum doors leak air and hallways are cold.

Recommendation:

Create vestibules at north and south secondary entrances by adding interior entrance doors in corridors, complete with sidelites and transoms to suit existing corridors. (Existing exterior doors to be replaced - see B2030.01). Estimate includes cost of partial demolition of demountable side walls and building insulated steel stud walls.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Program Functional Upgrade	2007	\$16,200	Low

Updated: March 4 2005

C1020.03 Interior Fire Doors*

(1968)(2002) Mostly single leaf hollow metal doors on pressed steel frames. Original east exterior door has been replaced by rated steel double door with fusible link and piano hinges. Boiler room exterior door has alarm contact - see also K40 Code Issues. Double leaf steel door with georgian wired glass, on steel frame in Gymnasium. Most original steel doors are not labeled.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	DEC-04

C1020.05.01 Coiling Doors and Grilles

(1968)(2002) Steel rolling shutter at Kitchen pass-thru is fire rated. Four coiling shutters with fusible links at windows in the core area.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	DEC-04

C1030.01 Visual Display Boards*

(1968)(2002) Chalk boards, white boards, tack boards and map rails throughout in Classrooms. Vinyl surfaced demountable walls are also used as tack boards heavily. Pull down maps in new Classrooms of addition. White board in Staff Room, Computer room and Art Room.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	DEC-04

C1030.02 Fabricated Compartments(Toilets/Showers)*

(2002) All toilet compartments are new.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
6 - Excellent	0	0	DEC-04

C1030.05 Wall and Corner Guards*

(1968) At several corners of corridor walls.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	DEC-04

C1030.08 Interior Identifying Devices*

(1968)(2002) Combination of lamicoid and cast aluminum signs.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	DEC-04

C1030.12 Storage Shelving*

(1968)(2002) Wood and steel shelving. Three prefabricated wooden storage units to store paper napkins are located in the north corridor. The corridor is also the required fire exit. The storage unit may not be permitted as it restricts the exit width. Metal boot racks at all entrance areas of the original building. Painted Storage units with lockable doors for music instruments in Music Room.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

C1030.14 Toilet, Bath, and Laundry Accessories*

(2002) Stainless steel combination paper towel dispensers and receptacles, tissue paper holders, soap dispensers.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
6 - Excellent	0	20	DEC-04

C2010 Stair Construction*

(1968) Concrete steps in corridor to Gymnasium. Concrete steps to Gymnasium from Stage / Art Room (both have 6 risers).

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	100	DEC-04

C2020.05 Resilient Stair Finishes*

(2002) Rubber treads and risers.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
6 - Excellent	0	20	DEC-04

C2020.08 Stair Railings and Balustrades*

(1968) Flat metal handrail with vinyl cap, anchored to walls with metal brackets.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	50	DEC-04

C3010.01 Concrete Wall Finishes*

(1968)(2002) Except in Boiler and other utility rooms, all concrete blocks were repainted in 2002. Old painted and surfaces in Boiler room have water stains from previous roof leaks.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	100	DEC-04

C3010.02 Wall Paneling*

(1968) Painted plywood panels (2100 mm high) in Gymnasium walls (repainted in 2002).

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	30	DEC-04

C3010.04 Gypsum Board Wall Finishes*

(1968)(2002) Painted gypsum board surfaces (repainted in 2002). Original vinyl finish gypsum boards (pin surface) in demountable walls.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	40	DEC-04

C3010.09 Acoustical Wall Treatment*

(1968) Vinyl surface demountable walls in Music Room.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	15	DEC-04

Event: Upgrade Music Room acoustics.**Concern:**

Existing walls, doors and ceilings do not provide any sound proofing. Extremely loud noises were heard in corridors and other Classrooms.

Recommendation:

Upgrade Music Room acoustically, including sound deadening surfaces on the interior walls and sound masking surfaces on ceilings and acoustic seals on Music Room doors. Input from an acoustic consultant is recommended (fee of \$4,000 is included in the estimate).

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Program Functional Upgrade	2008	\$32,400	Low

Updated: March 4 2005

C3010.09 Acoustical Wall Treatment*

(2002) Straw surfaced acoustic panels in upper portions of Gymnasium walls.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
6 - Excellent	0	20	DEC-04

C3010.13 Wall Trim and Decoration*

(2002) Accent paint stripes and a large painted mural on the walls of the main entrance. Birch chair rails in Administration area and Staff Room.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	10	DEC-04

C3010.14 Other Wall Finishes*

(1968) Original exterior brick surface now becomes interior surface at east addition.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	DEC-04

C3020.01 Concrete Floor Finishes*

(1968) Painted concrete floor in Boiler Room.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	75	DEC-04

C3020.04 Wood Flooring*

(1968) Maple wood flooring in Gymnasium. Wood floors were refinished in 2002.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	25	DEC-04

C3020.07.01 Resilient Tile Flooring

(1968) Original tiles in Gymnasium Storage and other utility rooms. Original tiles contain asbestos but are in good condition. All other VATs have been replaced with sheet flooring materials.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	20	DEC-04

C3020.07.02 Resilient Sheet Flooring

(2002) Original VATs have been replaced with resilient sheet flooring in most areas, including Boys' and Girls' Washrooms, Arts Room / Stage and corridors.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
6 - Excellent	0	0	DEC-04

C3020.08 Carpet Flooring*

(2002) New carpet in most areas, including old and new Classrooms, Administration area, Music Room, Computer Room and Library. Carpet in corridor of new addition.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
6 - Excellent	0	10	DEC-04

C3030.01 Concrete Ceiling Finishes*

(2002) Painted concrete ceilings in Gymnasium Storage.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	100	DEC-04

C3030.03 Plaster Ceiling Finishes*

(1968) Plaster ceiling in Boiler Room, not painted.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	DEC-04

C3030.04 Gypsum Board Ceiling Finishes*

(2002) Painted gypsum board ceilings in Gymnasium, Library, washrooms, corridor of new addition and west entrance, Storage and Supply, and other utility rooms. Corridor bulkheads.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	50	DEC-04

C3030.06 Acoustic Ceiling Treatment (Susp.T-Bar)*

(1968)(2002) 600 x 600 mm suspended T-Bar ceilings in most areas. Original tiles contain small traces of asbestos. Up to 40% of existing ceiling tiles were replaced in 2002. The remaining original tiles are in good condition. Suspended T-Bar ceilings in Classrooms of new addition.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	25	DEC-04

C3030.08 Ceiling Trim and Decoration*

(2002) Painted drywall ceiling borders in corridors.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

C3030.09 Other Ceiling Finishes*

(1968) Exposed steel deck and steel joists in mezzanine.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	DEC-04

S4 MECHANICAL**D2010.01 Water Closets***

(1968) Floor mounted flush tank water closets throughout.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	DEC-04

D2010.02 Urinals*

(1968) Floor mounted flush tank throughout.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	DEC-04

D2010.03 Lavatories*

(1998) Countertop stainless steel with single faucet, pushbutton, spring loaded brass.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	DEC-04

D2010.04 Sinks*

(1968)(2002) Stainless steel with standard "kitchen" type brass in classrooms and staff room. Not all classrooms have sinks. Lab type cup sinks with gooseneck brass in stage "classroom".

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	DEC-04

D2010.08 Drinking Fountains / Coolers*

(1968) Wall hung china in general areas. Not all classroom sinks have bubblers.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	DEC-04

D2020.01.01 Pipes and Tubes: Domestic Water*

(1968)(2002) Copper piping throughout.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	40	DEC-04

D2020.01.02 Valves: Domestic Water

(1968)(2002) Mixed manufacture gate valves.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

D2020.01.03 Piping Specialties (Backflow Preventors)*

(1968) Backflow preventer for makeup to expansion tanks.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	DEC-04

Event: **Relocate backflow preventer.**

Concern:

Backflow preventer located in close proximity to C/A opening and freezes at times.

Recommendation:

Relocate backflow preventer and associated piping away from C/A opening.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2006	\$3,240	Low

Updated: March 4 2005

D2020.02.02 Plumbing Pumps: Domestic Water*

(1999) DHWR pump replaced.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	20	DEC-04

D2020.02.06 Domestic Water Heaters*

(1999) Gas fired State model SBF75120NECGAD, 31.7 kW input, 386 l/hr recovery, 284 l storage capacity.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	20	DEC-04

D2020.03 Water Supply Insulation*: Domestic

(1968)(2002) Canvas covered.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	DEC-04

Event: **Repair insulation as required.**

Concern:

Insulation is separating from piping in some areas. Noted in area above stage. Insulation on fittings may contain asbestos.

Recommendation:

Reseal insulation as required.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2006	\$3,240	Low

Updated: March 4 2005

D2040.01 Rain Water Drainage Piping Systems*

(1968)(2002) Internal RWLs to storm sewer.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	DEC-04

D2040.02.04 Roof Drains*

(1968)(2002) Standard roof drains.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	40	DEC-04

Event: Add roof drains.**Concern:**

Existing roof drains are in good condition but ponding was seen on roof. Only one roof drain observed on each roof section.

Recommendation:

Add at least one roof drain on each roof section to prevent damage to roof.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Preventative Maintenance	2006	\$10,800	Low

Updated: March 4 2005

D3010.02 Gas Supply Systems*

(1968)(2002) Steel low pressure piping to all gas fired appliances.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	DEC-04

D3020.02.01 Heating Boilers and Accessories: H.W.*

(1968) Gas fired HW heating boilers. Peerless Model 210-17 CI sectional boilers.

(2002) Boiler controls replaced.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	DEC-04

Event: Install HW to Glycol converter.**Concern:**

A/H units use HW to heat outdoor air, limiting the amount of outdoor air that can be brought into the school.

Recommendation:

Install new HW to Glycol converter.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2006	\$27,000	Low

Updated: March 4 2005

D3020.02.02 Chimneys (&Comb. Air): H.W. Boiler*

(1968) Boiler section vents headered into central breeching. Breeching insulation contains asbestos. C/A is adequate.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	DEC-04

Event: Replace breeching insulation.**Concern:**

Breeching insulation contains asbestos in poor condition and moderately friable.

Recommendation:

Replace breeching insulation.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Hazardous Materials Abatement	2006	\$21,600	Low

Updated: March 4 2005

D3020.02.03 Water Treatment: H. W. Boiler*

(1968) Chemical feeder around heating water pump.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

D3040.01.01 Air Handling Units: Air Distribution*

(1968) Two indoor A/H units provide ventilation to admin areas, other core areas and gym. Both units are Canadian Buffalo size 183.

(2002) One roof mounted gas fired Engineered Air A/H unit provides ventilation in 2002 addition.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	DEC-04

Event: Replace indoor A/H units.**Concern:**

CB&F units are showing signs of wear. Outdoor air capability of units is limited as units have HW heating coils.

Recommendation:

Replace indoor A/H units with new units. New units should be equipped with glycol coils to provide greater quantities of outdoor air.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2006	\$43,200	Low

Updated: March 4 2005

D3040.01.04 Ducts: Air Distribution*

(1968)(2002) Galvanized steel distribution ducts.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	DEC-04

D3040.01.07 Air Outlets & Inlets:Air Distribution*

(1968)(2002) Gym has ceiling mounted S/A registers. Library has high sidewall mounted S/A registers. Other areas have diffusers.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	DEC-04

D3040.03.01 Hot Water Distribution Systems*

(1968)(2002) Piping is mixture of copper and steel. Heating water distributed by two end suction pumps rated at 20.4 l/s against a head of 13.7 m. Pumps are powered by 3.37kW motors.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	40	DEC-04

Event: Repair pipe supports.**Concern:**

Some piping supports are broken resulting in piping sagging.

Recommendation:

Repair/replace broken pipe supports.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2006	\$10,800	Low

Updated: March 4 2005

D3040.04.01 Fans*: Exhaust

(1968)(2002) Roof mounted centrifugal mushroom type fans.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	DEC-04

D3040.04.01 Fans*: General Exhaust

(1968)(2002) Roof mounted centrifugal mushroom type fans.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	DEC-04

Event: Replace general exhaust fans.**Concern:**

General exhaust fans do not have the capacity to exhaust high ventilation rates.

Recommendation:

Replace with roof mounted centrifugal exhaust fans.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2006	\$17,280	Low

Updated: March 4 2005

D3040.04.03 Ducts*: Exhaust

(1968)(2002) Galvanized steel ducts.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

D3040.04.03 Ducts*: General Exhaust

(1968)(2002) Galvanized steel in ceiling space.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	DEC-04

Event: Replace general exhaust ductwork.**Concern:**

General exhaust ductwork does not have capacity to handle increased ventilation rates.

Recommendation:

Replace with new exhaust ductwork and grilles.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2006	\$10,800	Low

Updated: March 4 2005

D3040.04.05 Air Outlets and Inlets*: Exhaust

(1968)(2002) Mostly egg crate type ceiling mounted grilles.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

D3050.02 Air Coils*

(1968)(2002) Coils are all HW heating coils. Main coils have no control valves.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	DEC-04

Event: Replace heating coils.**Concern:**

Heating coils are all HW heating coils and so are limited to the amount of outdoor air they can handle. With no control valves they run wild.

Recommendation:

Replace with new coils capable of handling glycol. Install three way control valves on all main heating coils.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2006	\$10,800	Low

Updated: March 4 2005

D3050.05.01 Convectors*

(1968) Semi recessed wall mounted convectors at some entrances.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	DEC-04

D3050.05.02 Fan Coil Units*

(1968)(2002) Fan coil units mounted in ceiling space at entrances.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

Event: Install additional fan coils**Concern:**

Fan coil unit at main entrance does not maintain comfort conditions in vestibule. Outlet only spans across one of three doors.

Recommendation:

Replace and/or install new fan coils units so all three doors are covered.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2006	\$6,480	Low

Updated: March 4 2005

D3050.05.03 Finned Tube Radiation*

(2002) Wall fin radiation in classrooms.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

D3050.05.07 Unit Ventilators*

(1968) HW Heating unit ventilators in classrooms.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	DEC-04

Event: Replace unit ventilators.**Concern:**

Unit ventilators have HW heating coils so are limited to the amount of outdoor air they can handle.

Recommendation:

Replace with finned tube radiation for base heat and new gas fired roof mounted central A/H units for ventilation. Extend ductwork in classroom ceiling spaces and supply ventilation air through ceiling diffusers.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2006	\$216,000	Low

Updated: March 4 2005

D3060.02.03 Pneumatic and Electric Controls*

(1968)(2002) Pneumatic controls.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	40	DEC-04

D4030.01 Fire Extinguisher, Cabinets and Accessories*

(1968) Mostly ABC throughout school.

(2002) Two pump tank type at entrances.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	DEC-04

Event: Replace pump tank type fire extinguishers.**Concern:**

Pump tank type fire extinguishers are subject to misuse.

Recommendation:

Replace with ABC dry chemical fire extinguishers.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2006	\$2,160	Low

Updated: March 4 2005

S5 ELECTRICAL**D5010.01 Main Electrical Transformers***

(1974) Incoming electrical underground service from a padmount transformer supplying 120/208 voltage.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	40	DEC-04

D5010.03 Main Electrical Switchboards (Main Distribution)*

(1974) Primary service is underground from a pad mounted utility transformer. Main service is rated at 600 amps, 120/208 volts, 3 phase, 4 wire. Service equipment is located in a separate electrical room. The configuration utilizes a fused switch and splitter arrangement. The service has ample spare capacity.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	40	DEC-04

D5010.05 Electrical Branch Circuit Panelboards (Secondary Distribution)*

(1968)(2002) Both original and new panelboards installed throughout.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	25	DEC-04

D5010.07.02 Motor Starters and Accessories*

(1968) MCC consists of splitters and loose starter arrangement which is original and in fair condition.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

D5020.01 Electrical Branch Wiring*

(2002) Installed in metallic or flexible conduit and upgraded in 2002.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	50	DEC-04

D5020.02.01 Lighting Accessories (Lighting Controls)*

(1996) Theatre style lighting in front and above stage area c/w dimmer/controller.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	30	DEC-04

D5020.02.02 Interior Florescent Fixtures*

(2002) Upgraded to T8 lamps and energy efficient ballasts in 2002.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	30	DEC-04

D5020.02.03 Emergency Lighting*

Integrated battery pack and remote lamps throughout. Exits upgraded to LED style in 2001.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	30	DEC-04

D5020.03.01.01 Exterior Incandescent Fixtures*

(1968) Incandescent fixtures on exterior walls/ceilings.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	30	DEC-04

D5020.03.01.04 Exterior H.P. Sodium Fixtures*

(1986) HID lighting mounted on exterior walls.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	30	DEC-04

D5020.03.02 Lighting Accessories (Lighting Controls)*

(1986) Exterior fixtures controlled by photocells.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	25	DEC-04

D5030.01 Detection and Alarm Fire Alarm*

(2002) Edwards EST Main Fire Alarm Panel c/w annunciator installed in 2002.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	25	DEC-04

D5030.02.02 Intrusion Detection*

(2000) Standard school board magnum alert system monitoring motion detectors, door alarms, mechanical, portables, computer room.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	25	DEC-04

D5030.03 Clock and Program Systems*

(1974) Simplex Master Clock System to ring bells only. Battery operated clocks throughout.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	25	DEC-04

D5030.04.01 Telephone Systems*

(1996) Nortel Norstar System integrated with Bogen.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	25	DEC-04

D5030.04.02 Paging Systems*

(1996) Bogen multi-com intercom system integrated with phone system.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	25	DEC-04

D5030.04.03 Call Systems*

(1996) Bogen handsets throughout.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	DEC-04

D5030.04.04 Data Systems*

(2002) CAT 5 UTP from all rooms including portables to network locations.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	DEC-04

D5030.04.05 Local Area Network Systems*

(2002) Main network location is adjacent to Electrical room. Installed in 2002.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	DEC-04

D5030.05 Public Address and Music Systems*

(1986)(1990) Bogen 2000 and a TOA amp located on the stage.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	DEC-04

D5030.06 Television Systems*

(2001) Co-ax cabling to each room throughout.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	DEC-04

D5090.01 Uninterruptible Power Supply Systems*

(2002) 600VA UPS for phone system and a 1600VA UPS for school server.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	25	DEC-04

S6 EQUIPMENT, FURNISHINGS AND SPECIAL CONSTRUCTION**E1020.02 Library Equipment***

(2002) Copier machine, book drop off bins.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	DEC-04

E1020.03 Theater and Stage Equipment*

(1968) Sound and lighting equipment. Stage curtain and folding acoustical partition when the Stage is not in use.

(2002) Stage / Art Room has perimeter curtain on ceiling tracks. When the Stage is being used the perimeter background curtain is drawn to hide all the Art Room perimeter millwork. TV and pull down projection screens in Classrooms. Large projection screen above Stage in Gymnasium.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	DEC-04

E1090.02 Solid Waste Handling Equipment*

(2000) The original incinerator has been removed. Use only commercial steel garbage bins.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	DEC-04

E1090.04 Residential Equipment*

(1968) Fridge, stove and microwave in a small Kitchen near Gymnasium.

(2002) Fridge, microwave ovens, coffee making machine, water cooler, stove and dishwasher in Staff Room.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	DEC-04

E1090.07 Athletic, Recreational, and Therapeutic Equipment*

(1968) 4 fixed basketball hoops on walls, floor hockey equipment, climbing apparatus, floor sockets, three badminton and two dodge ball courts. Court lines were repainted in 2002.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	DEC-04

E2010.02.05 Educational Facility Casework*

(2002) New Classrooms in addition - Painted cabinets with open shelving, cupboard with open shelving, sink cabinets, plastic laminate counter tops, painted book storage shelving, fixed and mobile in new Classrooms.

Arts Room / Storage - Extensive perimeter cabinets and cupboards for storage of large plastic bins, plastic laminate countertops with sinks, complete with TnS faucets, full height storage cupboards.

Computer Room - Perimeter painted cupboards, cabinets and plastic laminate work top counter.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
6 - Excellent	0	0	DEC-04

E2010.02.05 Educational Facility Casework*

(1968) Perimeter cabinets, painted with plastic laminate countertops and open shelving in Classrooms. Caseworks are small in most Classrooms (limited because of curved walls).

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	DEC-04

Event: **Provide cabinet and cupboards in four Classrooms.**

Concern:

Four Classrooms in original building do not have any cabinets and cupboards.

Recommendation:

Install cabinets and cupboards in four Classrooms of original building.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Program Functional Upgrade	2008	\$7,020	Low

Updated: March 4 2005

E2010.02.07 Kitchen Casework*

(1968) Painted cabinet with sink and plastic laminate countertop and cupboards in the small Kitchen near Gymnasium.
(2002) Birch cabinets, cupboards and post formed plastic laminate countertops with sinks in Staff Room.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	DEC-04

E2010.02.09 Library Casework*

(2002) Book shelves (painted and plastic laminate), metal wire and wood book display cases, magazine racks. All items, both in castors and fixed units. Plastic laminate finish Librarian's workstation, including cabinets, cupboards, countertop and reception counter. Painted storage units, full height.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
6 - Excellent	0	0	DEC-04

E2010.02.99 Other Casework*

(2002) New lavatory counters with stainless steel sinks in Boys' and Girls' Washrooms. Principal's workstations and storage and filing cabinets (plastic laminate). Birch computer work stations with cupboards and cabinets in Staff Work Room. A Large reception counter in Administration area, complete with four modular workstations (plastic laminate). Coat rod and shelves in new Classrooms. Wooden prefabricated closets (painted) with bi folding doors in Staff Room.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
6 - Excellent	0	0	DEC-04

E2010.03.01 Blinds*

(2002) Vinyl louvres in all new and old interior and exterior windows and sidelites. Accordion type pull up shades in Principal's Office.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
6 - Excellent	0	0	DEC-04

E2010.05 Fixed Multiple Seating*

(1968) Music Room has tiered seating platforms made of wood and is carpeted.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	DEC-04

E2020 Moveable Furnishings*

(1968)(2002) Classroom desks and chairs (plastic laminate), computer tables (plastic laminate), birch round tables and chairs (fabric finish) and sofas in Staff Room. Benches and seating in the main entrance and corridors and Gymnasium. Majority of loose furnishings is new. Old furnishings are in good condition.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	DEC-04

F1010.02.04 Portable and Mobile Buildings (Portable No.1)

Year built: 1992; Area: 84 sq.m. (approximate) - (identified as Portable #21 on site)

Architectural / Structural :

Wood frame construction bearing on wood sleepers. Envelope includes exterior prefinished metal panels on plywood sheathing and building paper, on 38 x 150 mm wood stud insulated walls, painted plywood skirting with vents, wood joists and plywood sheathing floor and roof structure, aluminum frame windows with bottom openable section and built-up roofing and metal vented soffits. Interior components include carpet, painted and vinyl faced gypsum board walls, suspended T-Bar ceiling, hollow metal doors on steel frames with panic sets, closers, weather stripping and locks. Cabinets with open shelving (melamine) and counter top with splash back (plastic laminate); vinyl louvre, white board, chalk boards, tack boards, map rails, coat hooks. Exterior steel grated entrance platform and steps with pipe rails (painted). The floor in entrance recess is painted and is slippery. Indoor / outdoor carpet should be provided as maintenance item. Doors and frames are not labeled. Average rating is 'acceptable' (4).

Mechanical:

Gas fired furnace provides heating and fixed minimum ventilation. No cooling. Air is supplied to the space via galvanized under floor ductwork. Overall rating is 'marginal' (3).

Electrical:

The electrical feed is from the MDP located in the school, along with data / telephone / catv and security is fed via overhead lines. 120/208 volt panel located in the portable is sufficient with an appropriate quantity of receptacles and data outlets. Lighting levels appear to be adequate utilizing T12 lamps and magnetic ballasts. Overall rating is 'acceptable' (4).

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	DEC-04

Event: Replace furnace in Portable No.1.**Concern:**

Furnace operates on a minimum fixed quantity of outdoor air.

Recommendation:

Replace the furnace with a new furnace, complete with proportional burner controls, capable of providing 100% outdoor air.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2007	\$3,780	Low

Updated: March 4 2005

F1010.02.04 Portable and Mobile Buildings Portable No.2)

Year built: 1992; Area: 84 sq.m. (approximate) - (identified as Portable #21 on site)

Architectural / Structural :

Wood frame construction bearing on wood sleepers. Envelope includes exterior prefinished metal panels on plywood sheathing and building paper, on 38 x 150 mm wood stud insulated walls, painted plywood skirting with vents, wood joists and plywood sheathing floor and roof structure, aluminum frame windows with bottom openable section and built-up roofing and metal vented soffits. Interior components include carpet, painted and vinyl faced gypsum board walls, suspended T-Bar ceiling, hollow metal doors on steel frames with panic sets, closers, weather stripping and locks. Cabinets with open shelving (melamine) and counter top with splash back (plastic laminate); vinyl louvre, white board, chalk boards, tack boards, map rails, coat hooks. Exterior steel grated entrance platform and steps with pipe rails (painted). The floor in entrance recess is painted and is slippery. Indoor / outdoor carpet should be provided as maintenance item. Doors and frames are not labeled. Average rating is 'acceptable' (4).

Mechanical:

Gas fired furnace provides heating and fixed minimum ventilation. No cooling. Air is supplied to the space via galvanized under floor ductwork. Overall rating is 'marginal' (3).

Electrical:

The electrical feed is from the MDP located in the school, along with data / telephone / catv and security is fed via overhead lines. 120/208 volt panel located in the portable is sufficient with an appropriate quantity of receptacles and data outlets. Lighting levels appear to be adequate utilizing T12 lamps and magnetic ballasts. Overall rating is 'acceptable' (4).

Rating	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	DEC-04

Event: Replace furnace in Portable No.1.**Concern:**

Furnace operates on a minimum fixed quantity of outdoor air.

Recommendation:

Replace the furnace with a new furnace, complete with proportional burner controls, capable of providing 100% outdoor air.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2007	\$3,780	Low

Updated: March 4 2005

F1030.05 Other Special Construction Systems*

(1968) Gymnasium chair storage under the Stage.

Rating	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

F2020.01 Asbestos*

(1968) An asbestos survey was completed for Edmonton Public Schools in 2000. It identified asbestos in elbow muds (35 to 40% chrysotile), boiler breachings (45% chrysotile), textured tile ceilings (1.3% chrysotile), vinyl floor tiles (6% chrysotile). Asbestos from the central circular building areas has been removed during the 2002 renovations. Asbestos in Boiler Room and other areas has been incorporated in Mechanical evaluation. The remaining asbestos containing materials, such as ceiling and floor tiles are in good condition and can remain until future renovations.

Rating	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

F2020.02 PCBs*

Ballasts containing PCBs were removed during 2002 renovations. No known PCBs.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	DEC-04

F2020.03 Mercury*

Not known or reported.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

F2020.04 Mould*

Not known or reported.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

Facility Details**Building Name:** Kildare Elementary School**Address:****Location:** Edmonton**Building Id:** S3182**Gross Area (sq. m):** 0.00**Replacement Cost:** \$0**Construction Year:** 0**Evaluation Details****Evaluation Company:****Evaluation Date:****Evaluator Name:****Total Maintenance Events Next 5 years:** **\$30,240****5 year Facility Condition Index (FCI):** **0%****General Summary:**

Paved staff and visitor parking is located in the NW corner. Paved parent drop off area is located along 76 Street (west). School buses drop off in the front (144 Avenue). Two concrete sidewalks in the front, one in NW corner connecting to parking lot and another directly to the north, to 144 Avenue. Sidewalks around the building and on the west side connecting to parent drop off. Asphalt surfaces in basketball court and in adjacent area. Large grass play field to the south and east with basketball and soccer fields.

Sidewalks along building walls should be mud jacked. The concrete pad at the front entrance should be re-built. The deteriorated asphalt surfaces near basketball court should be re-built. School bus drop off area should be relocated along 76 Street (behind parent drop off). Overall rating is 'acceptable' (4).

Mechanical:

Site is serviced by City of Edmonton water, sanitary and storm sewers. Gas is provided from utility mains. catch basin in the play field. Overall rating for site mechanical systems is 'acceptable' (4).

Electrical Summary:

Lighting is adequate, recommend adding ten (10) new car plug-ins. Overall site rating is 'acceptable' (4).

Structural Summary:**Envelope Summary:****Interior Summary:****Mechanical Summary:****Electrical Summary:****Rating Guide**

Condition Rating	Performance
1 - Critical	Unsafe, high risk of injury or critical system failure.
2 - Poor	Does not meet requirements, has significant deficiencies. May have high operating/maintenance costs.
3 - Marginal	Meets minimum requirements, has significant deficiencies. May have above average operating maintenance costs.
4 - Acceptable	Meets present requirements, minor deficiencies. Average operating/maintenance costs.
5 - Good	Meets all present requirements. No deficiencies.
6 - Excellent	As new/state of the art, meets present and foreseeable requirements.

S7 SITE

G2010.02.02 Flexible Pavement Roadway (Asphalt)*

(1990) The access road to the parking lot (NW corner) and the new parent drop off on the west side (75 Street).

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	

G2010.02.02 Flexible Pavement Roadway (Asphalt)*

(1968) School buses currently drop off in 144 Avenue.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	20	

Event: Create a bus drop off zone behind parent drop off area.

Concern:

Currently all the school buses drop off on the north side on the very busy 144 Avenue.

Recommendation:

Carve out a drive and bus drop off area along 76 Street on the east side, behind parent drop off area, complete with a new sidewalk, linking with the existing (asphalt:\$182,000, Concrete sidewalks and curbs:\$123,000).

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Program Functional Upgrade	2008	\$329,400	Medium

Updated: March 3 2005

G2010.05 Roadway Curbs and Gutters*

(1990) Concrete curbs along the drive in parent drop off area.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	

G2010.06 Roadway Appurtenances*

(1990) Directional signage, parent drop off and pedestrian zones have been identified with signage.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	

G2020.02.02 Flexible Paving Parking Lots(Asphalt)*

(1990) The original gravel staff and visitor parking area (NW corner) and overflow parking near portable were paved in 1990. It accommodates 45 staff and 5 visitor stalls. A catch basin has been provided. Adequate slopes.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	

G2020.05 Parking Lot Curbs and Gutters*

(1990) Concrete curbs.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	

G2020.06.01 Traffic Barriers*

(1968) A pipe rail swinging barrier is located at the NW corner of the parking lot. A chain gate is located at the NE corner of the parking lot to control traffic from 144 Avenue and another chain barrier provided between portables and the school building. In addition, pressure treated wood posts have been incorporated to prevent traffic short cuts. Painted pipe rails.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	

G2020.06.02 Parking Bumpers*

(1968) Original precast concrete bumpers have been reused.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	

G2020.06.03 Parking Lot Signs*

(1968)(1990) Free standing and wall mounted signs for staff and visitor parking.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	

G2020.06.04 Pavement Markings*

(1990)

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	

G2030.02.02 Asphalt Pedestrian Pavement*

(1998) The area adjacent to the basketball court is paved. This area used have portables.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	25	

Event: Repair asphalt surfaces near basket ball court.**Concern:**

The asphalt area (exposed after old portables were removed) is in poor condition, with a mixture of grass, gravel , broken asphalt and pot holes.

Recommendation:

Repair pot holes and repair surfaces and repave with asphalt.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2007	\$21,600	Low

Updated: March 3 2005

G2030.04 Rigid Pedestrian Pavement (Concrete)*

(1968)(1990) Concrete sidewalk around the circular building. Concrete sidewalk in the front along the curved wall of Gymnasium portion. North sidewalk from 144 Avenue to the north entrance of circular building. Concrete pad at the main entrance. Proposed new concrete sidewalks in the new bus drop off area have been incorporated in G2030.02.02.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	

Event: **Mud jack concrete sidewalks.**

Concern:

The front curved sidewalk and portions of sidewalk along the circular building has negative slope towards building walls. The concrete pad at the main entrance has separated and has negative slope.

Recommendation:

Mud jack all negatively sloped sidewalks. Rebuild the concrete pad at front entrance.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2007	\$8,640	Low

Updated: March 3 2005

G2030.06 Exterior Steps and Ramps*

(1968) Concrete steps in the sidewalk along the curved Gym area wall.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	

G2040.02 Fences and Gates*

(1990) 1.5m high chain link fence along west side of property (76 Street).

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	

G2040.03 Athletic and Recreational Surfaces*

(1968)(1990) Grass play fields and asphalt basket ball court. A catch basin is located in the SE corner of school building. The site slopes southward (away from school building).

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	

G2040.04 Athletic and Recreational Equipment*

(1968) Four baseball diamonds, two large and two small soccer fields with goal posts.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	25	

G2040.05 Site and Street Furnishings*

(1990) A temporary bleacher near west baseball diamond. Wood benches near basketball court.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	

G2040.06 Exterior Signs*

(1968) A large metal school sign, mounted on the front curved wall of Gymnasium block. Free standing wood sign post for announcements in the front, facing 144 Avenue.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	

G2040.08 Flagpoles*

(1968) One flag pole in the front , mounted in the wall.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	

G2040.11 Retaining Walls*

(1968) A short concrete and treated wood retaining wall at the NW portion in the front.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	

G2050.04 Lawns and Grasses*

(1968) Front area has lawn. Play field is grassed.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	

G2050.05 Trees, Plants and Ground Covers*

(1968) Mature evergreens throughout the south portion of play field. Mature evergreen and deciduous trees in the front.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	

G3010.02 Site Domestic Water Distribution*

(1968)(2001)Water is provide by the City of Edmonton.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	

G3020.01 Sanitary Sewage Collection*

(1968)(2001)Site is connected to the City of Edmonton sanitary sewer system.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	

G3030.01 Storm Water Collection*

(1968)(2001) Site is connected to the City of Edmonton storm sewer system

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	

G3060.01 Gas Distribution*

(1968)(2001)Low pressure gas is provided from utility mains.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	

G4010.02 Electrical Power Distribution Lines*

(1974) Underground services from pad mount transformer to building. Overhead service split fed to two (2) portables.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	

G4010.03 Electrical Power Distribution Equipment*

(1974) Pad mount transformer.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	

G4010.04 Car Plugs-ins*

(1991) Rail mounted receptacles controlled by a contactor/thermostat configuration.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	

Event: Upgrade car plug-ins.**Concern:**

Staff vehicles to car plug-in ratio insufficient.

Recommendation:

Install ten (10) new car plug-ins c/w controller.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Program Functional Upgrade	2007	\$9,180	Low

Updated: March 3 2005

G4020.01 Area Lighting*

(1996) Combination of HID and incandescent fixtures.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	

S8 FUNCTIONAL ASSESSMENT

K40 Current Code Issues

The two exits at both ends of the new corridor is located in the recess between old and new structures.

The small Mechanical Room and adjacent Storage doors, and the west exit door in Gymnasium area are solid core wood on steel frames.

Paint and other volatile substances have been stored in the Storage next to the small Mechanical Room. All volatile substances should be removed and stored in the Supply Storage area.

There is a large hole on the wall between Supply Storage and Boiler Room (may have been for pipes). It should be filled with grout or with expandable fire stopping material.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
2 - Poor	0	0	DEC-04

Event: Fill existing recesses with vestibules at the two ends of the new corridor. Replace doors in fire separations.

Concern:

The existing recesses get filled with snow. The exit doors can not be opened. The west exit door does not have a panic device; the door is not rated. The small Mechanical room and adjacent Storage do not have rated doors and frames.

Recommendation:

Existing recesses, at the two ends of the new corridor between existing and the new buildings, should be filled with construction of new vestibules. Scope includes, extending slab on grade and roof and new glazed exterior doors, complete with transoms and sidelites.

Replace existing doors at the west exit and the small Mechanical room and adjacent Storage with new hollow metal doors, complete with proper hardware to comply with building codes.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Code Upgrade	2007	\$32,400	High

Updated: March 4 2005

K4010.01 Barrier Free Route: Parking to Entrance

(1968) Currently the barrier free door is located to the back of the Main Entrance. It has an automatic opener. A new entrance is required on the north side - see K4010.02 below.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

K4010.02 Barrier Free Entrances

(1968) Currently the barrier free door is located to the back of the Main Entrance. It has an automatic opener.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	DEC-04

Event: **Provide a new handicapped entrance at the north door of circular building.**

Concern:

The existing handicapped entrance is rarely used since all handicapped students are dropped off at the front (144 Avenue) and use the sidewalk directly to north of the circular building. It is difficult for wheelchairs to go around the building, especially in winter.

Recommendation:

Install a new entrance double door at the north entrance of the circular building, complete with automatic openers with remote actuator buttons. Costs of new doors and a new vestibule at this location have been included in B2030.01 and C1020.02. Estimate here is for two automatic openers

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Program Functional Upgrade	2007	\$17,280	Low

Updated: March 4 2005

K4010.03 Barrier Free Interior Circulation

(1968)(2002) Except Gymnasium, access to all parts of the building possible. Doors are wide enough for wheelchairs to most rooms. The corridor to Gymnasium has steps (6 risers). An interior ramp is not possible. Options include allowing wheelchairs from the west exit door or installation of a wheelchair lift.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

K4010.04 Barrier Free Washrooms

(2002) Barrier free Boys' and Girls' Washrooms have created along the corridor to the Gymnasium.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
6 - Excellent	0	0	DEC-04