

RECAPP Facility Evaluation Report



Prince Charles Elementary School

B3251A
Edmonton

Facility Details

Building Name: Prince Charles Elementary School
Address: 12325 - 127 Street
Location: Edmonton

Building Id: B3251A
Gross Area (sq. m): 0.00
Replacement Cost: \$4,405,208
Construction Year: 0

Evaluation Details

Evaluation Company: Koliger Schmidt
Evaluation Date: December 1 2004
Evaluator Name: Mr. Mario Macchione

Total Maintenance Events Next 5 years: \$434,484
5 year Facility Condition Index (FCI): 9.86%

General Summary:

Prince Charles elementary school was built in 1954 and an addition complete in 1956, both of wood framed construction. The total area of the facilities is 2736.4 m². Four freestanding portables are located on site on the east side of the school. In 1994 a minor modernization of the administration area was complete. The plans given to us by Alberta Infrastructure do not reflect this renovation nor the change to the boys and girls washroom areas. This school is no longer part Junior high.

Near closure years ago due to student population, the school has developed a "focus" that incorporates it's location in the city and represents the students that attend. It's strength in aboriginal studies and culture have allowed this school to become populated again. Unfortunately many items in this school are in need of replacement and a modernization of the entire school is recommended. Also considerations for barrier free access are necessary. Prince Charles is in fair condition.

Structural Summary:

This is a single storey wood framed construction with concrete floors. Minor settlement cracks in terazzo and in hallway ceiling. Structurally in good condition.

Envelope Summary:

The 1954 and 1956 building consist of painted stucco, brick wainscoting, glass block and some wood decorative panning above windows in the front of the school. Almost all exterior windows and doors have been upgraded from wood to vinyl windows and insulated hollow metal doors. The roof was redone in 1988 but extensive water damage is apparent in the access area up to the roof. Past report has noted the knowledge of the roof leaks and has been monitored by the division. The building envelope is in fair condition.

Interior Summary:

School walls are a painted plaster, sheet flooring, wood bases and painted plaster with 12x12 accoustical tile ceilings. On the 1956 building side most rooms have newer carpet and all areas have drop ceilings. Asbestos is present in parts of the school materials and needs to be removed. Modernization of the interior finishes are required, most are outdated and need to be replaced. The schools interior is in fair condition.

Mechanical Summary:

The heating is provide by two steam boilers originally fired by coal and converted to natural gas. The steam is supplied to perimeter fin throughout the building. One air handling provides air to the school. There is a pneumatic system for local controls only. Generally, the mechanical systems are the same since the original construction of the building in 1954. There is minimal ventilation supplied to classrooms. A major mechanical upgrade is recommended as part of a building modernization.

The mechanical systems are in poor condition.

Electrical Summary:

Main service is two parts. First service is 350 Amp, single phase, 120/240 volt. Second service is 50 Amp, three phase, 240 volt.. Branch circuit panel boards are located throughout the facility. The lighting consists of T12 fluorescent light fixtures with some incandescent and HID light fixtures. Emergency lighting consists of battery packs c/w remote heads with energy efficient LED style exit lights throughout. The fire alarm system is Simplex 2001. Cat5 data network cabling is installed throughout. Telephone system is by Nortel. Paging system is Bogen. Upgrade main distribution switchgear. Upgrade Fire Alarm System by adding strobes. Replace existing lighting system with new T5 lighting system for energy efficiency and life cycle replacement. The electrical is in fair condition.

Rating Guide	
Condition Rating	Performance
1 - Critical	Unsafe, high risk of injury or critical system failure.
2 - Poor	Does not meet requirements, has significant deficiencies. May have high operating/maintenance costs.
3 - Marginal	Meets minimum requirements, has significant deficiencies. May have above average operating maintenance costs.
4 - Acceptable	Meets present requirements, minor deficiencies. Average operating/maintenance costs.
5 - Good	Meets all present requirements. No deficiencies.
6 - Excellent	As new/state of the art, meets present and foreseeable requirements.

S1 STRUCTURAL

A1010 Standard Foundations*

1954 and 1956 buildings

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	100	DEC-04

A1030 Slab on Grade*

1954 gymnasium, front and south entrances to school.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	100	DEC-04

A2020.01.01 Cast-in-place Concrete: Basement Wall

Boiler room.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

B1010.01 Floor Structural Frame*(Building Frame)

Wood

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	100	DEC-04

B1010.01.01 Columns Supporting Floors

Basement boiler room.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	DEC-04

B1010.01.02.01 Cast-in-place Concrete: Beams

Basement boiler room

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	DEC-04

B1010.03 Floor Decks, Slabs, and Toppings*

1954 and 1956 buildings

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	100	DEC-04

B1010.07.01 Cast-in-place Concrete:Exterior Stairs

North and east side of school

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

B1010.09 Floor Construction Fireproofing*

Crawl space. See F2020.01

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

B1010.10 Floor Construction Firestopping*

Boiler room in basement.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
2 - Poor	0	0	DEC-04

Event: **Fill and seal ceiling and wall penetrations with firestopping material.**

Concern:

Unsealed penetrations (conduit and pipe) through ceiling and walls compromising fire separations.

Recommendation:

Fill and seal ceiling and wall penetrations with firestopping material to meet code.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Code Repair	2005	\$6,480	High

Updated: February 18 2005

**B1010.11.01 Catwalks**

1954 building- Above stage area (wood construction)

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

B1020.01 Roof Structural Frame*

Wood

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	100	DEC-04

B1020.04 Canopies*

1954 and 1956 buildings- wood construction, stucco finish.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	100	DEC-04

S2 ENVELOPE

B2010.01.02.01 Brick Masonry: Ext. Wall Skin*

Wainscoting of wall and entrance cove areas.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	75	DEC-04

Event: Repointing of brick.

Concern:


Brick has cracked and deteriorated joints allowing water to penetrate inside, possibly causing future problems

Recommendation:

Repoint areas of brick work. (approx. 25m²)

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2006	\$1,620	Low

Updated: February 18 2005



B2010.01.06.04 Wood Siding*

Wood panelling above windows on west side.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	40	DEC-04

Event: Sand and repaint panelling.

Concern:

Wood panelling above windows on the west side are peeling.

Recommendation:

Sand down, prime and repaint panels (approx. 186m²)

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2006	\$4,320	Low

Updated: February 18 2005



B2010.01.08 Portland Cement Plaster: Ext. Wall*

1954 and 1956 buildings -painted; minor cracking.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	75	DEC-04

B2010.02.03.04 Glass Masonry Units (Glass Block)

1954 building- Front of school, gymnasium, east side entrance

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	DEC-04

Event: **Repair window joints.****Concern:**

Glass block seals are cracked and discolored.

Recommendation:

Repair and reseal glass on exterior and interior side of block.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2006	\$1,080	Low

Updated: February 18 2005**B2010.02.05 Wood Framing*: Ext. Wall Const.**

1954 and 1956 buildings

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	100	DEC-04

B2010.03 Exterior Wall Vapor Retarders, Air Barriers, and Insulation*

1954 and 1956 buildings

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	20	DEC-04

B2010.06 Exterior Louvers, Grilles, and Screens*

1954 and 1956 building

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	20	DEC-04

B2010.09.04 Portland Cement Plaster:Soffits

1954 and 1956 buildings- painted

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

B2020.01.01.05 Wood Windows*

1954 building -Second floor projection and storage area.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
2 - Poor	0	35	DEC-04

Event: Replace wood windows**Concern:**

Original wood windows haven't been replaced and area is cool and drafty. Window are showing signs of rotting and major deterioration.

Recommendation:

Replace windows with vinyl windows. 3 sets of double windows.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2005	\$2,160	Medium

Updated: February 18 2005

**B2020.01.01.06 Vinyl, Fibreglass &Plastic Windows***

Newly replaced windows in 1954 and 1956 buildings

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	35	DEC-04

B2030.01.02 Steel-Framed Storefronts*

2003- 1954 and 1956 buildings- New doors and hardware (panic bars).

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	30	DEC-04

B2030.02.01 Metal Doors and Frames

2003- 1954 building- Exit from boiler room to grade and 2 other exit doors (all east side of building) all with panic bar hardware.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	DEC-04

B3010.01 Deck Vapor Retarder and Insulation*

1954 building- Prior roof leaks but no apparent problems at this time.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

B3010.04.04 Modified Bituminous Membrane Roofing (SBS)*

1988 reroofed- 1954 and 1956 buildings- 2 ply SBS roofing with internal drainage; prior roof leaks and regular maintenance but at present time no apparent problems. Otherwise winter conditions apply to exterior viewing.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	25	DEC-04

B3010.09 Roof Specialties and Accessories*

Ladder

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	25	DEC-04

S3 INTERIOR**C1010.01 Interior Fixed Partitions***

1956 building- Library has a partial wall with windows and door that separates main library from resource office area. As well as science room has a partial wall that separates storage area.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	50	DEC-04

C1010.01.07 Framed Partitions (Wood Stud)

1954 and 1956 buildings, painted.


<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	DEC-04

Event: Patch, repair and repaint Gym storage area.**Concern:**

Gym storage area with staircase up to projection room (which is used for storage now) has walls with crack and holes in the gypsum, also it's paint is peeling.

Recommendation:

Patch, repair and repaint walls in staircase area, projection room and upper storage room. If this area is going to be a permanent storage facility then provide shelves for better use of space. Coordinate with replacement of windows in B2020.01.01.05. (approx. 140m²)



<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2006	\$4,536	Low

Updated: February 18 2005

Event: Repair stage walls and ceiling in roof/catwalk access area.**Concern:**

Water leak from roof has caused paint to peel and ceiling to crack and sag.

Recommendation:

Walls- remove paint, repair damages to building material and prime and repaint access area.
Ceiling- Remove ceiling and repair any further damages to roof construction, electrical work and investigate other leaks and repair. Install new ceiling (drop ceiling for easy access to roof construction if more leaks appear (can replace tile instead of whole ceiling.)

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2006	\$7,560	Low

Updated: February 18 2005

C1010.04 Interior Balustrades and Screens, Interior Railings*

1954 building

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	40	DEC-04

Event: **Install handrails to main stairs.****Concern:**

Main entrance to 1954 building has a set of stairs without stair railings.

Recommendation:

Install a handrail to the main stairs.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Code Upgrade	2006	\$1,080	Medium

Updated: February 18 2005

C1010.05 Interior Windows*

1954 building- Main office, coucillors office, family coucilling; non-operable metal units.
1956 building- Library

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	40	DEC-04

C1010.07 Interior Partition Firestopping*

Boiler room- See B1010.10

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	DEC-04

C1020.01.07 Wood Doors

1954 and 1956 buildings- solid wood frames and doors.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	DEC-04

Event: **Replace all interior doors and frames****Concern:**

All doors within the school are painted original solid wood core and frames with original hardware. These have been painned numerous times and are chipping. Some doors have windows, some have grilles, some have neither, all seem to be mismatched.

Recommendation:

Replace all wood doors and frames (approx 78 doors) and update hardware.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2006	\$75,600	Low

Updated: February 18 2005



C1020.02 Interior Entrance Doors*

1954 and 1956 buildings

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	50	DEC-04

Event: Original hardware**Concern:**

Solid wood doors have original hardware.

Recommendation:

Replace hardware on 21 doors. Install panic bars.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2006	\$20,520	Low

*Updated: February 18 2005***C1020.03 Interior Fire Doors***

1954 and 1956 buildings.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
2 - Poor	0	50	DEC-04

Event: Hold open devices and fire rated labels for doors.**Concern:**

1954 building- Doesn't have fire rated labels or hold open devices.

1956 building- Doesn't have fire rated labels

Recommendation:

1954 building- Install hold open devices for 2 doors and get fire rated sticker for each. (materials \$500, labour \$250 each door)
 Cost for Fire alarm panel interface and power supply \$1,000 per door assembly.

1956 building- Requires fire labeled doors (2 doors)

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Code Upgrade	2006	\$4,860	High

Updated: February 18 2005

C1030.01.01 Chalkboards

1954 building- Classrooms 5,6 and 25 (on plan)

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	DEC-04

Event: Replace chalkboards with whiteboards.**Concern:**


Some children are allergic to chalk and also causes a mess with chalk residue on floors and walls.

Recommendation:

Replace 5 chalkboards with whiteboards. Repair walls as needed.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Operating Efficiency Upgrade	2006	\$4,320	Low

Updated: February 18 2005

**C1030.01.02 Markerboards**

1954 and 1956 buildings- All classrooms except the ones listed in 1030.01.01

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	DEC-04

C1030.01.03 Tackboards and Visual Aid Boards

1954 and 1956 buildings

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

C1030.02 Fabricated Compartments(Toilets/Showers)*

1954 building- Boys and girls washrooms

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
2 - Poor	0	0	DEC-04

Event: Replace washroom partitions**Concern:**

Old, rusted, stained and paint is peeling off. Hardware is also old and probably original.

Recommendation:

Remove existing partitions and hardware and replace with new. (8 in total 1 in each washroom should be barrier free)

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2006	\$22,680	Medium

Updated: February 18 2005



C1030.08 Interior Identifying Devices*

1954 building- Main entrance has school plan and other signs showing school's focus.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

C1030.12 Storage Shelving*

1954 and 1956 building- Metal and wood shelving units in storage rooms, boiler room and classroom storage closets.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

C1030.14 Toilet, Bath, and Laundry Accessories*

1954 building- See C1030.02

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	20	DEC-04

C2010.01 Cast-In-Place Concrete Stair Construction

1954 building- Boiler room and hallway stairs.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

C2010.04 Wood Stair Construction

1954 building- Stage stairs down to gym and gym storage room up to projection loft.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

C2020.02 Terrazzo Stair Finishes*

1954 and 1956 buildings- Hallway stairs to exits (North, south and west sides of building)

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	75	DEC-04

C2020.05 Resilient Stair Finishes*

1954 building- Stage stairs down to gym and gym storage room up to projection loft; sheet

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	20	DEC-04

C2020.08.04 Wood Framed Railings and Balustrades

1954 building- Gym storage room up to projection loft and both entrances from hallway up to stage area; painted.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

C2020.08.06 Metal Railings and Balustrades

1954 building- Boiler room; painted.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

C2020.08.07 Wood Railings

1954 building- Stage stairs down to gym; painted.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

C3010.03 Plaster Wall Finishes*

1954 and 1956 buildings; painted.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	40	DEC-04

C3010.04 Gypsum Board Wall Finishes*

1954 and 1956 buildings- Main office area and library; painted.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	40	DEC-04

C3010.06 Tile Wall Finishes*

1954 building- Boys & girls and staff male & female washrooms.


<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	50	DEC-04

Event: Girls and Boys washrooms.**Concern:**

Tiles are old, cracked and discolored with stained grout. If a modernization is taking place and most of the finishes in these 2 washrooms need to be upgraded then the tiles should be as well. Boys washroom has a newer type of tile on most walls except urinal wall.

Recommendation:

Replace wall tiles.(approx 40m² in total both washrooms)
Match tiles in boys washroom on urinal wall to the rest of the tiles in the room. Schedule following mechanical event to replace old floor urinals to wall mounted. D2010.02 Repair and paint top portion of boys and girls walls after all construction has been completed.



<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2006	\$8,640	Low

Updated: February 18 2005

C3010.09 Acoustical Wall Treatment*

1954 building- Music room and gymnasium.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	20	DEC-04

C3010.14 Other Wall Finishes*

1954 building- main office, detention rooms have special wall treatment to allow for easy removal of graffiti.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	DEC-04

C3020.02 Tile Floor Finishes*

1954 building- Boys and mens staff washrooms. See Mech D2010.02 for tile replacement in boys washroom.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	DEC-04

C3020.03 Terrazzo Floor Finishes*

1954 and 1956 buildings- Hallways, boys and girls washrooms.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	70	DEC-04

C3020.04 Wood Flooring*

1954 building- Gymnasium and stage.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
2 - Poor	0	25	DEC-04

Event: **Anchor gym floor.**

Concern:

Gym flooring is wavy in areas and has overly loud areas of squeaking. Could potentially mean that the wood floor isn't properly fastened down to the subflooring.

Recommendation:

Fasten down wood flooring to subflooring. (Otherwise replacing gym floor will cost \$50,000)

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2006	\$2,160	Medium

Updated: February 18 2005

C3020.07 Resilient Flooring*

1954 building- Classrooms, kitchen, staff room, staff washroom, science room and storage rooms.
 1956 building- Classrooms.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	20	DEC-04

Event: Replace flooring.**Concern:**

1954 building- Original sheet flooring in classrooms; Old, stained and in some classrooms is worn down.

Recommendation:

Replace all sheet flooring with VCT and install new rubber base where needed. (Approx. 873.6m²)

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2006	\$34,560	Low

Updated: February 18 2005

**C3020.08 Carpet Flooring***

1954 and 1956 building- Office area, councilors office, family services office, staff room, library and classrooms 28 & 34

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	10	DEC-04

Event: Install rubber feet to desks and chairs.**Concern:**


Classrooms are the first places showing holes in new carpet due to metal feet on chairs and desks.

Recommendation:

Fix holes that have appeared in carpet. In all areas carpeted it is necessary to use chairs and desks that increase the longevity of the flooring. Existing chairs and desks can also have rubber pads or covers added to their metal feet.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Preventative Maintenance	2005	\$1,080	Low

Updated: February 18 2005

**C3020.11 Floor Painting**

1954 building- Concrete floor in boiler room and in boys & girls corridors.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

C3030.03 Plaster Ceiling Finishes*

1954 building- Classrooms and hallways

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	50	DEC-04

Event: Install drop ceiling**Concern:**

Tiles stained, cracked and missing from ceilings.

Recommendation:

Install drop ceilings to all classrooms and hallways that have painted plaster 12x12 accoustical tile. (approx. 934m²)

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2006	\$37,800	Low

Updated: February 18 2005

**C3030.06 Acoustic Ceiling Treatment (Susp.T-Bar)***

1954 building- Classroom 25, 28 & 34, main office, staff room, gym and music room.

1956 building- All classrooms, library and office.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	25	DEC-04

S4 MECHANICAL

D2010.01 Water Closets*

2000 - Floor mounted, flush valve, open front seats. Some flush tank toilets in staff washrooms.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	30	DEC-04

D2010.02 Urinals*

1954 - Floor mounted urinals with automatic flush system.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
2 - Poor	0	30	DEC-04

Event: Replace urinals in main boys washroom.

Concern:

Urinals are stained and discolored.

Recommendation:

Replace 5 urinals with new wall hung units. Replace tile around urinals (Arch C3010.06)

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2006	\$16,200	Low

Updated: February 18 2005



D2010.03 Lavatories*

2000 - Stainless steel lavatories with mixing tee in handicapped accessible washroom.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	30	DEC-04

D2010.03 Lavatories*

1954 - Original vitreous china lavatories with separate hot and cold water taps.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
2 - Poor	0	30	DEC-04

Event: Replace lavatories.**Concern:**

Individual hot taps on lavatories means scalding is possible.
Parts for taps likely not available.

Recommendation:

Replace 12 lavatories with stainless steel lavatories with mixing tees in millwork.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2006	\$16,200	High

Updated: February 18 2005

**D2010.04 Sinks***

1980 - Stainless steel sinks in a few rooms, floor mounted plastic sink in janitor closet.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	DEC-04

D2010.04 Sinks*

1954, 1956 - Steel enameled sinks in individual classrooms with mixing tees and drinking fountain bubbler.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	DEC-04

Event: Replace sinks in classrooms.**Concern:**

Sinks in classrooms are stained, parts for trim unavailable.

Recommendation:

Replace 11 sinks with stainless steel ones and install new trim.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2007	\$10,800	Low

Updated: February 18 2005



D2010.08 Drinking Fountains / Coolers*

1954 - Vitreous china drinking fountain.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	DEC-04

Event: **Replace drinking fountains.**

Concern:

Drinking fountains stained and parts likely not available.

Recommendation:

Replace 4 drinking fountains with new fibreglass ones.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2006	\$4,320	Low

Updated: February 18 2005

D2020.01.01 Pipes and Tubes: Domestic Water*

1954,1956 - Copper piping.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	40	DEC-04

D2020.01.02 Valves: Domestic Water

1954 - Gate valves on main water line into building.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

D2020.01.03 Piping Specialties (Backflow Preventors)*

No backflow preventor on main water line. Backflow preventor on steam boiler makeup feed. Vacuum breakers on non-freeze hose bibbs outside building.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

D2020.02.02 Plumbing Pumps: Domestic Water*

Recirculation pump on domestic hot water.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	20	DEC-04

D2020.02.06 Domestic Water Heaters*

1954 - Mor-Flo domestic water heater with 41 kW input.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
2 - Poor	0	20	DEC-04

Event: Replace hot water heater.

Concern:

Hot water tank is energy inefficient.

Recommendation:

Replace hot water heater.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2006	\$1,620	Low

Updated: February 18 2005

D2020.03 Water Supply Insulation*: Domestic

1980 - Some of the water piping is insulated.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

D2030.01 Waste and Vent Piping*

1954, 1956 - Cast iron hub and spigot. Some new abs where new water closets have been installed.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	DEC-04

D2040.01 Rain Water Drainage Piping Systems*

1954, 1956 - Cast iron.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	DEC-04

D2040.02.04 Roof Drains*

1954, 1956 - Gravel guards on roof drains.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	40	DEC-04

D3010.02 Gas Supply Systems*

Gas distribution piping to boilers, domestic water heater, and portable furnaces.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	DEC-04

D3020.01.01 Heating Boilers & Accessories: Steam*

1949 - Two Reliance Welding Works cast iron steam boilers. Converted from coal fired to natural gas fired. 53.61 m² heating surface.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
2 - Poor	0	35	DEC-04

Event: Upgrade to hot water boiler system.

Concern:

Existing steam boilers are inefficient. Components of the steam system are rusting and degraded.

Recommendation:

Upgrade steam system to hot water boiler system. Replace boilers, install new hot water coils for ventilations systems, install new fin radiation in classrooms and at entrances. Install new chimney and combustion air. This should be completed as part of a school modernization.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Energy Efficiency Upgrade	2007	\$162,000	Low

Updated: February 18 2005

**D3020.01.03 Chimneys (&Comb. Air) : Steam Boilers***

1954 - Metal chimney from boilers connects into ceramic chimney up to roof. (See Heating Boilers for action)

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
2 - Poor	0	0	DEC-04

D3020.01.04 Water Treatment: Steam Boilers*

1954 - Condensate receiver with chemical pot feeder.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
2 - Poor	0	0	DEC-04

D3040.01.01 Air Handling Units: Air Distribution*

1954 - One central fan supplies air to all rooms from underground trench. Includes low efficiency filters and steam heating coil. Motorized fresh and return dampers.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
2 - Poor	0	30	DEC-04

Event: Upgrade school ventilation system.

Concern:

The air handling system provides insufficient ventilation for classrooms. Large amounts of dust accumulation in building due to poor filtering.

Recommendation:

Provide new central air handling unit for school complete with high efficiency filters, hot water heating coils, mixing sections. Provide new ducting and air diffusers for each room. Should be completed as part of a school modernization.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Indoor Air Quality Upgrade	2007	\$172,800	Medium

Updated: February 18 2005

**D3040.01.04 Ducts: Air Distribution***

1954 - Galvanized ducts supply air to each classroom. (See Air Handling Units for event.)

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	50	DEC-04

D3040.01.07 Air Outlets & Inlets: Air Distribution*

1954, 1956 - Cone diffusers supply into rooms. Sidewall grills for return.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	DEC-04

D3040.02 Steam Distribution Systems: Piping/Pumps*

1954 - Steam distribution piping steel. Steam traps upgraded over the years. (See steam boilers for event)

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	DEC-04

D3040.04.01 Fans*: Exhaust

1954 - Two downblast fans on roof of building, one for washroom exhaust, one for general exhaust.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	DEC-04

D3040.04.03 Ducts*: Exhaust

Low velocity metal ducts.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	DEC-04

D3040.04.05 Air Outlets and Inlets*: Exhaust

1954 - Eggcrate style grills for washroom exhaust.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

D3050.05.03 Finned Tube Radiation*

1954, 1956 - Fin tube radiation in all classrooms and at entrances. (See steam boilers for event.)

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	DEC-04

D3060.02.02 Pneumatic Controls*

1980 - Pneumatic compressor for steam control valves and dampers in air handling unit.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	40	DEC-04

Event: Upgrade control system.**Concern:**

Based on major heating and ventilation system changes recommended, controls should be upgraded to work with the new equipment installed.

Recommendation:

Installed new control system, including front end BMCS.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2007	\$75,600	Low

Updated: February 18 2005

D4030.01 Fire Extinguisher, Cabinets and Accessories*

Chemical fire extinguishers mounted on wall.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	30	DEC-04

S5 ELECTRICAL**D5010.01 Main Electrical Transformers***

Underground service from transformer located on south side of property. Original installation

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	40	DEC-04

D5010.03 Main Electrical Switchboards (Main Distribution)*

Original Square D Main Distribution Panel c/w 16 spaces. Four spares are available. First service is 350 Amp, single phase, 120/240 volt. Second service is 50 Amp, three phase, 240 volt.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	40	DEC-04

Event: **Original Equipment. First service is 350 Amp, single phase, 120/240 volt. Second service is 50 Amp, three phase, 240 volt.**

Concern:

Equipment has passed its expected life expectancy. Breakers may fail in case of an electrical fault. Spare parts are no longer available.

Recommendation:

Replace existing switchgear with new equipment. Consolidate the service in new 400 Amp 120/208 volt three phase service.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2005	\$48,600	High

Updated: February 18 2005

Event: **Original Service of 350 Amp single phase and 50 Amp three phase.**

Concern:

Current service size may not meet future electrical needs of the school. Switch gear equipment is recommended for upgrade due to age.

Recommendation:

Conduct load analysis of existing electrical and mechanical loads and potential future loads to determine adequate service size.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Study	2005	\$5,400	High

Updated: February 18 2005

D5010.05 Electrical Branch Circuit Panelboards (Secondary Distribution)*

1997 upgraded- Federal Pioneer Panels. Spare capacity available.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	25	DEC-04

D5010.07 Motor Control Centers (Motor Control)*

Individual Motor controls.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

D5010.07.02 Motor Starters and Accessories*

Individual motor starters manufactured by Square D and other models.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

D5020.01 Electrical Branch Wiring*

Wiring is original, installed in conduit.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	DEC-04

D5020.02 Interior Lighting

Wrap Around Surface and Recessed 2x4 fluorescent light fixtures c/w magnatic ballasts and T12 lamps. Acrylic lenses shield the lamps.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	35	DEC-04

Event: Classrooms and Hallways use fluorescent light fixtures c/w T12 lamps and Acrylic lenses and magnatic ballasts.

Concern:

Existing light fixtures are at end of life. Acrylic lenses are yellowing in some areas. Existing light fixtures performance does not comply with IES recommendations for classrooms with VDT monitors. T12 technology c/w magnatic ballasts uses 75% more energy for a 2x4 light fixture c/w 4 lamps vs new 2x4 T5 light fixture c/w two lamps. Light levels in various areas are above new recommended light levels by IES for classroom environments.

Recommendation:

Upgrade lighting system in school with new light fixtures that utilize T5 lamps and electronic ballasts. Direct and indirect lighting should be utilized in classrooms with computers. Layout of the new lighting system shall be redesigned to comply with new layout of classrooms and computers. Payback will be within 5 year cycle.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Energy Efficiency Upgrade	2005	\$246,240	Medium

Updated: February 18 2005

D5020.02.01 Lighting Accessories (Lighting Controls)*

Original Line voltage switching used in classrooms. Keyed switches are used in hallways and bathrooms. Individual dimming controls used in stage lighting.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	DEC-04

Event: Line voltage toggle switches are used to turn lights off. Keyed switches are used in common areas.

Concern:

Lights are left on without occupants in the area. Electrical energy is wasted. No master sweep to turn lights on or off at end or start of working hours.

Recommendation:

Install new Low Voltage relay system c/w programmable time clock for the various areas of the school c/w motion sensors in classrooms and washrooms.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Energy Efficiency Upgrade	2005	\$23,760	Low

Updated: February 18 2005

D5020.02.03 Emergency Lighting*

Wall mounted battery packs c/w remote heads located through the school. Exit signs, c/w LED lamps located at required exits.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	DEC-04

D5020.03 Exterior Building Lighting

Original HID and Incandescent light fixtures located around the exterior of the school.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	25	DEC-04

D5030.01 Detection and Alarm Fire Alarm*

1987 Installed- Simplex 2001 Fire Alarm Control Panel. Inspected on annual basis.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	25	DEC-04

Event: **1987 installed- Fire Alarm Control panel Simplex 2001. Hard wired c/w 12 zones.**

Concern:

Fire Alarm Control Panel has life span of 20 years. Approaching end of life cycle. Panel does not have capacity to handle new strobes.

Recommendation:

Replace control panel with new Fire alarm control panel.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2012	\$27,000	Low

Updated: February 18 2005

Event: **Current fire alarm Bells do not have Strobes for the visual annunciation of the fire alarm signal in all areas.**

Concern:

Hearing impaired occupants may be exposed to risk by not having proper notification of presense of an fire alarm signal.

Recommendation:

Install new strobes with current location of all bells.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Code Upgrade	2005	\$5,400	High

Updated: February 18 2005

D5030.02.02 Intrusion Detection*

Motion detectors are located in common areas and where windows are located. Magnum Alert Security System.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	25	DEC-04

D5030.03 Clock and Program Systems*

Master Controller used for Bells only. Individual battery operated clocks are located in classrooms.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	25	DEC-04

D5030.04.01 Telephone Systems*

Norsta Meridian telephone system c/w four outside lines and one fax line. Telephone c/w intercom feature.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	25	DEC-04

D5030.04.02 Paging Systems*

2003 installed -New Paging, Music System by Bogen Muticom 2000.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	25	DEC-04

D5030.04.05 Local Area Network Systems*

1998 installed - Cat5 data cabling, wired in conduit and free air and is located through out the school. Drops are in surface mounted conduit. Supernet is installed in school.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

D5030.05 Public Address and Music Systems*

2003 installed - Paging system and music system is in working order. Manufactured by Bogen Muticom 2000.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

D5030.06 Television Systems*

Cable TV is located in every classroom.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

D5090.01 Uninterruptible Power Supply Systems*

Individual Stand alone UPS Backup APC 1000 installed in Server Room. Emergency Battery Packs installed through the school for emergency lighting.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	25	DEC-04

S6 EQUIPMENT, FURNISHINGS AND SPECIAL CONSTRUCTION**E1020.02 Library Equipment***

1956 building

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

E1020.03 Theater and Stage Equipment*

Lighting, curtains and painted backgrounds.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

E1090.02.03 Bins

East side of building are the city recycle and waste management bins.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

E1090.03 Food Service Equipment*

Countertop warmers.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	DEC-04

E1090.04 Residential Equipment*

1954 building- Staff kitchen has a deep freezer, fridge, water cooler, range, dishwasher, toaster and 5 microwaves.
 1956 building- Kitchen has 1 range and fridge.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

E1090.07 Athletic, Recreational, and Therapeutic Equipment*

1954 building- Gym- basket ball net, hockey equip, balls, nets and mats.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

E2010.02.05 Educational Facility Casework*

1954 and 1956 building- Classrooms

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
2 - Poor	0	0	DEC-04

Event: **Replace all countertops and casework that support integral sinks.**

Concern:

Vanities contain asbestos and supporting millwork for the sinks are old and worn.

Recommendation:

Replace all countertops and casework that support integral sinks. Co-ordinate with mechanical replacement of sinks D2010.04. Otherwise all other casework is old but well maintained. (11 sinks)

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2006	\$11,880	Medium

Updated: February 18 2005

E2010.02.07 Kitchen Casework*

1954 and 1956 buildings- Staff kitchen and school kitchen.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

E2010.02.08 Laboratory Casework*

1954 building- Science room- Minor maintenance to laminate counter top required.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

E2010.02.09 Library Casework*

1956 building- painted wood

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

E2010.03.01 Blinds*

1954 and 1956 building- Verticle blinds.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

E2010.03.06 Curtains and Drapes*

1954 building- Classrooms 28 and 34

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

E2020 Moveable Furnishings*

1954 building- Audience seating under stage

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

E2020.05 Moveable Interior Landscaping

1954 and 1956 building- In hallway, stage, in front of office and hallways.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	DEC-04

F1010.02.04 Portable and Mobile Buildings 211

1990 construction, signage designates as portable 211.

Arch: Wood framed construction on concrete pads. Envelope consists of metal cladding, 2 ply SBS roofing membrane and aluminum framed windows with wire mesh security grilles. Interior components include carpet and VCT flooring, metal frames & doors, acoustical drop ceilings with painted gypsumboard, painted millwork and chalkboards / whiteboards / tackboards.

Mech: Heating and ventilation provided by Palm-Aire furnace with 30.8 kW input and 23.4 kW output. Programmable digital thermostat for control. The furnace comes with an outside wall intake louvre for fresh air and supplies air along ductwork to grills in the millwork of the portable. The furnace cannot provide the required minimum fresh air required by ASHRAE 62.

Elec: Electrical service is fed from main building. T12 wrap around light fixtures c/w line voltage switching.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	DEC-04

Event: Install furnace and fresh air system for portable 211.

Concern:

Furnace incapable of supplying sufficient fresh air for portable.

Recommendation:

Install new furnace and fresh air system.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Indoor Air Quality Upgrade	2006	\$12,960	Low

Updated: February 18 2005

F1010.02.04 Portable and Mobile Buildings 216

1990 construction, signage designates as portable 216.

Arch: Wood framed construction on concrete pads. Envelope consists of metal cladding, 2 ply SBS roofing membrane and aluminum framed windows with wire mesh security grilles. Interior components include carpet and VCT flooring, metal frames & doors, acoustical drop ceilings with painted gypsumboard, painted millwork and chalkboards / whiteboards / tackboards. Appears to be an after school centre.

Mech: Heating and ventilation provided by Palm-Aire furnace with 30.8 kW input and 23.4 kW output. Programmable digital thermostat for control. The furnace comes with an outside wall intake louvre for fresh air and supplies air along ductwork to grills in the millwork of the portable. The furnace cannot provide the required minimum fresh air required by ASHRAE 62.

Elec: Electrical service is fed from main building. T12 wrap around light fixtures c/w line voltage switching.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	DEC-04

Event: **Install furnace and fresh air system for portable 216.**

Concern:

Furnace incapable of supplying sufficient fresh air for portable.

Recommendation:

Install new furnace and fresh air system.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Indoor Air Quality Upgrade	2006	\$12,960	Low

Updated: February 18 2005

F1010.02.04 Portable and Mobile Buildings 239

1991 construction, signage designates as portable 239.

Arch: Wood framed construction on concrete pads. Envelope consists of metal cladding, 2 ply SBS roofing membrane and aluminum framed windows with wire mesh security grilles. Interior components include carpet and VCT flooring, metal frames & doors, acoustical drop ceilings with painted gypsumboard, painted millwork and whiteboards / tackboards.

Mech: Heating and ventilation provided by Lennox furnace with 30.8 kW input and 23.4 kW output. Programmable digital thermostat for control. The furnace comes with an outside wall intake louvre for fresh air and supplies air along ductwork to grills in the millwork of the portable. The furnace has an economiser on the intake.

Elec: Electrical service is fed from main building. T12 wrap around light fixtures c/w line voltage switching.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	DEC-04

Event: Replace verticle blinds and carpet.**Concern:**

Carpet is stained and worn and the blinds are discolored and coming apart.

Recommendation:

Install new carpet and roll-down blinds.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2006	\$9,180	Low

Updated: February 18 2005



F1010.02.04 Portable and Mobile Buildings 242

1991 construction, signage designates as portable 242.

Arch: Wood framed construction on concrete pads. Envelope consists of metal cladding, 2 ply SBS roofing membrane and aluminum framed windows with wire mesh security grilles. Interior components include carpet and VCT flooring, metal frames & doors, acoustical drop ceilings with painted gypsumboard, painted millwork and whiteboards / tackboards.

Mech: Heating and ventilation provided by Lennox furnace with 29.3 kW input and 23.4 kW output. Programmable digital thermostat for control. The furnace comes with an outside wall intake louvre for fresh air and supplies air along ductwork to grills in the millwork of the portable. The furnace has an economiser on the intake.

Elec: Electrical service is fed from main building. T12 wrap around light fixtures c/w line voltage switching.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	DEC-04

Event: Add slip resistant material to exterior landing**Concern:**

Existing carpet is worn and has large holes in it and is causing a huge tripping hazard.

Recommendation:

Remove carpet on stair landing and replace with a slip material thin enough for door to pass.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2005	\$108	Medium

Updated: February 18 2005

**Event: Install new carpet and blinds****Concern:**


Carpet is stained and worn and the blinds are discolored and coming apart.

Recommendation:

Install new carpet and roll-down blinds.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2006	\$9,180	Low

Updated: February 18 2005



F2020.01 Asbestos*

1954 and 1956 buildings

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
2 - Poor	0	0	DEC-04

Event: Investigate extent of asbestos materials.**Concern:**

Materials in school are presumed to contain asbestos:

Hallways: painted wainscoting.

Gymnasium foyer: asbestos board

Classrooms: vanities.

Both buildings- asbestos ceiling tiles.

Recommendation:

Investigate asbestos containing materials from classrooms (replace vanities E2010.02.05 includes costing) and from gym foyer. Hallway area requires to be continually maintained and repaired if damage occurs to the painted surface.



<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Study	2005	\$2,160	Medium

Updated: February 18 2005

F2020.09 Other Hazardous Materials*

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

Facility Details**Building Name:** Prince Charles Elementary S**Address:****Location:** Edmonton**Building Id:** S3251**Gross Area (sq. m):** 0.00**Replacement Cost:** \$0**Construction Year:** 0**Evaluation Details****Evaluation Company:****Evaluation Date:****Evaluator Name:****Total Maintenance Events Next 5 years:****5 year Facility Condition Index (FCI):****0%****General Summary:**

Prince Charles is located on 127 street and 123 ave. The staff parking is located on the eastside of the school and other drop off areas are located in front of the school on 127street and on the north side. Field and play areas are large and have basketball hoops, baseball diamonds and soccer posts to play with. Winter conditions were present at time of evaluation so further inspection of grasses and tarmac area may be needed, no problems noted. Conflicts between onsite vehicle traffic and children is apparent and a new staff parking lot should be constructed on the southside with appropriate fencing and control equipment. Otherwise site is in good condition.

Mechanical: The storm and sanitary sewers connect to municipal systems. Gas and water lines connect to utility mains. This is a fire hydrant near the school.

Electrical: Car receptacles are in good working order. Pad mounted transformer is in good condition. Exterior area lighting is adequately covered.

Structural Summary:**Envelope Summary:****Interior Summary:****Mechanical Summary:****Electrical Summary:****Rating Guide**

Condition Rating	Performance
1 - Critical	Unsafe, high risk of injury or critical system failure.
2 - Poor	Does not meet requirements, has significant deficiencies. May have high operating/maintenance costs.
3 - Marginal	Meets minimum requirements, has significant deficiencies. May have above average operating maintenance costs.
4 - Acceptable	Meets present requirements, minor deficiencies. Average operating/maintenance costs.
5 - Good	Meets all present requirements. No deficiencies.
6 - Excellent	As new/state of the art, meets present and foreseeable requirements.

S7 SITE**G2010.02.02 Flexible Pavement Roadway (Asphalt)***

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	

G2010.05 Roadway Curbs and Gutters*

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	

G2020.02.01 Aggregate Parking Lots (Gravel)*

East side of 1954 building.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	

Event: Relocate and pave parking lot.**Concern:**

Currently staff parking is located on east side of school and has no separation between pedestrians and vehicles. Parking lot has 15 parking stalls allocated in a gravel lot with no guard rails or fencing. Visitor parking is on grass.

Recommendation:

Relocate parking lot to southside of building grade and pave. Size new parking lot for 28 regular stalls 2 handicaped ones.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Operating Efficiency Upgrade	2006	\$43,200	Low

Updated: February 18 2005



G2020.05 Parking Lot Curbs and Gutters*

Rating	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	

Event: **Install curbs and catch basin with construction of new parking lot.**

Concern:

With new parking lot to be relocated to the southside of school appropriate curbs and catch basin should be installed.

Recommendation:

Install curbs and catch basin to new paved parking lot, allow for appropriate curb cuts and ramp for barrier free access. Included is mechanical catch basin and trenching (\$10,000).

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Operating Efficiency Upgrade	2006	\$23,760	Low

Updated: February 18 2005

G2020.06.01 Traffic Barriers*

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	

Event: Install duplex receptacles.**Concern:**

Receptacles are needed for new parking lot for cars to plug in.

Recommendation:

Install electrical duplex receptacles c/w weatherproof covers and 2 dedicated circuits per receptacle:

15 duplex receptacles (\$50 each)

30 new dedicated circuits (\$2,000 -subject to wire lengths)

New 200 Amp, three phase 120/208 Volt panel, mounted in the parking lot c/w 42 spaces. (\$1,500)

New 200 Amp breaker inside the main electrical distribution of the building (\$500 plus feeder at \$750 for a total of \$1,250)

A new service from EPCOR with seperate metering (further analysis is required)

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Operating Efficiency Upgrade 2006		\$5,940	Low

Updated: February 18 2005

Event: Install posts and railings**Concern:**

New parking lot will require barriers

Recommendation:

Install metal posts and railings to incorporate car plug in receptacles.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Operating Efficiency Upgrade 2006		\$27,000	Low

Updated: February 18 2005

Event: Install staff parking lighting.**Concern:**

Security lighting for new staff parking.

Recommendation:

Install lighting for staff parking lot. Allow one pole mounted light fixture for each 8 cars. This would be 4 light posts at a cost of \$5,000 for each. Power for these fixtures would be from the new parking panel.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Operating Efficiency Upgrade 2006		\$21,600	Low

Updated: February 18 2005

G2020.06.03 Parking Lot Signs*

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	

Event: Install parking identification signs.**Concern:**

With new parking lot to be relocated to the southside of school appropriate signage should be installed.

Recommendation:

Install parking identification signs to designate staff parking stalls, visitor stalls and barrier free parking. Replace existing warning sign with new metal one.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Operating Efficiency Upgrade	2006	\$1,080	Low

Updated: February 18 2005

**G2020.06.04 Pavement Markings***

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	

Event: Paint parking lot pavement markings.**Concern:**

With new parking lot to be relocated to the southside of school appropriate painted markings should be installed.

Recommendation:

Install new parking lot lines and painted barrier free stalls.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Operating Efficiency Upgrade	2006	\$1,080	Low

Updated: February 18 2005

G2030.03 Pedestrian Unit Pavers*

Access to school from westside (front of school)

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	

G2030.06 Exterior Steps and Ramps*

1954 building- eastside

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	

Event: Install barrier free ramp.**Concern:**

No barrier free access to east side of building.

Recommendation:

Install barrier free ramp, incorporate with new stair construction.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Barrier Free Access Upgrade	2006	\$3,888	Medium

Updated: February 18 2005**Event: Replace cracked stairs.****Concern:**

Concrete stairs are cracked.

Recommendation:

Replace exterior stairs on boys side. (4 m²)

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Operating Efficiency Upgrade	2006	\$5,400	Low

Updated: February 18 2005**G2030.06.05 Metal Handrails and Railings**

East side and south side of school; required.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	

Event: Install appropriate handrails and railings.**Concern:**

1954 eastside and south side entrances require stair handrails.

Recommendation:

East side- Install two handrails on boys side of stairs and one handrail to girls entrance stairs. Coordinate with stair replacement. Install appropriate railings and curbs on new ramp construction as well.

South side- New exterior stairs and ramp require appropriate railings. Coordinate with south side entrance upgrade.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Code Upgrade	2006	\$5,400	Medium

Updated: February 18 2005

G2040.02 Fences and Gates*

Wire fences surround field area.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	

Event: Install fence**Concern:**

No separation between pedestrian traffic and vehicle traffic near east side playing field.

Recommendation:

Install fence along east side of back road, separating playing field from parking lot area. (match to existing fence along street)

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Operating Efficiency Upgrade	2006	\$2,160	Low

Updated: February 18 2005

**G2040.03 Athletic and Recreational Surfaces***

Winter conditions, no apparent problems.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	

G2040.05.04 Bicycle Racks

East side of school.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	

G2040.06 Exterior Signs*

1954 building- Sign mounted on building indicating school and date built (original) and another wood sign visible to 127 st.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	

G2040.08 Flagpoles*

1954 building- Metal flag pole mounted to roof.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	

G2050.04 Lawns and Grasses*

Winter conditions, no apparent problems.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	

G2050.05 Trees, Plants and Ground Covers*

Large trees and shrubs in front of school and surrounding field.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	

G3010.02 Site Domestic Water Distribution*

150 mm water line connected to City main.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	

G3010.03 Site Fire Protection Water Distribution*

One fire hydrant across street from school.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	

G3020.01 Sanitary Sewage Collection*

Two separate sanitary sewer lines connected to two different city mains, one for each of the 1954 and 1956 buildings.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	

G3030.01 Storm Water Collection*

Storm sewer line connected to city main.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	

G3060.01 Gas Distribution*

Gas line runs out to utility gas mains buried in street.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	

G4010.02 Electrical Power Distribution Lines*

Pad mounted transformer. Power lines main and secondary are buried underground. Not accessible.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	

G4010.04 Car Plugs-ins*

Weatherproof, rail mounted duplex receptacles are allocated as one duplex receptacle per each two stalls. Total of 16 energized stalls.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	

G4020.01 Area Lighting*

Parameter lighting is mounted to the side of the building.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	

S8 FUNCTIONAL ASSESSMENT

K1010 Site Location & Access

Building can be accessed on the west, north and south sides of the site. Staff parking and fire lane is located on the southside entrance from the street.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

K2010.01 Building Entrance/ Reception (location)

Located beside the main school entrance doors; was modernized in 1994.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	DEC-04

K2010.02 Major Corridors (Layout, Orientation)

Schools main hallway runs north to south with the schools main entrance in the middle on the west side.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	DEC-04

K4010.01 Barrier Free Route: Parking to Entrance

Westside of building and south entrance is at grade at present time. See K4010.03 for modification of south entrance.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
2 - Poor	0	0	DEC-04

K4010.02 Barrier Free Entrances

1954 building

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
2 - Poor	0	0	DEC-04

Event: Install power assist hardware to 2 exterior and interior doors.

Concern:

This school has no barrier free entrances with power assist doors.

Recommendation:

Front entrance (at grade) requires power assist hardware and west entrance that will soon have a barrier free ramp will require power assist hardware. (2 exterior doors and 2 interior vestibule doors) Require hardware on entrances so that they can open both exterior and interior entrance doors simultaneously. Install push button door openers on both sides (interior and exterior). (\$850 each for electrical hook up included.)

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Barrier Free Access Upgrade	2006	\$16,200	Medium

Updated: February 18 2005

K4010.03 Barrier Free Interior Circulation

1954 building

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
2 - Poor	0	0	DEC-04

Event: Construct new ramp.**Concern:**

Ramp on west side of school (main entrance) is not to code. Distance is too short between top landing and interior vestibule doors.

Recommendation:

Remove existing wood ramp and construct code compliant ramp on other side of same stairs (furthest from office doors; north side). It will be necessary to remove a portion of the stairs to construct new ramp. Also possible to add a wheelchair lift instead of constructing ramp; install to north side of main stairs (away from office).



<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Barrier Free Access Upgrade	2006	\$12,960	Medium


Updated: February 18 2005

Event: Modify southside foyer.**Concern:**

The southside entrance and foyer area is not able to allow for easy access to and from the building for barrier free individuals. Storefront frames are too narrow, no power assist door hardware and vestibule area is too small to install a code compliant ramp.

Recommendation:

Modify existing vestibule area to allow for barrier free traffic. Raise vestibule floor to the same height of the main building floor of school and install the new exterior storefront to the new height. (same as interior storefront). This will allow for barrier free travel within the interior vestibule to be void of ramps and lack of space. Replace interior and exterior storefronts to allow for 2 doors not 3 small doors (28" clear opening with 3) modify walls to allow for new storefronts. Install power assist doors on one exterior and one interior door (to open simultaneously) Install exterior stairs and ramp to now suit this newly renovated entrance.



<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Barrier Free Access Upgrade	2006	\$64,800	Medium

Updated: February 18 2005

K4010.04 Barrier Free Washrooms

1954 building- Boys and girls washrooms.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
2 - Poor	0	0	DEC-04

Event: **Replace girls doors and install power assist door hardware.**

Concern:


The girls washroom has double doors (in & out doors) that are too narrow for barrier free access.

The boys washroom has upgraded their doors from in and out doors to a single regular sized door but requires power assist hardware.

Recommendation:

Replace the girls washroom door to a single door large enough for barrier free access.

Install power assist hardware to both the boys and girls washroom doors. (1 for each washroom) (electrical service to doors is \$850 each)



<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Barrier Free Access Upgrade	2006	\$16,200	Medium

Updated: February 18 2005