

RECAPP Facility Evaluation Report

Rocky View Sch Div #41



Springbank Community High School

B2375A
Springbank

Facility Details

Building Name: Springbank Community High
Address: 32226 Springback Road
Location: Springbank

Building Id: B2375A
Gross Area (sq. m): 7,882.10
Replacement Cost: \$13,794,295
Construction Year: 0

Evaluation Details

Evaluation Company: Quinn Young Architects Ltd.
Evaluation Date: July 14 2006
Evaluator Name: Barry McCallum

Total Maintenance Events Next 5 years: **\$1,040,200**
5 year Facility Condition Index (FCI): **7.54%**

General Summary:

The original 2,495 sq.m. one storey building was constructed in 1975 and was attached on the south side to an existing community arena. In 1980 two small additions comprising of 521.6 sq.m. were added to provide CTS and Home Economics spaces. In 1994 major new additions and a modernization was done to provide permanent classroom space with reuse of some of the portables then on site. The new addition comprised of 3317.1 sq.m. of library, science, classrooms and physical education space. Four 1990 portables were relocated & new connecting link/corridor was added (total portable & link area = 499.7 sq.m.) at this time. In 1999 four more portables and corridor was added with an additional area of 367.4 sq.m.. In 2001 two additional portables were relocated to the site for another 188.5 sq.m.. The total area of the current school is +/- 7882.10 sq.m. (excluding the mezzanine space)

Structural Summary:

Strip footing and cast in place foundation wall with concrete slab on grade and a combination of load bearing concrete block walls and steel columns supporting steel beam or OWSJ supporting a metal roof deck.
 There is a small mezzanine area adjacent to the main gymnasium constructed of a reinforced concrete slab
 The structure is in good condition.

Envelope Summary:

Exterior is a combination of giant brick and brick/block veneer with metal fascias. Most of the existing roof was replaced in 1996 with a two ply SBS roof system.. Aluminum framed windows/doors, double glazed, Standing seamed roof over library and corridor.
 The envelope is in good condition.

Interior Summary:

Interior partition finishes consist of painted drywall and concrete block, solid core wood doors, some with glazing panels, flooring is a mixture VCT and carpet, ceilings are mainly T-Bar with a minor amount of drywall.

Overall the interior is in acceptable condition.

Mechanical Summary:

Site services consist of: Six inch fire and domestic water supply, 150 drain to sewage lift station and to lagoon, storm drainage system to ditch and pressure gas from utility to gas meter room.
 The plumbing fixtures, drainage and distribution system is in good condition.
 Boilers provide heat for fan coil units, radiation fins and heat exchanger.
 Cooling tower provides condenser water cooling for heat pumps.
 Condenser water storage tank is provided for energy storage.
 Heat pumps supplied for various zones provide heat or cooling for the respective zones.
 Some ducting and heat pump modification and addition required for computer repair room and LAN room.
 The systems are in good condition.

Electrical Summary:

The facility is fed by a 500 KVA pad mounted transformer with a 1600 amp Westinghouse brake 120/208V, 3 phase, 4 wire service. Branch circuit panels are located throughout the building. Lighting is generally T-8 florescent with HP sodium in the gym. Exterior lighting is a mix of HP sodium and metal halide. Emergency/ exterior lighting is florescent through a backup Onan generator. The fire alarm system is a simplex 4100 which meets current standards. Intrusion detection is by motion detectors and 10 video cameras. (3 cameras do telecasts/announcements)

The electrical system is in good condition.

Rating Guide	
Condition Rating	Performance
1 - Critical	Unsafe, high risk of injury or critical system failure.
2 - Poor	Does not meet requirements, has significant deficiencies. May have high operating/maintenance costs.
3 - Marginal	Meets minimum requirements, has significant deficiencies. May have above average operating maintenance costs.
4 - Acceptable	Meets present requirements, minor deficiencies. Average operating/maintenance costs.
5 - Good	Meets all present requirements. No deficiencies.
6 - Excellent	As new/state of the art, meets present and foreseeable requirements.

S1 STRUCTURAL

A1010 Standard Foundations*

1975: Reinforced concrete foundation walls on reinforced concrete strip footing approximately 1220 below grade.
1994: Reinforced grade beams on concrete piles or concrete pedestals and footings.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	100	MAR-07

A1030 Slab on Grade*

1975: 102mm reinforced concrete slab on grade. Slab depressed at Gymnasium floor and at vestibules where ceramic tile on mortar bed is installed. Slab thickening at block walls
1994: 200mm reinforced concrete slab on grade. Slab thickening at interior block walls and staircases. Dropped slab at library reading room

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	100	MAR-07

B1010.01 Floor Structural Frame*(Building Frame)

Mezzanine slab supported by block and poured concrete wall.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	100	MAR-07

B1010.02 Structural Interior Walls Supporting Floors (or Roof)*

Load bearing concrete block walls throughout (2 - steel columns at storage /music room)

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	100	MAR-07

B1010.05 Mezzanine Construction*

200 and 250mm deep reinforced concrete slabs at new gymnasium

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	80	MAR-07

B1010.09 Floor Construction Fireproofing*

200 and 250mm reinforced concrete slabs exceed the 1hr FRR required

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	50	MAR-07

B1010.10 Floor Construction Firestopping*

Ducts through mezzanine floor are dampered. Communication riser at storage room not protected

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	1994	50	MAR-07

Event: Firestop opening in floor slab**Concern:**

No Fire stopping has been installed where communication cables have been installed between the main floor and mezzanine storage rooms

Recommendation:

Install appropriate fire stop or enclose cable riser with protected enclosure and access panel.

Consequences of Deferral:

No smoke or fire separation between mezzanine and main floor

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Code Repair	2007	\$1,000	High

Updated: MAR-07

B1020.01 Roof Structural Frame*

1975: Metal pan supported on OWSJ's

1994: Metal pan supported on a combination of OWSJ's and steel beams

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	100	MAR-07

B1020.04 Canopies*

1975: Recessed entrance areas are formed by roof structural frame above

1994: Steel columns and steel structural frame at main entrance

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	MAR-07

S2 ENVELOPE**B2010.01.02.01 Brick Masonry: Ext. Wall Skin***

1975: 102mm Brick veneer
 1994: 100mm Masonry veneer

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	75	MAR-07

Event: Replace damaged giant brick**Concern:**

Giant Brick veneer damaged around door and below window on east elevation

Recommendation:

Remove damaged brick and install new brick veneer

Consequences of Deferral:

Water penetration into wall cavity and damage to interior surfaces.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2007	\$2,000	Unassigned

Updated: MAR-07

B2010.01.06.03 Metal Siding**

Painted metal fascia at connecting link to portables.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	40	MAR-07

Event: Remove damaged fasica and reclad**Concern:**

Metal Cladding on upper fascia at connecting link to portables.
 Has come loose exposing the inner wall to the exterior

Recommendation:

Remove damaged cladding, investigate and repair any damage to substrate, replace upper cladding section

Consequences of Deferral:

Interior wall damage due to water penetration

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2007	\$2,000	Unassigned

Updated: MAR-07

B2010.01.09 Expansion Control: Exterior Wall Skin*

1975, 1980 & 1994: Typical control joints at windows and between large brick panels on exterior wall

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1975	75	MAR-07

B2010.01.11 Joint Sealers (caulking): Ext. Wall**

Caulking around windows and sill flashings, typical

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	1994	20	MAR-07

Event: Replace caulking at window sills**Concern:**

Caulking between sill flashing and window frame is cracked, separating or missing on a number of windows

Recommendation:

Inspect all caulking around exterior windows and replace as required.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2007	\$1,500	High

Updated: MAR-07**B2010.02.03 Masonry Units: Ext. Wall Const.***

1975: 204 brick cavity wall

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1975	100	MAR-07

B2010.03 Exterior Wall Vapor Retarders, Air Barriers, and Insulation*

1975: 25mm Rigid insulation and vapour barrier towards interior wall face

1994: 50mm Rigid insulation over air/vapour barrier membrane towards exterior wall face

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1975	30	MAR-07

B2010.06 Exterior Louvers, Grilles, and Screens*

Painted Metal wall louvers

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	30	MAR-07

B2010.09 Exterior Soffits*

Prefinished metal panels over z-girts and 13mm gypsum board on suspended carrying channels

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	30	MAR-07

B2020.01.01.02 Aluminum Windows (Glass & Frame)**

Double glazed sealed units in Duranar/Duracron coated exterior finish and clear anodized interior finish

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	1994	40	MAR-07

Event: Replace latch mechanisms and seals**Concern:**

Aluminum levers and latchsets are bent and broken on 10 to 15 windows. Rubber seals are loose on at least three windows

Recommendation:

Replace broken latches/levers and install new rubber seals in windows where required

Consequences of Deferral:

Some security risk if windows are not latched properly.
Energy loss due to seals in windows

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2007	\$7,000	Unassigned

Updated: MAR-07

B2020.02.01 Aluminum-Framed Storefronts**

Double glazed sealed units in Duracron/Duranar aluminum frames @ main entrance vestibule

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	40	MAR-07

Event: Replace door**Concern:**

Door is dented near lock assembly (possibly from attempted break-in)

Recommendation:

Investigate whether damage affects hardware or door operation.
Replace door if required.

Consequences of Deferral:

Appearance and security

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Preventative Maintenance	2009	\$1,500	Medium

Updated: MAR-07

B3010.01 Deck Vapor Retarder and Insulation*

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	25	MAR-07

B3010.04.04 Modified Bituminous Membrane Roofing (SBS)**

Most of BUR roof system was replaced in 1996 with a 2-ply SBS roofing system. Roofing Report completed in 2000

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	1996	25	MAR-07

Event: **Repair bagging, wrinkles, membrane flashings, etc.**

Concern:

Severe Bagging on upper gym roof, wrinkles evident in cap sheet, Debris on roof (loose nails), water ponds in some locations.

Recommendation:

Cut and repair bagged membrane, Remove debris to prevent punctures, repair wrinkles and modify slopes where ponding occurs.

.Replace missing splashpads at bottom of downspouts at roof.

Consequences of Deferral:

Premature failure where debris is located or where repairs are required

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2007	\$12,000	High

Updated: MAR-07

B3010.07 Sheet Metal Roofing**

Prefinished standing seam metal roof over entry and corridors

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	40	MAR-07

B3010.08 Flashing and Sheet Metal

Flashings around windows and at parapets

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	1994	30	MAR-07

Event: Repair flashings at clerestorey window**Concern:**

Flashings are loose and missing at sill of clerestorey windows

Recommendation:

Replace missing and adjust loose flashings

Consequences of Deferral:

Water penetration into wall cavity

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2007	\$2,000	High

Updated: MAR-07**B3010.08.02 Metal Gutters and Downspouts****

Internal roof drains in most roof areas with scuppers and downspouts between roof surfaces

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	30	MAR-07

Event: Repair or replace scuppers and downspouts**Concern:**

4 - downspouts and scuppers require repairs or replacement

Recommendation:

Replace or repair scuppers and downspouts

Consequences of Deferral:

Poor drainage and damage at wall locations

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Preventative Maintenance	2007	\$1,500	Medium

Updated: MAR-07

B3020.01 Skylights**

Acrylic barrel vault skylight in anodized aluminum frame

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	1994	20	MAR-07

Event: Replace Acrylic skylight and finish curb**Concern:**

Acrylic skylight has been damaged due to vandalism. The surface has been cleaned to remove the graffiti but the surface is now badly etched.

The top of the curb at the skylight has never been finished and moisture damage is evident (probably from condensation in cold weather)

Recommendation:

Replace acrylic, finish top of curb and install new seal/flashing.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2008	\$2,500	High

Updated: MAR-07

B3020.02 Other Roofing Openings (Hatch,Vent, etc)*

Metal access hatch

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	25	MAR-07

S3 INTERIOR**C1010.01 Interior Fixed Partitions***

A combination of concrete block walls and drywall partitions.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1975	50	MAR-07

Event: Repair drywall and repaint**Concern:**

Drywall is scratched and marred on exterior wall in Rooms 143 & 144. Hole in drywall in Room 140 & 123

Recommendation:

Patch & repair wall and repaint entire wall to nearest break/corner

Consequences of Deferral:

Additional damage

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2007	\$1,500	High

Updated: MAR-07

C1010.03 Interior Operable Folding Panel Partitions**

1975: Folding wood partitions to separate stage, ancillary and lounges spaces
 1994: Folding Moderco Partition at Science labs Room # 147 & 148

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	MAR-07

Event: Adjust junction between stage and folding partition and finish opening**Concern:**

Folding partition has been pulled back from opening at stage.
 The opening is unfinished

Recommendation:

Redesign so that folding partition is useable to isolate stage
 and finish opening with suitable trim.

Consequences of Deferral:

Stage remains accessible limiting use of room for other
 purposes.
 Rough block opening poses risk of injury.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2007	\$3,000	High

Updated: MAR-07

Event: Replace folding panel partitions

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2010	\$40,000	Low

Updated: MAR-07

C1010.05 Interior Windows*

A combination of aluminum and painted pressed steel frames with wired or tempered glazing

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	40	MAR-07

C1010.07 Interior Partition Firestopping*

1975: All mechanical rooms concrete block & drywall walls are rated and penetrations are insulated and caulked
 1994: no fire separation/firestopping required at janitor rooms (building is sprinklered)
 - storage rooms are isolated and have rated painted gypsum board ceilings
 - 2 hour fire walls where portables are attached to Fire Compartment A (permanent school)

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	50	MAR-07

C1020.01 Interior Swinging Doors**

A combination of clear stained solid core birch doors some with half glazed or vision panels
 Full lite birch doors into staff workroom and administration areas at main entrance
 Most wood doors were replaced in 1994 modernization

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	40	MAR-07

C1020.03 Interior Fire Doors*

Painted metal doors with closure, panic bars and hold open devices in fire walls

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	1994	50	MAR-07

Event: Replace Dutch Door at Kitchen**Concern:**

No rated fire door to kitchen.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Code Repair	2007	\$1,000	High

Updated: MAR-07

C1030.01 Visual Display Boards**

1994: Tackboards and whiteboards throughout

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	20	MAR-07

Event: Replace 5 damaged tackboards**Concern:**

Damaged vinyl surface to a few tackboards

Recommendation:

Replace with new tackboard

Consequences of Deferral:

Further damage as students peel damaged vinyl surface

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2007	\$1,000	High

Updated: MAR-07

C1030.02 Fabricated Compartments(Toilets/Showers)**

1975: Painted metal toilet compartments (original)

1994: New and Modernized painted metal toilet compartments

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	MAR-07

Event: Replace original toilet compartments

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2010	\$15,000	Low

Updated: MAR-07**C1030.08 Interior Identifying Devices***

Lamacoid signage at most doors. Directional signage is minimal

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	1994	20	MAR-07

Event: Install additional directional signage**Concern:**

Limited directional signage as there are 5 sub-corridors off the main corridor

Recommendation:

Add directional signage to assist with directions to major spaces (library, gymnasium, drama, music, etc.)

Consequences of Deferral:

New students and visitors get lost and need to ask for assistance.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2008	\$2,000	Medium

Updated: MAR-07

C1030.10 Lockers**

Painted metal lockers.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	30	MAR-07

Event: Repal lockers**Concern:**

Some locker doors showing minor dents and twists due to student abuse

Recommendation:

Monitor and replace when damage becomes significant

Consequences of Deferral:

Inability to use lockers

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2008	\$2,000	Medium

Updated: MAR-07**C1030.12 Storage Shelving***A combination of metal and birch shelving in janitor and storage rooms
Clear birch storage cabinets in Art room

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	20	MAR-07

C1030.14 Toilet, Bath, and Laundry Accessories*

Soap dispensers, Mirrors, Pare Towel dispensers, Toilet paper holders,Towel/Robe hooks, Shower curtains in locker rooms, typical

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	20	MAR-07

C1030.17 Other Fittings*

Welded hooks with rubber covers in Locker rooms

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	10	MAR-07

C2010 Stair Construction*

Concrete staircase to mezzanine

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	100	MAR-07

C2020.05 Resilient Stair Finishes**

Rubber treads and riser @ mezzanine

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	1994	20	MAR-07

Event: Replace Nosings and risers**Concern:**

Nosings damaged in two locations riser is missing on west exit

Recommendation:

Inspect all nosings and replace damaged treads. Replace missing riser

Consequences of Deferral:

Potential tripping hazard if further deterioration occurs

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2007	\$1,000	Unassigned

Updated: MAR-07**C2020.08 Stair Railings and Balustrades***

Painted hollow metal tubing handrails with painted HSS guard rails with horizontal pickets @ 800 o.c.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	50	MAR-07

C2030.01 Ramp Construction*

1994: 38 X 235 wood joists @ 400 o.c. supported on grade beam and 400mm diameter concrete piles

2000: wood ramp to access stage in ancillary classroom #117

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	100	MAR-07

C2030.02 Ramp Finishes*

Altro 20 walkway (slip resistant sheet vinyl) flooring on ramp to Drama room stage

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	2000	0	MAR-07

C2030.03 Ramp Railings*

1994: Painted metal wall railings

2000: painted metal railing on wood ramp to stage

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	MAR-07

C3010.04 Gypsum Board Wall Finishes*

GWB on

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	60	MAR-07

C3010.06 Tile Wall Finishes**

102mmX102mm ceramic wall tiles behind urinals in original 1975 washrooms

102mmX102mm ceramic wall tiles in locker rooms, PE instructor washrooms and modernized 1994 washrooms to +/- 1800 AFF

102mmX102mm ceramic wall tiles in 1994 shower areas to u/s of ceiling

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	40	MAR-07

C3010.09 Acoustical Wall Treatment**

Cork mounted on upper walls of old gym (now Art room, Special Education and Ancillary space)
Minimal acoustical panels in music room and low ceiling.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	1994	20	MAR-07

Event: Program Functional Upgrade**Concern:**

Poor quality acoustics in Gym and 4 special purpose rooms.

Recommendation:

Implement the results of the study to improve acoustics.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Program Functional Upgrade	2009	\$20,000	Unassigned

Updated: MAR-07

Event: Review acoustics and make recommendations to improve**Concern:**

Acoustical and sound control does not appear to be addressed with the current use of rooms.

Poor quality acoustics and sound control in music area should be reviewed

Recommendation:

Review current acoustical performance of the Main gymnasium, and Rooms #120, 107, 116 and 117.

Coordinate review with 2007 modernization study

Consequences of Deferral:

Inability to meet basic acoustical requirements recommended by Alberta Infrastructure

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Study	2007	\$3,000	High

Updated: MAR-07

C3010.11 Interior Wall Painting**

Painted concrete block and drywall partitions throughout

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	10	MAR-07

Event: Repaint walls

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2010	\$75,000	Low

Updated: MAR-07

C3020.01.02 Paint Concrete Floor Finishes**

Mechanical rooms
Custodial room 135

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	1994	10	MAR-07

Event: Repair thinset topping and repaint floors**Concern:**

Thinset topping in #122 has lifted exposing concrete sub-surface.

Paint finish is marred and scratched in all mechanical rooms

Recommendation:

Repair topping and repaint all mechanical room floors with new epoxy coating.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2009	\$10,000	High

Updated: MAR-07

C3020.02 Tile Floor Finishes**

1975: 25mmx25mm ceramic tiles and 102mmx102mm tile base in washrooms 104, 106, 135 and 136

1994: 200mmx200mm porcelain tiles and 100mmx200mm tile base in office washrooms, locker rooms, at vestibule entrances

1994: 50mmx50mm tiles and 100mmx200mm tile base in shower stalls

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	MAR-07

C3020.04 Wood Flooring**

Sprung hardwood strip floor in gymnasium. Floor was covered with protective coverings at time of inspection

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	30	MAR-07

C3020.07 Resilient Flooring**

VCT flooring throughout classrooms in 1975 corridors and in staff washrooms
VCT in custodial room 108

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	20	MAR-07

Event: Replace flooring in 108**Concern:**

VCT tiles are lifting around slop sink in room 108.
VCT tile is missing at edge of fumehood in room 155.
VCT floor at main corridor shows signs of cracking and is uneven in some locations. Previous report indicates that some slab movement occurred at the main entrance

Recommendation:

Remove VCT tiles in custodial room #108 and install epoxy floor finish

Install new VCT tile at fumehood.

Replace cracked tile at main entrance (may require some concrete removal and thin-set to restore and level floor)

Consequences of Deferral:

Concrete floor exposed to cleaning chemicals and tiles in room will continue to lift

Chemical spill at fumehood cannot be easily contained or cleaned.

Floor at main corridor becomes difficult to clean and maintain

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2007	\$3,000	Unassigned

Updated: MAR-07

C3020.08 Carpet Flooring**

Low level loop Antron nylon carpet in rooms # 107, 120, 137, 138, 141, 142, 143, 144, 145, 146, 147,165 , library and administration offices and staff work areas

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	15	MAR-07

Event: Replace flooring with sheet vinyl or carpet

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2010	\$70,000	Low

Updated: MAR-07

C3020.09 Access Flooring**

In slab raceways have been installed in the computer lab locations with floor access junction boxes

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	25	MAR-07

Event: Replace damaged cover plates**Concern:**

Aluminum cover plates are cracked

Recommendation:

Replace +/- 7 metal cover plates

Consequences of Deferral:

Carpet edge will be exposed at junction box and may fray.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2007	\$1,000	High

Updated: MAR-07

C3020.11 Floor Painting

Typical line painting in gymnasium (not reviewed as it was covered at time of inspection)

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	2000	5	MAR-07

Event: Repaint court and line markings

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2010	\$5,000	Low

Updated: MAR-07

C3030.04 Gypsum Board Ceiling Finishes*

Painted gypsum ceilings in custodial, washrooms and locker rooms throughout.

Painted gypsum ceilings in storage areas

Gypsum bulkheads at office reception counters and in main corridors

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	50	MAR-07

C3030.06 Acoustic Ceiling Treatment (Susp.T-Bar)**

T-bar ceilings throughout administration and classroom areas.

Sloped grid system in library most ceilings are in good shape less than 5 % damaged areas

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	25	MAR-07

Event: Replace damaged Ceiling Tiles**Concern:**

Ceiling tile in corridor has serious bulge and stain. Indication of serious heat pump or roof leak. Location is where roofing report indicates some problems.

Damaged tiles in random areas either due to maintenance access or student damage.

Recommendation:

Investigate whether source of leak has been corrected and replace tile.

Replace damaged tiles in other areas

Consequences of Deferral:

Further damage in corridor if leak not repaired.

Further deterioration and vandalism where tiles are already damaged

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2007	\$2,000	High

Updated: MAR-07

C3030.07 Interior Ceiling Painting**

Painted ceilings in locker rooms, washrooms and storage areas

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	20	MAR-07

C3030.09 Other Ceiling Finishes*

Exposed painted metal deck at main hallway, ancillary spaces (old gym), gymnasium, mechanical rooms

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	50	MAR-07

D1010.02 Lifts**

Open lift in library to mezzanine

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	1994	25	MAR-07

Event: Service Lift and stabilize platform**Concern:**

Librarian reports that the lift platform tilts to the open railing when loaded. This may panic a user.

Recommendation:

Service elevator and adjust lift platform so it does not tilt forward

Consequences of Deferral:

Inconvenience to user. This may be a sign of further problems or potential failure.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2007	\$2,000	Unassigned

Updated: MAR-07

S4 MECHANICAL**D2010.01 Water Closets****

(1975) (1994)

Water closets with flush valves and open front seat.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	35	MAR-07

Event: **Replace water closets and flush valves in 1975 section.**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2010	\$12,000	Low

Updated: MAR-07**D2010.02 Urinals****

(1975) (1994)

Waterless wall hung urinals provided.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	35	MAR-07

Event: **Replace 1975 urinals**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	0	\$4,000	Low

Updated: MAR-07**D2010.03 Lavatories****

(1975) (1994)

Vitreous china lavatories installed in vanities. Metered push button supply provided for each lavatory. Temperature mixing valves provided for supply trim. Private washrooms have wall hung vitreous china lavatory.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	35	MAR-07

Event: **Replace lavatories in 1975 section**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2010	\$7,500	Low

Updated: MAR-07

D2010.04 Sinks**

(1975) (1980)

Single stainless steel sink c/w swing spout.

Double stainless steel sink with swing spout.

Triple stainless steel sink with swing spout in kitchen.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	30	MAR-07

Event: replace stainless sinks in 1975 section

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2010	\$6,000	Low

Updated: MAR-07**D2010.05 Showers****

Heavy duty wall shower heads complete with push button timer for supply trim in cubicals. Temperature mixing valves provided for hot water supply. Staff shower has pressure balancing mixing valve.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	1994	30	MAR-07

D2010.08 Drinking Fountains / Coolers**

(1975) (1980) (1994)

Vitreous china semi recessed drinking fountain installed in corridors.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	35	MAR-07

Event: replace drinking fountain in 1975 section

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2010	\$6,000	Low

Updated: MAR-07**D2010.09 Service Sinks ****

Janitor's sink enamel on cast iron installed on base.

410 mm x 1070 mm stainless steel sink in band room.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1975	30	MAR-07

Event: replace service sink

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2010	\$4,000	Low

Updated: MAR-07

D2010.09 Other Plumbing Fixtures**

Janitor's sink enamel on cast iron installed on base.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	30	MAR-07

D2020.01.01 Pipes and Tubes: Domestic Water*

Copper pipes and tubes used for domestic service.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	40	MAR-07

D2020.01.02 Valves: Domestic Water**

(1975) (1980) (1994)

Gate, ball, and butterfly valves used.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	40	MAR-07

D2020.01.03 Piping Specialties (Backflow Preventors)**

Water meters and pressure regulators installed for water make up line to glycol fill system and chemical feed system.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1975	20	MAR-07

Event: Replace pressure regulators

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2010	\$4,000	Low

Updated: MAR-07

D2020.01.03 Piping Specialties (Backflow Preventors) IrrigationSystem**

Backflow preventors supplied for irrigation system.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	20	MAR-07

D2020.01.08 Hose Bibbs

Frost-proof hose bibbs installed on exterior wall.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	MAR-07

D2020.02.02 Plumbing Pumps: Domestic Water**

(2) Well XTROL Amtrol pressure tanks complete with duplex pumps 7 1/2 H.P. each for potable water system. Domestic hot water recirculation pump.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	20	MAR-07

D2020.02.03 Water Storage Tanks**

10,000 gallon potable water storage tank inside mechanical room #161.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	20	MAR-07

D2020.02.04 Domestic Water Conditioning Equipment**

Filter, water softener and R.O. Water treatment system c/w chemical feed system for water supply.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	20	MAR-07

D2020.02.06 Domestic Water Heaters**

State Sandblaster SBF75120HECGAD with 75 gallon storage and 108.0 MBH Input. Unit c/w vent damper. Domestic hot water recirculation pump installed.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	1975	20	MAR-07

Event: Replace domestic water heater

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2010	\$8,500	Low

Updated: MAR-07

D2020.03 Water Supply Insulation: Domestic*

Domestic water system insulated.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	30	MAR-07

D2020.03.02 Equipment Insulation: Domestic Water

Storage tank for domestic water is insulated.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	MAR-07

D2030.01 Waste and Vent Piping*

Copper and cast iron pipe used for waste and vent piping.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	50	MAR-07

D2030.03.03 Pumps: Waste

Duplex sewage pump c/w automatic controls used to lift sewage.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1975	0	MAR-07

D2040.01 Rain Water Drainage Piping Systems*

Rain water drain piping connect all roof drains and exit building below grade at one location.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	50	MAR-07

D2040.02.04 Roof Drains**

Cast iron roof drains provided throughout roof area.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1975	40	MAR-07

D2040.03 Rain Water Drainage Insulation

Roof drain uninsulated for most part. Drain lines near roof drain insulated.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	MAR-07

D3020.01 Steam Boilers

Weil McLain C.I. Modular steam boiler EG50-PIN with 175.0 MBH Input used for humidifier.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1975	35	MAR-07

D3020.01.01 Heating Boilers & Accessories: Steam**

Steam traps.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1975	35	MAR-07

D3020.01.04 Water Treatment: Steam Boilers*

Chemical feed tank and pump supplied for steam boiler.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	35	MAR-07

D3020.02.01 Heating Boilers and Accessories: H.W.**

Two Super Hot AA-2760-NM - water tube boilers - single stage with 2760.0 Input each.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1975	35	MAR-07

D3020.02.02 Chimneys (&Comb. Air): H.W. Boiler**

Chimney and combustion air insulated. Combustion air complete with skirt. Projection heater provided to heat combustion air.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1975	30	MAR-07

Event: Replacde chimney and combustion air supply.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2010	\$6,000	Low

Updated: MAR-07

D3020.02.03 Water Treatment: H. W. Boiler*

Pot feeder, micron filter and site glass provided for heating glycol solution system.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	30	MAR-07

D3030.05.04 Liquid Coolers and Evaporative Condensers*

BAC cooling tower model VFL-722M installed in room #139. Used for cooling condenser water from heat pumps. Unit c/w 1 1/2 H.P. motor spray pump.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	25	MAR-07

D3030.05.05 Water Treatment Equipment*

Chemical feed pump and tank provided cooling tower water treatment.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	25	MAR-07

D3030.07 Heat Pumps 1975**

Heat pumps complete with compressor, fan and filter installed in corridor ceiling space. Unit complete with condenser water supply. Sensor in respective zone or classroom, control each heat pump.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1975	15	MAR-07

Event: Replace heat pumps

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2010	\$95,000	Low

Updated: MAR-07

D3030.07 Heat Pumps 1994**

Heat pumps complete with compressor, fan and filter installed in corridor ceiling space. Unit complete with condenser water supply. Sensor in respective zone or classroom, control each heat pump.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	15	MAR-07

D3040.01.01 Air Handling Units: Air Distribution**

Ventilation supply Eng 'A' LM 13C with 15 H.P. Motor provide outdoor air supply to each heat pump unit. Unit c/w filter and heating coil. Unit located in mechanical room #122.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	1975	30	MAR-07

Event: replace 1975 AHU

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2010	\$20,000	Low

Updated: MAR-07

D3040.01.03 Air Cleaning Devices:Air Distribution*

50 mm flat filters installed in air handling unit. Pad filter installed in each heat pump unit.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	MAR-07

D3040.01.04 Ducts: Air Distribution*

Outdoor air supply is distributed near each heat pump unit in ceiling space. Duct is connected to main air handler in mechanical room #122.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	MAR-07

D3040.03.01 Hot Water Distribution Systems**

Glycol solution heating pump Armstrong base mounted centrifugal pump with 15 H.P. motor (2) supply hot water to radiation fins, fan coils, etc. Glycol solution heating pumps Armstrong 4030 15 H.P. Motor circulate condenser water from boiler to storage or tower to heat pumps. Two diaphragm expansion tanks installed on floor.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1975	40	MAR-07

D3040.04.01 Fans: Exhaust**

(1975) (1980)

Washroom and dressing rooms have dome type roof exhaust fans. Either Greenheck or Penn manufacturers. Greenheck CUBE18DHP up blast fan for kitchen hood.

Roof mounted centrifugal exhaust fans installed for welding, spray booth, etc.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	30	MAR-07

Event: Replace exhaust fans

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2010	\$24,000	Low

Updated: MAR-07

D3040.04.01 Fans: Fume Hoods

Fume hoods installed in science rooms # 149 and # 152.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	1994	30	MAR-07

D3040.04.01.01 Fans: Exhaust**

Roof exhaust fan for labs and washrooms.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	1994	30	MAR-07

D3040.04.03 Ducts: Exhaust*

Central roof fans are connected to ceiling grilles in washrooms, dressing room and janitor's room.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	50	MAR-07

D3040.04.05 Air Outlets and Inlets: Exhaust*

Generally grid type ceiling grilles used for exhaust system.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	30	MAR-07

D3050.03 Humidifiers**

Steam diffusers installed in supply duct. Steam piped from steam boiler to diffuser. Pipes insulated. Traps provided as required.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1975	25	MAR-07

Event: replace humidifiers

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2010	\$3,500	Low

Updated: MAR-07

D3050.05.02 Fan Coil Units**

(1975) (1980)

Fan coil units installed in vestibules' ceiling space.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	30	MAR-07

Event: Lifecycle Replacement

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2010	\$4,800	Low

Updated: MAR-07

D3050.05.03 Finned Tube Radiation**

(1975) (1980) (1994)

Perimeter finned tube radiation supplied for storage rooms, washrooms, etc.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	40	MAR-07

D3050.05.06 Unit Heaters**

Unit heaters installed in mechanical room, storage room etc.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	1975	30	MAR-07

Event: Replace unit heaters

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2010	\$3,600	Low

Updated: MAR-07

D3060.02.01 Electric and Electronic Controls**

Electric controls for fan coil unit and unit heaters for 1975 and 1994 sections

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	1975	30	MAR-07

Event: Replace electronic controls for unit heaters

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2010	\$225,000	Low

Updated: MAR-07

D3060.02.05 Building Systems Controls (BMCS, EMCS)**

Johnson Metasys system installed.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1975	25	MAR-07

Event: Replace BS controls

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2010	\$225,000	Low

Updated: MAR-07

D3090 Other Special HVAC Systems and Equipment*

Heat pump storage tank installed in room #161. Tank used to store tempered water for heat pump.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	1994	25	MAR-07

D4010 Sprinklers: Fire Protection*

Sprinkler system throughout building. 20 H.P. motor Armstrong fire pump provided on sprinkler system. 2 - 2 1/2 " fire pump connection provided in west wall of mechanical room #161.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	60	MAR-07

D4030.01 Fire Extinguisher, Cabinets and Accessories**

(1975) (1980)

Fire extinguisher in cabinet throughout corridor, classrooms and mechanical rooms.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	30	MAR-07

Event: **Replace 1975 and 1980 fire extinguisher.**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2010	\$3,300	Low

Updated: MAR-07**D4030.01.01 Fire Extinguisher, Cabinets and Accessories** 1994**

Recessed stainless steel cabinet provided throughout corridors and gym.

Dry chemical fire extinguishers unless noted otherwise.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	1994	30	MAR-07

D4090.04 Dry Chemical Fire Extinguishing Systems (Kitchen Hood Extinguishing Systems)**

Kitchen # 114 has commercial hood c/w dry chemical fire extinguishing system.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	1975	50	MAR-07

S5 ELECTRICAL**D5010.01 Main Electrical Transformers****

The main transformer feeding the school is a 500KVA pad mount transformer and is located on the north side of the facility.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1996	40	MAR-07

D5010.03 Main Electrical Switchboards (Main Distribution)**

The main CDP is a Westinghouse 120/208V 3phase 4wire rated at 1600 amps, and has plenty of capacity and meets current and future needs.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1996	40	MAR-07
	<u>Capacity Size</u>	<u>Capacity Unit</u>	
	1600	amps	

D5010.05 Electrical Branch Circuit Panelboards (Secondary Distribution)**

The original building core was built in 1975 and some panels are original in the core. There was an addition in 1980 and some panels were added. Then in 1996 there was another addition and new distribution was added, and the original panels were kept, and more were added to meet the growth of the addition. The panels are all Westinghouse 42cct 225amp rated 120/208V 3 phase 4 wire and have sufficient capacity current standards and future growth.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	MAR-07

D5010.07 Motor Control Centers (Motor Control)**

There is a MCC is a Westinghouse and is located in mechanical room 122 and it has sufficient capacity for current and future needs.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1996	30	MAR-07

D5020.01 Electrical Branch Wiring*

The wiring is in good condition through out and as additions have been done more has been added.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1975	50	MAR-07

D5020.02.01 Lighting Accessories (Lighting Controls)*

There is a low voltage switching cabinet in the Facility Operators room where all the corridor lighting can be controlled from by the Operator.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1996	30	MAR-07

D5020.02.02.02 Interior Florescent Fixtures**

The Lighting through out is generally fluorescent T-8 fixtures with electronic ballasts, in the corridors it is 1X4 with 2 lamps and K-12 lenses, classrooms have 2X4 parabolic with 3 lamps, science rooms have 2X4 deep cell with 3 lamps, storage rooms have 1X4 surface strips with 2 lamps, and washrooms have 2 lamp 4' cube lights, and it has been upgraded for cost savings and to meet current standards.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1996	30	MAR-07

D5020.02.02.04 Interior H.P. Sodium Fixture*

This lighting in the gymnasium was installed in 1996 when the gymnasium was added on. I believe that the lighting could be upgraded to T-5 or T-8 boxes to lower operating costs and increased efficiency as well as better lighting colors. Although the lighting is in good shape, and we found no noted deficiency's.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1996	30	MAR-07

D5020.02.03.01 Emergency Lighting Built-in*

The emergency lighting is in the form of fluorescent fixtures through the back up generator which currently provides adequate egress coverage.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1996	35	MAR-07

D5020.02.03.03 Exit Signs*

Exit lights are connected to emergency power supplied by the emergency generator and have LED style bulbs which meet current standards.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1996	30	MAR-07

D5020.02.05 Special Purpose Lighting*

There are some spot lights in the drama room for doing performances they are standard stage lights and seems to be in good order, and meet current needs.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1996	30	MAR-07

D5020.03.01.04 Exterior H.P. Sodium Fixtures*

There are 10 high press sodium wall packs installed around the exterior of the school and controlled by low voltage relay's and a time clock.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1996	30	MAR-07

D5020.03.02 Lighting Accessories: Exterior (Lighting Controls)*

There is a low voltage relay switching cabinet and a time clock which controls the exterior lighting.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1996	30	MAR-07

D5030.01 Detection and Fire Alarm**

The fire alarm system is a Simplex 4100 addressable single stage system, and has bell strobe combinations for annunciating devices. The system was last tested may 2006 and meets current standards.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1996	25	MAR-07

D5030.02.01 Door Answering*

There is currently a doorbell at the front door which rings a tone through out the school by means of a speaker paging system.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	25	MAR-07

D5030.02.02 Intrusion Detection**

There is a Magnum Alert security panel installed in the main data room. There are currently 2 keypads to arm and disarm the system with 1 located at the main entrance and 1 located at the cafeteria south entrance, also there are motion sensor's mounted through out the facility.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1996	25	MAR-07

D5030.02.04 Video Surveillance**

The video surveillance consist of 10 cameras located through out the interior and exterior of the facility. It is a Intellex DVMS with a recorder system, and a monitor, and mouse control pad located in the main office.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1996	25	MAR-07

D5030.03 Clock and Program Systems**

There is a master clock system in the main office which rings the bells, the classrooms all have battery operated clocks through out.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	25	MAR-07

D5030.04.01 Telephone Systems**

The current phone system is a Rauland phone system 5.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	25	MAR-07

D5030.04.03 Call Systems**

The call system is a Rauland which is located in the library office and seems to work well for the current needs.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	25	MAR-07

D5030.04.04 Data Systems**

The data system consists of Cat 5 and 5E, there are computer labs in approximately 4 classrooms, as well as some mobile labs with computers. The wiring is in good condition and meets current standards. There is wireless access and all teachers have 1 computer station as well. There is also Supernet into the facility.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	2002	25	MAR-07

D5030.05 Public Address and Music Systems**

The system is part of the Rauland telecentre and is dated and does meet current standards, it has a cassette player as well and doesn't meet the needs of the school and is show its age.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	1994	20	MAR-07

D5030.06 Television Systems*

The system is a Rauland telecentre 21 which is located in the library office. There are TV monitors in each classroom which they do announcements on, and are able to address the entire school at one time. There are also 3 camera's that they use to do different telecasts or announcements.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	20	MAR-07

D5090.01 Uninterruptible Power Supply Systems**

There are UPS's on the servers located in room 138 and meet current standards. The only thing that should happen is to add some cooling to this room to protect the equipment.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	2003	30	MAR-07

D5090.02 Packaged Engine Generator Systems (Emergency Power System)**

The generator is an Onan diesel fired 200KW emergency generator and is in good shape, it has sufficient capacity and is well maintained. It feeds a 200A fire pump and a 100A emergency panel for the school for exits and emergency lighting and other emergency systems.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1996	35	MAR-07

S6 EQUIPMENT, FURNISHINGS AND SPECIAL CONSTRUCTION**E1020.02 Library Equipment***

Security system, book charging system

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	25	MAR-07

E1020.03 Theater and Stage Equipment*

Stage lighting, etc. At drama room #117

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	25	MAR-07

E1020.07 Laboratory Equipment*

Fumehood cabinet in Room 155. Small flammable storage cabinet

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	25	MAR-07

E1090.03 Food Service Equipment*

2 residential refrigerators, 2 upright drink coolers, 1 residential freezer
 2 stainless steel ovens , 2 deep fryers, 1 cook-top all under stainless steel hood with fire suppression system
 Stainless steel condiment cart
 Stainless steel pot washing sink and separate hand washing sink
 Cash register

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	25	MAR-07

E1090.04 Residential Equipment*

6 residential stoves in Home Economics lab (no range hoods
 Washer and dryer in Home Economics room
 Refrigerator and Washer and Dryer in storage rooms next to locker areas (Physical Education use)
 Refrigerator in PE office
 Refrigerator, 3 microwaves, coffee maker and dishwasher in Staff room
 Refrigerator in Infirmary (old 1980's model)

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	2000	25	MAR-07

E1090.06 Darkroom Equipment

Darkroom pivoting door, casework and stainless steel sink

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	0	MAR-07

E1090.07 Athletic, Recreational, and Therapeutic Equipment*

Scoreboard, Basketball hoops, gymnasium divider curtain, floor sockets, etc. typical

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	15	MAR-07

E2010.02 Fixed Casework**

1980: paint plywood cabinets with laminated counter tops in Home Economics Classroom

1994: clear stained birch millwork in modernization and addition

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	35	MAR-07

Event: Repair cabinets until modernization/replacement**Concern:**

Water leaks beneath sinks have damaging the millwork.
Doors are loose and out of alignment

Recommendation:

Repair damaged doors, adjust drawers and doors and repaint cabinets

Consequences of Deferral:

Further deterioration and increase maintenance. If repairs are not made soon the replacement should be made before 2010

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2007	\$8,000	High

Updated: MAR-07**Event: Replace millwork in Home Econmics area****Concern:**

Cabinets consist of painted plywood with economical details and residential grade hinges and hardware (Design life will be reached within 5 years)

There are water stains and blistering within sink units and drawers are loose and out of alignment. Countertops have gouges and scratches

Doors are marred at edges

Recommendation:

Replace cabinets and reconfigure space.

Consequences of Deferral:

Increasing maintenance costs and repairs

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2010	\$65,000	High

Updated: MAR-07

E2010.03.01 Blinds**

Vertical PVC blinds on classroom exterior windows and on office interior windows
 Horizontal venetian blinds on half-lite glazed doors
 Roller shades on gymnasium clerestorey windows

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	30	MAR-07

Event: Replace missing slats, and pulls**Concern:**

A few missing or damaged slats some loose pulls and missing control rods, etc, Some roller shades in gymnasium look as if pulls are missing

Recommendation:

Repair missing or damaged slats, adjust mechanisms, Inspect roller shades for missing components and functionality and install new control rods, etc,

Consequences of Deferral:

Difficult to control light or privacy

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2007	\$1,000	High

Updated: MAR-07

E2010.03.06 Curtains and Drapes**

Black stage curtains at drama area

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	30	MAR-07

E2010.05 Fixed Multiple Seating**

Fixed bench installed around planter beneath skylight

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	35	MAR-07

E2010.06 Fixed Interior Landscaping*

Concrete block pony wall forming planter in student gathering space

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	10	MAR-07

E2020 Moveable Furnishings*

Infirmery beds, stretcher, portable bleachers in gymnasium corridor and in room 107, folding tables for lunch and stacking chairs on cart,typical classroom desks and chairs.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	20	MAR-07

F1010.02.04 Portable and Mobile Buildings* P101

1990 Portable Relocated in 1994

Architectural:

- wood floor joists with insulated cavity supported on concrete piers with metal clad plywood skirting
- vertical ribbed metal clad insulated wood wall frame and drywall construction over 300mm crawl space
- aluminum clad wood window with sealed glass lites and vertical vinyl blinds
- sheet vinyl flooring
- T-Bar acoustic ceiling panels
- vented wood roof joists with insulated cavity
- BUR (Tar & Gravel) roof
- connected to portables with wood framed corridor/ramp c/w drywall bulkheads and lockers

Mechanical:

Package roof top HVAC unit model Lennox LGA-0360 5514 with 78.0 MBH input shared with P102.
 75mm gas line with capacity of 1300 CFH runs down corridor in ceiling space and goes up to roof to service RTU's.
 Fire extinguisher cabinet mounted in corridor

Electrical:

- 2-50mm EC stubbed out in ceiling space to connect portables to main service panel LN and PN
- 610 x 1220 recessed light fixtures
- recessed pot lights in soffit over exit door at corridor
- Battery Packs located in corridor
- 4-25mm conduit form cable tray run downlink/corridor to portables

Rating	Installed	Design Life	Updated
4 - Acceptable	1990	25	MAR-07

Event: Repair wood casing around window**Concern:**

Casing has become loose

Recommendation:

Remove casing insert foam sealant in cavity for energy efficiency and install new casing

Consequences of Deferral:

Casing can be pulled off by students causing further damage

Type	Year	Cost	Priority
Repair	2007	\$1,000	High

Updated: MAR-07**Event: Replace roof**

Type	Year	Cost	Priority
Lifecycle Replacement	2010	\$5,000	Low

Updated: MAR-07

F1010.02.04 Portable and Mobile Buildings* P102

1990 Portable relocated in 1994

Architectural:

- wood floor joists with insulated cavity supported on concrete piers with metal clad plywood skirting
- vertical ribbed metal clad insulated wood wall frame and drywall construction over 300mm crawl space
- aluminum clad wood window with sealed glass lites and vertical vinyl blinds
- sheet vinyl flooring
- T-Bar acoustic ceiling panels
- vented wood roof joists with insulated cavity
- BUR (Tar & Gravel) roof
- connected to portables with wood framed corridor/ramp c/w drywall bulkheads and lockers

Mechanical:

Package roof top HVAC unit model Lennox LGA-0360 5514 with 78.0 MBH input shared with P101.
 Fed from 75mm gas line with capacity of 1300 CFH in corridor ceiling space near P101 and goes up to roof to service RTU's.
 Fire extinguisher cabinet mounted in corridor

Electrical:

- 2-50mm EC stubbed out in ceiling space @ vestibule to connect portables to main service panel LN and PN
- 610 x 1220 recessed light fixtures Light fixtures
- recessed pot lights in soffit over exit door at corridor
- Battery Packs located in corridor
- 4-25mm conduit form cable tray run downlink/corridor to portables

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1990	0	MAR-07

Event: Replace roofing

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2010	\$5,500	Low

Updated: MAR-07

F1010.02.04 Portable and Mobile Buildings* P103

1990 Portable Relocated in 1994

Architectural:

- wood floor joists with insulated cavity supported on concrete piers with metal clad plywood skirting
- vertical ribbed metal clad insulated wood wall frame and drywall construction over 300mm crawl space
- aluminum clad wood window with sealed glass lites and vertical vinyl blinds
- sheet vinyl flooring
- T-Bar acoustic ceiling panels
- vented wood roof joists with insulated cavity
- BUR (Tar & Gravel) roof
- connected to portables with wood framed corridor/ramp c/w drywall bulkheads and lockers

Mechanical:

Package roof top HVAC unit model Lennox LGA-0360 5514 with 78.0 MBH input shared with P104.
 75mm gas line with capacity of 1300 CFH runs down corridor in ceiling space and goes up to roof to service RTU's.
 Fire extinguisher cabinet mounted in corridor

Electrical:

- 2-50mm EC stubbed out in ceiling space @ vestibule to connect portables to main service panel LN and PN
- 610 x 1220 recessed light fixtures
- recessed pot lights in soffit over exit door at corridor
- Battery Packs located in corridor
- 4-25mm conduit form cable tray run downlink/corridor to portables

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1990	0	MAR-07

Event: Replace ceiling Tile**Concern:**

Stained ceiling indicates roof leak

Recommendation:

Investigate reason for stained tile. Probably flashing or gum box on roof at shared RTU. Once repaired replace tile

Consequences of Deferral:

Water damage

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2007	\$1,000	High

Updated: MAR-07

Event: Replace with SBS roofing

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2010	\$5,500	Low

Updated: MAR-07

F1010.02.04 Portable and Mobile Buildings* P104

1990 Portable Relocated in 1994

Architectural:

- wood floor joists with insulated cavity supported on concrete piers with metal clad plywood skirting
- vertical ribbed metal clad insulated wood wall frame and drywall construction over 300mm crawl space
- aluminum clad wood window with sealed glass lites and vertical vinyl blinds
- sheet vinyl flooring
- T-Bar acoustic ceiling panels
- vented wood roof joists with insulated cavity
- BUR (Tar & Gravel) roof & SBS Roof System
- connected to portables with wood framed corridor/ramp c/w drywall bulkheads and lockers

Mechanical:

Package roof top HVAC unit model Lennox LGA-0360 5514 with 78.0 MBH input shared with P103.
 75mm gas line with capacity of 1300 CFH runs down corridor in ceiling space and goes up to roof to service RTU's.
 Fire extinguisher cabinet mounted in corridor

Electrical:

- 2-50mm EC stubbed out in ceiling space at vestibule to connect portables to main service panel LN an PN
- 610 x 1220 recessed light fixtures Light fixtures
- recessed pot lights in soffit over exit door at corridor
- Battery Packs located in corridor
- 4-25mm conduit form cable tray run downlink/corridor to portables

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1990	0	MAR-07

Event: Investigate leak and replace ceiling tile**Concern:**

Stained ceiling indicates roof leak

Recommendation:

Investigate reason for stained tile. Probably flashing or gum box on roof at shared RTU. Once repaired replace tile

Consequences of Deferral:

Water damage

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2007	\$1,000	High

Updated: MAR-07

Event: Replace roofing

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2010	\$3,000	Low

Updated: MAR-07

F1010.02.04 Portable and Mobile Buildings* P105

1999 Portable

Architectural:

- wood floor joists with insulated cavity supported on concrete piers with metal clad plywood skirting
- vertical ribbed metal clad insulated wood wall frame and drywall construction over 300mm crawl space
- PVC windows with sealed glass lites, wood liners and vertical vinyl blinds
- sheet vinyl flooring and carpet
- T-Bar acoustic ceiling panels
- vented wood roof joists with insulated cavity
- SBS Roof system
- connected to portables with wood framed corridor/ramp c/w drywall bulkheads and lockers

Mechanical:

Package roof top HVAC unit model R4GA-036-C096 with 96.0 MBH.
 Gas line with capacity of 1300 CFH runs along roof above corridor to service RTU's.
 Fire extinguisher cabinet mounted in corridor

Electrical:

- 2-50mm EC stubbed out in ceiling space to connect portables to main service panel LW and PN
- 610 x 1220 recessed light fixtures
- recessed pot lights in soffit over exit door at corridor
- Battery Packs located in corridor
- conduit from cable tray in main building runs downlink/corridor to portables

Rating	Installed	Design Life	Updated
4 - Acceptable	1999	0	MAR-07

Event: Repair drywall and repaint wall**Concern:**

Drywall is scratched along lower wall

Recommendation:

Repair damaged drywall and repaint damaged wall

Consequences of Deferral:

Further damage/vandalism

Type	Year	Cost	Priority
Repair	2007	\$1,500	High

Updated: MAR-07

F1010.02.04 Portable and Mobile Buildings* P106

1999 Portable

Architectural:

- wood floor joists with insulated cavity supported on concrete piers with metal clad plywood skirting
- vertical ribbed metal clad insulated wood wall frame and drywall construction over 300mm crawl space
- PVC windows with sealed glass lites, wood liners and vertical vinyl blinds
- sheet vinyl flooring and carpet
- T-Bar acoustic ceiling panels
- vented wood roof joists with insulated cavity
- SBS roof system
- connected to portables with wood framed corridor/ramp c/w drywall bulkheads and lockers

Mechanical:

Package roof top HVAC unit model R4GA-036-C096 with 96.0 MBH.
 Gas line with capacity of 1300 CFH runs along roof above corridor to service RTU's.
 Fire extinguisher cabinet mounted in corridor

Electrical:

- 2-50mm EC stubbed out in ceiling space to connect portables to main service panel LW and PN
- 610 x 1220 recessed light fixtures
- recessed pot lights in soffit over exit door at corridor
- Battery Packs located in corridor
- conduit from cable tray in main building runs downlink/corridor to portables

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1999	0	MAR-07

Event: Repair drywall and repaint wall**Concern:**

Drywall is scratched along lower wall.

Recommendation:

Repair damaged drywall and repaint damaged wall.

Consequences of Deferral:

Further damage/vandalism

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2007	\$1,500	High

Updated: MAR-07

F1010.02.04 Portable and Mobile Buildings* P107

1999 Portable

Architectural:

- wood floor joists with insulated cavity supported on concrete piers with metal clad plywood skirting
- vertical ribbed metal clad insulated wood wall frame and drywall construction over 300mm crawl space
- PVC windows with sealed glass lites, wood liners and vertical vinyl blinds
- sheet vinyl flooring and carpet
- T-Bar acoustic ceiling panels
- vented wood roof joists with insulated cavity
- SBS roof system
- connected to portables with wood framed corridor/ramp c/w drywall bulkheads and lockers

Mechanical:

Package roof top HVAC unit model R4GA-036-C096 with 96.0 MBH.
 Gas line with capacity of 1300 CFH runs along roof above corridor to service RTU's.
 Fire extinguisher cabinet mounted in corridor

Electrical:

- 2-50mm EC stubbed out in ceiling space to connect portables to main service panel LW and PN
- 610 x 1220 recessed light fixtures
- recessed pot lights in soffit over exit door at corridor
- Battery Packs located in corridor
- conduit from cable tray in main building runs downlink/corridor to portables

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1999	0	MAR-07

Event: Repair drywall, repaint wall, clean carpet stain**Concern:**

Drywall is scratched along lower wall
 Minor carpet stain.

Recommendation:

Repair damaged drywall and repaint damaged wall.
 Clean stain on carpet

Consequences of Deferral:

Further damage/vandalism

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2007	\$2,000	High

Updated: MAR-07

F1010.02.04 Portable and Mobile Buildings* P108

1999 Portable

Architectural:

- wood floor joists with insulated cavity supported on concrete piers with metal clad plywood skirting
- vertical ribbed metal clad insulated wood wall frame and drywall construction over 300mm crawl space
- PVC windows with sealed glass lites, wood liners and vertical vinyl blinds
- sheet vinyl flooring
- T-Bar acoustic ceiling panels
- vented wood roof joists with insulated cavity
- SBS roof system
- connected to portables with wood framed corridor/ramp c/w drywall bulkheads and lockers

Mechanical:

Package roof top HVAC unit model R4GA-036-C096 with 96.0 MBH.
 Gas line with capacity of 1300 CFH runs along roof above corridor to service RTU's.
 Fire extinguisher cabinet mounted in corridor

Electrical:

- 2-50mm EC stubbed out in ceiling space to connect portables to main service panel LW and PN
- 610 x 1220 recessed light fixtures
- recessed pot lights in soffit over exit door at corridor
- Battery Packs located in corridor
- conduit from cable tray in main building runs downlink/corridor to portables

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1999	0	MAR-07

Event: Repair drywall and repaint wall**Concern:**

Drywall is scratched along lower wall

Recommendation:

Repair damaged drywall and repaint damaged wall

Consequences of Deferral:

Further damage/vandalism

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2007	\$1,500	High

Updated: MAR-07

F1010.02.04 Portable and Mobile Buildings* P109

1991 Portables relocated in 2001

Architectural:

- wood floor joists with insulated cavity supported on concrete piers with metal clad plywood skirting
- vertical ribbed metal clad insulated wood wall frame and drywall construction over 300mm crawl space
- prefinished aluminum clad wood window with sealed glass lites and vertical vinyl blinds
- carpet
- T-Bar acoustic ceiling panels
- vented wood roof joists with insulated cavity
- BUR (Tar & Gravel) roof (corridor has SBS roof)
- connected to portables with wood framed corridor/ramp c/w drywall bulkheads and lockers

Mechanical:

Package roof top HVAC unit model
 Gas line with capacity of 1300 CFH runs along roof above corridor to service RTU's.
 Fire extinguisher cabinet mounted in corridor

Electrical:

- panel in portables connected to main service panel LW and PN
- 610 x 1220 recessed light fixtures Light fixtures
- recessed pot lights in soffit over exit door at corridor
- Battery Packs located in corridor
- conduit from cable tray in main building runs downlink/corridor to portables

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	2001	0	MAR-07

Event: Replace roofing

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2010	\$5,500	Low

Updated: MAR-07

F1010.02.04 Portable and Mobile Buildings* P110

1991 Portable relocated in 2001

Architectural:

- wood floor joists with insulated cavity supported on concrete piers with metal clad plywood skirting
- vertical ribbed metal clad insulated wood wall frame and drywall construction over 300mm crawl space
- prefinished aluminum clad wood window with sealed glass lites and vertical vinyl blinds
- carpet
- T-Bar acoustic ceiling panels
- vented wood roof joists with insulated cavity
- BUR (Tar & Gravel) roof (corridor has SBS roof)
- connected to portables with wood framed corridor/ramp c/w drywall bulkheads and lockers

Mechanical:

Package roof top HVAC unit model
 Gas line with capacity of 1300 CFH runs along roof above corridor to service RTU's.
 Fire extinguisher cabinet mounted in corridor

Electrical:

- panel in portables connected to main service panel LW and PN
- 610 x 1220 recessed light fixtures
- recessed pot lights in soffit over exit door at corridor
- Battery Packs located in corridor
- conduit from cable tray in main building runs downlink/corridor to portables

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	2001	0	MAR-07

Event: Repair hole in roof and replace Ceiling Tile**Concern:**

missing ceiling tile and electrical feed to RTU has not been sealed.

Recommendation:

Seal hole in roof and replace ceiling tile

Consequences of Deferral:

Water damage

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2007	\$1,000	Unassigned

Updated: MAR-07

Event: Replace with SBS roofing

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2010	\$5,500	Low

Updated: MAR-07

F1020.02.13 Paint Booths*

Paint booth in Art room

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	50	MAR-07

F2020.01 Asbestos*

Possible Asbestos in pipe elbow insulations. None evidenced. None reported

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1975	0	MAR-07

F2020.02 PCBs*

Most lite fixtures have been upgraded. There may be some PCB's in older equipment however none were reported. None evidenced

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1975	0	MAR-07

F2020.03 Mercury*

None evidenced. None Reported.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1975	0	MAR-07

F2020.04 Mould*

None Evidenced. None Reported. Monitor top ledge of skylight area and were water leaks have occurred

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1975	0	MAR-07

F2020.09 Other Hazardous Materials*

None Evidenced. None Reported.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1975	0	MAR-07

S8 FUNCTIONAL ASSESSMENT**K4010.01 Barrier Free Route: Parking to Entrance**

Main entrance has long overwidth ramp @ 1:12 slope

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	0	MAR-07

K4010.02 Barrier Free Entrances

Auto-operator is installed at main entrance

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	0	MAR-07

K4010.03 Barrier Free Interior Circulation

All areas are acceptable except for the mezzanine above the gymnasium.
A lift is provided in the library

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	1994	0	MAR-07

Event: Provide access to weight training**Concern:**

The weight training area which is the old viewing area to the gymnasium is not accessible.
This has not been a problem to-date but could be if a disabled student requests access

Recommendation:

Provide alternate facility or provide a lift to the mezzanine area

Consequences of Deferral:

Potential accessibility problem.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Barrier Free Access Upgrade	2010	\$15,000	Medium

Updated: MAR-07

K4010.04 Barrier Free Washrooms

Washrooms meet accessibility requirements

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	0	MAR-07

RECAPP Facility Evaluation Report



Springbank Schools

S2375
Springbank

Facility Details**Building Name:** Springbank Schools**Address:****Location:** Springbank**Building Id:** S2375**Gross Area (sq. m):** 0.00**Replacement Cost:** \$0**Construction Year:** 0**Evaluation Details****Evaluation Company:** Quinn Young Architects Ltd.**Evaluation Date:** July 14 2006**Evaluator Name:** Barry McCallum**Total Maintenance Events Next 5 years:** **\$304,000****5 year Facility Condition Index (FCI):** **0%****General Summary:**

The 7.86 acre (31,804 sq.m.) school site is shared with an adjacent community arena and playing fields . Parking lots, access roads and a Bus loop/firelane which runs around the school are all paved. The school is located below a playing field to the north which drains down toward the school catch basins have been installed on the north side to catch runoff water from the playing fields

Structural Summary:**Envelope Summary:****Interior Summary:****Mechanical Summary:****Electrical Summary:****Rating Guide**

Condition Rating	Performance
1 - Critical	Unsafe, high risk of injury or critical system failure.
2 - Poor	Does not meet requirements, has significant deficiencies. May have high operating/maintenance costs.
3 - Marginal	Meets minimum requirements, has significant deficiencies. May have above average operating maintenance costs.
4 - Acceptable	Meets present requirements, minor deficiencies. Average operating/maintenance costs.
5 - Good	Meets all present requirements. No deficiencies.
6 - Excellent	As new/state of the art, meets present and foreseeable requirements.

S7 SITE**G1030 Site Earthwork (Site Grading)***

Grades slope down on west side at main entrance and drains away from the school. The grades slope toward the school and there are steps down at the southeast locker area. Drainage appears adequate but the asphalt hard surface area on the east side appears to be settling where old portables were located. Piles appear to be located in this area. Because of the drop there is some ponding at this location which keeps water away from the building.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	50	MAR-07

G2010.02.02 Flexible Pavement Roadway (Asphalt)**

The bus loop and parking lot were paved in 1999

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1999	25	MAR-07

G2010.04 Rigid Roadway Pavement (Concrete)**

Garbage bin apron is concrete

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	25	MAR-07

G2010.05 Roadway Curbs and Gutters*

Integral sidewalk and curb and parking lot islands (refer to parking lots and sidewalks)

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1999	25	MAR-07

G2010.06 Roadway Appurtenances*

Metal concrete filled bollards at ramp at main entrance to prevent loading to get too close to building

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	25	MAR-07

G2020.02.02 Flexible Paving Parking Lots(Asphalt)**

Gravel lot and bus loop was paved in 1999

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1999	10	MAR-07

Event: Repave parking lot

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2010	\$290,000	Low

Updated: MAR-07

G2020.05 Parking Lot Curbs and Gutters*

Cast-in place concrete curbs forming islands in parking area

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1999	25	MAR-07

Event: Replace missing curb**Concern:**

Island on west side has lost a portion of curb. Some curbing is damaged along edge of bus drop off area

Recommendation:

Replace section to complete island

Consequences of Deferral:

Further damage when parking lot is cleaned

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2007	\$2,000	High

Updated: MAR-07

G2020.06.01 Traffic Barriers*

Chain and gate at bus loop entrance and exit to control after hours use of bus loop/road.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	25	MAR-07

G2020.06.02 Parking Bumpers*

Precast parking bumpers are used to form curb along bus loop on playing field side

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1999	25	MAR-07

G2020.06.03 Parking Lot Signs*

Speed signs, No parking signs and Handicapped signs in roadways

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1999	25	MAR-07

G2020.06.04 Pavement Markings*

Painted yellow markings

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1999	25	MAR-07

Event: Repaint speed bumps**Concern:**

Markings at speed bumps are worn

Recommendation:

Repaint speed bumps

Consequences of Deferral:

No warning drivers to slow down

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2007	\$1,000	Medium

Updated: MAR-07**G2030.02.02 Asphalt Pedestrian Pavement****

Asphalt connecting walkway from portables. Walkway is uneven (refer to G2030.06 for costs)

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	2001	10	MAR-07

G2030.04 Rigid Pedestrian Pavement (Concrete)**

3.0m concrete sidewalk with curb along bus loop

2.0m sidewalk with curb along front of school

Sidewalk/steps to community entrance (refer to G2030.06 for costs)

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	1999	15	MAR-07

G2030.06 Exterior Steps and Ramps*

1980: Sidewalk and steps to community entrance

1994: Sidewalk/ramp at main entrance and sidewalks/steps along bus loop and at east side

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	1980	15	MAR-07

Event: Adjust asphalt walkway**Concern:**

Step from portable floor to grade exceeds 200mm

Recommendation:

Use one row of retaining wall block to raise asphalt walk at step to reduce height or regrade topsoil to meet new walk

Consequences of Deferral:

Tripping or falling hazard

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Code Repair	2007	\$1,000	Medium

Updated: MAR-07

Event: Replace sidewalk/steps at community entrance**Concern:**

Sidewalk and steps are worn edges are deteriorating (spalling).

Recommendation:

Replace with new walkway/ramp to access community (after hours) door

Consequences of Deferral:

Further deterioration and repairs will be required soon.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2008	\$8,000	High

Updated: MAR-07

G2040.02 Fences and Gates**

Ranch/farm wood fence along 181st Street

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	30	MAR-07

G2040.03 Athletic and Recreational Surfaces**

Large irrigated playing field on northeast side, Baseball diamond on Northwest portion of site, Asphalt area adjacent to garbage enclosure with basketball hoops.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1999	25	MAR-07

G2040.05 Site and Street Furnishings*

Park bench located near entrance to school and one located in island behind handicapped stalls.
(Refer to G2050.07 to refinishing costs to benches and garbage containers)

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	2007	15	MAR-07

G2040.06 Exterior Signs*

Large wall mounted lettering on building

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	25	MAR-07

G2040.08 Flagpoles*

2 Aluminum flagpoles at main entrance

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	30	MAR-07

G2040.11 Retaining Walls*

Concrete wall at edge of ramp. Low Alan block retaining walls at grassed area and walkway

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	50	MAR-07

G2050.01 Irrigation Systems*

Rain Bird 8005-NP-20 rotary sprinklers with electric control system to irrigate main sports field on east side of bus loop.
Sleeved under asphalt bus loop from 50mm water service.
Sprinklers are controlled via a mini-weather station on roof of school.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	2002	10	MAR-07

G2050.04 Lawns and Grasses*

Last regrading and grass changes when road and parking lot was paved.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1999	15	MAR-07

G2050.05 Trees, Plants and Ground Covers*

Wide variety of shrubs and trees around school, bark mulch in parking islands.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1999	10	MAR-07

G2050.07 Planting Accessories*

Variety of precast and wood garbage cans located around site.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	1999	10	MAR-07

Event: Refinish wood benches and garbage containers**Concern:**

Wood benches and wood garbage containers are in need of restaining

Recommendation:

Refinish wood benches and garbage containers or replace wood with maintenance free recycled boards

Consequences of Deferral:

Eventual rot and replacement

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2007	\$2,000	High

Updated: MAR-07

G3010.02 Site Domestic Water Distribution*

150 diameter water service fed from 250mm Raw Water line running along 181st Street.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	MAR-07

G3010.03 Site Fire Protection Water Distribution*

Two fire hydrants are provided for site.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	50	MAR-07

G3020.01 Sanitary Sewage Collection*

150 Sanitary sewer drained by gravity to sump with dual lift pumps on site. Force main is directed to shared lagoon.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	50	MAR-07

G3030.01 Storm Water Collection*

Roof drains are collected by gravity drain system and drained via 350 storm to ditch. Three catch basins also collect ground water to storm system

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	50	MAR-07

G3060.01 Gas Distribution*

Pressure gas is supplied from utility to gas meter room #122.
Gas meter sized for 9000 CFH

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	50	MAR-07

G4010.02 Electrical Power Distribution Lines*

Underground service in 150 concrete encased PVC duct fed from overhead service on south side of arena running northeast adjacent to firelane then northwest along firelane to pad mount transformer

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	50	MAR-07

G4010.03 Electrical Power Distribution Equipment*

500 KVA pad mounted transformer located on north side of school.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	50	MAR-07

G4010.04 Car Plugs-ins*

75mm feeder PP 4#350MCM

20mm control #3 14

20mm LS-37 2#8

40 parking pedestals with a total of 106 stall outlets are fed from Panel PP West and PP East

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1999	25	MAR-07

G4020.01 Area Lighting*

6 - 30' metal halide street lights in parking lots

10 high pressure sodium wall packs around the exterior of the school on a low voltage relay and time clock

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1994	25	MAR-07