Part I - Facility Profile and Summary

School Name:	St. Gabri	el Schoo	l		School Code:	1890
Location:	Fort McM	lurray, Al	berta		Facility Code:	2150
Region: Jurisdiction:	North Fort McM R.C.S.S.I				Superindendent: Contact Person: Telephone:	Dam McIssac Bill Pringle (780) 799-5700
Grades:	K-VIII				School Capacity:	590
Building Section	Year of Compl.	No. of Floors	Gross Bldg Area (Sq.M.)	Type of Construction (i.e., structure, roof, cladding)	Description of Mechanical Systems (incl. major upgrades)	Comments/Notes
Original Building	1980	1	2368.83	Masonry/Metal Clad Fascia/4 Ply BUR	Two coppertube heating boilers. 100% standby circ pumps, reverse return piping systems, radiation. Two built up air system. Pneumatic controls.	In general well constructed functional building. Finishes are tired and in need of a complete paint job.
Additions/ Expansions	1982	1	1557	To match above.	One built up air system for classrooms and gas fired unit for Industrial Arts. Industrial Arts reduced in size. Gas fired unit reused for ventilation. Radiant panels installed.	

Evaluator's Name: Kim Ziola/Brinsmead Ziola Associates & Company:

Upgrading/ Modernization (identify whether minor or major)						
Portable Struct. (identify whether attached/perman. or free-standing/ relocatable)	1981	6	770.63	Attached/Permanent	Gas fired furnace complete with Dx cooling coil for each portable.	

Supplementary	Standard Assessment & Utilization Report Fire Inspection Report 98/11/11 Roofing Report 99/12/01

School Facility Evaluation Project Part I - Facility Profile and Summary

Evaluation Components	Summary Assessment	Estim. Cost
Site Conditions	Adequate. Poor soil conditions to yard and asphalt areas that cannot be corrected for reasonable expenditure.	
Building Exterior	Roof Maintenance required. Roofing replacement should be scheduled in 2 to 4 years. (\$305,000)	\$4,200.
Building Interior	Fair condition. Tired finishes could benefit from clean up and paint job.	
Mechanical Systems	Systems in general in good condition. Some plumbing fixture brass high maintenance and should be replaced. Combustion air requires upgrade.	\$43,000.
Electrical Systems	The electrical power distribution system appears to be in good condition and is adequate for present and future loads. Lighting throughout the school generally appears adequate. All remaining systems appear to be adequate for present use and in good condition. Regular maintenance is being carried out as required.	\$55,000.
Portable Buildings	Remove and install equipment which will provide required outdoor air to maintain acceptable CO2 levels.	\$112,000
Space Adequacy:		
7.1 Classrooms		
7.2 Science Rooms/Labs		
7.3 Ancillary Areas		
7.4 Gymnasium		
7.5 Library/Resource Areas		
7.6 Administration/Staff Areas		
7.7 CTS Areas		
7.8 Other Non-Instructional Areas (incl. gross-up)		
Overall School Conditions & Estim. Costs		\$204,20

	Site Conditions	Rating	Comments/Concerns	Estim. Cost
1.1	General Site Condions			
1.1.1	Overall site size.	4	Adequate size.	
1.1.2	Outdoor athletic areas.	4	Adequate size.	
1.1.3	Outdoor playground areas, including condition of equipment and base.	4		
1.1.4	Site landscaping.	4		
1.1.5	Site accessories (i.e., perimeter and other fencing, guard rails, bike stands, flag poles).	4		
	Surface drainage conditions (i.e., drains away from building, signs of ponding).	4	Maintenance on east sidewalk completed due to soil subsistence. Poor 'muskeg' type soil conditions.	
1.1.7	Evidence of sub-soil problems.	4	Poor soil type makes proper drainage a problem. No reasonable economic solution.	
1.1.8	Safety and security concerns due to site conditions.	4	Some evidence of vandalism but no serious concerns expressed by maintenance or school personnel.	
Other				
1.2	Access/Drop-Off Areas/Roadways/Bus Lanes			

	Site Conditions	Rating	Comments/Concerns	Estim. Cost
1.2.1	Vehicular and pedestrian access points (i.e., size, number, visibility, safety).		Limited bus drop off area. Standard congestion problems. No exceptional concerns.	
		4		
1.2.2	Surfacing of on-site road network (note whether asphalt or gravel).		Paved parking area.	
		4		
1.2.3	Bus lanes/drop-off areas (note whether on-site or off- site).		On site. Limited size.	
		4		
1.2.4	Fire vehicle access.			
		4		
1.2.5	Signage.			
		4		
Other				

	Site Conditions	Rating	Comments/Concerns	Estim. Cost
	Parking Lots and Sidewalks			
1.3.1	Number of parking spaces for staff, students and visitors (including stalls for disabled persons).	4	50 stalls inclusive of H.C.	
1.3.2	Layout and safety of parking lots.	4	Satisfactory.	
1.3.3	Surfacing and drainage of parking lots (note whether asphalt or gravel).	4	Asphalt. Drainage acceptable.	
1.3.4	Layout and safety of sidewalks.	4		
1.3.5	Surfacing and drainage of sidewalks (note type of material).	4	Concrete.	
1.3.6	Curb cuts and ramps for barrier free access.	4		
Other				
	Overall Site Conditions & Estimated Costs			

Part I - Facility Profile and Summary

St. Gabriel School 12/15/99

ection 2	Building Exterior	Rating		Comments/Concerns	Estim. Cost
2.1	Overall Structure		Bldg.		
2.1.1	Floor structure and beams (i.e., signs of bending, cracking, heaving, settlement, voids, rust, stains).		Section	Description/Condition No visible problems.	
		4	80 82 81		
2.1.2	Wall structure and columns (i.e., signs of bending, cracking, settlement, voids, rust, stains).				
		4	80 82 81		
2.1.3	Roof structure (i.e., signs of bending, cracking, voids, rust, stains).				
		4	80 82 81		
Other					

Roofing and Skylights				Estim. Cost
dentify the availability of an up-to-date inspection report or roofing program. Note if roof sections are of different ages and/or in varying states of repair.		Bldg. Section or Roof <u>Section</u>	Description/Condition/Age	
Based on the inspection report (and to the extent possible, direct observation), assess and rate roof conditions and estimate costs for required mprovements (i.e., covering materials, membrane, nsulation, other components).		80	See roof report. Rated roof as in poor to fair condition and should be scheduled for re-roofing in 2 to 4 years. Recommended immediate maintenance as follows: - regravel bare spots - repair all buckle and blisters - repair membrane flashing at gravel stop detail - reinstall base flashing where metal has dropped below counter flashing - recaulk reglet flashings and storm collars - clean debris.	(305,000.00
	3	82 81) \$ 4,200.00
Roof accessories (i.e., ladders, stairs, hatches, masts, exhaust hoods, chimneys, gutters, downspouts, eplashpads).	4	80 82 81		
Control of ice and snow falling from roof.	4		No reported problem areas.	
Skylights (i.e., signs of distress, leaks, ice build-up, condensation, deteriorated materials/seals).	N/A			
	xhaust hoods, chimneys, gutters, downspouts, plashpads). control of ice and snow falling from roof. kylights (i.e., signs of distress, leaks, ice build-up,	toof accessories (i.e., ladders, stairs, hatches, masts, xhaust hoods, chimneys, gutters, downspouts, plashpads). 4 control of ice and snow falling from roof. 4 kylights (i.e., signs of distress, leaks, ice build-up, ondensation, deteriorated materials/seals).	toof accessories (i.e., ladders, stairs, hatches, masts, xhaust hoods, chimneys, gutters, downspouts, plashpads). 80 toof accessories (i.e., ladders, stairs, hatches, masts, xhaust hoods, chimneys, gutters, downspouts, plashpads). 4 toof accessories (i.e., signs of distress, leaks, ice build-up, ondensation, deteriorated materials/seals). 4	 reinstall base flashing where metal has dropped below counter flashing - recaulk reglet flashings and storm collars clean debris. 3 82 81

Part I - Facility Profile and Summary

Section 2 Building Exterior Rating Comments/Concerns Estim. Cost 2.3 Exterior Walls/Building Envelope Bldg. Section **Description/Condition** 2.3.1 Exterior wall finishes (i.e., signs of deterioration, cracks, Masonry with metal fascia. No evident problem areas. brick spalling, effluorescence, water stains). 80 4 82 81 2.3.2 Fascias, soffits, parapets (i.e., signs of looseness, stains, rust, peeling paint). 80 82 4 81 2.3.3 Building envelope (i.e., evidence of air infiltration/ exfiltration through the exterior wall or ice build up on wall, eaves, canopy). 80 82 4 81 2.3.4 Interface of roof drainage and ground drainage No reported problems. systems. 4 2.3.5 Inside faces of exterior walls (i.e., signs of cracks, water No visible signs of deterioration. stains, dust spots). 4 Other 2.4 Exterior Doors and Windows Bldg. Section Description/Condition

Section 2	Building Exterior	Rating		Comments/Concerns	Estim. Cost
2.4.1	Doors (i.e., signs of deterioration, rusting metal, glass cracks, peeling paint, damaged seals, sealed unit failure).	4	80 82 81	Metal doors. Maintenance program has kept doors in reasonable operating condition.	
2.4.2	2 Door accessories (i.e., latches, hardware, screens, locks, alarms, holders, closers, security devices).	4	80 82 81	Reasonable operating condition.	
2.4.3	B Exit door hardware (i.e., safety and/or code concerns).	4	80 82 81	Appears to be code compliant.	
2.4.4	Windows (i.e., signs of deterioration, rusting metal, glass cracks, peeling paint, damaged seals, sealed unit failure).	4	80 82 81	Aluminum frame/sealed units.	
2.4.5	Window accessories (i.e., latches, hardware, screens, locks, alarms, holders, closers, security devices).	4	80 82 81	Good condition.	
2.4.6	Building envelope (i.e., signs of heavy condensation on doors or windows).	4	80 82 81	No signs of problem areas. No reported problems.	
Other	r				
	Overall Bldg Exterior Condition & Estim Costs				\$4,200.00

	Building Interior - Overall Conditions	Rating		Comments/Concerns	Estim. Cost
	Interior Structure		Bldg. Section	Description/Condition	
3.1.1	Interior walls and partitions (i.e., signs of cracks, spalling, paint peeling).		80/82	Masonry. Some evidence of very minor cracks.	
		4	81	Gypsum Board.	
3.1.2	Floors (i.e., signs of cracks, heaving, settlement).			No serious problems evident.	
		4	80 82 81		
Other					
					-
	Materials and Finishes		Bldg. Section	Description/Condition	
3.2.1	Floor materials and finishes.				
		4	80/82 81	Lino-carpet in minor areas. VCT.	
3.2.2	Wall materials and finishes.				
		4	80/82 81	Masonry and Gypsum Board. Gypsum Board.	
			01	Very tired but functional. Recommend a clean-up and paint throughout.	
3.2.3	Ceiling materials and finishes.				
		4		T-bar. T-bar.	
3.2	Materials and Finishes (cont'd)		Bldg.		

Part I - Facility Profile and Summary

St. Gabriel School 12/15/99

	Building Interior - Overall Conditions	Rating		Comments/Concerns	Estim. Cost
3.2.4	Interior doors and hardware.	4	80/82 81	S.C. Wood Reasonable condition. S.C. Wood Reasonable condition.	_
3.2.5	Millwork	4	80/82 81	Functional - some modification to Home Ec. By school board completed.	
3.2.6	Fixed/wall mounted equipment (i.e., writing boards, tackboards, display boards, signs).	4	80/82 81	Functional.	
3.2.7	Any other fixed/mounted specialty items (i.e., CTS equipment, gymnasium equipment).	4	80/82 81	Functional.	
3.2.8	Washroom materials and finishes.	4	80/82 81	New vanities and clean up by school board.	
Other					
3.3	Health and Safety Concerns Intent is to identify renovations considered necessary to meet applicable codes, primarily due to safety concerns. Basis of evaluation should be an up-to-date inspection report from the authority having jurisdiction together with direct observations as appropriate. Evaluator should note if in his opinion a comprehensive code evaluation is required.		Bldg. <u>Section</u>	Description/Condition	

	Building Interior - Overall Conditions	Rating		Comments/Concerns	Estim. Cost
3.3.1	Building construction type - combustible or non- combustible, sprinklered or non-sprinklered.	4	80/82 81	Non combustible/Non sprinklered.	
3.3.2	Fire separations (i.e., between buildings, wings, zones if non-sprinklered).	4	80/82 81	Appear to comply with code.	
3.3.3	Fire resistance rating of materials (i.e., corridor walls and doors).	4	80/82 81	Appear adequate.	
3.3.4	Exiting distances and access to exits.	4	80/82 81	Appear to provide reasonable and safe egress.	
3.3.5	Barrier-free access.	4	80/82 81	All areas accessible.	
3.3.6	Availability of hazardous materials audit (i.e., evidence of safety concerns with respect to asbestos, PCB's, chemicals).	4	80/82 81	No report available. No concerns raised through interview process.	
3.3.7	Other health and safety concerns (i.e., evidence of excessive noise conditions, air quality problems)	4	80/82 81	No concerns raised.	
Other					
	Overall Bldg Interior Condition & Estim Costs				

	Mechanical Systems	Rating	Comments/Concerns	Estim. Cost
	Mechanical Site Services			
	Site drainage systems (i.e., surface and underground systems, catch basins).			
	Exterior plumbing systems (i.e., irrigation systems, hose bibs).	4	Non freeze hose bibbs. No vacuum breakers. Irrigation system with backflow preventor.	
4.1.3	Outside storage tanks.		N/A	
Other				
4.2	Fire Suppression Systems		Bldg. Section Description/Condition	
4.2.1	Fire hydrants and siamese connections.	4	Fire hydrant located within 90 m of front entrance.	LI
4.2.2	Fire suppression systems (i.e., pumps, sprinklers, piping, reservoirs, hoses, stand pipes, CO2 systems).		N/A	
	Hand extinguishers, blankets and showers (i.e., in CTS areas).	4	A.B.C. and pump tank fire extinguishers. Science room complete with fire blanket and portable eye wash.	
4.2.4	Other special situations (e.g., flammable storage areas, science labs, CTS areas).			
Other				

	Mechanical Systems	Rating		Comments/Concerns	Estim. Cost
4.3	Water Supply and Plumbing Systems		Bldg. Section	Description/Condition	
4.3.1	Domestic water supply (i.e., pressure, volume, quality - note whether municipal or well supply).	4		100 mm water service connected to City main. Pressure and volume adequate.	
4.3.2	Water treatment system(s).			None.	
4.3.3	Pumps and valves (including backflow prevention valves).	4		No system pumps. Valves appear to be in good condition. No leaks.	
4.3.4	Piping and fittings.	4		Sewer piping - cast iron and copper. Domestic water - copper.	
4.3.5	Plumbing fixtures (i.e., toilets, urinals, sinks)	4		Flush valve water closets and urinals. Time delay faucets on lavs, S.S. sinks. Showers with central tempered mix valve.	
4.3.6	Domestic hot water system (i.e., heater, storage tanks, failure alarms, pressure, volume, recirculation).	4		Two (2) domestic H.W. heaters, complete with recirc pump. One heater valved off due to excess capacity.	
4.3.7	Sanitary and storm sewers, including sumps and pits (note whether sewage system is municipal or septic).	4		Separate sanitary and storm sewer systems connected to City mains.	
Other		3		Maintenance indicated time delay faucets are high maintenance item. Water temperature inadequate for good hygiene.	\$4,000.00

	Mechanical Systems	Rating		Comments/Concerns	Estim. Cost
4.4.1	Heating Systems Heating capacity and reliability (including backup capacity).	4	Bldg. <u>Section</u>	<u>Description/Condition</u> Two copper tube heating boilers, 1,630,000 BTU/hr each. Two 100% circulation pumps.	
4.4.2	Heating controls (including use of current energy management technology.	4		Boilers provided with integral controls to maintain heating system supply temperature.	
4.4.3	Fresh air for combustion and condition of the combustion chimney.	3		Combustion air and unit heater ductwork to assist in tempering the combustion air poorly terminated. Upgrade required.	\$2,000.00
4.4.4	Treatment of water used in heating systems.	4		Chemical pot feeder provided to add chemicals into heating system. Side stream filter assembly installed.	
	Low water cutoff/pressure relief valves and failure alarms (i.e., hot water heating).	4		L.W.C.O., pressure relief valve, high limit control provided.	
4.4.6	Heating air filtration systems and filters.			N/A	
4.4.7	Heating humidification systems and components.			N/A	

Part I - Facility Profile and Summary

St. Gabriel School 12/15/99

Section 4	Mechanical Systems	Rating		Comments/Concerns	Estim. Cost
	Heating Systems (cont'd) Heating distribution systems (i.e., piping, ductwork) and associated components (i.e., diffusers, radiators).	4	Bldg. <u>Section</u>	<u>Description/Condition</u> Reverse return black iron piping system to mechanical room unit heaters, air system heating coils, entrance heaters, reheat coils and 1995 upgrade radiant panels.	_
4.4.9	Heating piping, valve and/or duct insulation.	4		Heating piping and valve bodies insulated.	
4.4.10	Heat exchangers.			None.	
4.4.11	Heating mixing boxes, dampers and linkages.			None.	
4.4.12	Heating distribution/circulation in larger spaces (i.e., user comfort, temperature of outside wall surfaces).			N/A	
4.4.13	Zone/unit heaters and controls.			N/A	
Other					

	Mechanical Systems	Rating		Comments/Concerns	Estim. Cost
	Ventilation Systems Air handling units capacity and condition.	4	Bldg. <u>Section</u>	<u>Description/Condition</u> Three built up air systems provide ventilation air to 1980 original building and 1982 addition. Gas fired rooftop air system which formerly supplied ventilation air to Industrial Arts area was reused to ventilation CTS renovation.	
4.5.2	Outside air for the occupant load (if possible, reference CFM/occupant).	3		Outside air volume of 3.8 l/s per person appears to be maintained when only the classroom air systems are energized. Outdoor air volume not sufficient for the occupant load.	
4.5.3	Air distribution system (if possible, reference number of air changes/hour).	4		Low velocity ductwork distribution to round ceiling diffusers, sidewall grilles and high throw grilles in gymnasium.	
4.5.4	Exhaust systems capacity and condition.	4		Roof mounted exhaust fans, condition good.	
4.5.5	Separation of out flow from air intakes.			Good.	
4.5.6	Special/dedicated ventilation and/or exhaust systems (i.e., kitchen, labs, CTS areas).			N/A	
Other					
4.5	Ventilation Systems (cont'd) Note: Only complete the following items if there are separate ventilation and heating systems.		Bldg. <u>Section</u>	Description/Condition	

	Mechanical Systems	Rating	Comments/Concerns	Estim. Cost
4.5.7	Ventilation controls (including use of current energy management technology).	4	Air systems activated via central time clock. Override timers provided to allow time clock override.	
4.5.8	Air filtration systems and filters.	3	Low efficiency pad filters. Upgrade to pleated filters.	
4.5.9	Humidification system and components.	4	Electric canister humidifiers with steam grid. Not in operation due to reduction in maintenance budgets.	
4.5.10	Heat exchangers.		None.	
4.5.11	Ventilation distribution system and components (i.e., ductwork, diffusers, mixing boxes, dampers, linkages).	4	Three built up air systems consisting of supply and return fans, mixed air dampers, heating coil in the return air, low efficiency pad filters. Low velocity ductwork distribution to round ceiling diffusers, sidewall grilles and high throw grilles in gymnasium. Gymnasium ducted return. Other systems ceiling space return.	
Other				

	Mechanical Systems	Rating		Comments/Concerns	Estim. Cost
	Cooling Systems Cooling system capacity and condition (i.e., chillers,		Bldg. <u>Section</u>	Description/Condition N/A	
	cooling towers, condensers).				
4.6.2	Cooling distribution system and components (i.e., ductwork, diffusers, mixing boxes, dampers, linkages)			N/A	
	Cooling system controls (including use of current energy management technology).			N/A	
4.6.4	Special/dedicated cooling systems (i.e., labs, CTS areas).			N/A	
Other					
4.7	Building Control Systems		Bldg.		
				Description/Condition	
4.7.1	Building wide/system wide control systems and/or energy management systems.			Duplex air compressor complete with refrigerated air dryer. Manual adjustment of humidity and discharge air temperature setpoints at local control panels. Day/night thermostats. Installation of building management system would reduce maintenance costs and reduce utilities.	\$35,000.00
			3		
			-		
	Overall Mech Systems Condition & Estim. Costs		4		\$35,000.0

Part I - Facility Profile and Summary

St. Gabriel School 12/15/99

Section 5	Electrical Systems	Rating	Comments/Concerns	Estim. Cost
	Site Services Primary service capacity and reliability (i.e., access, location, components, installation, bus sizes - note whether overhead or underground).	4	The incoming underground power service to the school originates from an Alberta Power padmounted transformer and terminates in a 800 A, 120/208 V 3 phase, 4 wire Westinghouse Main Distribution Panel (MDP) located in the main electrical room and was installed in 1980. The existing service has sufficient capacity to accommodate additional loads.	
5.1.2	Site and building exterior lighting (i.e., safety concerns).	4	Exterior lighting consists of pole and wall mounted HID luminaires located in the parking lot and around the perimeter of the building. According to the users, pedestrian routes and parking lot are adequately illuminated and in good working condition.	
5.1.3	Vehicle plug-ins (i.e., number, capacity, condition).	4	The parking lot electrical plug-ins service is comprised of 52 stalls and is in good working condition.	
Other				
5.2	Life Safety Systems		Bidg.	
5.2.1	Fire and smoke alarm systems (i.e., safety concerns, up- to-date technology, regularly tested).	3	Section Description/Condition The existing fire alarm system is manufactured by Edwards, Model 7600, hardwired, supervised system. The 6500 series system is no longer manufactured, however, it is still serviceable. The existing fire alarm system does not make use of current technologies. System is regularly tested and has been verified in 1999.	\$30,000.00
5.2.2	Emergency lighting systems (i.e., safety concerns, condition).	4	Emergency lighting is provided by integral and remote heads powered by battery packs located throughout the school and are in satisfactory condition. Placement and location of emergency lighting units appears adequate and in good working condition.	
5.2.3	Exit lighting and signage (i.e., safety concerns, condition).	4	Exit lights are stencil faced internally illuminated exit signs. The exit lights are 120 volt AC and 12 volt DC emergency. Some exit signs that were checked had burnt out AC lamps.	
Other				

Part I - Facility Profile and Summary

St. Gabriel School 12/15/99

	Electrical Systems	Rating		Comments/Concerns	Estim. Cost
	Power Supply and Distribution Power service surge protection.		Bldg. Section	Description/Condition	
		4		Main distribution panel is equipped with transient surge suppressor.	
5.3.2	Panels and wireways capacity and condition.	4		Branch circuit panels are located throughout the school. Most of the panels have spaces available and have sufficient capacity to accommodate additional loads, and are in good operating condition. (If additional computer outlets are required in all classrooms, additional duplex receptacles are to be installed.)	
5.3.3	Emergency generator capacity and condition and/or UPS (if applicable).				
		NA		The facility is not equipped with an emergency power system.	
5.3.4	General wiring devices and methods.				
		4		The facility is equipped with both convenience and dedicated duplex receptacles. Duplex receptacles are provided throughout the school. The number of receptacles in classrooms are generally satisfactory.	
5.3.5	Motor controls.				
		4		Motors starters appear to be in good operating condition.	
Other					

	Electrical Systems	Rating	Comments/Concerns	Estim. Cost
	Lighting Systems Interior lighting systems and components (i.e., illumination levels, conditions, controls).	4	Description/Condition Lighting throughout the school is primarily fluorescent the number and location of luminaires are appropriate and adequate for the functions. Lighting levels in the facility appeared to be acceptable according to maintenance staff most of the lamps are T12, warm white and electronic ballasts. Local line voltage switching is provided. The classrooms have multi-level switching. The majority of the fluorescent luminaires are in satisfactory condition.	
5.4.2	Replacement of ballasts (i.e., health and safety concerns).	NA		
5.4.3	Implementation of energy efficiency measures and recommendations.	3	Install motion sensors in washrooms, storage and utility rooms. Retrofit existing luminaires with highly reflective reflectors. Reduce the number of luminaires.	\$10,000.00
Other				

tion 5	Electrical Systems	Rating		Comments/Concerns	Estim. Cos
	Network and Communication Systems		Bldg. Section	Description/Condition	
5.5.1	Telephone system and components (i.e., capacity, reliability, condition).	4		The existing telephone distribution system consist of conduit and wire to telephone outlets throughout the facility. The system is in good condition and has capacity for expansion.	
5.5.2	Other communication systems (i.e., public address, intercom, CCTV, satellite or cable TV).	4		The school is equipped with a sound communication system. Return calls and speakers are provided in the classrooms. The gymnasium is served by a separate sound system. Television distribution system is provided throughout the school. All communication systems appear to be in satisfactory operation condition.	
5.5.3	Network cabling (if available, should be category 5 or better).	3		Network cabling consists of Category 3 cables. We recommend that the existing network cabling be replaced with Category 5E.	\$15,000.0
5.5.4	Network cabling installation (i.e., in conduit, secured to walls or tables).	4		All methods of supports are used.	
5.5.5	Wiring and telecommunication closets (i.e., size, security, ventilation/cooling, capacity for growth).	4		Size is adequate. Doors are locked and some ventilation provided. Acceptable capacity for growth.	
5.5.6	Provision for dedicated circuits for network equipment (i.e., hubs, switches, computers).	FI		Cannot determine without more investigation. Tracing of wiring and circuits is required.	
Other					

Section 5	Electrical Systems	Rating	Comments/Concerns	Estim. Cost
5.6	Miscellaneous Systems		Bldg.	
5.6.1	Site and building surveillance system (if applicable).		Section Description/Condition	
			None existing.	
5.6.2	Intrusion alarms (if applicable).	4	The school is equipped with a passive infrared security system consisting of an exit / entry touchpads and a control panel located in the main electrical room. The system is a DSC Digital PC 4000 Security System. Motion sensors are located in the corridors and selected classroom. The system is in good working condition.	
	Master clock system (if applicable).	4	The school is equipped with a Simplex 2350 master program clock (MPC) located in general office. The MPC controls the Time Changes Signal, horns and clocks. Synchronous clocks are utilized throughout the school. The system is in good working condition.	
Other				
5.7	Elevators/Disabled Lifts (If applicable)			
	Elevator/lift size, access and operating features (i.e., sensing devices, buttons, phones, detectors).		The facility is not equipped with an elevator or lift.	
5.7.2	Condition of elevators/lifts.			
			Not applicable.	
5.7.3	Lighting and ventilation of elevators/lifts.			
			Not applicable.	
Other				
	Overall Elect. Systems Condition & Estim Costs			

ction 6	Portable Buildings	Rating	Comments/Concerns	
	Note: Separate sheets can be completed, if necessary, for portable buildings of different ages and/or conditions.	4	Reasonable condition/functional. Cleaning/painting.	
	Foundation and structure (i.e., signs of bending, cracking, settlement, rust, voids, stains).	4	No visible signs of distress.	
	Roof materials and components (i.e., signs of deterioration, leaks, ice build-up).	3	Maintenance required. New roof 2 to 4 years. See roof report. Cost included in 2.2.1	
6.1.3	Exterior wall finishes (i.e., signs of deterioration, cracks, water stains).	4	No visible signs of problem areas.	
6.1.4	Doors and windows (i.e., signs of deterioration, rusting hardware, glass cracks, peeling paint, damaged seals).	4	Functional.	
6.1.5	Interior finishes (i.e., floors, walls, ceiling).	4	Functional but tired.	
6.1.6	Millwork (i.e., counters, shelving, vanities, cabinets).	4	See note above.	
	Fixed/wall mounted equipment (i.e., writing boards, tackboards, display boards, signs)	4	Adequate.	
6.1.8	Heating system.	3	Palm Air vertical furnace package with distribution duct and grilles. Provided with Dx cooling coil and remote condensing unit. No outside air for occupant load during extreme outside temperatures. Replace units.	\$112,000.0
6.1.9	Ventilation system.		Same as heating.	
6.1.10	Electrical, communication and data network systems.	4	Lighting throughout the portables generally appears adequate and in fair condition. The branch circuit panels appear to be in good condition and adequate for present use all remaining system appear to be satisfactory.	
	Health and safety concerns (i.e., fire and smoke alarms, fire protection systems, exiting, fire resistance rating of materials).	4	A.B.C. fire extinguishers.	
6.1.12	Barrier-free access.	4	Adequate.	
	Overall Portable Bldgs Condition & Estim Costs	3		\$112,000.00

St. Gabriel School 12/15/99

			This Fa	cility	Equiv. New Facility			Surplus/	
Section 7	Space Adequacy	No.	Size	Total Area	No.	Size	Total Area	Deficiency	Comments/Concerns
	Classrooms	8	1@ 66.88 1@ 69.04 5@ 70.0 1@73.4	559.4	9	80	720	-160.6	Based on 390 capacity on permanent 400 core.
7.2	Science Rooms/Labs	2	1@ 79.30 1@ 93.04	172.34	3	95	285	-112.66	
7.3	Ancillary Areas (i.e., Art, Computer Labs, Drama, Music,)	5	1@ 80.90 1@ 84.30 5@ 97.58 1@115.10 1@ 147.60	525.48	4	1@130 3@90	400	125.48	
7.4	Gymnasium (incl. gym storage)		1@ 412.3 1@ 35.2	447.5		1@ 430 1@ 43	473	-25.5	
7.5	Library/Resource Areas		1@ 197.0 1@ 30.0	227		1@ 260	260	-33	
7.6	Administration/Staff, Physical Education, Storage Areas			332.42			502	-169.58	
7.7	CTS Areas 7.7.1 Business Education								
	7.7.2 Home Economics	-	-	-	-	-	-	-	
		1	140	140	0	0	0	140	
	7.7.3 Industrial Arts	1	200	200	0	0	0	200	
	7.7.4 Other CTS Programs	-	-	-	-	-	-	-	
7.8	Other Non-Instructional Areas (i.e., circulation, wall area, crush space, wc area)	Indete	rminent					1008	
	Overall Space Adequacy Assessment								

Evaluation Component/ Sub-Component	Additional Notes and Comments

Evaluation Component/ Sub-Component	Additional Notes and Comments

Evaluation Component/ Sub-Component	Additional Notes and Comments

Evaluation Component/ Sub-Component	Additional Notes and Comments

Evaluation Component/ Sub-Component	Additional Notes and Comments

Evaluation Component/ Sub-Component	Additional Notes and Comments