

School Name: St. Francis Xavier Catholic School

Location: 9250 163 Street

Edmonton, Alberta

Region: Central

Jurisdiction: Edmonton Catholic Regional School

Division No. 40

Grades: 10 to 12

School Code: 8405

Facility Code: 2056

Superintendent: Dr. Dale W. Ripley

Contact Person: Mr. Garnet McKee

Telephone: 1-780-453-4500

School Capacity: 1030

| Building Section | Year of Compl | No. of Floors | Gross Bldg Area (Sq.M.) | Type of Construction (i.e., structure, roof, cladding) | Description of Mechanical Systems (incl. major upgrades) | Comments/Notes |
|-----------------------|---------------|---------------|-------------------------|--|--|---|
| Original Building | 1958 | One | 2500.0 | Wood frame walls and roof on cast-in-place concrete foundations. Exterior walls are finished with plaster / gypsum board on the interior and brick veneer on the exterior. Roofing is built-up asphalt and gravel on insulated wood deck. Underside of roof structure is finished with 12" x 12" ship-lap edge acoustic ceiling tiles. | There are 13 furnaces (3 per classroom/ limited fresh air/ poor condition). There is no humidification and no cooling. The boilers are original | The heating and ventilating systems are in poor condition and should be upgraded. |
| Additions/ Expansions | 1963 | One / Two | 2860.9 | Plexi-core panels supported on load-bearing concrete block and cast-in-place concrete foundations. Exterior walls are painted concrete block (interior) and brick veneer (exterior) cavity walls. Roofing is built-up asphalt and gravel. Ceilings in this section are either painted plaster / gypsum board or suspended tee-bar grid with lay-in acoustic tiles. | See above | The heating and ventilating systems are in poor condition and should be upgraded. |

Evaluator's Name: Merv Weiss & James Dykes

& Company: Kasian Kennedy

| Building Section | Year of Compl | No. of Floors | Gross Bldg Area (Sq.M.) | Type of Construction (i.e., structure, roof, cladding) | Description of Mechanical Systems (incl. major upgrades) | Comments/Notes |
|---|---------------|---------------|-------------------------|---|---|---|
| Additions/ Expansions (cont'd) | 1968 | One / Two | 4152.4 | Steel deck on open-web steel joists and steel beams on load-bearing concrete block on cast-in-place concrete foundations. Exterior walls are painted concrete block (interior) and brick veneer (exterior) cavity walls. Roofing is built-up asphalt and gravel. Ceilings in this section are either suspended gypsum board or suspended tee-bar grid with lay-in acoustic tiles. | See above. | The heating and ventilating systems are in poor condition and should be upgraded. |
| | 1996 | Two | 691.6 | Steel deck on open-web steel joists and steel beams supported by steel columns and load bearing masonry. There are no exterior walls to this area of the building. Perimeter walls are the old exterior walls of the school. Roofing is a sloped glazing system with aluminum frames. This section appears to have been a courtyard previously. | Good condition. Cooling has been provided to the cafeteria. | |
| Upgrading/ Modernization (identify whether minor or major) | 1994 | | | Central control desk added to Library. Library Offices converted to a Conference Room. | | Major Upgrading |
| | 1994 | | | Industrial Arts area renovated. A portion of the space was converted into a computer area and C.T.S. lab. | | Major Modernization |
| | 1998 | | | Industrial Arts construction and fabrication lab upgraded. | | Major Upgrading |

| Building Section | Year of Compl | No. of Floors | Gross Bldg Area (Sq.M.) | Type of Construction (i.e., structure, roof, cladding) | Description of Mechanical Systems (incl. major upgrades) | Comments/Notes |
|---|---------------|---------------|-------------------------|---|--|----------------|
| Portable Struct. (identify whether attached/perman. or free-standing/relocatable) | | | 261.0 | There are three portables at this school. Two of these are arranged as a pod and share a common foyer and washrooms. The Division identifies these units as Portable No. 79 and Portable No. 80. The third portable is a stand alone unit. The Division identifies this unit as Portable No. 188. | | |

| | | | | | | |
|--|---|--|--|--|--|--|
| List of Reports/ Supplementary Information | <p>Leased out area = 0 Gross Capacity = 1030 - 45 for program exemptions = 985 Net Capacity Current Enrollment = 1048 or 106.4% of net capacity</p> | | | | | |
|--|---|--|--|--|--|--|

| | Evaluation Components | Summary Assessment | Estim. Cost |
|---|---|--|-------------|
| 1 | Site Conditions | With the exception of the grassed area and retaining wall east of the building, site conditions are good. There are some deficiencies which are described later in the report. | \$142,500 |
| 2 | Building Exterior | The building exterior is primarily brick veneer and is generally in good condition. There is a severe settlement problem at this school however, which will be detrimental to the exterior finishes of the building in the near future. | \$60,000 |
| 3 | Building Interior | The building interior has some problems. There are many areas where floor finishes should be replaced as they have exceeded their life expectancy. Wall finishes are in good condition where the settlement problem mentioned previously has not caused them to crack and shift. Lay-in acoustic ceiling tiles should be replaced in many areas of the building because they are broken, stained, or have deteriorated to the point where they may fall out of the grid. | \$299,000 |
| 4 | Mechanical Systems | Site drainage should be improved. The heating and ventilating systems are in poor condition and should be upgraded. There is no humidification and only limited cooling in this school. Plumbing in the labs should be corrected. | \$490,000 |
| 5 | Electrical Systems | Many of the panels are full, antiquated and/or obsolete and should be replaced. Receptacles in the 1958 section are damage, circuits are overloaded and breakers are constantly tripping. A total lighting upgrade is required for this school. | \$378,500 |
| 6 | Portable Buildings | All portables are in fairly good condition. The pod consisting of Portable No. 79 and Portable No. 80 should have its vinyl composite tile flooring replaced and should have its lay-in acoustic ceiling tiles replaced. Portable No. 188 has no notable deficiencies. | \$7,500 |
| 7 | Space Adequacy: 7.1 Classrooms | -178.7 | |
| | 7.2 Science Rooms/Labs | 60 | |
| | 7.3 Ancillary Areas | 52.6 | |
| | 7.4 Gymnasium | -590.8 | |
| | 7.5 Library/Resource Areas | -127.9 | |
| | 7.6 Administration/Staff Areas | 674 | |
| | 7.7 CTS Areas | 284.4 | |
| | 7.8 Other Non-Instructional Areas (incl. gross-up) | 918.3 | |
| | Overall Space Adequacy Assessment | 1091.9 (Leased out area = 0) | |
| | Overall School Conditions & Estimated Costs | | \$1,377,500 |

| Section 1 | Site Conditions | Rating | Comments/Concerns | Estimated Cost |
|------------|---|--------|--|-------------------|
| 1.1 | General Site Conditions | | | \$125,000 |
| 1.1.1 | Overall site size. | 4 | The site is too small for a school of this size. Many activities are conducted off-site because the on-site facilities are inadequate. | |
| 1.1.2 | Outdoor athletic areas. | 4 | There is a football field and two soccer fields on site to the west of the school. There is also a baseball / fastball diamond on site to the west of the building. All are in good condition. | |
| 1.1.3 | Outdoor playground areas, including condition of equipment and base. | 4 | Acceptable | |
| 1.1.4 | Site landscaping. | 3 | Site landscaping is in fairly good condition with the exception of the lawn between the building and the east property line. This is in poor condition, probably due to the movement it is experiencing as the retaining wall at the east property line collapses. | \$5,000 |
| 1.1.5 | Site accessories (i.e., perimeter and other fencing, guard rails, bike stands, flag poles). | 2 | Perimeter fencing is in good condition everywhere except along the east property line. At this location there is a steel post and rail fence on top of a brick veneered retaining wall. The retaining wall is leaning over the City Of Edmonton sidewalk along the entire length of the east property line and is failing structurally. Photo No. 10 and Photo No. 11 show the condition of the fence and retaining wall at this location. A handrail is missing at the north stairs on the east property line. This is shown in Photo No. 14. | \$95,000 |
| 1.1.6 | Surface drainage conditions (i.e., drains away from building, signs of ponding). | 3 | Surface drainage conditions at the site are marginal. There is little or no positive slope away from the entire north side of the building. The existing conditions in this area are shown in Photo No. 15. The area east of the building is constantly shifting and changing the drainage flow as a result. Downspouts from the roof surface discharge into this grassed area causing an erosion problem. This condition is shown in Photo No. 9 | \$25,000 |
| 1.1.7 | Evidence of sub-soil problems. | 4 | There is little evidence of sub-soil problems on the exterior of the building. The one exception to this is the pending collapse of the retaining wall at the east property line. With the amount of settlement happening inside the building, one would expect the grade beams to be spalling and the brick veneer to be cracking. There is only minor evidence of grade beam stress on the west side of the original (1958) section of the building as shown by Photo No. 24. | |
| 1.1.8 | Safety and security concerns due to site conditions. | 2 | The sidewalk along the north side of the building ices up badly. The condition of this sidewalk makes walking in this area treacherous. This walkway is situated between the parking lot and a primary building entrance and, as a result handles a lot of pedestrian traffic. Photo No. 16 shows the condition of the sidewalk in this area. | included in 1.1.6 |

| Section 1 | Site Conditions | Rating | Comments/Concerns | Estimated Cost |
|-----------|--|--------|---|----------------|
| Other | | | | |
| 1.2 | Access/Drop-Off Areas/Roadways/Bus Lanes | | | \$0 |
| 1.2.1 | Vehicular and pedestrian access points (i.e., size, number, visibility, safety). | 4 | There is only on on-site vehicular and pedestrian access point, that being the parking lot to the north of the building. This seems to function in an acceptable manner. | |
| 1.2.2 | Surfacing of on-site road network (note whether asphalt or gravel). | 4 | The on-site students and staff parking lot has an asphalt surface. The lot is served by two internal catch basins. The lot is accessible from 163 Street. | |
| 1.2.3 | Bus lanes/drop-off areas (note whether on-site or off-site). | 4 | There are no on-site bus lanes or bus passenger drop-off areas. The west curb of 163 Street is used for this purpose. There are no evident problems with this system. | |
| 1.2.4 | Fire vehicle access. | 4 | Fire vehicles can gain access to the entire perimeter of the building. The east elevation is accessible from 163 Street. The south elevation is accessible from the parking lot of the community swimming pool to the south. The north elevation is accessible from the staff and student parking lot to the north of the building. The west elevation is accessible from the vehicle service road which leads from the west end of the staff / student parking lot at the north end of the site. | |
| 1.2.5 | Signage. | 4 | There is building identification signage at both the east entrance to the 1963 section of the building and at the north east entrance to the 1968 section of the building. Both signs are visible to traffic on 163 Street. | |

| Section 1 | Site Conditions | Rating | Comments/Concerns | Estimated Cost |
|-----------|-----------------|--------|-------------------|----------------|
| Other | | | | |

| Section 1 | Site Conditions | Rating | Comments/Concerns | Estimated Cost |
|------------|--|--------|---|------------------|
| 1.3 | Parking Lots and Sidewalks | | | \$17,500 |
| 1.3.1 | Number of parking spaces for staff, students and visitors (including stalls for disabled persons). | 4 | There are approximately 70 on-site parking stalls for staff and students north of the school building. There is one designated parking stall for disabled persons in this lot. | |
| 1.3.2 | Layout and safety of parking lots. | 4 | There are no layout or safety concerns with the on-site parking lot. | |
| 1.3.3 | Surfacing and drainage of parking lots (note whether asphalt or gravel). | 4 | The on-site parking lot has an asphalt surface. There are no surface drainage concerns. | |
| 1.3.4 | Layout and safety of sidewalks. | 3 | The layout of sidewalks on the site is acceptable. Sidewalks to the east of the building are in poor condition and should be replaced along with the retaining wall. The sidewalk north of the building is cracked and broken and should be replaced. | \$10,000 |
| 1.3.5 | Surfacing and drainage of sidewalks (note type of material). | 3 | Sidewalks on the site have good drainage with the exception of the walk north of the building. The site should be re-graded in this area and the sidewalk re-constructed. | \$7,500 |
| 1.3.6 | Curb cuts and ramps for barrier free access. | 4 | There is a curb cut at the parking stall for disabled persons at the north east corner of the building. This entrance and the entrance west of the gymnasium are wheelchair accessible. | |
| Other | | | | |
| | Overall Site Conditions & Estimated Costs | | With the exception of the grassed area and retaining wall east of the building, site conditions are good. There are some deficiencies which are described later in the report. | \$142,500 |

| Section 2 | Building Exterior | Rating | Comments/Concerns | | Estimated Cost |
|-----------|---|--------|-------------------------|--|--------------------|
| 2.1 | Overall Structure | | Building Section | Description/Condition | \$42,500.00 |
| 2.1.1 | Floor structure and beams (i.e., signs of bending, cracking, heaving, settlement, voids, rust, stains). | 2 | 1958 | The exterior walls of all classrooms in the original (1958) section of the building have settled. Classroom floors slope down anywhere from 4 to 8 inches across their width in this section of the building. Photos 18, 19, and 20 attempt to show this condition. | \$25,000.00 |
| | | | 1963 | The exterior walls on the south and west sides of the 1963 section of the building have settled. The problem is not quite as severe as it is in the 1958 section but, there is a major problem here just the same. Photos 28, 29, 30, and 31 show this condition. | \$15,000.00 |
| 2.1.2 | Wall structure and columns (i.e., signs of bending, cracking, settlement, voids, rust, stains). | 4 | All | There are numerous locations where the settlement described in section 2.1.1 has caused wall finishes to crack or buckle. There is no evidence that the structural integrity of the walls has been compromised. | |
| 2.1.3 | Roof structure (i.e., signs of bending, cracking, voids, rust, stains). | 4 | All | No problems to report. | |
| Other | | 3 | 1963 & 1968 | There is an expansion joint in the floor between the 1963 and 1968 sections of the building. The expansion joint has not been continued into the wall and ceiling finishes at this location and these have cracked. Photo No. 84 shows how the concrete block wall on the west side of the corridor has cracked. | \$2,500.00 |

| Section 2 | Building Exterior | Rating | Comments/Concerns | | Estimated Cost |
|-----------|---|--------|--|---|-------------------|
| 2.2 | Roofing and Skylights <i>Identify the availability of an up-to-date inspection report or roofing program. Note if roof sections are of different ages and/or in varying states of repair.</i> | | Building. Section or Roof Section | Description/Condition/Age | \$4,500.00 |
| 2.2.1 | Based on the inspection report (and to the extent possible, direct observation), assess and rate roof conditions and estimate costs for required improvements (i.e., covering materials, membrane, insulation, other components). | 2 | All | All roof surfaces are asphalt overlaid with concret masonry pavers. There is a great deal of vegetation establishing itself in the cracks between the pavers. The entire roof area should be treated with a herbicide in order to arrest this condition. Photo No. 71 shows an example of the roof surface. | \$3,500.00 |
| 2.2.2 | Roof accessories (i.e., ladders, stairs, hatches, masts, exhaust hoods, chimneys, gutters, downspouts, splashpads). | 3 | All | Roof accessories appear to be in acceptable condition. An internal access to the roof surfaces should be provided. | \$1,000.00 |
| 2.2.3 | Control of ice and snow falling from roof. | 4 | All | No areas of concern. Drainage from the 1958 section of the building is via external downspouts from the overhangs. Drainage from other sections of the building is internal. | |
| 2.2.4 | Skylights (i.e., signs of distress, leaks, ice build-up, condensation, deteriorated materials/seals). | 5 | 1996 | The 1996 section of the building has a sloped glazing system roof. There is no evidence of problems with this roof. | |
| Other | | | | | |

| Section 2 | Building Exterior | Rating | Comments/Concerns | | Estimated Cost |
|-----------|--|--------|-------------------------|---|----------------|
| 2.3 | Exterior Walls/Building Envelope | | Building Section | Description/Condition | \$500.00 |
| 2.3.1 | Exterior wall finishes (i.e., signs of deterioration, cracks, brick spalling, effluorescence, water stains). | 4 | All | No problems to report. | |
| 2.3.2 | Fascias, soffits, parapets (i.e., signs of looseness, stains, rust, peeling paint). | 4 | All | No problems to report. | |
| 2.3.3 | Building envelope (i.e., evidence of air infiltration/ exfiltration through the exterior wall or ice build up on wall, eaves, canopy). | 4 | All | No problems to report. | |
| 2.3.4 | Interface of roof drainage and ground drainage systems. | 3 | 1958 | Downspouts on the east side of the 1958 section of the building discharge into the grassed area between the building and the retaining wall at the east property line. Splashpads should be added at the base of all such downspouts in order to control the erosion of the soil. | \$500.00 |
| 2.3.5 | Inside faces of exterior walls (i.e., signs of cracks, water stains, dust spots). | 4 | 1963 & 1968 | There are areas where movement has caused some cracking where interior walls meet exterior walls. This is mainly evident at the 1963 and 1968 sections where these walls are concrete block. Photo No. 83 shows an example. | |

| Section 2 | Building Exterior | Rating | Comments/Concerns | | Estimated Cost |
|-----------|-------------------|--------|-------------------|--|----------------|
| Other | | | | | |

| Section 2 | Building Exterior | Rating | Comments/Concerns | | Estimated Cost |
|------------|---|--------|-------------------------|---|--------------------|
| 2.4 | Exterior Doors and Windows | | Building Section | Description/Condition | \$12,500.00 |
| 2.4.1 | Doors (i.e., signs of deterioration, rusting metal, glass cracks, peeling paint, damaged seals, sealed unit failure). | 4 | All | Routine general maintenance (painting) of exterior wood doors is required. All are in sound condition but, require re-finishing. | |
| 2.4.2 | Door accessories (i.e., latches, hardware, screens, locks, alarms, holders, closers, security devices). | 4 | All | No problems to report. | |
| 2.4.3 | Exit door hardware (i.e., safety and/or code concerns). | 4 | All | No problems to report. | |
| 2.4.4 | Windows (i.e., signs of deterioration, rusting metal, glass cracks, peeling paint, damaged seals, sealed unit failure). | 3 | All | Seals to 90 per cent of the operable window sections in the building are in poor condition and should be replaced. At least a dozen operable window sections have damaged sash and should be replaced. Photo No. 57 shows an example of damaged sash. Windows in the west wall of the 1958 section of the building are very difficult to operate due to the settlement. These windows will soon be completely inoperable. | \$7,500.00 |
| 2.4.5 | Window accessories (i.e., latches, hardware, screens, locks, alarms, holders, closers, security devices). | 3 | All | Window latches require adjustment throughout the school. Most are intact but are worn. About 20 per cent of the between-glass venetian blinds no longer function. | \$5,000.00 |
| 2.4.6 | Building envelope (i.e., signs of heavy condensation on doors or windows). | 4 | All | No problems to report. | |
| Other | | | | | |
| | Overall Building Exterior Condition & Estimated Costs | | | The building exterior is primarily brick veneer and is generally in good condition. There is a severe settlement problem at this school however, which will be detrimental to the exterior finishes of the building in the near future. | \$60,000.00 |

| Section 3 | Building Interior - Overall Conditions | Rating | Comments/Concerns | | Estimated Cost |
|-----------|---|--------|-------------------------|---|------------------|
| 3.1 | Interior Structure | | Building Section | Description/Condition | \$50,000 |
| 3.1.1 | Interior walls and partitions (i.e., signs of cracks, spalling, paint peeling). | 4 | 1958 | Interior walls and partitions in the 1958 section of the building are painted plaster / gypsum board. Other than some minor cracking, these are in good condition. | |
| 3.1.2 | Floors (i.e., signs of cracks, heaving, settlement). | 3 | All | Interior walls and partitions in the 1963, 1968, and 1996 sections of the building are painted concrete block or glazed concrete block. Other than some minor cracking, these are in good condition. | |
| | | | 1963 & 1968 | There are some locations where the grade supported slab has cracked. This is particularly noticeable at washrooms which have an epoxy floor finish where the cracking has telegraphed into the finish. | \$50,000 |
| Other | | | | | |
| 3.2 | Materials and Finishes | | Building Section | Description/Condition | \$101,000 |
| 3.2.1 | Floor materials and finishes. | 3 | 1968 | Epoxy floor finishes in the locker rooms and washrooms at the gymnasium should be overlaid with a similar finish. Photo No. 47 shows the damaged finish in this area. | \$40,000 |
| | | | 1963 | The hardwood stage floor should be re-finished. Photo No. 51 shows its existing condition. | \$1,000 |
| | | | All | Many classrooms, service rooms, and storage rooms have a vinyl asbestos tile floor finish. This type of tile should be replaced throughout the building. | |
| | | | 1958 & 1963 | Floor surfaces throughout the 1958 and 1963 sections of the building are uneven to the point where they will cause excessive wear to the sheet flooring finish applied to them. Photos 21 and 32 show examples of this. | \$10,250 |
| | | | 1963 | The carpet finish in the auditorium is worn and should be replaced. Photo No. 27 shows the existing carpet. | \$8,500 |
| | | | 1968 | Tile floor finishes in the corridor south of the locker rooms (at the gymnasium) are broken and need to be replaced. Photo No. 45 shows the tiles at the entrance to the fitness room. | \$6,250 |
| | | | 1958 | Sheet flooring in the washrooms in the original (1958) section of the building is broken and needs to be replaced. Photo No. 72 shows an example of the existing condition. | \$2,500 |

| Section 3 | Building Interior - Overall Conditions | Rating | Comments/Concerns | | Estimated Cost |
|-----------|---|--------|-------------------------|---|----------------|
| 3.2 | Materials and Finishes (cont'd) | | Building Section | Description/Condition | |
| 3.2.2 | Wall materials and finishes. | 4 | 1958 | Interior walls of the original (1958) section of the building are primarily painted plaster / gypsum board. Some have cracked due to the settlement problems this section is experiencing. Defects of this nature are being repaired on an ongoing basis and as a result there were no major deficiencies noted at the time of the inspection. | |
| | | | 1963 & 1968 | Interior walls in the 1963 and 1968 sections of the building are primarily painted concrete block. Vestibules and corridors in this section have a factory glazed block. Many of these are damaged but were being repaired and painted at the time of the inspection. Photo No.28 shows the condition of the glazed block prior to painting. These surfaces are all being brought up to "like new" condition as they are painted. | |
| 3.2.3 | Ceiling materials and finishes. | 3 | All | Ceilings in classrooms, ancillary rooms and corridors are generally suspended tee-bar grid with lay-in acoustic tiles. Tiles in most corridors are discolored and broken and should be replaced throughout. Most classrooms have at least a couple of broken tiles. It is estimated that 15 per cent of the acoustic tile in the building should be replaced. | \$22,500 |
| 3.2.4 | Interior doors and hardware. | 4 | All | No problems to report. | |
| 3.2.5 | Millwork | 4 | All | No problems to report. | |
| 3.2.6 | Fixed/wall mounted equipment (i.e., writing boards, tackboards, display boards, signs). | 4 | All | No problems to report. | |
| 3.2.7 | Any other fixed/mounted specialty items (i.e., CTS equipment, gymnasium equipment). | 4 | All | No problems to report. | |
| 3.2.8 | Washroom materials and finishes. | 3 | 1958 | Washrooms in the 1958 section of the building have a combination of ceramic tile and sheet flooring. The sheet flooring needs to be replaced as it is not an appropriate finish. Metal toilet partitions should be repaired and re-finished. | \$10,000 |
| Other | | | | | |

| Section 3 | Building Interior - Overall Conditions | Rating | Comments/Concerns | | Estimated Cost |
|-----------|--|--------|----------------------|--|------------------|
| 3.3 | Health and Safety Concerns --- Intent is to identify renovations considered necessary to meet applicable codes, primarily due to safety concerns. Basis of evaluation should be an up-to-date inspection report from the authority having jurisdiction together with direct observations as appropriate. Evaluator should note if in his opinion a comprehensive code evaluation is required. | | Bldg. Section | Description/Condition | \$148,000 |
| 3.3.1 | Building construction type - combustible or non-combustible, sprinklered or non-sprinklered. | 4 | 1958 & 1963 | The 1958 and 1963 sections of the building are of combustible construction. They are not sprinklered. They should be sprinklered to conform to current codes. | |
| 3.3.2 | Fire separations (i.e., between buildings, wings, zones if non-sprinklered). | 4 | 1968 | The 1968 sections of the building are of non-combustible construction. They are not sprinklered. | |
| 3.3.3 | Fire resistance rating of materials (i.e., corridor walls and doors). | 4 | All | Each section (construction phase) of the building is separated from adjacent sections by a glazed fire separation which bears no fire-resistance rating. These assemblies have wired glass sidelites and transoms. These assemblies have solid core wood doors with closers. The assemblies are framed with pressed steel sections. | |
| 3.3.4 | Exiting distances and access to exits. | 3 | All | Classrooms and ancillary rooms are not separated from corridors by fire-separations. The walls surrounding these rooms extend to the underside of the roof structure for acoustical control. Doors and frames within these walls however, bear no fire-resistance label and, are not fitted with closers. | \$6,000 |
| 3.3.5 | Barrier-free access. | 4 | All | Appears to conform to code. | |
| 3.3.6 | Availability of hazardous materials audit (i.e., evidence of safety concerns with respect to asbestos, PCB's, chemicals). | 3 | All | Barrier free access to the building is not available from 163 Street. The south entry of the 1958 section of the building as well as the south entry of the 1963 section of the building are grade level accesses however, disabled persons would have to cross a grass field to get to these doors. Barrier free access to the building is available from the parking lot north of the building via two entrances - the east entrance at the north end of the 1968 section of the building and the north entrance of the 1968 section of the building west of the gymnasium. Barrier free access is available to the sunken cafeteria area. Barrier free access is not available to the second floor areas of the building. | \$42,000 |

| Section 3 | Building Interior - Overall Conditions | Rating | Comments/Concerns | | Estimated Cost |
|-----------|--|--------|----------------------|---|------------------|
| 3.3 | Health and Safety Concerns --- <i>Intent is to identify renovations considered necessary to meet applicable codes, primarily due to safety concerns. Basis of evaluation should be an up-to-date inspection report from the authority having jurisdiction together with direct observations as appropriate. Evaluator should note if in his opinion a comprehensive code evaluation is required.</i> | | <u>Bldg. Section</u> | <u>Description/Condition</u> | |
| 3.3.7 | Other health and safety concerns (i.e., evidence of excessive noise conditions, air quality problems) | 3 | All | There were no hazardous materials audits available at the time of the inspection. The old 9"x9" floor tile used in various sections of the building is the original floor tile and as such would be vinyl asbestos tile. This tile should be removed. | \$100,000 |
| Other | | | | | |
| | Overall Building Interior Condition & Estimated Costs | | | The building interior has some problems. There are many areas where floor finishes should be replaced as they have exceeded their life expectancy. Wall finishes are in good condition where the settlement problem has not caused them to crack and shift. Lay-in acoustic ceiling tiles should be replaced in many areas of the building because they are broken, stained, or have deteriorated to the point where they may fall out of the grid. | \$299,000 |

| Section 4 | Mechanical Systems | Rating | Comments/Concerns | | Estimated Cost |
|------------|--|--------|-------------------------|---|-----------------|
| 4.1 | Mechanical Site Services | | Building Section | Description/Condition | \$20,000 |
| 4.1.1 | Site drainage systems (i.e., surface and underground systems, catch basins). | 2 | | Site drainage should be improved to prevent ice build-up in parking lot and on walkway to portable buildings. | \$20,000 |
| 4.1.2 | Exterior plumbing systems (i.e., irrigation systems, hose bibs). | 4 | | Hose bibbs (total of 10) in good condition | |
| 4.1.3 | Outside storage tanks. | N/A | | | |
| Other | | N/A | | | |
| 4.2 | Fire Suppression Systems | | Building Section | Description/Condition | \$0 |
| 4.2.1 | Fire hydrants and siamese connections. | N/A | 1958 1963 1968 | | |
| 4.2.2 | Fire suppression systems (i.e., pumps, sprinklers, piping, reservoirs, hoses, stand pipes, CO2 systems). | 4 | 1958 | N/A except one hose cabinet added in 1996 | |
| | | | 1963 | N/A | |
| | | | 1968 | Hose cabinets in good condition. | |
| 4.2.3 | Hand extinguishers, blankets and showers (i.e., in CTS areas). | 4 | 1958 1963 1968 | All fire extinguishers in good condition; serviced annually. | |
| 4.2.4 | Other special situations (e.g., flammable storage areas, science labs, CTS areas). | N/A | | | |

| Section 4 | Mechanical Systems | Rating | Comments/Concerns | | Estimated Cost |
|-----------|--------------------|--------|-------------------|---|----------------|
| Other | | 4 | | Sprinklers added to Library in 1996 renovation. | |

| Section 4 | Mechanical Systems | Rating | Comments/Concerns | | Estimated Cost |
|-----------|---|--------|-------------------------|--|----------------|
| 4.3 | Water Supply and Plumbing Systems | | Building Section | Description/Condition | \$6,000 |
| 4.3.1 | Domestic water supply (i.e., pressure, volume, quality - note whether municipal or well supply). | 4 | 1958 | 3" Municipal water complete with backflow/no insulation | |
| | | | 1963 | Extended from 1958 addition. | |
| | | | 1968 | Extended from 1958 addition. | |
| 4.3.2 | Water treatment system(s). | N/A | 1958 1963 1968 | | |
| 4.3.3 | Pumps and valves (including backflow prevention valves). | 3 | 1958 | Backflow preventer on water service | |
| | | | 1963 | No vacuum breakers on lab faucets | \$1,000 |
| | | | 1968 | N/A | |
| 4.3.4 | Piping and fittings. | 4 | All | Reported pipe freeze-ups in numerous areas; piping and fittings generally look good. | |
| 4.3.5 | Plumbing fixtures (i.e., toilets, urinals, sinks) | 4 | 1958 | Fixtures are in poor condition but are working. | |
| | | | 1963 | Some fixtures replaced, but working. | |
| | | | 1968 | Some fixtures replaced, but working. | |
| 4.3.6 | Domestic hot water system (i.e., heater, storage tanks, failure alarms, pressure, volume, recirculation). | 4 | 1958 | water extended from 1963 addition. | |
| | | | 1963 | One new heater, Super Hot #82CG State #SBT-75-140 Heaters appear to be working okay | |
| | | | 1968 | N/A - water extended from 1963 addition. | |
| 4.3.7 | Sanitary and storm sewers, including sumps and pits (note whether sewage system is municipal or septic). | 3 | 1958 | Minimal problems. | |
| | | | 1963 | Plumbing serving labs plug regularly and should be corrected. | \$5,000 |
| | | | 1968 | Minimal problems. | |

| Section 4 | Mechanical Systems | Rating | Comments/Concerns | | Estimated Cost |
|-----------|--------------------|--------|-------------------|--|----------------|
| Other | | | | | |

| Section 4 | Mechanical Systems | Rating | Comments/Concerns | | Estimated Cost |
|-----------|---|--------|-------------------------|--|------------------|
| 4.4 | Heating Systems | | Building Section | Description/Condition | \$124,000 |
| 4.4.1 | Heating capacity and reliability (including backup capacity). | 2 | 1958 | 13 furnaces; 3 per classroom/ limited fresh air/ poor condition. | \$78,000 |
| | | | 1963 | No reported problems; original boilers. | |
| | | | 1968 | No reported problems - extended from 1963 addition. | |
| 4.4.2 | Heating controls (including use of current energy management technology). | 4 | 1958 | Poor temperature control - 3 rooms per furnace. | |
| | | | 1963 | Original boiler control, updated with DDC. | |
| | | | 1968 | Original controls updated with DDC. | |
| 4.4.3 | Fresh air for combustion and condition of the combustion chimney. | 3 | 1958 | Limited fresh air/no equipment room relief. | \$5,000 |
| | | | 1963 | Combustion air okay; no boiler room relief. | \$1,000 |
| | | | 1968 | N/A | |
| 4.4.4 | Treatment of water used in heating systems. | 4 | 1958 | N/A | |
| | | | 1963 | Dearborn - no problems reported. | |
| | | | 1968 | N/A | |
| 4.4.5 | Low water cutoff/pressure relief valves and failure alarms (i.e., hot water heating). | 4 | 1958 | N/A | |
| | | | 1963 | No problems reported. | |
| | | | 1968 | N/A | |
| 4.4.6 | Heating air filtration systems and filters. | 4 | 1958 | 1" - 15% or less efficient - disposable; changed regularly. | |
| | | | 1963 | 1" - 15% or less efficient - disposable; changed regularly. | |
| | | | 1968 | 1" - 15% or less efficient - disposable; changed regularly. | |
| 4.4.7 | Heating humidification systems and components. | 1 | All | No humidification | \$40,000 |

| Section 4 | Mechanical Systems | Rating | Comments/Concerns | | Estimated Cost |
|-----------|---|--------|-------------------------|---|----------------|
| 4.4 | Heating Systems (cont'd) | | <u>Building Section</u> | <u>Description/Condition</u> | |
| 4.4.8 | Heating distribution systems (i.e., piping, ductwork) and associated components (i.e., diffusers, radiators). | 4 | 1958 | Underfloor ductwork - no means to balance | |
| | | | 1963 | Hydronic heat okay - no problems reported | |
| | | | 1968 | Hydronic heat okay - no problems reported | |
| 4.4.9 | Heating piping, valve and/or duct insulation. | 4 | 1958 | Fresh air plenum only insulated - poor condition | |
| | | | 1963 | Some insulation missing from heating piping - otherwise okay. | |
| | | | 1968 | Some insulation missing from heating piping - otherwise okay. | |
| 4.4.10 | Heat exchangers. | 3 | 1958 | Furnace heat exchangers in poor condition. | Refer to 4.4.1 |
| | | | 1963 1968 | N/A | |
| 4.4.11 | Heating mixing boxes, dampers and linkages. | 2 | 1958 | Fixed fresh air. | Refer to 4.4.1 |
| | | | 1963 | Herman Nelson units - poor control - goes off on freeze protection. | |
| | | | 1968 | Separate air system - good condition. | |
| 4.4.12 | Heating distribution/circulation in larger spaces (i.e., user comfort, temperature of outside wall surfaces). | 2 | 1958 | Very poor comfort | Refer to 4.4.1 |
| | | | 1963 | Marginal comfort | |
| | | | 1968 | Good comfort | |
| 4.4.13 | Zone/unit heaters and controls. | 4 | 1958 | N/A | |
| | | | 1963 | No reported problems - looks okay | |
| | | | 1968 | No reported problems - looks okay | |
| Other | | | | | |

| Section 4 | Mechanical Systems | Rating | Comments/Concerns | | Estimated Cost |
|-----------|--|--------|-------------------------|--|------------------|
| 4.5 | Ventilation Systems | | Building Section | Description/Condition | \$340,000 |
| 4.5.1 | Air handling units capacity and condition. | 2 | 1958 | Furnaces serve classrooms/Drama room has separate unit. System is inadequate and should be upgraded. | \$340,000 |
| | | | 1963 | Herman Neilson units in classrooms and library | Refer to 4.5.1 |
| | | | 1968 | Cafeteria unit/gym unit/industrial arts/central unit for classrooms - acceptable | |
| 4.5.2 | Outside air for the occupant load (if possible, reference CFM/occupant). | 3 | 1958 | Fixed - likely insufficient | Refer to 4.5.1 |
| | | | 1963 | Herman Nelson unit okay | |
| | | | 1968 | Air systems with free cooling (100% O/A) capability - acceptable | |
| 4.5.3 | Air distribution system (if possible, reference number of air changes/hour). | 2 | 1958 | One furnace/3 classrooms inadequate | Refer to 4.5.1 |
| | | | 1963 | Questionable air changes | Refer to 4.5.1 |
| | | | 1968 | Central air system - no complaints - acceptable | |
| 4.5.4 | Exhaust systems capacity and condition. | 3 | 1958 | Washrooms are smelly | Refer to 4.5.1 |
| | | | 1963 1968 | Seems okay | |
| 4.5.5 | Separation of out flow from air intakes. | 4 | 1958 1963 1968 | Okay | |
| 4.5.6 | Special/dedicated ventilation and/or exhaust systems (i.e., kitchen, labs, CTS areas). | 4 | 1968 | Cafeteria /Industrial Arts/Gym/Drama all have dedicated units | |

| Section 4 | Mechanical Systems | Rating | Comments/Concerns | | Estimated Cost |
|-----------|--|--------|-------------------------|-------------------------------------|----------------|
| Other | | | | | |
| 4.5 | Ventilation Systems (cont'd) | | Building Section | <u>Description/Condition</u> | |
| | <i>Note: Only complete the following items if there are separate ventilation and heating systems.</i> | | | | |
| 4.5.7 | Ventilation controls (including use of current energy management technology). | 4 | All | DDC update and operating well. | |
| 4.5.8 | Air filtration systems and filters. | N/A | | | |
| 4.5.9 | Humidification system and components. | 1 | | | Refer to 4.4.7 |
| 4.5.10 | Heat exchangers. | N/A | | | |
| 4.5.11 | Ventilation distribution system and components (i.e., ductwork, diffusers, mixing boxes, dampers, linkages). | 2 | | | Refer to 4.5.1 |
| Other | | | | | |

| Section 4 | Mechanical Systems | Rating | Comments/Concerns | | Estimated Cost |
|-----------|---|--------|-------------------------|--|------------------|
| 4.6 | Cooling Systems | | Building Section | Description/Condition | \$0 |
| 4.6.1 | Cooling system capacity and condition (i.e., chillers, cooling towers, condensers). | 2 | | Cafeteria system only - added in 1996 - unit reported to be under capacity. | Refer to 4.5.1 |
| 4.6.2 | Cooling distribution system and components (i.e., ductwork, diffusers, mixing boxes, dampers, linkages) | 4 | 1963 | Cafeteria air system only - added in 1996 | |
| 4.6.3 | Cooling system controls (including use of current energy management technology). | 4 | | Cafeteria unit | |
| 4.6.4 | Special/dedicated cooling systems (i.e., labs, CTS areas). | 4 | | Cafeteria unit | |
| Other | | | | | |
| 4.7 | Building Control Systems | | Building Section | Description/Condition | \$0 |
| 4.7.1 | Building wide/system wide control systems and/or energy management systems. | 4 | All | Control system serving school was updated to a DDC system. | |
| | Overall Mechanical Systems Condition & Estimated Costs | | | The heating and ventilating systems are in poor condition and should be upgraded. There is no humidification and limited cooling in this school. | \$490,000 |

| Section 5 | Electrical Systems | Rating | Comments/Concerns | | Estimated Cost |
|------------|--|--------|-------------------------|--|-----------------|
| 5.1 | Site Services | | Building Section | Description/Condition | \$0 |
| 5.1.1 | Primary service capacity and reliability (i.e., access, location, components, installation, bus sizes - note whether overhead or underground). | 4 | | 1200 amp, 120/208V, 3 phase, 4 wire as manufactured by Westinghouse Located in electrical room, north side Underground services Vintage 1969 See Comments (Part 8) | |
| 5.1.2 | Site and building exterior lighting (i.e., safety concerns). | 4 | | Adequate, no concerns | |
| 5.1.3 | Vehicle plug-ins (i.e., number, capacity, condition). | 4 | | 31 plug-ins complete with exterior panel 1 damaged post Time clock control | |
| Other | | | | | |
| 5.2 | Life Safety Systems | | Building Section | Description/Condition | \$12,500 |
| 5.2.1 | Fire and smoke alarm systems (i.e., safety concerns, up-to-date technology, regularly tested). | 4 | 1996 | 26 zones, one spare, as manufactured by Simplex 2001 "hardwire" Located in 1996 addition Bells with visual only in the 1996 portion office area Verified August, 1999 | |
| 5.2.2 | Emergency lighting systems (i.e., safety concerns, condition). | 4 | 1958 1963 1968 | Added new battery pack down hallways; fed from surface mounted receptacle. | |
| 5.2.3 | Exit lighting and signage (i.e., safety concerns, condition). | 3 | 1958 1963 1968 | Old incandescent exit lights No power source | \$12,500 |

| Section 5 | Electrical Systems | Rating | Comments/Concerns | | Estimated Cost |
|-----------|--------------------|--------|-------------------|--|----------------|
| Other | | | | | |

| Section 5 | Electrical Systems | Rating | Comments/Concerns | | Estimated Cost |
|-----------|--|--------|-------------------------|--|------------------|
| 5.3 | Power Supply and Distribution | | Building Section | Description/Condition | \$101,000 |
| 5.3.1 | Power service surge protection. | 3 | | Not present. | |
| 5.3.2 | Panels and wireways capacity and condition. | 3 | 1958 | Panel full, antiquated/obsolete | \$6,000 |
| | | | 1963 & 1968 | Panel full, obsolete | |
| | | | 1996 | Panel full, obsolete New CDP as manufactured by Siemens | |
| 5.3.3 | Emergency generator capacity and condition and/or UPS (if applicable). | N/A | | | |
| 5.3.4 | General wiring devices and methods. | 3 | 1958 | Receptacles are damaged, 2 or 3 receptacles per classroom; circuits are overloaded; breakers are tripping. | \$95,000 |
| | | | 1963 & 1968 | Other areas are adequate. | |
| 5.3.5 | Motor controls. | 4 | 1958 1963 1968 | Local starters as manufactured by Westinghouse and GE, adequate. | |
| Other | | | | | |

| Section 5 | Electrical Systems | Rating | Comments/Concerns | | Estimated Cost |
|------------|--|--------|-------------------------|--|------------------|
| 5.4 | Lighting Systems | | Building Section | Description/Condition | \$265,000 |
| 5.4.1 | Interior lighting systems and components (i.e., illumination levels, conditions, controls). | 4 | | The only area that does not meet the light level for Alberta infrastructure guidelines is the gym. Refer to "Comments". | |
| 5.4.2 | Replacement of ballasts (i.e., health and safety concerns). | 4 | | Ballasts are being replaced with Mark III Philip; refer to Comments. | |
| 5.4.3 | Implementation of energy efficiency measures and recommendations. | 3 | | In conversation with the staff, this school is planning to have a total lighting upgrade. The majority of light fixture lens have been removed, which has increased lighting levels. | \$265,000 |
| Other | | | | | |
| 5.5 | Network and Communication Systems | | Building Section | Description/Condition | \$0 |
| 5.5.1 | Telephone system and components (i.e., capacity, reliability, condition). | 5 | | Nutec plan/Nitsuko America system new Installed in 1996 Located in Art room. | |
| 5.5.2 | Other communication systems (i.e., public address, intercom, CCTV, satellite or cable TV). | 4 | | CCTV cameras in parking lot Public address system upgrade in 1996 as manufactured by Petcom Cable TV, videotron at all televisions in classrooms | |
| 5.5.3 | Network cabling (if available, should be category 5 or better). | 4 | | Total school is networked, 3 main services; 1 admin, 2 education Cat.5 cabling Three main switches are located in computer lab 133; all hubs are tied to here. | |
| 5.5.4 | Network cabling installation (i.e., in conduit, secured to walls or tables). | 4 | | In conduit and cable management secured to walls Hubs and switches are wall mounted, close to the ceiling Cabling for desk on labs is secured to desks | |
| 5.5.5 | Wiring and telecommunication closets (i.e., size, security, ventilation/cooling, capacity for growth). | 4 | | Surface wall mounted hubs in computer labs in telecom room No ventilation in telephone room off of art room. | |
| 5.5.6 | Provision for dedicated circuits for network equipment (i.e., hubs, switches, computers). | 4 | | Separate power panel for Library only Computer lab approximately 5 circuits per, shared from other panels Separate circuit for hubs and switches | |
| Other | | | | | |

| Section 5 | Electrical Systems | Rating | Comments/Concerns | | Estimated Cost |
|-----------|--|--------|-------------------------|---|------------------|
| 5.6 | Miscellaneous Systems | | Building Section | Description/Condition | \$0 |
| 5.6.1 | Site and building surveillance system (if applicable). | 4 | | 3 cameras; 2 in staff parking lot; 1 in student parking lot | |
| 5.6.2 | Intrusion alarms (if applicable). | 4 | | Yes, Telsco | |
| 5.6.3 | Master clock system (if applicable). | 4 | | N/A Digital clock in 1996 renovation 120V plug type everywhere else | |
| Other | | | | | |
| 5.7 | Elevators/Disabled Lifts (If applicable) | | Building Section | Description/Condition | \$0 |
| 5.7.1 | Elevator/lift size, access and operating features (i.e., sensing devices, buttons, phones, detectors). | N/A | | | |
| 5.7.2 | Condition of elevators/lifts. | N/A | | | |
| 5.7.3 | Lighting and ventilation of elevators/lifts. | N/A | | | |
| Other | | | | | |
| | Overall Electrical Systems Condition & Estimated Costs | | | Many of the panels are full, antiquated and/or obsolete and should be replaced. Receptacles in the 1958 section are damage, circuits are overloaded and breakers are constantly tripping. A total lighting upgrade is required for this school. | \$378,500 |

| Section 6 | Portable Buildings | Rating | Comments/Concerns | Estimated Cost |
|-----------|--|--------|---|----------------|
| | <i>Note: Separate sheets can be completed, if necessary, for portable buildings of different ages and/or conditions.</i> | | | |
| 6.1.1 | Foundation and structure (i.e., signs of bending, cracking, settlement, rust, voids, stains). | 4 | No problems to report. | |
| 6.1.2 | Roof materials and components (i.e., signs of deterioration, leaks, ice build-up). | 4 | No problems to report. | |
| 6.1.3 | Exterior wall finishes (i.e., signs of deterioration, cracks, water stains). | 4 | No problems to report. | |
| 6.1.4 | Doors and windows (i.e., signs of deterioration, rusting hardware, glass cracks, peeling paint, damaged seals). | 4 | No problems to report. | |
| 6.1.5 | Interior finishes (i.e., floors, walls, ceiling). | 3 | Floor finishes in the common area (including the washrooms) between Portable No. 79 and Portable No. 80 should be replaced. Tiles are lifting and are broken. | \$1,500 |
| 6.1.6 | Millwork (i.e., counters, shelving, vanities, cabinets). | 4 | No problems to report. | |
| 6.1.7 | Fixed/wall mounted equipment (i.e., writing boards, tackboards, display boards, signs) | 4 | No problems to report. | |
| 6.1.8 | Heating system. | 4 | New furnaces - Weather Maker 8000, Model 58 WAV091-14 | |
| 6.1.9 | Ventilation system. | 4 | Fresh air to furnaces | |
| 6.1.10 | Electrical, communication and data network systems. | 3 | No fire alarm; no exits; no emergency lighting | \$3,000 |
| 6.1.11 | Health and safety concerns (i.e., fire and smoke alarms, fire protection systems, exiting, fire resistance rating of materials). | 4 | Fire extinguishers | |
| 6.1.12 | Barrier-free access. | 3 | There is no barrier free access to any of the three portables. | \$3,000 |
| | Overall Portable Buildings Condition & Estimated Costs | | All portables are in fairly good condition. | \$7,500 |

| Section 7 | Space Adequacy | This Facility | | | Equiv. New Facility | | | Surplus/ Deficiency | Comments/Concerns |
|-----------|---|---------------|-------|------------|---------------------|------|------------|------------------------|---|
| | | No. | Size | Total Area | No. | Size | Total Area | | |
| 7.1 | Classrooms | | | 1901.3 | 26 | 80 | 2080 | -178.7 | Gross Capacity = 1030 - 45 for program exemptions = 985 Net Capacity |
| | | 10 | 68.4 | | | | | | Current Enrollment = 1048 or 106.4% of net capacity |
| | | 2 | 68.7 | | | | | | |
| | | 2 | 70 | | | | | | |
| | | 4 | 78.5 | | | | | | |
| | | 1 | 78.1 | | | | | | |
| | | 1 | 79.6 | | | | | | |
| | | 1 | 77.8 | | | | | | |
| | | 1 | 48.5 | | | | | | |
| | | 1 | 55.7 | | | | | | |
| | | 1 | 64.2 | | | | | | |
| | Portables | 3 | 74 | | | | | | |
| 7.2 | Science Rooms/Labs | | | 660 | 5 | 120 | 600 | 60 | |
| | | 2 | 97.2 | | | | | | |
| | | 4 | 68.7 | | | | | | |
| | | 2 | 95.4 | | | | | | |
| 7.3 | Ancillary Areas (i.e., Art, Computer Labs, Drama, Music,) | | | 672.6 | | | 620 | 52.6 | |
| | Art | 1 | 113.3 | | 2 | 130 | | | |
| | Auditorium | 1 | 161.6 | | 4 | 90 | | | |
| | | 1 | 118.4 | | | | | | |
| | Stage | 1 | 60.6 | | | | | | |
| | Computer | 1 | 113.7 | | | | | | |
| | Computer | 1 | 105 | | | | | | |
| 7.4 | Gymnasium (incl. gym storage) | | | 834.2 | | | 1425 | -590.8 | The new cafeteria/multipurpose room (formerly an outdoor courtyard) serves as a major public gathering space. |
| 7.5 | Library/Resource Areas | | | 382.1 | | | 510 | -127.9 | |
| | | 1 | 118.9 | | | | | | |
| | | 1 | 105.3 | | | | | | |
| | | 1 | 157.9 | | | | | | |

| | | No. | Size | Total Area | No. | Size | Total Area | Deficiency | |
|-----|--|-----|-------|----------------|-----|------|-------------|---------------|---------------------|
| 7.6 | Administration/Staff, Physical Education, Storage Areas | | | 1864 | | | 1190 | 674 | |
| 7.7 | CTS Areas | | | 744.4 | | | 460 | 284.4 | |
| | 7.7.1 Business Education | 1 | 70 | | 4 | 115 | | | |
| | 7.7.2 Home Economics | 1 | 224.4 | | | | | | |
| | 7.7.3 Industrial Arts | 1 | 450 | | | | | | |
| | 7.7.4 Other CTS Programs | | | | | | | | |
| 7.8 | Other Non-Instructional Areas (i.e., circulation, wall area, crush space, wc area) | | | 3407.3 | | | 2489 | 918.3 | |
| | Overall Space Adequacy Assessment | | | 10465.9 | | | 9374 | 1091.9 | Leased out area = 0 |

| Evaluation Component/ Sub-Component | Additional Notes and Comments |
|--|--|
| Lighting System | Conversation with the staff, this school is going to have a total lighting upgrade. A majority of light fixture lens have been removed, which has increased lighting levels. |
| Rating 4 | Mechanical equipment located on roof requires regular maintenance - no provisions for perimeter roof access exists. |
| Site Services | In conversation with EPCOR, the existing power demand is 768 amp which represents approximately 65% of the service being used. |
| | |
| | |
| | |
| | |