Part II - Physical Condition

School Name:	St. John	Element	ary School		School Code:	802
Location:	10231 - 1	120th Str	eet, Edmontor	n, Alberta	Facility Code:	196
Region:	Central				Superindendent:	Mr. Garnet McKee
Jurisdiction:		on Roma	n Catholic Sch	nools Regional Division #40	Contact Person:	Mr. Ken Yakimovich
				J	Telephone:	(780) 453-4500
Grades:	V - XII (S	Special E	d). Leased		School Capacity:	200 (Leased)
Building Section	Year of Compl.	No. of Floors	Gross Bldg Area (Sq.M.)	Type of Construction (i.e., structure, roof, cladding)	Description of Mechanical Systems (incl. major upgrades)	Comments/Notes
Original Building	1939	1 & Mezz	1059.80	Wood frame construction. Flat roof, stucco exterior	Consists of original steam system, served by one (1) original steam boiler, converted from coal fired to gas fired boiler, located in the Basement of this section of the school. The ventilation system does not exist.	The Boiler Plant serving original school has exceeded its life expectancy and is in poor condition. The ventilation system does not exist. This can not meet ASHRAE 62-1989 Standard, and is against health and safety requirements. The entire mechanical system shall be replaced.
Additions/ Expansions	1954	1	431.10 260.00	Wood frame construction. Flat roof, stucco exterior Steel frame gym addition, sloping metal roof, metal panel walls. Pre-engineered building.	Consists of steam system, served by steam boiler plant located in the original school. The ventilation system consists of Univents with steam coils. The 1971 section of the school is served by two (2) natural gas fired furnaces.	The Boiler Plant serving the entire school is in poor condition, has exceeded its life expectancy and shall be replaced with a new hot water heating boiler plant. The existing ventilation system serving all sections of the school cannot meet ASHRAE 62 1989 Standard and shall be replaced with a new ventilation system.
					Evaluator's Name:	Janusz Najfeldt
1					& Company:	Najfeldt Architect

School: St. John Date: April 11, 2000

Part II - Physical Condition

Upgrading/ Modernization				
Modernization				
(identify whether				
minor or major)				
Portable Struct.	 			
(identify whether				
attached/perman. or				
free-standing/				
relocatable)				
l'elocatable)				
List of Reports/			 	
Supplementary				
Information				

Part II - Physical Condition

Evaluation Components	Summary Assessment	L	Estim. Cost
Site Conditions	Create playfield. Replace sidewalks and guardrails.	\$	157,500.0
Building Exterior	Replace windows. Roofing inspection recommended.	\$	256,000.0
Building Interior	Major overhaul of interior finishes recommended. Provide new lockers and millwork.	\$	377,300.
Mechanical Systems	The existing steam system and univent Ventilation system cannot meet ASHRAE 62-1989 Standard and present ventilation code requirements. The existing mechanicaal system shall be replaced with a new hot water heating and ventilation system.		225,000.
Electrical Systems	The main electrical service is in poor condition. Retrofit existing luminaires with new T8 lamps and electronic ballasts. Upgrade fire alarm system to current code.	\$	156,600.
6 Portable Buildings	None	\$	-
7 Space Adequacy:			
7.1 Classrooms	Somewhat Deficient52.40		
7.2 Science Rooms/Labs	Somewhat Excessive 32.00		
7.3 Ancillary Areas	Deficient -147.00		
7.4 Gymnasium	Somewhat Deficient -25.00		
7.5 Library/Resource Areas	Excessive 55.00		
7.6 Administration/Staff Areas	Deficient -105.50		
7.7 CTS Areas			
7.8 Other Non-Instructional Areas (incl. gross-up)	Excessive 155.80		
Overall School Conditions & Estim. Costs	-87.10	\$	1,172,400.

School: St. John

Date: April 11, 2000

Part II - Physical Condition

Section 1	Site Conditions	Rating	Comments/Concerns	Estim. Cost
1.1	General Site Conditions			
1.1.1	Overall site size.	4	Small site. Cannot be expanded.	\$ -
1.1.2	Outdoor athletic areas.	2	Asphalt - paved, very poor. Baseball diamond, two homemade basketball hoops. Recommend removal of asphalt and sodding of playfield.	\$ 100,000.00
1.1.3	Outdoor playground areas, including condition of equipment and base.	4	None present or required.	\$ -
1.1.4	Site landscaping.	4	Playfield - asphalt paved - in poor condition. Small grass area in front and south end of site. Mature trees in front yard.	\$ -
1.1.5	Site accessories (i.e., perimeter and other fencing, guard rails, bike stands, flag poles).	3	One flag pole and one bike stand - poor condition. Guard rails in front of building - poor condition, provide new rails and posts. Entire site fenced off with chain link fencing.	\$ 11,500.00
1.1.6	Surface drainage conditions (i.e., drains away from building, signs of ponding).	3	Poor drainage at front sidewalk, ponding along North wall. Replace sidewalks, improve slope.	\$ 14,000.00
1.1.7	Evidence of sub-soil problems.	4	No issues	\$ -
1.1.8	Safety and security concerns due to site conditions.	N/A	None	\$ -
Other				\$ -

Part II - Physical Condition

Section 1	Site Conditions	Rating	Comments/Concerns	Estim. Cost
1.2	Access/Drop-Off Areas/Roadways/Bus Lanes			
1.2.1	Vehicular and pedestrian access points (i.e., size, number, visibility, safety).		Access from back lane only. Walkways to all entrances - all adequate.	\$ -
1.2.2	Surfacing of on-site road network (note whether asphalt or gravel).	4	No on-site roads.	\$ -
1.2.3	Bus lanes/drop-off areas (note whether on-site or offsite).	4	Off-site, along 120th street, adequate	\$ -
1.2.4	Fire vehicle access.	4	Adequate - all around the building.	\$ -
1.2.5	Signage.		On the building - adequate. Leasee has own free standing sign.	\$ -
Other				\$ -

Part II - Physical Condition

ection 1	Site Conditions	Rating	Comments/Concerns	Es	stim. Cost
1.3	Parking Lots and Sidewalks				
1.3.1	Number of parking spaces for staff, students and visitors (including stalls for disabled persons).	3	Staff parking at rear from back alley - adequate. No student or visitor parking on-site. No stalls provided for disabled - allocate one stall.	\$	500.00
1.3.2	Layout and safety of parking lots.	4	Adequate.	\$	-
1.3.3	Surfacing and drainage of parking lots (note whether asphalt or gravel).	3	Gravel surfaced, good slope. Marginal condition, gravel very soft. Resurfacing or asphalt paving recommended.	\$	15,000.00
1.3.4	Layout and safety of sidewalks.	3	Layout adequate, but slabs moved and settled, creating unsafe condition. Replace walks and base.	\$	15,000.00
1.3.5	Surfacing and drainage of sidewalks (note type of material).	3	Concrete, poor drainage at rear. See 1.3.4 Exit pad at gym collapsed. Replace pad and base.	\$	1,500.00
1.3.6	Curb cuts and ramps for barrier free access.	4	None provided. No curbs at parking.	\$	-
Other				\$	-
	Overall Site Conditions & Estimated Costs			\$ 1	57,500.00

Part II - Physical Condition

	Building Exterior	Rating		Comments/Concerns	Estim.	Cost
2.1	Overall Structure		Bldg.			
211	Floor structure and beams (i.e., signs of bending,	4		Description/Condition	\$	
	cracking, heaving, settlement, voids, rust, stains).	4		Wood floors over crawl space. Concrete foundation walls.	Ф	-
			1954	Concrete foundation walls.		
			1971	Slab on grade and concrete grade beam.		
				All in satisfactory condition.		
2.1.2	Wall structure and columns (i.e., signs of bending, cracking, settlement, voids, rust, stains).	4	All	Wood structure - in good condition.	\$	-
2.1.3	Roof structure (i.e., signs of bending, cracking, voids, rust, stains).	4	All	No signs of structural distress.	\$	-
Other					\$	-

Part II - Physical Condition

Section 2	Building Exterior	Rating		Comments/Concerns	Estim. Co	st
2.2	Roofing and Skylights Identify the availability of an up-to-date inspection report or roofing program. Note if roof sections are of different ages and/or in varying		Bldg. Section or Roof Section	Description/Condition/Age		
2.2.1	Based on the inspection report (and to the extent possible, direct observation), assess and rate roof conditions and estimate costs for required improvements (i.e., covering materials, membrane, insulation, other components).	3	1939 1954	History of water entry along west wall. Tar and gravel built-up roofing. Roof leak occurred in 1996 over east side classroom. Metal pre-engineered building roofing. Comprehensive roofing inspection recommended. Re-roofing recommended.	\$ 139,000.0	00
2.2.2	Roof accessories (i.e., ladders, stairs, hatches, masts, exhaust hoods, chimneys, gutters, downspouts, splashpads).	4		No internal access provided - via ladders only. Provide internal acces when re-roofing.	See 2.2.1	
2.2.3	Control of ice and snow falling from roof.	4	All	No issues reported or observed relating to ice and snow hazard.	\$ -	
2.2.4	Skylights (i.e., signs of distress, leaks, ice build-up, condensation, deteriorated materials/seals).	N/A		None	\$ -	
Other					\$ -	

Part II - Physical Condition

Section 2	Building Exterior	Rating		Comments/Concerns	Es	tim. Cost
2.3	Exterior Walls/Building Envelope		Bldg.			
ļ			<u>Section</u>	<u>Description/Condition</u>		
2.3.1	Exterior wall finishes (i.e., signs of deterioration,	3		Painted stucco in good condition. Some cracks present, no expansion joints.	\$	5,500.00
	cracks, brick spalling, effluorescence, water stains).		1954	South face stucco peeling off - poor condition. Replace stucco on south wall.		
			1971	Pre-finished metal panel - in good condition.		
2.3.2	Fascias, soffits, parapets (i.e., signs of looseness, stains, rust, peeling paint).	3	1954	Stucco soffits and pre-finished metal fascias - in good condition.	\$	5,000.00
				G.I. Parapet flashing in poor condition, replace. Stucco soffits and fascia - in good condition.		
			1971	Pre-finished metal - in good condition.		
	Building envelope (i.e., evidence of air infiltration/ exfiltration through the exterior wall or ice build up on wall, eaves, canopy).	4	All	No evidence of air movement damage to building components.	\$	-
2.3.4	Interface of roof drainage and ground drainage systems.	4		Acceptable, no issues observed or reported. All main roofs on areas drain internally, except for gymnasium structure.	\$	-
2.3.5	Inside faces of exterior walls (i.e., signs of cracks, water stains, dust spots).	3	1939	West side classrooms, water entry at window sills. Repair wall.	\$	3,500.00
Other					\$	-

Part II - Physical Condition

Section 2	Building Exterior	Rating		Comments/Concerns	Estim. Cost
2.4	Exterior Doors and Windows		Bldg. Section	Description/Condition	
	Doors (i.e., signs of deterioration, rusting metal, glass cracks, peeling paint, damaged seals, sealed unit failure).	2	All	<u>Description/Condition</u> Wood doors in wood frames, all painted - poor condition. Replacement required, c/w weatherstripping and hardware.	\$ 18,000.00
	Door accessories (i.e., latches, hardware, screens, locks, alarms, holders, closers, security devices).	2		Old - in poor condition. Loose knobs and strikes. Keys not fitting properly, closers loose.	\$ 10,000.00
2.4.3	Exit door hardware (i.e., safety and/or code concerns).	4		Older type, problematic to service and maintain. Consider replacement together with doors.	See 2.4.1
	Windows (i.e., signs of deterioration, rusting metal, glass cracks, peeling paint, damaged seals, sealed unit failure).	2	1954	Painted wood windows with bottom sliders and glass block or metal panel top insert combination. All in poor condition - replacement recommended.	\$ 75,000.00
	Window accessories (i.e., latches, hardware, screens, locks, alarms, holders, closers, security devices).	2	All	Older and in poor condition. Replace with windows.	See 2.4.4
	Building envelope (i.e., signs of heavy condensation on doors or windows).	4	All	No signs of condensation damage around doors and windows.	
Other					
	Overall Bldg Exterior Condition & Estim Costs				\$ 256,000.00

Part II - Physical Condition

Section 3	Building Interior - Overall Conditions	Rating		Comments/Concerns	Estim. Co	ost
3.1	Interior Structure		Bldg. Section	Description/Condition		
3.1.1	Interior walls and partitions (i.e., signs of cracks, spalling, paint peeling).	4	All	Joints in plywood dado throughout. Otherwise no major cracks or deterioration.	\$	-
3.1.2	Floors (i.e., signs of cracks, heaving, settlement).	2		Wood floors noisy to walk on. A lot of sub-floor movement. Reset sub-floor when changing carpets and provide underlay sheet to VCT flooring.	\$ 45,000	0.00
Other					\$	-
3.2	Materials and Finishes		Bldg.			
			Section	<u>Description/Condition</u>		
3.2.1	Floor materials and finishes.	2	1954	All areas carpeted - in poor condition. Replace with VCT. Hallway VCT and sheet flooring. Classrooms - carpet - poor condition. Replace with VCT. VCT tile - adequate.	\$ 58,000).00
3.2.2	Wall materials and finishes.	2	1954	Drywall painted with painted plywood dado combination - in poor condition. Patch and repaint all areas. Painted plywood dado, wire mesh above - acceptable.	\$ 42,000).00
3.2.3	Ceiling materials and finishes.	2	1954	Spraytex and painted combination - acceptable.	\$ 51,000	0.00
			1939	T-bar and tentest - in poor condition. Replace.		
			1971	Wood board ceiling painted - adequate.		

Part II - Physical Condition

	Building Interior - Overall Conditions	Rating		Comments/Concerns	Estim. C	ost
3.2	Materials and Finishes (cont'd)		Bldg.			
			<u>Section</u>	<u>Description/Condition</u>		
3.2.4	Interior doors and hardware.	2		Wood doors in wood frames, painted - in poor condition.	\$ 38,500	0.00
				Replacement recommended.		
				Hardware functional.		
325	Millwork	2	All	Old - in poor condition. Painted plywood and plastic laminate tops.	\$ 43,000	0.00
0.2.0	WillWOTK			Replacement recommended.	Ψ 45,000	0.00
				Inceptacement recommended.		
3.2.6	Fixed/wall mounted equipment (i.e., writing boards,	2	All	Lockers in poor condition.	\$ 37,500	0.00
	tackboards, display boards, signs).			Replacement recommended.		
0.07	Annually as five diversity of a significant field of the significant fi		4074	Frank and all lands and all a half and A have at	Φ.	
	Any other fixed/mounted specialty items (i.e., CTS equipment, gymnasium equipment).	4	1971	Four basketball hoops and volleyball set. Adequate.	\$	-
	oquipmoni, gjimaoium oquipmoni,					
3.2.8	Washroom materials and finishes.	2	All	Walls - Plastered painted - marginal.	\$ 19,800	0.00
				Floors - painted concrete, base falling off, poor condition.		
				Ceiling - Plaster painted - marginal.		
				Repair floor base and repaint all. Replace metal toilet partitions.		
Other		2		Wood steps at entrances and wood step to basement - in poor condition.	\$ 6,500	0.00
				Replace steps at entrances.		

Part II - Physical Condition

Section 3	Building Interior - Overall Conditions	Rating		Estim. Cost	
3.3	Health and Safety Concerns Intent is to		Bldg.		
	identify renovations considered necessary to meet applicable codes, primarily due to safety		Section	Description/Condition	
	concerns. Basis of evaluation should be an up-to-				
	date inspection report from the authority having				
	jurisdiction together with direct observations as appropriate. Evaluator should note if in his				
	opinion a comprehensive code evaluation is				
3.3.1	Building construction type - combustible or non- combustible, sprinklered or non-sprinklered.	4	All	Non-sprinklered, wood frame construction and steel frame construction combination.	\$ -
3.3.2	Fire separations (i.e., between buildings, wings, zones if non-sprinklered).	4	All	Block fire wall between 1954 and 1971. Adequate.	\$ -
3.3.3	Fire resistance rating of materials (i.e., corridor walls and doors).	4	All	Appears adequate	\$ -
3.3.4	Exiting distances and access to exits.	4	All	Adequate.	\$ -
3.3.5	Barrier-free access.	3	All	None provided. No ramps or automatic entry. Provide ramps to W.C. and automatic openers. W.C. not provided. Provide special stalls.	\$ 36,000.00
3.3.6	Availability of hazardous materials audit (i.e., evidence of safety concerns with respect to asbestos, PCB's, chemicals).	4	All	None observed, no audit available.	\$ -
3.3.7	Other health and safety concerns (i.e., evidence of excessive noise conditions, air quality problems)	2	All	Poor air quality, dusty carpets.	See Mechanical
Other					
	Overall Bldg Interior Condition & Estim Costs				\$ 377,300.00

Part II - Physical Condition

ection 4	Mechanical Systems	Rating		Comments/Concerns		
4.1	Mechanical Site Services					
	Site drainage systems (i.e., surface and underground systems, catch basins).	4		The site drainage system is underground system installed on the site. The system is fine.		
	Exterior plumbing systems (i.e., irrigation systems, hose bibs).	5		The irrigation system does not exist. The NFHB are in fair condition.		
4.1.3	Outside storage tanks.	N/A		None		
Other						
4.2	Fire Suppression Systems		Bldg. <u>Section</u>	Description/Condition		
4.2.1	Fire hydrants and Siamese connections.	N/A		None		
4.2.2	Fire suppression systems (i.e., pumps, sprinklers, piping, reservoirs, hoses, stand pipes, CO2 systems).	N/A		None are required		
	Hand extinguishers, blankets and showers (i.e., in CTS areas).	4	All sections	Fire extinguishers are in fair condition.		
	Other special situations (e.g., flammable storage areas, science labs, CTS areas).	N/A	All section	None are required		
Other						

Part II - Physical Condition

Section 4	Mechanical Systems	Rating	Comments/Concerns		Estim. Cost
4.3	Water Supply and Plumbing Systems		Bldg. <u>Section</u>	Description/Condition	
4.3.1	Domestic water supply (i.e., pressure, volume, quality note whether municipal or well supply).	5	All sections	Domestic water supply is from the water main in the street (municipal water supply). There is no problem with water pressure, volume and water quality.	
4.3.2	Water treatment system(s).	5	All sections	The domestic water supply is from the City Main. The water is treated and is in good condition.	
4.3.3	Pumps and valves (including Backflow prevention valves).	5	All sections	The domestic water circulation pumps and valves are in good condition.	
4.3.4	Piping and fittings.	5		All piping and fittings are not showing evidence of corrosion and are in fair condition.	
4.3.5	Plumbing fixtures (i.e., toilets, urinals, sinks)	4		All plumbing fixtures have individual isolation valves, and meet all code requirements.	
	Domestic hot water system (i.e., heater, storage tanks, failure alarms, pressure, volume, recirculation).	5		The domestic hot water system consists of one (1) natural gas fired heater. The capacity and conditions are good.	
	Sanitary and storm sewers, including sumps and pits (note whether sewage system is municipal or septic).	4	All sections	The sanitary sewer system including sumps and pits is municipal type of system and is in fair condition. Storm system inside of the building is also in fair condition.	
Other					

Part II - Physical Condition

Section 4	Mechanical Systems	Rating		Comments/Concerns		
4.4	Heating Systems		Bldg. <u>Section</u>	Description/Condition		
4.4.1	Heating capacity and reliability (including backup capacity).	1	All sections	The existing heating system consists of two (2) natural gas fired Standard Dominion original steam boilers converted from coal fired to gas fired and condensate return system and pump in the Boiler Room. The system is obsolete, and has exceeded its life expectancy. The existing heating system should be replaced with new hot water heating system.	\$95,000	
4.4.2	Heating controls (including use of current energy management technology.	1	All sections	The existing mechanical system is not using current energy management technology. New DDC control system is recommended.	included in 4.4.1	
4.4.3	Fresh air for combustion and condition of the combustion chimney.	1	All sections	The existing combustion air is not sufficient and a new chimney is required.	included in 4.4.1	
4.4.4	Treatment of water used in heating systems.	N/A	All sections			
4.4.5	Low water cutoff/pressure relief valves and failure alarms (i.e., hot water heating).	1	All sections	Each boiler is complete with pressure relief valve, but conditions are poor	included in 4.4.1	
4.4.6	Heating air filtration systems and filters.	N/A	All sections			
4.4.7	Heating humidification systems and components.	N/A	All sections			

Part II - Physical Condition

Section 4	Mechanical Systems	Rating		Comments/Concerns		
4.4	Heating Systems (cont'd)		Bldg. <u>Section</u>	Description/Condition		
	4.8 Heating distribution systems (i.e., piping, ductwork) and associated components (i.e., diffusers, radiators).	1	All sections	The existing steam system is obsolete and has exceeded its life expectancy. The new hot water heating piping system and ductwork components are required.	see 4.4.1	
4.4.9	Heating piping, valve and/or duct insulation.	1	All sections	The thermal insulation on the existing ductwork and piping system is in poor condition. A new hot water heating pipes insulation will be required.	included in 4.4.1	
4.4.10	Heat exchangers.	N/A	All sections			
4.4.11	Heating mixing boxes, dampers and linkages.	N/A	All sections			
4.4.12	Heating distribution/circulation in larger spaces (i.e., user comfort, temperature of outside wall surfaces).	2	1939	A hot water perimeter radiation system serving Gymnasium does not exist. The heat distribution is poor. A new heating and ventilation system is required.	included in 4.4.1	
4.4.13	Zone/unit heaters and controls.	3		All unit heaters and entrance forced flow heaters are steam type heaters and are obsoltete. A new hot water heaters will be required.	included in 4.4.1	
Other						

Part II - Physical Condition

Section 4	Mechanical Systems	Rating		Comments/Concerns		
4.5	Ventilation Systems		Bldg. Section	Description/Condition		
4.5.1	Air handling units capacity and condition.	1	sections	The existing ventilation system consists of two (2) original Flame Master furnaces serving Gymnasium, and two (2) original classroom mounted univents with steam coil. The entire system is obsolete and had exceeded its life expectancy. The system cannot meet present codes established by ASHRAE 62-1989 Standard. The new ventilation system is required with centrally located,	\$100,000	
	Outside air for the occupant load (if possible, reference CFM/occupant).	1	All sections	The furnaces and univents serving Gymnasium and two (2) classrooms are not capable to provide required minimum 15.0 CFM/student of outside air. A new ventilation system is required.	Cost included in 4.5.1	
	Air distribution system (if possible, reference number of air changes/hour).	1		The air changes provided to each Classroom and Gymnasium are set at 2. A new air ductwork is required.	See 4.5.1	
4.5.4	Exhaust systems capacity and condition.	4	All sections	All exhaust fans have sufficient capacity and are in good condition.		
4.5.5	Separation of out flow from air intakes.	4	All sections	Are set at min. 10 Ft. which is acceptable		
	Special/dedicated ventilation and/or exhaust systems (i.e., kitchen, labs, CTS areas).	4	All sections	The fume hood is not provided in the lab area.		
Other						

Part II - Physical Condition

Section 4	Mechanical Systems	Rating		Comments/Concerns			
	Ventilation Systems (cont'd)		Bldg. <u>Section</u>	Description/Condition			
	Note: Only complete the following items if there are separate ventilation and heating systems.						
4.5.7	Ventilation controls (including use of current energy management technology).	N/A	All sections				
4.5.8	Air filtration systems and filters.	N/A	All sections				
4.5.9	Humidification system and components.	N/A	All sections				
4.5.10	Heat exchangers.	N/A	All				
4.5.11	Ventilation distribution system and components (i.e., ductwork, diffusers, mixing boxes, dampers,	N/A	All				
Other	auctwork, unusers, mixing boxes, uampets,		sections				

Part II - Physical Condition

Section 4	Mechanical Systems	Rating		Comments/Concerns	Estim. Cost
4.6	Cooling Systems		Bldg. <u>Section</u>	Description/Condition	
4.6.1	Cooling system capacity and condition (i.e., chillers, cooling towers, condensers).	N/A			
4.6.2	Cooling distribution system and components (i.e., ductwork, diffusers, mixing boxes, dampers, linkages)	N/A			
4.6.3	Cooling system controls (including use of current energy management technology).	N/A			
4.6.4	Special/dedicated cooling systems (i.e., labs, CTS areas).	N/A			
Other					
	Building Control Systems		Bldg. <u>Section</u>	Description/Condition	
4.7.1	Building wide/system wide control systems and/or energy management systems.	2	All sections	A new DDC control sysytem is recommended for the new heating and ventilation system.	\$30,000
	Overall Mech Systems Condition & Estim. Costs				\$225,000

Part II - Physical Condition

Section 5	Electrical Systems	Rating		Comments/Concerns	Estim. Cost
5.1	Site Services				
5.1.1	Primary service capacity and reliability (i.e., access, location, components, installation, bus sizes - note whether overhead or underground).	3		Overhead electrical service 300A 120/240V single phase and 3 wire. The peak demand in the last 12 months was 27 KVA = 113A. The service is original and in poor condition. Provide new distribution system.	\$20,000.00
5.1.2	Site and building exterior lighting (i.e., safety concerns).	4		The Building Lighting has a mixture of incandescent wall lights and exterior HID luminaires. No safety concerns. Lighting is in good condition.	
5.1.3	Vehicle plug-ins (i.e., number, capacity, condition).	4		Adequate capacity to handle all staff and teachers. Total of 9 existing car plugs. Car plugs are in good condition.	
Other					
5.2	Life Safety Systems		Bldg. Section	Description/Condition	
5.2.1	Fire and smoke alarm systems (i.e., safety concerns, up-to-date technology, regularly tested).	4	1954	The fire alarm control panel is a Simplex 2001 and installed in September 1986. Tested on an annual basis. 8 zone panel c/w 1 spare zone.	
5.2.2	Emergency lighting systems (i.e., safety concerns, condition).	2		Emergency lighting, is in poor condition. The battery packs and remote heads are original to the building. Provide new battery packs and remote heads.	\$2,000.00
5.2.3	Exit lighting and signage (i.e., safety concerns, condition).	3		Exit signs are old incandescent style. Provide new energy efficient LED exit lights.	\$1,500.00
Other		2		There are four existing fire alarm bells. Replace with four new fire alarm bell/strobe combinations.	\$1,000.00

Part II - Physical Condition

Sch	nool:	St.	John
Date:	April	11,	2000

	Electrical Systems	Rating		Comments/Concerns	Estim. Cost
5.3	Power Supply and Distribution		Bldg.	Description (Constitute	
5.3.1	Power service surge protection.	N/A	Section	<u>Description/Condition</u>	
5.3.2	Panels and wireways capacity and condition.	3	ALL	Panels are at 95% of capacity. Panels are in poor condition. Provide new	\$5,500.00
				panels.	
5.3.3	Emergency generator capacity and condition and/or UPS (if applicable).	N/A			
	or of the appropriately.				
5.3.4	General wiring devices and methods.	3	ALL	Wiring is in poor condition. Original to building. Provide new branch circuit wiring.	\$20,000.00
525	Motor controls.	4	ALL	Controls are in fair condition. Original to building. Controls are pneumatic.	
3.3.3	iviolor controls.	4	ALL	Controls are in fair condition. Original to building. Controls are prieumatic.	
Other					

Part II - Physical Condition

Section 5	Electrical Systems	Rating		Comments/Concerns	Estim. Cost
5.4	Lighting Systems		Bldg.	D 111 (0 111)	
5.4.1	Interior lighting systems and components (i.e., illumination levels, conditions, controls).	2	<u>Section</u> 1939	<u>Description/Condition</u> Library 500 Lux; Classroom 450 Lux; Science Lab 500 Lux; Office Area 600 Lux; Classroom 500 Lux; Gym 350 Lux. The existing lighting is T12 magnetic ballasts and lamps. Upgrade to T8 electronic ballasts and lamps.	\$70,500.00
			1954	Office Area 600 Lux; Classroom 500 Lux. The existing lighting is T12 magnetic ballasts and lamps. Upgrade to T8 electronic ballasts and lamps.	
			1971	Gym 350 Lux. The existing lighting is T12 magnetic ballasts and lamps. Upgrade to T8 electronic ballasts and lamps.	
5.4.2	Replacement of ballasts (i.e., health and safety concerns).	3	ALL	PCB ballasts are replaced when they burn out. Replace all PCB ballasts.	\$3,500.00
5.4.3 Other	Implementation of energy efficiency measures and recommendations.	2	ALL	Upgrade all T12 magnetic ballasts and lamps to T8 electronic ballast and energy efficient lamps.	See 5.4.1

Part II - Physical Condition

Section 5	5 Electrical Systems	Rating	Comments/Concerns					
5.5	5 Network and Communication Systems		Bldg. Section Description/Condition					
5.5.1	Telephone system and components (i.e., capacity, reliability, condition).	4		There are two outside lines and one fax line. One internet line. Telephone system is in good condition.				
5.5.2	Other communication systems (i.e., public address, intercom, CCTV, satellite or cable TV).	2		There is no PA system. No CCTV, satellite, or cable T.V. Provide new PA system.	\$25,000.00			
	Network cabling (if available, should be category 5 or better).	N/A						
5.5.4	Network cabling installation (i.e., in conduit, secured to walls or tables).	N/A						
	Wiring and telecommunication closets (i.e., size, security, ventilation/cooling, capacity for growth).	2		No capacity for growth on existing server. Server Room is not ventilated. Provide new exhaust fan. Provide new 24 port patch panel and hub. Provide new data outlet in each classroom.	\$7,000.00			
	Provision for dedicated circuits for network equipment (i.e., hubs, switches, computers).	3	ALL	Provide new dedicated outlet in each classroom. Provide dedicated outlet for server.	\$600.00			
Other								

Part II - Physical Condition

Section 5	Electrical Systems	Rating		Comments/Concerns	Estim. Cost
5.6	Miscellaneous Systems		Bldg. Section	Description/Condition	
5.6.1	Site and building surveillance system (if applicable).	N/A			
5.6.2	Intrusion alarms (if applicable).	4	ALL	Microcom model# AM1800 monitoring system with motion sensors in office area and corridors. The system is in good condition.	
5.6.3	Master clock system (if applicable).	4	ALL	No master clock system. Clocks are battery operated. Good condition.	
Other					
5.7	Elevators/Disabled Lifts (If applicable)				
	Elevator/lift size, access and operating features (i.e., sensing devices, buttons, phones, detectors).	N/A			
5.7.2	Condition of elevators/lifts.	N/A			
5.7.3	Lighting and ventilation of elevators/lifts.	N/A			
Other					
	Overall Elect. Systems Condition & Estim Costs				\$156,600.00

Part II - Physical Condition

Section 6	Portable Buildings	Rating	Comments/Concerns	Estim. Cost
	Note: Separate sheets can be completed, if necessary, for portable buildings of different ages and/or conditions. Foundation and structure (i.e., signs of bending,		Not Applicable	
	cracking, settlement, rust, voids, stains).			
	Roof materials and components (i.e., signs of deterioration, leaks, ice build-up).			
	Exterior wall finishes (i.e., signs of deterioration, cracks, water stains).			
	Doors and windows (i.e., signs of deterioration, rusting hardware, glass cracks, peeling paint, damaged seals).			
6.1.5	Interior finishes (i.e., floors, walls, ceiling).			
6.1.6	Millwork (i.e., counters, shelving, vanities, cabinets).			
	Fixed/wall mounted equipment (i.e., writing boards, tackboards, display boards, signs)			
6.1.8	Heating system.			
6.1.9	Ventilation system.			
6.1.10	Electrical, communication and data network systems.			
	Health and safety concerns (i.e., fire and smoke alarms, fire protection systems, exiting, fire resistance rating of materials).			
6.1.12	Barrier-free access.			
	Overall Portable Bldgs Condition & Estim Costs			

School Facility Evaluation Project Part II - Physical Condition

0			This Fa	cility	Ec	quiv. Nev	w Facility	Surplus/	
Section 7	Space Adequacy	No.	Size	Total Area	No.	Size	Total Area	Deficiency	Comments/Concerns
7.1	Classrooms	4	66.90	267.60	4	80	320	-52.4	
7.2	Science Rooms/Labs	1		127.00	1		95	32	
7.3	Ancillary Areas (i.e., Art, Computer Labs, Drama, Music,)	1		163.00	1 2	130 90	310	-147	
7.4	Gymnasium (incl. gym storage)	1		250.00	1	250 25	275	-25	
7.5	Library/Resource Areas	1		155.00	1		100	55	
	Administration/Staff, Physical Education, Storage Areas			153.50			259	-105.5	
7.7	CTS Areas								
1.1	7.7.1 Business Education								
	7.7.2 Home Economics								
	7.7.3 Industrial Arts								
	7.7.4 Other CTS Programs								
	Other Non-Instructional Areas (i.e., circulation, wall area, crush space, wc area)			634.80			479	155.8	
	Overall Space Adequacy Assessment			1750.9			1838.00	-87.1	

School: St. John Date: April 11, 2000

Part II - Physical Condition

Evaluation Component/ Sub-Component Additional Notes and Comments	
	i