

School Facility Evaluation Project
Part III - Space Adequacy

School Name:	St. Martha School			School Code:	8050	
Location:	Edmonton			Facility Code:	1993	
Region:	Central			Superintendent:	Dr. Dale Ripley	
Jurisdiction:	Edmonton Catholic Regional Division No. 40			Contact Person:	Mr. Garnet Mc Kee	
				Telephone:	(780) 453-4500	
Grades:	K-6			School Capacity:	450	
Building Section	Year of Compl.	No. of Floors	Gross Bldg Area (Sq.M.)	Type of Construction (i.e., structure, roof, cladding)	Description of Mechanical Systems (incl. major upgrades)	Comments/Notes
Original Building	1980	1	2338.3	masonry construction, steel structure, flat and low slope roof, face brick and stucco cladding.	hot water heating, air handling units.	
Additions/ Expansions	1981	1	393.60	wood frame portables	furnaces	
	1985	1	167.0	wood frame portables	furnaces	
	1992	1	83.50	wood frame portables	furnaces	
	1994	1	83.50	wood frame portables	furnaces	
					Evaluator's Name:	Burgess Bredo
					& Company:	Burgess Bredo Architect Ltd.

School Facility Evaluation Project
Part III - Space Adequacy

Upgrading/ Modernization (identify whether minor or major)	1991	1	74.0	Minor: covert stage to a computer room.		
	1996	1	128.5	Minor: new carpet in Library.		
	1997	1	580.5	Minor: replace flooring in 8 portables with vinyl tiles.		
	2000	1	128.5	Minor: upgrade ventilation system within computer lab/library (August 2000).		
Portable Struct. (identify whether attached/perman. or free-standing/ relocatable)	1981	1	393.6	wood frame, flat roof, wood cladding.	furnaces	4 units built in 1981 (ECS units 163-166) attached to school, relocatable.
	1985	1	203.6	wood frame, flat roof, wood cladding.	furnaces	2 units built in 1982 (ECS units 185, 186) attached to school, relocatable.
	1992		105.0	wood frame, flat roof, wood cladding.	furnaces	1 unit built in 1986 (ECS unit 223) attached to school, relocatable.
	1994		85.0	wood frame, flat roof, wood cladding.	furnaces	1 unit built in 1990 (ECS unit 238) attached to school, relocatable.
List of Reports/ Supplementary Information	Fire Alarm System Annual Test; August 18, 1999 (Top Fire Safety)					

School Facility Evaluation Project
Part III - Space Adequacy

	Evaluation Components	Summary Assessment	Estim. Cost
1	Site Conditions	Repair problems due to settlement. Re-configure parking to eliminate unsafe condition.	\$29,500.00
2	Building Exterior	Replace roofing. Miscellaneous minor repairs.	\$133,000.00
3	Building Interior	Mud jack slab. Upgrade finishes and selected millwork. Replace acoustic wall panels. Modification for barrier free access.	\$147,600.00
4	Mechanical Systems	Mechanical system is in good shape with only minor repairs required to hot water tank.	\$300.00
5	Electrical Systems	Electrical system generally in good shape, however, fire alarm system is old and should be upgraded along with emergency lighting system, exit signs, and building intercom system. Also, fluorescent lights should be retrofitted to T8 style lamps with electronic ballasts.	\$164,800.00
6	Portable Buildings	Replace roofing. Upgrade interior finishes. Reinforce floor assembly.	\$124,200.00
7	Space Adequacy:		
	7.1 Classrooms	Slightly Excessive +9.5	
	7.2 Science Rooms/Labs	Deficient -184.3	
	7.3 Ancillary Areas	Deficient -165.9	
	7.4 Gymnasium	Excessive +47.4	
	7.5 Library/Resource Areas	Deficient -55.7	
	7.6 Administration/Staff Areas	Deficient -350.8	
	7.7 CTS Areas		
	7.8 Other Non-Instructional Areas (incl. gross-up)	Deficient -291.3	
	Overall School Conditions & Estim. Costs	Deficient -639.1	\$599,400.00

School Facility Evaluation Project
Part III - Space Adequacy

Section 1	Site Conditions	Rating	Comments/Concerns	Estim. Cost
1.1	General Site Conditions			
1.1.1	Overall site size.	4	Large site shared with adjacent Community League.	
1.1.2	Outdoor athletic areas.	4	Grass and hard surface. Topsoil and re-seeding required on several areas adjacent school. Asphalt hard surface behind school.	
1.1.3	Outdoor playground areas, including condition of equipment and base.	4	Basketball backboards on hard surface and adventure playground on sand base, located on adjacent Community League property but used by school. Softball and soccer field.	
1.1.4	Site landscaping.	4	Mature trees and lawn located on east side of school. Balance is rough grass.	
1.1.5	Site accessories (i.e., perimeter and other fencing, guard rails, bike stands, flag poles).	4	Railing along parking lot, bike stands and flag poles. No fencing.	
1.1.6	Surface drainage conditions (i.e., drains away from building, signs of ponding).	3	Settlement in areas causing drainage towards building. Re-grade and re-seed.	\$2,500.00
1.1.7	Evidence of sub-soil problems.	3	Settlement causing sidewalks to crack and break up.	Costed in 1.3.5
1.1.8	Safety and security concerns due to site conditions.	3	Students crossing parking lot to access basketball and playground is a concern. Re-configure parking lot and introduce barrier (fence) to avoid conflict.	\$22,000.00
Other				
1.2	Access/Drop-Off Areas/Roadways/Bus Lanes			
1.2.1	Vehicular and pedestrian access points (i.e., size, number, visibility, safety).	4	Single vehicle access from 180 Street, pedestrian access from City sidewalk along 180 Street.	

School Facility Evaluation Project
Part III - Space Adequacy

Section 1	Site Conditions	Rating	Comments/Concerns	Estim. Cost
1.2.2	Surfacing of on-site road network (note whether asphalt or gravel).	4	Short asphalt paved driveway from 180 Street to parking lot.	
1.2.3	Bus lanes/drop-off areas (note whether on-site or off-site).	4	Bus drop off located off site on 180 Street.	
1.2.4	Fire vehicle access.	4	Good access to all portions of building.	
1.2.5	Signage.	4	Building signed. Parking signed.	
Other				

School Facility Evaluation Project
Part III - Space Adequacy

Section 1	Site Conditions	Rating	Comments/Concerns	Estim. Cost
1.3	Parking Lots and Sidewalks			
1.3.1	Number of parking spaces for staff, students and visitors (including stalls for disabled persons).	4	16 energized stalls for staff, 18 stalls for visitors/Community League.	
1.3.2	Layout and safety of parking lots.	3	Layout of parking is functional but students crossing parking lot to access playground is a safety hazard.	Costed in 1.1.8
1.3.3	Surfacing and drainage of parking lots (note whether asphalt or gravel).	4	Driveway and parking aisle closest to school are paved. Aisle farthest from school is gravel. Drainage appears sufficient.	
1.3.4	Layout and safety of sidewalks.	4	Sidewalks separated from vehicle traffic.	
1.3.5	Surfacing and drainage of sidewalks (note type of material).	3	Concrete sidewalks cracking and breaking up due to settlement. Some have already been replaced, additional areas require replacement.	\$5,000.00
1.3.6	Curb cuts and ramps for barrier free access.	4	No curb cuts provided but no step between parking lot and sidewalk to main entrance.	
Other				
	Overall Site Conditions & Estimated Costs			\$29,500.00

School Facility Evaluation Project
Part III - Space Adequacy

Section 2	Building Exterior	Rating	Comments/Concerns		Estim. Cost
2.1	Overall Structure		Bldg. Section	Description/Condition	
2.1.1	Floor structure and beams (i.e., signs of bending, cracking, heaving, settlement, voids, rust, stains).	3	1980	Concrete slab on grade, suspended floors are cast in place concrete. Settlement problems in a number of areas. Mud jack slab to raise floor level.	Costed in 3.1.2
2.1.2	Wall structure and columns (i.e., signs of bending, cracking, settlement, voids, rust, stains).	4	1980	Concrete block; no problems evident.	
2.1.3	Roof structure (i.e., signs of bending, cracking, voids, rust, stains).	4	1980	Open web steel joists with metal deck; no problems evident.	
Other					

Section 2	Building Exterior	Rating	Comments/Concerns	Estim. Cost
2.2	Roofing and Skylights <i>Identify the availability of an up-to-date inspection report or roofing program. Note if roof sections are of different ages and/or in varying</i>			
2.2.1	Based on the inspection report (and to the extent possible, direct observation), assess and rate roof conditions and estimate costs for required improvements (i.e., covering materials, membrane, insulation, other components).	3	1980 Original conventional BUR, near flat in most areas; pitched 1:7 adjacent gymnasium. Chronic Leaks in a number of areas; replace roof (2,338 sq.m.). No roofing report available.	\$130,000.00
2.2.2	Roof accessories (i.e., ladders, stairs, hatches, masts, exhaust hoods, chimneys, gutters, downspouts, splashpads).	4	1980 Roof accessed by door from mechanical mezzanine; no problems evident.	
2.2.3	Control of ice and snow falling from roof.	4	1980 No problems evident.	
2.2.4	Skylights (i.e., signs of distress, leaks, ice build-up, condensation, deteriorated materials/seals).	N/A	No skylights	
Other				

Section 2	Building Exterior	Rating	Comments/Concerns	Estim. Cost
2.3	Exterior Walls/Building Envelope			
2.3.1	Exterior wall finishes (i.e., signs of deterioration, cracks, brick spalling, effluorescence, water stains).	4	1980 Face brick, metal wall cladding and stucco; minor damage to metal wall cladding otherwise good condition.	
2.3.2	Fascias, soffits, parapets (i.e., signs of looseness, stains, rust, peeling paint).	4	1980 Vented stucco soffits, pre-finished metal flashings at parapets; no problems evident. Attractive painted mural at fascia over main entrance.	
2.3.3	Building envelope (i.e., evidence of air infiltration/exfiltration through the exterior wall or ice build up on wall, eaves, canopy).	4	1980 Painted concrete block walls and conventional BUR are primary components of envelope. No evidence of air infiltration/exfiltration.	
2.3.4	Interface of roof drainage and ground drainage systems.	4	1980 Roof drains tied in to City storm sewer.	
2.3.5	Inside faces of exterior walls (i.e., signs of cracks, water stains, dust spots).	4	1980 Minor cracking in concrete block walls but otherwise in good condition.	
Other				
2.4	Exterior Doors and Windows			
2.4.1	Doors (i.e., signs of deterioration, rusting metal, glass cracks, peeling paint, damaged seals, sealed unit failure).	4	1980 Hollow metal doors with and without glazing set in pressed steel frames; no problems evident.	

Section 2	Building Exterior	Rating	Comments/Concerns		Estim. Cost
2.4.2	Door accessories (i.e., latches, hardware, screens, locks, alarms, holders, closers, security devices).	3	1980	Weather-stripping worn; replace.	\$500.00
2.4.3	Exit door hardware (i.e., safety and/or code concerns).	4	1980	Panic hardware functioning properly.	
2.4.4	Windows (i.e., signs of deterioration, rusting metal, glass cracks, peeling paint, damaged seals, sealed unit failure).	3	1980	Aluminum framed with vents. Windows feel drafty and vent hardware a problem; replace hardware and weather stripping.	\$1,500.00
2.4.5	Window accessories (i.e., latches, hardware, screens, locks, alarms, holders, closers, security devices).	3	1980	Insect screens missing on a number of vents; replace. Security grilles on a number of doors adjacent play areas.	\$1,000.00
2.4.6	Building envelope (i.e., signs of heavy condensation on doors or windows).	4	1980	Aluminum windows and glazed hollow metal doors; no problems evident.	
Other					
	Overall Bldg Exterior Condition & Estim Costs				\$133,000.00

School Facility Evaluation Project
Part III - Space Adequacy

Section 3	Building Interior - Overall Conditions	Rating	Comments/Concerns		Estim. Cost
3.1	Interior Structure		Bldg. Section	Description/Condition	
3.1.1	Interior walls and partitions (i.e., signs of cracks, spalling, paint peeling).	4	1980	Concrete block and frame; no problems evident.	
3.1.2	Floors (i.e., signs of cracks, heaving, settlement).	3	1980	Concrete slab on grade; settlement problems in a number of areas, mud jack slab.	\$2,000.00
Other					
3.2	Materials and Finishes				
3.2.1	Floor materials and finishes.	3	1980	Vinyl tile in halls and most classrooms; good. Carpet in one classroom worn; replace. Wood parquet floor in gym damaged where slab has settled; repair and refinish after mud jacking. Seamless flooring cracked, repair after mud jacking.	\$14,500.00
3.2.2	Wall materials and finishes.	3	1980	Painted concrete block and gypsum board; should be re-painted. Acoustic wall panels in gym coming apart; replace.	\$34,000.00
3.2.3	Ceiling materials and finishes.	3	1980	Acoustic tiles set in T-bar grid in most areas, painted gypsum board. Tiles damaged and water stained in areas; replace approximately 25%	\$7,000.00

School Facility Evaluation Project
Part III - Space Adequacy

Section 3	Building Interior - Overall Conditions	Rating	Comments/Concerns	Estim. Cost
3.2	Materials and Finishes (cont'd)			
3.2.4	Interior doors and hardware.	4	1980 Wood and hollow metal set in pressed steel frame; no problems evident.	
3.2.5	Millwork	3	1980 Boot shelves below coat racks in hallways are millwork item with plastic laminate in poor condition; replace. Additional storage shelving required in classrooms. Painted wood cabinets with plastic laminate in balance; good condition. Add purpose built millwork in former science lab being adapted for use as computer lab.	\$43,000.00
3.2.6	Fixed/wall mounted equipment (i.e., writing boards, tackboards, display boards, signs).	3	1980 60% of boards are whiteboards; replace remainder. Tackboards in good condition.	\$2,800.00
3.2.7	Any other fixed/mounted specialty items (i.e., CTS equipment, gymnasium equipment).	4	1980 Climbing apparatus and basketball backboards in good condition.	
3.2.8	Washroom materials and finishes.	3	1980 Floors: vinyl tile in mismatched patterns and in poor condition; replace. Walls: painted concrete block; good. Ceilings: painted gypsum board; good.	\$1,600.00
Other		3	1980 Metal toilet partitions in good condition. Acoustic wall panels in gym coming apart; replace.	\$12,300.00

Section 3	Building Interior - Overall Conditions	Rating	Comments/Concerns	Estim. Cost
3.3	Health and Safety Concerns --- <i>Intent is to identify renovations considered necessary to meet applicable codes, primarily due to safety concerns. Basis of evaluation should be an up-to-date inspection report from the authority having jurisdiction together with direct observations as appropriate. Evaluator should note if in his opinion a comprehensive code evaluation is</i>			
3.3.1	Building construction type - combustible or non-combustible, sprinklered or non-sprinklered.	4	1980 Non-combustible, non-sprinklered.	
3.3.2	Fire separations (i.e., between buildings, wings, zones if non-sprinklered).	3	1980 Building split into zones but corridor doors are wedged open; replace with electromagnetic hold opens.	\$2,400.00
3.3.3	Fire resistance rating of materials (i.e., corridor walls and doors).	4	1980 Appear to comply.	
3.3.4	Exiting distances and access to exits.	4	1980 Appear to comply.	
3.3.5	Barrier-free access.	3	1980 Path of travel: stair lift required to Stage(instructional space). Doors and doorways: power assisted entrance required. Washrooms: minor modifications required to comply.	\$23,000.00
3.3.6	Availability of hazardous materials audit (i.e., evidence of safety concerns with respect to asbestos, PCB's, chemicals).	3	1980 No asbestos audit available; provide.	\$5,000.00
3.3.7	Other health and safety concerns (i.e., evidence of excessive noise conditions, air quality problems)	4	1980 No concerns.	
Other				
	Overall Bldg Interior Condition & Estim Costs			\$147,600.00

Section 4	Mechanical Systems	Rating	Comments/Concerns		Estim. Cost
4.1	Mechanical Site Services				
4.1.1	Site drainage systems (i.e., surface and underground systems, catch basins).	4	1980	One catch basin to parking lot and surface drainage to field. No problems noted.	
4.1.2	Exterior plumbing systems (i.e., irrigation systems, hose bibs).	4	1980	A few hose bibBs at building exterior. No Irrigation. No problems noted.	
4.1.3	Outside storage tanks.	N/A			
Other					
4.2	Fire Suppression Systems				
4.2.1	Fire hydrants and siamese connections.	N/A			
4.2.2	Fire suppression systems (i.e., pumps, sprinklers, piping, reservoirs, hoses, stand pipes, CO2 systems).	N/A		Not required.	
4.2.3	Hand extinguishers, blankets and showers (i.e., in CTS areas).	4	1980	Pump type water fire extinguishers, last certified 08/99 in recessed cabinets.	
4.2.4	Other special situations (e.g., flammable storage areas, science labs, CTS areas).	N/A		Not required.	
Other					

Section 4	Mechanical Systems	Rating	Comments/Concerns		Estim. Cost
4.3	Water Supply and Plumbing Systems				
4.3.1	Domestic water supply (i.e., pressure, volume, quality note whether municipal or well supply).	4	1980	101 mm main water service with a 25 mm water meter. All appear in good shape with no problems noted.	
4.3.2	Water treatment system(s).	N/A			
4.3.3	Pumps and valves (including backflow prevention valves).	4	1980	No pumps, Valves appear in good shape. No problems noted.	
4.3.4	Piping and fittings.	4	1980	Copper water supply piping. All piping appears in good shape.	
4.3.5	Plumbing fixtures (i.e., toilets, urinals, sinks)	4	1980	Wall hung urinals with flush valves, recess lavatories, and floor mounted water closets with flush valves. No problems noted.	
4.3.6	Domestic hot water system (i.e., heater, storage tanks, failure alarms, pressure, volume, recirculation).	2	1980	State 75 gal hot water heater complete with Armstrong pump. Draft hood has separated from breaching and tank and requires immediate repair.	\$300.00
4.3.7	Sanitary and storm sewers, including sumps and pits (note whether sewage system is municipal or septic).	4	1980	Municipal service connection to building with no problems noted.	
Other					

Section 4	Mechanical Systems	Rating	Comments/Concerns		Estim. Cost
4.4	Heating Systems				
4.4.1	Heating capacity and reliability (including backup capacity).	4	1980	Two Raypak 749.8 boilers with two circulating pumps. Installation appears in good shape with no problems noted.	
4.4.2	Heating controls (including use of current energy management technology).	4	1980	Boilers controlled by building energy management system with no problems noted.	
4.4.3	Fresh air for combustion and condition of the combustion chimney.	4	1980	Combustion air appears to be adequate. Chimney constructed of galvanized sheet metal and appears in good shape.	
4.4.4	Treatment of water used in heating systems.	4	1980	Heating water treated with chemicals on a regular basis with no problems noted.	
4.4.5	Low water cutoff/pressure relief valves and failure alarms (i.e., hot water heating).	4	1980	Low water cut-off, pressure relief, and flow switches to boilers. Boiler alarm provided through building energy management system. All appears in good shape with no problems noted.	
4.4.6	Heating air filtration systems and filters.	4	1980	Ventilation system has replaceable media type filters in metal frames. No problems noted.	
4.4.7	Heating humidification systems and components.	4	1980	Two Nortec steam type humidifiers with one installed per ventilation unit. No problems noted.	

Section 4	Mechanical Systems	Rating	Comments/Concerns		Estim. Cost
4.4	Heating Systems (cont'd)				
4.4.8	Heating distribution systems (i.e., piping, ductwork) and associated components (i.e., diffusers, radiators).	4	1980	Schedule 40 steel piping provided for hot water heating and ductwork for ventilation air. No problems noted.	
4.4.9	Heating piping, valve and/or duct insulation.	4	1980	Fiberglass pipe insulation provided to all domestic water and heating piping. Insulation appears in good shape with no problems noted.	
4.4.10	Heat exchangers.	4	1980	Tube style boilers. Heat exchangers appear in good shape with no problems noted.	
4.4.11	Heating mixing boxes, dampers and linkages.	4	1980	Ventilation units appear in good shape with no problems noted.	
4.4.12	Heating distribution/circulation in larger spaces (i.e., user comfort, temperature of outside wall surfaces).	4	1980	Even heating throughout building with no problems noted.	
4.4.13	Zone/unit heaters and controls.	4	1980	Convectors in corridors, force flow units in vestibules, and unit heater in mechanical room. No problems noted.	
Other					

Section 4	Mechanical Systems	Rating	Comments/Concerns		Estim. Cost
4.5	Ventilation Systems				
4.5.1	Air handling units capacity and condition.	4	1980	Two built-up Trane ventilating units with supply and return fans, mixing section, and heating coil for heating. All appear in good shape with no problems noted.	
4.5.2	Outside air for the occupant load (if possible, reference CFM/occupant).	4	1980	Design requirements unknown. Likely designed for 15 CFM per student. Installation appears satisfactory with no problems noted.	
4.5.3	Air distribution system (if possible, reference number of air changes/hour).	4	1980	Design requirements unknown. Air flow appears good with no problems noted.	
4.5.4	Exhaust systems capacity and condition.	4	1980	Exhaust system capacity unknown. Exhaust system appears to service washrooms and storage areas with no problems noted.	
4.5.5	Separation of out flow from air intakes.	4	1980	Appears to be good separation with no problems noted.	
4.5.6	Special/dedicated ventilation and/or exhaust systems (i.e., kitchen, labs, CTS areas).	N/A			
Other					

Section 4	Mechanical Systems	Rating	Comments/Concerns		Estim. Cost
4.5	Ventilation Systems (cont'd)				
	<i>Note: Only complete the following items if there are separate ventilation and heating systems.</i>				
4.5.7	Ventilation controls (including use of current energy management technology).	N/A			
4.5.8	Air filtration systems and filters.	N/A			
4.5.9	Humidification system and components.	N/A			
4.5.10	Heat exchangers.	N/A			
4.5.11	Ventilation distribution system and components (i.e., ductwork, diffusers, mixing boxes, dampers, linkages).	N/A			
Other					

Section 4	Mechanical Systems	Rating	Comments/Concerns		Estim. Cost
4.6	Cooling Systems				
4.6.1	Cooling system capacity and condition (i.e., chillers, cooling towers, condensers).	N/A			
4.6.2	Cooling distribution system and components (i.e., ductwork, diffusers, mixing boxes, dampers, linkages)	N/A			
4.6.3	Cooling system controls (including use of current energy management technology).	N/A			
4.6.4	Special/dedicated cooling systems (i.e., labs, CTS areas).	4	1980	Construction is underway to provide air conditioning to the Library/Computer room.	
Other					
4.7	Building Control Systems				
4.7.1	Building wide/system wide control systems and/or energy management systems.	4	1980	Andover DDC control system. No problems noted.	
Overall Mech Systems Condition & Estim. Costs					\$300.00

School Facility Evaluation Project
Part III - Space Adequacy

Section 5	Electrical Systems	Rating	Comments/Concerns		Estim. Cost
5.1	Site Services				
	5.1.1 Primary service capacity and reliability (i.e., access, location, components, installation, bus sizes - note whether overhead or underground).	4	1980	Underground service from pad mounted transformer to 600A main circuit breaker in Federal Pioneer Switchgear, 120/208V/3PH/4W. No problems noted.	
	5.1.2 Site and building exterior lighting (i.e., safety concerns).	3	1980	Upgrade exterior lighting to replace incandescent lights with high pressure sodium fixtures.	\$5,000.00
	5.1.3 Vehicle plug-ins (i.e., number, capacity, condition).	4	1980	Approximately 16 electrified stalls. No problems noted.	
	Other				
5.2	Life Safety Systems				
	5.2.1 Fire and smoke alarm systems (i.e., safety concerns, up-to-date technology, regularly tested).	3	1980	Edwards 6500 fire alarm system. System is old and should be upgraded in order to provide continued service. Also, provide visual strobe lights to comply with current code.	\$40,000.00
	5.2.2 Emergency lighting systems (i.e., safety concerns, condition).	4	1980	DC style battery pack units with remote heads. System appears to be in good operating order with no problems noted.	
	5.2.3 Exit lighting and signage (i.e., safety concerns, condition).	3	1980	Incandescent type exit signs, all in poor shape, upgrade to LED type exit signs.	\$6,000.00
	Other				

Section 5	Electrical Systems	Rating	Comments/Concerns		Estim. Cost
5.3	Power Supply and Distribution				
5.3.1	Power service surge protection.	3	1980	Provide surge protection.	\$4,000.00
5.3.2	Panels and wireways capacity and condition.	3	1980	Panelboards located throughout building. Panels are generally full with minimal spare capacity for future additions. Provide two extra panels to accommodate future wiring.	\$6,000.00
5.3.3	Emergency generator capacity and condition and/or UPS (if applicable).	N/A			
5.3.4	General wiring devices and methods.	3	1980	Wiring devices generally in good shape with stainless steel coverplates. Insufficient receptacles to classrooms to accommodate current electrical loads. Provide additional receptacles to classrooms.	\$8,000.00
5.3.5	Motor controls.	4	1980	Motor starters provided to major motor loads. Starters appear in good shape with no problems noted.	
Other					

Section 5	Electrical Systems	Rating	Comments/Concerns		Estim. Cost
5.4	Lighting Systems				
5.4.1	Interior lighting systems and components (i.e., illumination levels, conditions, controls).	3	1980	Lighting in building generally comprises of surface mounted fluorescent light fixtures using T12 lamps. Fixtures and light levels appear good with no problems noted.	Costs in 5.4.3
5.4.2	Replacement of ballasts (i.e., health and safety concerns).	4	1980	No concerns noted.	
5.4.3	Implementation of energy efficiency measures and recommendations.	3	1980	Recommend that fluorescent lighting be retrofitted to T8 style lamps with electronic ballasts.	\$60,800.00
Other					

Section 5	Electrical Systems	Rating	Comments/Concerns		Estim. Cost
5.5	Network and Communication Systems				
5.5.1	Telephone system and components (i.e., capacity, reliability, condition).	4	1980	Standard telephone system with telephones provided to general office. No problems noted.	
5.5.2	Other communication systems (i.e., public address, intercom, CCTV, satellite or cable TV).	3	1980	Older Bogen MCP-35A intercom system. Recommend system be upgraded in order to provide continued service.	\$35,000.00
5.5.3	Network cabling (if available, should be category 5 or better).	4	1980	Category type 5 wiring with no problems noted.	
5.5.4	Network cabling installation (i.e., in conduit, secured to walls or tables).	4	1980	Wiring installed in conduit and wireways. No problems noted.	
5.5.5	Wiring and telecommunication closets (i.e., size, security, ventilation/cooling, capacity for growth).	4	1980	Dedicated hub location. No problems noted.	
5.5.6	Provision for dedicated circuits for network equipment (i.e., hubs, switches, computers).	4	1980	Power wiring to computers and equipment appears to be good with no problems noted.	
Other					

Section 5	Electrical Systems	Rating	Comments/Concerns		Estim. Cost
5.6	Miscellaneous Systems				
5.6.1	Site and building surveillance system (if applicable).	N/A			
5.6.2	Intrusion alarms (if applicable).	4	1980	General type of security system using motion detectors, magnetic door contact switches, and alarm keypad. System monitored through central monitoring station with no problems noted.	
5.6.3	Master clock system (if applicable).	4	1980	Class change appears to be controlled through intercom system.	
Other					
5.7	Elevators/Disabled Lifts (If applicable)				
5.7.1	Elevator/lift size, access and operating features (i.e., sensing devices, buttons, phones, detectors).	N/A			
5.7.2	Condition of elevators/lifts.	N/A			
5.7.3	Lighting and ventilation of elevators/lifts.	N/A			
Other					
Overall Elect. Systems Condition & Estim Costs					\$164,800.00

Section 6	Portable Buildings	Rating	Comments/Concerns	Estim. Cost
	<i>Note: Separate sheets can be completed, if necessary, for portable buildings of different ages and/or conditions.</i>		ST.MARTHA SCHOOL 4 attached on north side, 4 attached on west side. Portables built in 1981 (4), 1982 (2), 1986 (1) and 1990 (1).	
6.1.1	Foundation and structure (i.e., signs of bending, cracking, settlement, rust, voids, stains).	3	Wood blocking on temporary foundations and concrete piles. Floor assembly spongy in areas; reinforce.	\$1,200.00
6.1.2	Roof materials and components (i.e., signs of deterioration, leaks, ice build-up).	3	Conventional BUR, chronic roof leaks; replace roofing.	\$60,000.00
6.1.3	Exterior wall finishes (i.e., signs of deterioration, cracks, water stains).	4	Wood siding re-painted in 1999; no problems evident.	
6.1.4	Doors and windows (i.e., signs of deterioration, rusting hardware, glass cracks, peeling paint, damaged seals).	4	Wood doors set in wood frames. Aluminum framed windows and vents replaced in 1998.	
6.1.5	Interior finishes (i.e., floors, walls, ceiling).	3	Vinyl tile in classrooms replaced in 1997. Vinyl tile in hallways and links in poor condition; replace. Gypsum board walls require re-painting. Acoustic tiles in T-bar grid ceiling in good condition.	\$9,000.00
6.1.6	Millwork (i.e., counters, shelving, vanities, cabinets).	4	Clear finish wood bookshelves.	
6.1.7	Fixed/wall mounted equipment (i.e., writing boards, tackboards, display boards, signs)	4	Whiteboards and tackboards.	
6.1.8	Heating system.	3	Furnaces in portables appear to be Palm Air and are very old and in poor shape - replace with new.	\$40,000.00
6.1.9	Ventilation system.	3	Ventilation provided through furnaces in portables. Replace furnaces with new.	Costs in 6.1.8
6.1.10	Electrical, communication and data network systems.	3	Upgrade lighting to use T8 lamps with electronic ballasts.	\$8,000.00
6.1.11	Health and safety concerns (i.e., fire and smoke alarms, fire protection systems, exiting, fire resistance rating of materials).	3	Upgrade fire alarm bells to include visual strobes. Upgrade emergency lighting as units are old.	\$6,000.00
6.1.12	Barrier-free access.	4	No problems evident.	
	Overall Portable Bldgs Condition & Estim Costs			\$124,200.00

School Facility Evaluation Project
Part III - Space Adequacy

Section 7	Space Adequacy	This Facility			Equiv. New Facility			Surplus/ Deficiency	Comments/Concerns
		No.	Size	Total Area	No.	Size	Total Area		
7.1	Classrooms	14	72.2	1009.5	5 6	80 100	1000	9.5	Based on elementary core tables, capacity 450 (300 core, 150 portables).
7.2	Science Rooms/Labs	1		100.7	3	95	285	-184.3	
7.3	Ancillary Areas (i.e., Art, Computer Labs, Drama, Music,)	2	117	234.1	1 3	130 90	400	-165.9	
7.4	Gymnasium (incl. gym storage)			520.4	1 1	430 43	473	47.4	
7.5	Library/Resource Areas			164.3	1	220	220	-55.7	
7.6	Administration/Staff, Physical Education, Storage Areas			138.2	1 1 1	357 70 62	489	-350.8	
7.7	CTS Areas								
	7.7.1 Business Education								
	7.7.2 Home Economics								
	7.7.3 Industrial Arts								
	7.7.4 Other CTS Programs								
7.8	Other Non-Instructional Areas (i.e., circulation, wall area, crush space, wc area)			546.7	1 1 1 1	445 213 120 60	838	-291.3	
	Overall Space Adequacy Assessment			3065.9			3705	-639.1	