

# **RECAPP Facility Evaluation Report**

## **Calgary School District #19**



### **Viscount Bennett School**

B2514A

Calgary

**Facility Details**

**Building Name:** Viscount Bennett School  
**Address:** 2519 Richmond Road S. W.  
**Location:** Calgary  
  
**Building Id:** B2514A  
**Gross Area (sq. m):** 18,184.90  
**Replacement Cost:** \$31,671,564  
**Construction Year:** 0

**Evaluation Details**

**Evaluation Company:** Quinn Young  
**Evaluation Date:** December 1 2004  
**Evaluator Name:** Mr. Sheldon Quinn

**Total Maintenance Events Next 5 years:** **\$2,161,620**  
**5 year Facility Condition Index (FCI):** **6.83%**

**General Summary:**

The original school was constructed in 1954 with a floor area of 6,935 s.m. In 1957 an addition of 4805 s.m. was built, in 1965 a 6102 s.m. building was added and in 1973 another addition of 1343 s.m. was constructed. The total building area now stands at 19,184.90 s.m..

The 1954 and 1957 buildings consist of a basement, main floor and second floor constructed of slab on grade, clay pot and concrete and metal pan and concrete floors and roof. The 1965 and 1973 buildings are constructed of concrete, steel and open web steel joist assemblies.

Student capacity is approximately 2000 students.

The building is in adequate condition but serious consideration must be given to current building code requirements and hazardous materials abatement.

**Structural Summary:**

The 1954 and 1957 buildings consist of a basement, main floor and second floor constructed of slab on grade, clay pot and concrete and metal pan and concrete floors and roof. The 1965 building consists of a main floor and second floor that are constructed of concrete, steel and open web steel joist assemblies. The 1973 building consists of a basement and a main floor and second floor that are constructed of concrete, steel and open web steel joist assemblies.

The structural components of the building appear to be in acceptable condition although some cracking of concrete elements is evident.

**Envelope Summary:**

The exterior of the buildings are generally finished with low maintenance materials, stucco and brick, but the wood window are in poor condition and should be replaced. Exterior doors are of wood construction, some metal clad, in wood or aluminum frames. The majority of the roof is a SBS modified system. Some areas are still BUR and require repair at the very least. Evidence of several serious roof leaks are visible in ceilings.

The building envelope is in fair condition.

**Interior Summary:**

As reported by the owner, vinyl tile flooring, plaster, drywall mud, pipe insulation and elbows, transite panels and ceiling sprayed texture are all contaminated with asbestos.

The main entrance/gymnasium circulation space has been recently renovated and the finishes are in good condition. Interior finishes in the 1954 & 57 buildings are rudimentary and dated but are in fair condition although carpet and textured ceiling finishes are in desperate need of replacement. Interior finishes in the 1965 and 1973 buildings are durable and in good condition.

**Mechanical Summary:**

The school is in very good condition. Sanitary and domestic water lines are in good shape. Heating distribution of hot water heating and AHUs is satisfactory with no complaints.

**Electrical Summary:**

Facility is in fair to good condition and due for life cycle replacement of some equipment. The facility has two separate groups (Westmount & Chinook) operating within. The main electrical service was upgraded in 1992. The majority of the panelboards are original and due for life cycle replacement. Consideration should be given to upgrading the interior light fixtures for renewed life cycle, improved illumination and energy efficiency. The fire alarm consists of a Simplex 4100 system installed in 1993. Recommendations should be considered to upgrading branch circuit panelboards, receptacles and life safety systems. Communication systems are kept up to date by each of the two user groups.

Rating Guide	
Condition Rating	Performance
1 - Critical	Unsafe, high risk of injury or critical system failure.
2 - Poor	Does not meet requirements, has significant deficiencies. May have high operating/maintenance costs.
3 - Marginal	Meets minimum requirements, has significant deficiencies. May have above average operating maintenance costs.
4 - Acceptable	Meets present requirements, minor deficiencies. Average operating/maintenance costs.
5 - Good	Meets all present requirements. No deficiencies.
6 - Excellent	As new/state of the art, meets present and foreseeable requirements.

## S1 STRUCTURAL

### A1010 Standard Foundations\*

Assumed concrete strip and spread footings throughout

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	100	DEC-04

### A1030 Slab on Grade\*

1954 & 1957: Concrete slab on grade throughout lower level  
 1965: Concrete slab on grade partial lower level and main floor level  
 1973: Concrete slab on grade partial lower level.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	100	DEC-04

### A2020 Basement Walls\*

Concrete basement walls throughout.  
 1965: Concrete service tunnel to connect 1965 addition to 1957 addition.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	100	DEC-04

#### Event: Replace service tunnel insulation

##### **Concern:**

Rigid board insulation adhered to concrete ceiling and upper portions of walls is delaminating and falling to the floor

##### **Recommendation:**

Remove remaining board insulation and replace with new durable material

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2005	\$9,180	Low

*Updated: February 17 2005*



### B1010.01 Floor Structural Frame\*(Building Frame)

There are a variety of floor systems throughout and many could not be viewed. The building owner noted some of the following:

1954: Cast in place concrete filled metal pan form. Suspended structural concrete slab.  
 1957: Cast in place concrete filled metal pan form. Suspended structural concrete slab.  
 1965: Hollow tile floor over partial basement. Metal deck and concrete topping.  
 1973: Suspended structural concrete slab main floor

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	100	DEC-04

### B1010.02 Structural Interior Walls Supporting Floors\*

Various cast in place concrete walls and concrete masonry unit walls throughout.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	100	DEC-04



**B1010.05 Mezzanine Construction\***

1954: 2 ply wood joists stacked on edge to form mezzanine floor deck in Arts & Crafts and in Ancillary Gymnasium.  
 1965: Precast concrete T's floor at Library mezzanine.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	100	DEC-04

**B1010.07 Exterior Stairs\***

Exterior concrete stairs to main and most secondary entrances.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	40	DEC-04

**B1010.09 Floor Construction Fireproofing\***

1954: Spray fireproofing on basement Boiler Room ceiling

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	0	DEC-04

**B1020.01 Roof Structural Frame\***

1954: Wood frame and decking over Staff Room/Offices. Wood deck on open web steel purlins on open web steel joists at gymnasium.  
 1957: Concrete filled metal pan  
 1965: Open web steel joists with wood decking  
 1973: Assumed open web steel joist with metal deck

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	100	DEC-04

**B1020.04 Canopies\***

1965: Canvas canopy with raw plywood soffit at the east link level access entrance. Cantilevered precast concrete canopies at the south entrance doors and at the north door to the courtyard.  
 1973: Main floor slab suspended over exterior covered parking

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	100	DEC-04

## S2 ENVELOPE

### B2010.01.01 Precast Concrete: Exterior Wall Skin\*

1965: Exposed aggregate panels above windows on north side and above and below windows on south side. Exposed concrete columns and beams and sun shade canopies.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	75	DEC-04

#### Event: Examine cracked concrete columns and beams

##### **Concern:**

Several concrete columns and beams show signs of stress on the exterior side.

##### **Recommendation:**

Examine concrete structures for degree of or possibility of failure

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Study	2005	\$4,860	Medium

*Updated: February 17 2005*



**B2010.01.02.01 Brick Masonry: Ext. Wall Skin\***

1954: Brick cladding of varying elevations and colours.

1957: Brick cladding of varying elevations and colours.

1965: Brick cladding to full height at some entrances and below glazing units throughout

1973: Brick cladding of varying elevations.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	75	DEC-04

**Event: Institute a masonry restoration program****Concern:**

1954: Brick surfaces are aging, staining and deteriorating throughout.

**Recommendation:**

Institute a restoration program

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Preventative Maintenance	2008	\$118,800	Low

*Updated: February 17 2005*

**Event: Repair brick cladding****Concern:**

Brick joint mortar is loose in numerous locations. There are cracks in brick walls and many bricks are falling out.

**Recommendation:**

Clean out and re-point failing brick joints. Remove loose brick, clean surfaces and re-lay brick.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2006	\$16,200	Low

*Updated: February 17 2005*

**B2010.01.06.03 Metal Siding\***

1965: A recent modernization (date unknown) has added corrugated prefinished metal cladding to cover the old Industrial Arts (now a library) overhead door.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	40	DEC-04

**B2010.01.08 Portland Cement Plaster: Ext. Wall\***

1954: Cement stucco cladding at second floor and upper levels.

1957: Cement parging at exposed basement level. Cement stucco cladding at second floor.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	75	DEC-04

**Event: Repair cracked cement stucco****Concern:**


Stucco and parging wall finish is cracked in several locations

**Recommendation:**

Repair cement stucco and parging

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2007	\$5,400	Low

*Updated: February 17 2005*

**B2010.01.09 Expansion Control: Exterior Wall Skin\***

Building and cladding expansion is controlled via joints of dissimilar materials and building connections. No purpose made expansion control is evident.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

**B2010.01.11 Joint Sealers (caulking): Ext. Wall\***

Joints at dissimilar materials are caulked

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

**Event: Re-seal joints and connections****Concern:**

Caulking at joints of dissimilar materials and building connections has weathered and shrunk in various locations throughout

**Recommendation:**

Clean out and re-seal all joints

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2005	\$12,420	Low

*Updated: February 17 2005*

**B2010.01.13 Paints (& Stains): Exterior Wall\***

1954: Stucco and parging wall finish is painted. Exposed concrete structure is painted. Wood soffits at entrances are painted.

1957: Stucco and parging wall finish is painted. Exposed concrete structure is painted.

1965: Exposed concrete structure and panels are painted. Exposed aggregate precast panels and brick panels in various locations are painted to cover graffiti

1973: Wood soffit around building perimeter is painted. Exposed concrete structure and panels are painted.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	15	DEC-04

**Event: Re-finish painted concrete and wood surfaces****Concern:**

Painted finish on concrete surfaces is peeling, delaminating and weathering. Wood soffits are peeling and delaminating and portions of the gymnasium soffit remain unfinished.

**Recommendation:**

Remove painted finish and where possible leave natural sealed finish to concrete. Where a finish is required re-finish with a quality concrete stain. Clean and re-paint wood soffits.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Preventative Maintenance	2007	\$28,080	Low

*Updated: February 17 2005*



**B2010.01.99 Other Exterior Wall Skin\***

1954: Corrugated panels over northeast entry doors reported by owner to be transite panels

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

**Event:** **Remove and replace corrugated transite panels over doors**

**Concern:**

Corrugated transite panels over northeast entrance doors are currently contained

**Recommendation:**

Remove contaminated panels and replace with prefinished metal siding

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Hazardous Materials Abatement	2008	\$4,860	Low

*Updated: February 17 2005*

**B2010.02.01 Cast-in-place Concrete:Ext.Wall Const\***

1973: Cast in place concrete (exposed basement wall) with exposed aggregate at covered parking.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	100	DEC-04

**B2010.02.02 Precast Concrete: Ext. Wall Const.\***

1965: Precast concrete wall construction throughout exterior

1973: Precast concrete wall construction throughout exterior

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	100	DEC-04

**B2010.02.03 Masonry Units: Ext. Wall Const.\***

1965: Concrete masonry unit exterior wall construction in various locations

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

**Event:** **Review wall cracks in concrete masonry units, report and propose remedial work**

**Concern:**

Wall cracks in high wall at music room practice areas

**Recommendation:**

Review and report

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Study	2005	\$2,160	Low

*Updated: February 17 2005*



**B2010.06 Exterior Louvers, Grilles, and Screens\***

Painted grilles and screens throughout over several lower window units.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	20	DEC-04

**B2010.09 Exterior Soffits\***

1954: Exposed wood member and decking (painted) at main entrances and around gymnasium.

1965: Precast concrete (painted) at south entrances.

1973: Exposed wood member and decking (painted) throughout.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	20	DEC-04

**Event:** **Replace wood soffits with prefinished metal soffits.**  
**Cost for finishing included in B2010.01.13.**

**Concern:**

Wood soffits on 1954 entrances, gymnasium and 1973 addition are painted and are delaminating and peeling.

**Recommendation:**

In lieu of re-painting the wood soffits, install a prefinished metal vented soffit. Cost for finishing included in B2010.01.13.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Preventative Maintenance	2007	\$0	Low

*Updated: February 17 2005*

**B2020.01.01.02 Aluminum Windows\***

1957: A few of the wood window units on the north side of the building have been replaced with aluminum framing systems.

1965: Aluminum framed windows throughout.

1973: Aluminum framed windows throughout.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	35	DEC-04

**B2020.01.01.05 Wood Windows\***

1954: Wood window units throughout

1957: Wood window units throughout with the exception of a few aluminum units on the north side of the building.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	35	DEC-04

**Event:** **1954 & 1957: In lieu of repairing and refinishing wood windows, replace them with aluminum framed units.**

**Concern:**

Wood windows throughout are drafty, damaged, rotting and or lacking seals and hardware. Windows have been covered with wood panels. Window finishes are delaminating and peeling.

**Recommendation:**

Remove wood windows and replace them with aluminum sealed units.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2008	\$372,600	Low

*Updated: February 17 2005*

**Event:** **1954 & 1957: Repair wood windows**

**Concern:**

Wood windows throughout are drafty, damaged, rotting and or lacking seals and hardware. Windows have been covered with wood panels. Window finishes are delaminating and peeling.

**Recommendation:**

Repair wood window units and panels, clean, prep and refinish

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2005	\$0	Low

*Updated: February 17 2005*

**Event:** **1957: Replace rotted wood windows on the north side of the building**

**Concern:**

Wood window units on the north side of the building have completely rotted out and will soon fail totally.

**Recommendation:**

Replace wood windows with aluminum units. Esitimated cost of replacing is \$80,000. See B2020.01.01.05

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2005	\$0	Medium

*Updated: February 17 2005*



**B2020.03 Glazed Curtain Wall\***

1973: Aluminum curtain wall at stairwell

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	35	DEC-04

**B2020.04 Other Exterior Windows\***

1954: Glass block in south stairwell to basement

1957: Glass block windows in stairwell and basement windows

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	35	DEC-04

**B2030.01.01 Aluminum-Framed Storefronts\***

1965: Aluminum framed entrances on south side of building

1973: Aluminum framed exit at stairwell

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	DEC-04

**B2030.01.10 Wood Entrance Door\***

1954: Wood entrance doors mounted in wood frames at main entrance (north), south entrance doors and ancillary exit entrance doors. Wood door mounted in pressed steel frame at northeast entrance. Hollow metal door in pressed steel frame at ancillary gymnasium.

1957: Wood doors in wood framed throughout

1965: Hollow metal doors mounted in aluminum frames at entrances. Wood door in pressed steel frame to service tunnel.

1973: Hollow metal door in aluminum frame at stairwell.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
N/A	0	30	DEC-04

**Event:** 1954: Replace rusted steel door frames. Replace abused wood doors and frames.

**Concern:**

Steel door frames are rusted and the anchors have failed. Some wood doors are heavily used and are damaged.

**Recommendation:**

Replace wood doors and frames, hardware and steel door frames with insulated hollow metal doors, upgraded hardware and pressed steel frames for 8 units.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2006	\$15,660	Low

Updated: February 17 2005

**B2030.02 Exterior Utility Doors\***

1954: Aluminum screen door at exterior entrance to basement kitchen. Coal chute steel hatch at boiler room.

1954/1957/1965: Wood or metal doors to service spaces throughout.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

**B3010.04.01 Built-up Bituminous Roofing (Asphalt & Gravel)\***

1954: 1982 re-roof  
 1957: 1982 re-roof  
 1965: 1982 re-roof  
 1973: Unknown

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	25	DEC-04

**Event:** 1954/1965/1973: Minor roof repair required in various locations

**Concern:**

Roof delamination, bubbling, creep and ripples are evident in various locations. Roof leakage has occurred as evidenced by ceiling damage. Some roof drain screens are missing.

**Recommendation:**

Repair roof as required.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2005	\$10,800	Low

*Updated: February 17 2005*

**Event:** 1957: Re-roof entire area  
1965: Repair flashing at link

**Concern:**

1957: BUR is rippled and bubbled in numerous locations throughout and there are several locations of roof leaks as evidenced by staining on the interior textured (contaminated) ceiling finish. Cap flashings are painted and are peeling.

1965: At link to 1957 addition, the painted metal flashing doesn't cover the top (cap) of the precast panels and leakage to interior has occurred.

**Recommendation:**

Replace roof with a 2 ply modified roof and install new prefinished metal flashings

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Preventative Maintenance	2005	\$140,400	Medium

*Updated: February 17 2005*

**B3010.04.04 Modified Bituminous Membrane Roofing (SBS)\***

1954: Various areas re-roofed, date unknown  
 1965: Various areas re-roofed, date unknown

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	25	DEC-04



**B3010.08.02 Metal Gutters and Downspouts\***

1954: Painted metal gutter and down pipes from gymnasium roof

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

**B3010.09 Roof Specialties and Accessories\***

Metal strainer type roof drains.

Access to roof is via man door from stairwell leading to roof top fan room. Painted steel roof ladders provide access to the various roof elevations but several of the ladders don't meet current Alberta Labour Standards requirements.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	25	DEC-04

**B3020.01 Skylights\***

1954: 3 pitched roof style skylights located over the staff room, ancillary gym and arts classroom wing.

1965: One pitched roof style skylight over the administration area.

1973: One pyramid style skylight over the library

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	20	DEC-04

**Event: 1954: Remove outdated skylights****Concern:**

Skylights at the 1965 and 1973 additions are in acceptable condition and are made use of. The skylights over the classroom wing (Staff Lounge) are outdated painted metal and the roof openings are covered from the interior. The glass seals are weathered and shrinking and the paint finish is delaminating.

**Recommendation:**

Remove the skylights and roof over the openings.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Preventative Maintenance	2008	\$10,260	Low

*Updated: February 17 2005*

### S3 INTERIOR

#### C1010.01 Interior Fixed Partitions\*

1954: Plaster on masonry units, gypsum board on framed stud in staff areas  
 1957: Plaster on masonry units, gypsum board on framed stud in staff areas  
 1965: Concrete masonry, glazed brick, gypsum board on framed stud in various locations  
 1973: Concrete masonry, framed walls and gypsum board

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	DEC-04

#### C1010.02 Interior Demountable Partitions\*

1954: Demountable partition in administration area and at south basement washrooms  
 1957: Demountable partitions at administration offices

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	DEC-04

#### C1010.03 Interior Operable Folding Panel Partitions\*

1954: Electric hardboard panel (painted) sliding gymnasium divider partition. Sliding wood panel corridor divider (not used) to separate classroom wing from gym circulation space.  
 1957: Sliding wood panel corridor divider to separate classroom wing from gym circulation space.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	DEC-04

#### Event: Repair folding corridor divider partitions

##### **Concern:**

Corridor divider partitions are in a state of disrepair and are unusable

##### **Recommendation:**

Repair door panels and hardware as required.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2007	\$3,240	Low

*Updated: February 17 2005*

#### C1010.04 Interior Balustrades and Screens, Interior Railings\*

1954: Painted steel handrails to service areas. Brass handrails in circulation areas. Painted steel handrail to staff lounge over boiler room and drama rooms under stage. Painted wood handrail at H/C ramp in basement.

1957: Painted steel handrails to service areas. Brass handrails in circulation areas.

1965: Painted steel guard at administration offices. Stainless steel guard at pipes in corridor by industrial arts. Painted steel rails in stairwells to service areas and in library to mezzanine. Vinyl covered steel handrail with wood balustrade in south stairwells.

1973: Painted steel handrail and guards in Library.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	40	DEC-04

#### Event: Upgrade landing guard heights

##### **Concern:**

Landing and mezzanine guards do not meet current code requirements with regard to rail height and horizontal climbable members.

##### **Recommendation:**

Increase railing heights as required and add glass and/or board paneling to eliminate climbable members.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Code Upgrade	2008	\$6,480	Low

*Updated: February 17 2005*

#### C1010.05 Interior Windows\*

1954: Single glazing in wood and metal frames in various locations throughout.

1957: Single glazing in wood frames in various locations. Wired glass in wood frames in stairwells/corridors.

1965: Single glazing in metal frames in various locations, industrial arts and in the administration area.

1973: Single glazing in wood frames in Library. Single glazing in metal frames in Library and book storage.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	40	DEC-04

#### C1010.06 Interior Glazed Partitions and Storefronts\*

1965: Single glazing in natural wood frame partition at Music Room offices.

1973: Single glazing in natural wood frame partition at Library office.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	40	DEC-04

**C1020.01 Interior Swinging Doors\***

1954: Solid core wood doors, many with single glazed lights, in wood frames throughout. Stairwell doors with wired glass.  
 1957: Solid core wood doors, many with single glazed lights, in wood frames throughout. Stairwell doors with wired glass.  
 1965: Solid core wood doors, many with single glazed lights, in pressed steel frames throughout. Stairwell doors are metal clad wood with wired glass.  
 1973: Solid core wood doors with single glazed lights in wood and/or pressed steel frames. Hollow metal doors, some with wired glass lights, in pressed steel frames.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	50	DEC-04

**Event:** **1954/1957/1965/1973: Install barrier free door hardware**

**Concern:**

The majority of doors are currently fitted with rounded knob style door latchsets.

**Recommendation:**

Install lever style barrier free latchsets for approximately 140 doors.

<b><u>Type</u></b>	<b><u>Year</u></b>	<b><u>Cost</u></b>	<b><u>Priority</u></b>
Barrier Free Access Upgrade	2005	\$51,840	Low

*Updated: February 17 2005*

**C1020.02 Interior Entrance Doors\***

1954: Clear finished wood frames and doors with wired glass lites at east entrance, painted finish at west entrance.  
 1957: Clear finished wood frames and doors with wired glass lites.  
 1965: Metal clad (painted) wood doors in aluminum frames at south and east entrances

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	50	DEC-04

**C1020.03 Interior Fire Doors\***

1954: Painted metal doors in metal frames at corridor to 1965 addition (no label). Painted metal clad doors to boiler room (no label). Wood doors/frames to caretaker and storage rooms. Stairwells at stage require closures.

1957: Wood doors/frames to fan room, caretaker and storage rooms (no label).

1965: Painted hollow metal doors to mechanical rooms and stairwells.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	50	DEC-04

**Event: 1954/1957: Install required firerated doors****Concern:**

Adequate labeled firerated closures are almost non-existent in this facility. Travel distances appear sufficient but need to be verified. Doors are required at the 1954/1957 corridor connection. Several rooms currently being used for storage were originally intended for other purposes. Doors are non-existent at the east 1957 stairwell. Labeled doors are required at mechanical, caretaker and storage rooms throughout.

**Recommendation:**

Install required firerated doors, frames and associated hardware and monitoring systems.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Code Repair	2005	\$37,800	Medium

*Updated: February 17 2005*

**C1020.07 Other Interior Doors\***

1954: Iron bar security door at Drama room circulation space/stairwell.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	DEC-04

**Event: Replace security bar door at drama area stairwell.****Concern:**

Security bar door at drama area stairwell is locked, creates a dead end corridor and doesn't allow exit.

**Recommendation:**

Remove security bar door, create a vestibule and install a labeled door, frame and hardware.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Code Repair	2005	\$5,940	Medium

*Updated: February 17 2005*

**C1030.01 Visual Display Boards\***

A variety of chalk, white and tackboards throughout.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04



**C1030.02 Fabricated Compartments(Toilets/Showers)\***

1954: Floor supported prepainted metal toilet compartments  
 1957: Floor supported prepainted metal toilet compartments  
 1965: Floor supported prepainted metal toilet compartments

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	0	DEC-04

**C1030.08 Interior Identifying Devices\***

A variety of plastic, metal and hand-made signage throughout.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	0	DEC-04

**C1030.10 Lockers\***

1954: Single tier prepainted metal student lockers  
 1957: Single tier prepainted metal student lockers  
 1965: Double tier gym change room lockers. Single tier prepainted metal student lockers. Double tier prepainted metal student lockers

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	30	DEC-04

**C1030.12 Storage Shelving\***

A variety of prepainted metal, painted wood, clear finished wood and laminate/melamine shelving throughout.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	0	DEC-04

**C1030.14 Toilet, Bath, and Laundry Accessories\***

Institutional grade mirrors, soap, toilet paper and paper towel dispensers and grab bars throughout

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	20	DEC-04

**C1030.17 Other Fittings\***

1954: Clear finished wood coat hook rails and painted wood boot shelves in corridors

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	0	DEC-04

**C2010 Stair Construction\***

1954: Wood stair to Ancillary Gym and Arts & Crafts mezzanines. Steel stair to boiler room.  
 1965: wood stair to Music room and administration mezzanines.  
 Balance of stairs throughout are of concrete construction.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	100	DEC-04

**C2020.01 Tile Stair Finishes\***

1957: Quarry tile stair treads on east and west stairs  
 1965: Quarry tile on west and south stairs  
 1973: Quarry tile on north stairs

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	DEC-04

**C2020.05 Resilient Stair Finishes\***

1954: Rubber treads on all stairs  
 1965: Vinyl tile treads on music room stair. Rubber treads on stair in administration  
 1973: Vinyl tile treads on library stair

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	20	DEC-04

**Event: Repair/replace stair treads****Concern:**

Several resilient stair treads are missing and numerous are damaged.

**Recommendation:**

Repair and replace stair treads as required

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2006	\$3,780	Low

*Updated: February 17 2005*

**C2020.11 Other Stair Finishes\***

1954/1957: Painted stair finishes to basement storage and service room areas.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
N/A	0	0	DEC-04

**C3010.01 Concrete Wall Finishes\***

1954/1957/1965: Natural concrete finish to service tunnel and basement storage/mechanical rooms.  
 Balance of concrete walls throughout are painted or plastered.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	100	DEC-04

**C3010.02 Wall Paneling\***

1954: Painted wood paneling in corridors. Clear finished plywood paneling in gymnasium.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	DEC-04

**C3010.03 Plaster Wall Finishes\***

1954/1957/1965: Painted plaster wall finishes throughout.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	40	DEC-04

**C3010.04 Gypsum Board Wall Finishes\***

1965/1973: Painted gypsum wall board finishes throughout

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	40	DEC-04

**C3010.06 Tile Wall Finishes\***

1954/1957: Ceramic tile wall finishes in stairwells and washrooms

1965: Ceramic tile wall finishes in washrooms and change/shower rooms

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	DEC-04

**C3010.09 Acoustical Wall Treatment\***

1965: Acoustic wall panels in music room and industrial arts

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	20	DEC-04

**C3010.11 Interior Wall Painting\***

Painted walls throughout

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	5	DEC-04

**C3020.01 Concrete Floor Finishes\***

1954: Raw concrete floor in east basement storage area and north service tunnel. Painted concrete floor in boiler room and south basement storage area.

1957: Raw concrete floor in service tunnel and west basement storage areas.

1965: Raw concrete finish in south basement storage room and library mezzanine.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	75	DEC-04

**Event: Refinish painted basement floors****Concern:**

Painted floor finishes have delaminated, are peeling and are worn to concrete in traffic areas/routes.

**Recommendation:**

Prep and refinish painted floor surfaces in storage rooms, caretaker rooms and facility operator offices and rooms throughout. Clean and refinish boiler room floor with a waterproof, chemical resistant non-slip traffic topping.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Preventative Maintenance	2007	\$24,300	Unassigned

Updated: February 17 2005

### C3020.02 Tile Floor Finishes\*

1954: Quarry tile flooring in basement kitchen and abandoned shower rooms. Quarry tile flooring in student washrooms, mosaic tile at urinals. Porcelain tile flooring in main entrance/gymnasium circulation space.

1957: Quarry tile flooring in student washrooms, mosaic tile at urinals. Ceramic tile flooring in basement art/sculpture rooms

1965: Porcelain tile flooring in administration circulation space. Quarry tile flooring in west link, south stairwells and in gymnasium change areas. Mosaic tile flooring in student washrooms and in gymnasium shower rooms.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	DEC-04

### C3020.04 Wood Flooring\*

1954: Natural finish plank flooring in both gymnasiums and on stage.

1965: Natural finish parquet flooring in industrial arts.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	25	DEC-04

### C3020.07 Resilient Flooring\*

1954/1957/1965: Predominately 9x9 vinyl tile flooring throughout (reported by owner to be asbestos tile).

1954: Vinyl composite tile in the main entrance vestibule and staff lunch room.

1965: Some vinyl composite tile at the library entrance and in some administration rooms. Sheet flooring in music room and in north basement classroom.

1973: Sheet flooring in library offices.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	20	DEC-04

#### Event: 1965: Replace failed Music Room mezzanine flooring

##### **Concern:**

Sheet flooring in music room is delaminating and is damaged at mezzanine.

##### **Recommendation:**

Replace flooring with new sheet goods.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2007	\$10,800	Low

*Updated: February 17 2005*



#### Event: Remove and replace contaminated vinyl tile flooring

##### **Concern:**

Vinyl tile throughout is predominately 9x9 vinyl asbestos tile as reported by the owner. Many tiles are missing and there are numerous cracks and failures.

##### **Recommendation:**

Remove and replace tiles with vinyl composite tiles.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Hazardous Materials Abatement	2008	\$669,600	Low

*Updated: February 17 2005*

**C3020.08 Carpet Flooring\***

1954: Carpet in main floor classroom wing corridor, majority of classrooms throughout and in administration offices.  
 1957: Carpet in administration offices and some classrooms.  
 1965: Carpet in administration offices, library and north basement book storage.  
 1973: Carpet in library

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
3 - Marginal	0	10	DEC-04

**Event:** **1954: Replace carpet throughout.**  
**1973: Replace carpet in upper library**

**Concern:**

Carpet throughout is dirty, stained, damaged and worn through.  
 It might be covering contaminated resilient flooring.

**Recommendation:**

Remove carpet throughout and install resilient flooring in it's place in classroom areas. Install new carpet in the upper 1973 library.

<b><u>Type</u></b>	<b><u>Year</u></b>	<b><u>Cost</u></b>	<b><u>Priority</u></b>
Failure Replacement	2005	\$145,800	Medium

*Updated: February 17 2005*

**C3030.01 Concrete Ceiling Finishes\***

Painted concrete ceilings in boiler room and building operator areas/rooms. Balance of concrete ceilings are raw concrete.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	100	DEC-04

**C3030.03 Plaster Ceiling Finishes\***

1954/1957/1965: Plaster ceilings (painted) in washrooms, change rooms, storage rooms, stairwells and caretaker rooms.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	50	DEC-04

**C3030.04 Gypsum Board Ceiling Finishes\***

1965/1973: Painted gypsum board ceilings in stairwells and storage rooms.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	50	DEC-04

**C3030.06 Acoustic Ceiling Treatment (Susp.T-Bar)\***

1954: Lay-in tile T-Bar ceilings in cafeteria, main floor circulation space and administration spaces.  
 1957: Lay-in tile T-Bar ceilings in administration spaces.  
 1965: Washable tile T-Bar in foods classroom. Lay-in tile T-Bar ceilings in corridors.  
 1973: Lay-in tile T-Bar ceilings in Library.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	25	DEC-04

**C3030.07 Interior Ceiling Painting\***

Bulkheads and hard ceilings throughout are painted.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	10	DEC-04

**C3030.09 Other Ceiling Finishes\***

1954/1957: Predominately textured spray ceilings throughout.  
 1965: Predominately 12x12 perforated tile ceiling in classrooms.  
 1973: 12x12 acoustic tile ceiling in library boardroom.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	DEC-04

**Event: Remove textured ceilings****Concern:**

Textured ceiling throughout are reported by the owner to be asbestos contaminated.

**Recommendation:**

Remove contaminated textured ceiling and replace with gypsum board and paint or new textured finish.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Hazardous Materials Abatement	2007	\$496,800	Low

*Updated: February 17 2005*

**D1010.02 Lifts\***

1965: A stair rail mounted lift is located in the west stairwell.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	25	DEC-04



## S4 MECHANICAL

### D2010.01 Water Closets\*

54, 57, 65 floor mounted with flush valves

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	DEC-04

### D2010.02 Urinals\*

65, stall urinals with auto flush tank

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	DEC-04

### D2010.03 Lavatories\*

54, 57, 65, side vanities replaced 1990s

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	30	DEC-04

### D2010.04 Sinks\*

1965, SS sinks in home ed, Science rooms single sinks,

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	DEC-04

### D2010.08 Drinking Fountains / Coolers\*

54 and 1990s mix of china drinking fountains

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	DEC-04

### D2010.09 Other Plumbing Fixtures\*

Kitchen sinks, grease trap, Janitors

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

### D2020.01.01 Pipes and Tubes: Domestic Water\*

54/57 mix of galv copper

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	40	DEC-04

### D2020.01.01 Pipes and Tubes: Domestic Water\*

65/73 copper

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	40	DEC-04

### D2020.01.01 Pipes and Tubes: Domestic Water\*

54, 100mm main supply, 100m to school, 65mm meter to field irrigation. 75mm to standpipe system.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	40	DEC-04

#### Event: 54/57 galv piping

##### **Concern:**

54/57 galv water pipes

##### **Recommendation:**

Replace with upgrade 54/57 side 5000 Sq m

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2011	\$388,800	Unassigned

*Updated: February 21 2005*

### D2020.01.02 Valves: Domestic Water

54/57/65

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

### D2020.01.03 Piping Specialties (Backflow Preventors)\*

1997, Backflows, Two 65mm on the 100mm to school, 65mm Irrigation, 75mm standpipe system, boiler feeds 65 Backflows on humidifiers.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

### D2020.02.02 Plumbing Pumps: Domestic Water\*

99, two inline recirc pumps for hot water tanks

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	20	DEC-04

### D2020.02.06 Domestic Water Heaters\*

54 main boiler room, Two 1999 State SVT100, gas fired.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	20	DEC-04

### D2020.03 Water Supply Insulation\*: Domestic

All years appear to be in reasonable condition

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

**D2030.01 Waste and Vent Piping\***

54/57 cast iron and galvanized.  
65/73 cast and copper

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	50	DEC-04

**D2030.02 Waste Piping Specialties\***

54/ 57/ 65 floor drains and trench drainage system ect

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	50	DEC-04

**D2030.03 Waste Piping Equipment\***

65 south wing sump / pump for mech room drains  
54, sump with hydramatic pump for boiler room drains  
54 sump / pump for trech draiage system.  
73, sump /pump in 049 mech room.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	0	DEC-04

**D2040.01 Rain Water Drainage Piping Systems\***

54/57/65/73 Internal rainwater system to City storm, cast iron

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	50	DEC-04

**D2040.02.04 Roof Drains\***

54/57/65/73 roof drains

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	40	DEC-04

**D2040.02.06 Area Drains\***

area drains in courtyard areas and perimeter

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	0	DEC-04

**D3010.02 Gas Supply Systems\***

150mm gas to boilers hot water tanks.  
Gas distribution to science rooms

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	50	DEC-04

**D3020.01.01 Heating Boilers & Accessories: Steam\***

54, Three Liberty boilers, 3000 mbh each, condensate tanks, pumps, Low water cut offs, boiler feeds, heat exchangers

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	35	DEC-04

**Event: 1954 steam boilers and equipment to replace****Concern:**

Well past life cycle

**Recommendation:**

Upgrade with new hot water system.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Energy Efficiency Upgrade	2011	\$1,118,880	Low

*Updated: February 21 2005*

**D3020.01.03 Chimneys (&Comb. Air) : Steam Boilers\***

54, Combustion air grilles at high level and open slot at the bottom,  
54 breechings and brick Chimney

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	DEC-04

**D3020.01.04 Water Treatment: Steam Boilers\***

54 Chemical pumped system, Treatment plan in place

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

**D3020.02.03 Water Treatment: H. W. Boiler\***

73 & 65 hot water systems (Steam heat exchangers) water treatment plan in place with pot feeders and by-pass filters.  
65 exchanger has chemical tank with gear pump and glycol tank  
65 south wing mech, by pass filter, pot feeder, treatment plan.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

**D3030.06.02 Refrigerant Condensing Units\***

65 rooftop Eng Air CUD-261-1 air cooled  
73, two rooftop units for library  
1990, Kitchen water cooled.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	25	DEC-04

**D3030.08 Other Refrigeration Systems\***

1990, Kitchen coolers

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

**D3040.01.01 Air Handling Units: Air Distribution\***

65, Band room area, AHU, make not known, steam coil, filters  
 65 classroom AHU with steam coil make unknown

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	DEC-04

**Event:** **54/57/65 HVAC equipment past life cycle.**

**Concern:**

Poor system, past life cycle.

**Recommendation:**

Replace HVAC system

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Indoor Air Quality Upgrade	2011	\$1,243,080	Low

*Updated: February 21 2005*

**D3040.01.01 Air Handling Units: Air Distribution\***

54, Gym Two Trane climate changers in the Mezz with steam coils only.  
 54, Main floor old automotive shop AHU, Trane Torri vent T-14 in mezz  
 54 Trane climate changer, AHU with steam coil for basement rooms below stage  
 54 Trane torrivent 6HFTH for main floor, steam coil

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	DEC-04

**D3040.01.01 Air Handling Units: Air Distribution\***

65 side, Atrium area, 1992 Eng Air LM10-1, 10326 cfm, glycol coil with 3-way pneumatic and cooling coil, mixed air with pneumatic dampers (mech room is the plenum)  
 73, Trane T10 torrivent in basement for library.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	30	DEC-04

**D3040.01.03 Air Cleaning Devices:Air Distribution\***

54, Basement, old dust collection unit  
 54, basement cafe area, three electric air filters.  
 All AHUs have filter banks

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

**D3040.01.04 Ducts: Air Distribution\***

54/57/65 condition unknown

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	DEC-04

**D3040.01.05 Duct Accessories: Air Distribution\***

54/57/65 flex connections

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

**D3040.01.07 Air Outlets & Inlets:Air Distribution\***

54, 57 Exterior unit ventilator grilles, grilles / diffusers

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	50	DEC-04

**D3040.02 Steam Distribution Systems: Piping/Pumps\***

54/57 distribution system piping in poor condition, some condensate tanks and pumps replaced.  
 Steam distribution to newer 65 and 73 additions

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	DEC-04

**Event:** **See D3020.01.01**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2011	\$0	Unassigned

*Updated: February 21 2005***D3040.03.01 Hot Water Distribution Systems\***

65 & 73 distribution from heat exchangers to radiation, coils, cabinet & unit heaters.  
 65 south wing mech, 2 vertical ex tanks, supply pumps to glycol and hot water radiation

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	40	DEC-04

**D3040.04 Special Exhaust Systems**

65, west end, Science, fume cabinet, Chemical storage  
 54, main floor old automotive shop exhaust fan in mezz, Trane B1-UB-CW  
 57 Art room system  
 57 Double kiln system.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	DEC-04



**D3040.04.01 Fans\*: Exhaust**

54 rooftop ex fan for main floor office  
 57, two fans for north wing basement, main & 2nd floors.  
 54, east wing, Canadian Buffalo KK7020 in the basement, for all floors.  
 54, East wing washrooms ex, Canadian Buffalo KK7027.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	DEC-04

**Event:** **See D3040.01.01**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2005	\$0	Unassigned

*Updated: February 21 2005***D3040.04.01 Fans\*: Exhaust**

54 side, 1990s Kitchen wall exhauster  
 65, classrooms ex fan, #11, Trane B11-BH-CW  
 65 classrooms ex fan #10.  
 washroom ex fan # 12.  
 92, Northern Blower fan for Atrium

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	DEC-04

**D3040.04.03 Ducts\*: Exhaust**

54 / 57 ducts

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

**Event:** **See 3040.01.01**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2011	\$0	Unassigned

*Updated: February 21 2005***D3040.04.04 Ducts Accessories\*: Exhaust**

54/57/65

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

**Event:** **See D3040.01.01**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2011	\$0	Unassigned

*Updated: February 21 2005*

**D3040.04.05 Air Outlets and Inlets\*: Exhaust**

54/57/65

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

**Event:** See D3040.01.01

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2011	\$0	Unassigned

*Updated: February 21 2005***D3040.05 Heat Exchangers\***

65 & 73 steam to hot water / glycol exchangers  
 65 south wing mech room steam exchanger

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	DEC-04

**D3040.06 Other HVAC Distribution Systems\***

73, Library Trane climate changer 25HFTH with cooling coil and roof top cond

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

**D3050.01.01 Computer Room Air Conditioning Units\***

92, main floor server room has 2 ton cooling unit, make unknown

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	DEC-04

**D3050.01.02 Packaged Rooftop Air Conditioning Units (& Heating Units)\***

54, main floor office area, Lennox GCS16-048, 120,000btu with cooling  
 73 Library gas fired unit.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

**D3050.02 Air Coils\***

54, Two reheat coils in the mezz library supply ducting to the old music room (now Art)  
 73, Rehaet coils to library

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	DEC-04

**D3050.03 Humidifiers\***

73 library AHU air wash humidifier  
 65 AHU has humidifier air wash system

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	25	DEC-04

**D3050.05.02 Fan Coil Units\***

65, hot water cabinet unit heaters at entrance ways  
 54 fan coil on Kitchen wall.  
 54/57 steam cabinet unit heaters at entrance ways.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	0	DEC-04

**D3050.05.03 Finned Tube Radiation\***

65 & 73, hot water perimeter radiation  
 92, Atrium area renovation, high level radiation.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	35	DEC-04

**D3050.05.03 Finned Tube Radiation\***

54 & 57, Steam perimeter radiation

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	0	DEC-04

**Event:** **See D3020.01.01**

<b><u>Type</u></b>	<b><u>Year</u></b>	<b><u>Cost</u></b>	<b><u>Priority</u></b>
Lifecycle Replacement	2011	\$0	Unassigned

*Updated: February 21 2005*

**D3050.05.06 Unit Heaters\***

65 Steam unit heaters

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	0	DEC-04

**D3050.05.07 Unit Ventilators\***

54, horizontal and vertical unit ventilators

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	0	DEC-04

**D3060.02.01 Electric and Electronic Controls\***

73 library AHU, powers controls  
 54 boilers and safetys.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	30	DEC-04

**D3060.02.02 Pneumatic Controls\***

54 , Brunner compressor & Devilbis dryer in main boiler room.  
 65, Devilbis compressor with dryer in roof mech room.  
 65, south wing, Athes Western compressor  
 Pneumatic heating valves and dampers throughout.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	40	DEC-04

**D3060.02.03 Pneumatic and Electric Controls\***

54/57/65/73 mix of pneumatis and electric controls

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
N/A	0	40	DEC-04

**D3060.02.05 Building Systems Controls(BMCS, EMCS)\***

No BMS, local control only.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	DEC-04

**Event: Controls system to upgrade with HVAC****Concern:**

HVAC upgrade will require control replacement.

**Recommendation:**

Upgrade to BMS

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2011	\$745,200	Low

*Updated: February 21 2005***D4010 Sprinklers: Fire Protection\***

No sprinkler system, school requires upograde.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	50	DEC-04

**Event: School to be upgraded****Concern:**

Existing systems are not adequate.

**Recommendation:**

Upgrade to latest codes

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Code Upgrade	2005	\$378,000	Medium

*Updated: February 21 2005***D4020 Standpipes\***

54/57/65/73 standpipe system

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	50	DEC-04

**Event: See 3020.01.01**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2011	\$0	Unassigned

*Updated: February 21 2005*

**D4030.01 Fire Extinguisher, Cabinets and Accessories\***

54/57/65/73 Fire extinguishers throughout

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	30	DEC-04

**D4090 Other Fire Protection Systems\***

90s Kitchen hood system

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	0	DEC-04

## S5 ELECTRICAL

### D5010.01 Main Electrical Transformers\*

Pad mounted utility owned transformer

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	40	DEC-04

### D5010.03 Main Electrical Switchboards (Main Distribution)\*

(1992) Square D, 120/208v, 2000A rated c/w 1800A trip, 3P, 4W, c/w integral CDP and sub CDP; fed U/G from utility. Adequate space for present and foreseeable future needs. Buss duct to sub distribution.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
6 - Excellent	0	40	DEC-04

### D5010.05 Electrical Branch Circuit Panelboards (Secondary Distribution)\*

(1954, 1957, 1973) Most panels are original Westinghouse with limited spare capacity and nearing the end of their life cycle. Some panels have been upgraded. Surge protection is installed at some panels for computer equipment protection.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	25	DEC-04

#### Event: Upgrade existing panel boards

##### **Concern:**

Existing equipment is nearing end of life cycle. Limited circuit capacity. Replacement parts are not available.

##### **Recommendation:**

Refit or replace existing panels to renew life cycle and increase circuit capacity.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2011	\$81,000	Low

*Updated: February 21 2005*

### D5010.07.02 Motor Starters and Accessories\*

(1954, 1957, 1973) Stand alone Allen-Bradley and Square D starters. Equipment has been replaced through attrition as needed

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

#### Event: Replace starters for mechanical equipment

##### **Concern:**

Equipment is at end of life cycle and replacement parts are difficult to obtain.

##### **Recommendation:**

Replace existing with new through attrition

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2011	\$51,840	Low

*Updated: February 21 2005*



**D5020.01 Electrical Branch Wiring\***

Conduit and wire system c/w flexible connections as required in good condition. Conduit for upgrades has been surface installed. Quantity of receptacles is limited throughout.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	DEC-04

**Event: Add receptacles and circuits****Concern:**

Outlet capacity is limited. Minimal access to power outlets for instructional use.

**Recommendation:**

Add branch circuits to improve outlet access

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Operating Efficiency Upgrade	2008	\$81,000	Low

*Updated: February 21 2005*

**D5020.02.01 Lighting Accessories (Lighting Controls)\***

Line voltage switching. Corridors are controlled direct with breakers.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	DEC-04

**Event: Install control of public area lighting****Concern:**

Corridor lighting is controlled direct with circuit breakers

**Recommendation:**

Provide switching system for switching purposes. Combine with lighting upgrade.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Preventative Maintenance	2008	\$16,200	Low

*Updated: February 21 2005*

**D5020.02.02.01 Interior Incandescent Fixtures\***

Incandescents are installed in storage rooms and tunnel.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	DEC-04

**Event:** Replace incandescent fixtures in storage rooms.  
Note costs included in fluorescent event.

**Concern:**

Incandescent fixtures are inefficient and maintenance intensive

**Recommendation:**

Replace concurrent with fluorescent upgrades

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Operating Efficiency Upgrade	2008	\$0	Low

*Updated: February 21 2005*

**D5020.02.02.02 Interior Florescent Fixtures\***

Obsolete T-12 technology fixtures throughout. 1x4, 2x4 surface mounted in corridors, elementary gymnasium and adminstrtion. Suspended blade fixtures in Library and classrooms. Some recessed fixtures in newer T-bar ceilings.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	DEC-04

**Event:** Upgrade lighting to modern technology

**Concern:**

Obsolete T-12 technology is inefficient. PCB's may be present in old ballasts.

**Recommendation:**

Replace or refit fixtures with new T-8 technology lamps and ballasts. Dispose of PCB ballasts appropriately.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Energy Efficiency Upgrade	2008	\$702,000	Low

*Updated: February 21 2005*

**D5020.02.02.05 Other Interior Fixtures\* Mercury Vapor**

Gymnasium has obsolete mercury vapor HID fixtures

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

**Event:** Replace or refit MV HID fixtures. Note costs included with fluorescent upgrades.

**Concern:**

Fixture performance deteriorates quickly with age.

**Recommendation:**

Replace with fluorescent technology to restore efficiency and color rendition.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2005	\$0	Low

*Updated: February 21 2005*

**D5020.02.03 Emergency Lighting\***

Battery packs c/w remote heads. Most exit fixtures are not interconnected to secondary power source

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	DEC-04

**Event:** Upgrade emergency lighting

**Concern:**

Exit fixtures are inefficient incandescent and not interconnected to secondary emergency source. Illumination levels should be improved

**Recommendation:**

Provide additional battery packs and remote heads c/w with interconnection to new technology LED exit fixtures

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Code Upgrade	2006	\$59,400	Medium

*Updated: February 21 2005*

#### D5020.03.01.05 Other Exterior Fixturess\*

Exterior wall mounted mercury vapor fixtures around perimeter

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	DEC-04

#### Event: Replace exterior wall pack fixtures

##### **Concern:**

Obsolete mercury vapor technology

##### **Recommendation:**

Replace through attrition with low wattage HPS technology to renew life cycle

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Operating Efficiency Upgrade	2010	\$10,800	Low

*Updated: February 21 2005*

#### D5020.03.02 Lighting Accessories (Lighting Controls)\*

Exterior lighting is time and PEC controlled

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	25	DEC-04

#### D5030.01 Detection and Alarm Fire Alarm\*

(1993) Newer Simplex 4100 fire alarm c/w audible/visual devices. Remote annunciator and non-active graphic at entrance.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	25	DEC-04

#### D5030.02.02 Intrusion Detection\*

(2000) Mircom security system c/w motion detectors, panic stations and keypad. In Chinook Side of building.

(2002) Silent Knight Regency head end equipment c/w motion detectors and keypad. In Westmount side of building.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
6 - Excellent	0	25	DEC-04

#### D5030.02.03 Security Access\*

Card access for staff door.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
6 - Excellent	0	25	DEC-04

#### D5030.02.04 Video Surveillance\*

Four color cameras on main level monitored by common security office

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	25	DEC-04

**D5030.03 Clock and Program Systems\***

New MultiNet system integrated with PA system in Westmount side.  
Simplex 2350 in Chinook side.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	20	DEC-04

**D5030.04.01 Telephone Systems\***

(2004) New Nortel Northstar system integrated with PA system. UPS installed for back-up power. On Chinnok side.  
(2002) Nortel Northstar integrated into PA system. On Westmount side.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
6 - Excellent	0	25	DEC-04

**D5030.04.04 Data Systems\***

SuperNet fibre service. Cat 5 cabling as needed throughout. Wireless devices used sparingly. Being upgraded as required.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	DEC-04

**Event: Remove redundant cable****Concern:**

Redundant communication cabling should be removed

**Recommendation:**

Remove cable and discard

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2008	\$2,700	Low

*Updated: February 21 2005*

**D5030.05 Public Address and Music Systems\* Chinook**

(2004) Refurbished TOA 900 series equipment

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
6 - Excellent	0	0	DEC-04

**D5030.05 Public Address and Music Systems\* Viscount**

(2002) New InterM PA-4000 system integrated with telephone system, on the Westmount side.  
(2004) Refurbished TOA 900 series equipment.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	DEC-04

## S6 EQUIPMENT, FURNISHINGS AND SPECIAL CONSTRUCTION

### E1020.02 Library Equipment\*

1965: Book theft protection system with handheld scanner.

1973: Book theft protection system with handheld scanner. Sliding cabinet file management system. Dumbwaiter book lift.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

### E1020.07 Laboratory Equipment\*

1957: Fume hood located in classroom. Chemical storage cabinet located in classroom.

1965: Fume hoods located in classrooms. Chemical storage cabinets located in classrooms.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

### E1030.03 Loading Dock Equipment\*

1954: Raised loading dock located at northeast entrance doors c/w dock bumpers.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

### E1090.03 Food Service Equipment\*

1954: Fully equipped kitchen located in basement c/w walk-in cooler and freezer, commercial grade range, grille, fryers, exhaust hood, dishwasher, convection oven, display coolers, pedestrian barriers and stainless servery row.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

### E1090.04 Residential Equipment\*

1954: Refrigerator in infirmary. Washer and dryer in south basement. Refrigerator and microwave in caretaker office. Refrigerators, range, dishwasher and microwaves in staff lounge.

1957: Refrigerator and dishwasher in science classroom. Refrigerators and microwave in staff lounge.

1965: Refrigerators, ranges, microwaves, dishwashers, washer and dryer in foods classroom.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

### E1090.07 Athletic, Recreational, and Therapeutic Equipment\*

1954: 2 plexiglass ceiling mounted up-lift backboards and 4 wood ceiling mounted up-lift basketball backboards in main gymnasium. Various volleyball and badminton nets and removable posts.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04

### E2010.02.05 Educational Facility Casework\*

Various built-in cabinets along windows in classrooms throughout. Some classrooms with sink cabinets. Laminate counters with wood cabinets in staff lounges.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	DEC-04



**E2010.02.07 Kitchen Casework\***

Stainless steel counters, prep tables and dish washing runs in cafeteria kitchen. Staff lounges with laminate tops on wood counters.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	0	DEC-04

**E2010.02.08 Laboratory Casework\***

Science rooms throughout with clear finish wood lower cabinets and sliding glass & wood upper cabinets, the majority with laminate counters, some are painted wood counters.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	0	DEC-04

**E2010.02.09 Library Casework\***

1965: Laminate circulation desk. A variety of shelving types including metal, melamine and wood.  
1973: Laminate circulation desk. A variety of shelving types including metal, melamine and wood.  
Laminate study carols and computer desks.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	0	DEC-04

**E2010.03.01 Blinds\***

Venetian blinds throughout with vertical blinds in the north library and a few classrooms the exception.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	0	DEC-04

**F1010.02.04 Portable and Mobile Buildings**

A metal storage shed on skids is located in the lower level of the south parking lot.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	0	DEC-04

**F1010.02.05 Grandstands and Bleachers\***

1954: Telescopic wood bleachers in the main gymnasium.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	0	DEC-04

**F1020.02 Special Purpose Rooms\***

1957: Clay modeling and kiln rooms in basement

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	0	DEC-04

**Facility Details**

**Building Name:** Viscount Bennett School  
**Address:**  
**Location:** Calgary  
  
**Building Id:** S2514  
**Gross Area (sq. m):** 0.00  
**Replacement Cost:** \$0  
**Construction Year:** 0

**Evaluation Details**

**Evaluation Company:**  
  
**Evaluation Date:**  
  
**Evaluator Name:**

**Total Maintenance Events Next 5 years:** **\$62,100**  
**5 year Facility Condition Index (FCI):** **0%**

**General Summary:**

The original school was constructed in 1954 with additions in 1957, 1965 and 1973. The total building area now stands at 19,184.90 s.m..  
 The 1954 and 1957 buildings consist of a basement, main floor and second floor. The 1965 building consists of a main floor and second floor and the 1973 addition has a basement and main floor.  
 Student capacity is approximately 2000 students.  
 The site is sloped and terraced from the north side up to the south end.  
 The site is in adequate condition but attention is needed at asphalt paving and with regard to barrier free access.

**Structural Summary:**

**Envelope Summary:**

**Interior Summary:**

**Mechanical Summary:**

**Electrical Summary:**

**Rating Guide**

<b>Condition Rating</b>	<b>Performance</b>
1 - Critical	Unsafe, high risk of injury or critical system failure.
2 - Poor	Does not meet requirements, has significant deficiencies. May have high operating/maintenance costs.
3 - Marginal	Meets minimum requirements, has significant deficiencies. May have above average operating maintenance costs.
4 - Acceptable	Meets present requirements, minor deficiencies. Average operating/maintenance costs.
5 - Good	Meets all present requirements. No deficiencies.
6 - Excellent	As new/state of the art, meets present and foreseeable requirements.

## S7 SITE

### G2010.02.02 Flexible Pavement Roadway (Asphalt)\*

Asphalt roadway from 25th Street leads to the south parking lots. Another asphalt roadway leading from the south parking area heads north along the east property line to access the interior courtyard area and Richmond Road to the north. An asphalt roadway from Richmond Road provides access to the north partially covered parking area.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	

**Event:** Repair the roadway along the east side of the building

**Concern:**

The roadway along the east side of the building is rough, cracked, crumbling and heaved in several locations.

**Recommendation:**

Repair the east roadway as required.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2006	\$8,100	Low

*Updated: February 19 2005*



### G2010.04 Rigid Roadway Pavement (Concrete)\*

A concrete partial roadway from 25th Street provides access to the 1965 west link.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	

**Event:** Repair the west concrete roadway.

**Concern:**

The west concrete roadway is cracked.

**Recommendation:**

Top the concrete roadway with asphalt

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2005	\$3,780	Low

*Updated: February 19 2005*



### G2010.05 Roadway Curbs and Gutters\*

Concrete curbs and gutters at the majority of paved areas.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
N/A	0	0	

**Event:** **Replace damaged curbs**

**Concern:**

Curbs are damaged and failing in several locations

**Recommendation:**

Replace damaged/failed concrete curbs

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2006	\$7,020	Low

*Updated: February 19 2005*



### G2010.06 Roadway Appurtenances\*

Asphalt speed bumps throughout

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	

### G2020.02.02 Flexible Paving Parking Lots(Asphalt)\*

Staff parking lot for 18 vehicles on the west side of the building off 25th Street. 16 of these stalls are energized. The south parking lot is terraced with the lower level reserved for staff. There are 94 energized staff parking stalls, 9 visitor stalls along the building (8 energized) and 229 student parking stalls in the upper parking lot. Parking is also allowed along the access road to the south parking lot. There are approximately 14 staff and service parking stalls at the paved interior courtyard area, 4 staff at the northeast corner of the site off the east roadway and 10 partially covered energized staff stalls below the north library.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	

**Event:** **Re-pave the lower south parking lot.**

**Concern:**

The lower south parking lot is cracked, crumbling and rough.

**Recommendation:**

Re-pave the lower south parking lot.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2006	\$27,000	Low

*Updated: February 19 2005*



### G2020.05 Parking Lot Curbs and Gutters\*

No curbs are present at the west parking lot or the interior courtyard area. Concrete curbs are located at the north parking lot, the access road to the south parking lot and the parking lot perimeter and the ease side of the east roadway.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	

### G2020.06.01 Traffic Barriers\*

250mm precast concrete curbs are used as traffic control barriers in various locations.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	

### G2020.06.02 Parking Bumpers\*

Precast concrete bumpers are located at the vast majority of parking stalls.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	

### G2020.06.03 Parking Lot Signs\*

There are various metal stop and one way traffic control signs. Painted metal parking control signs are mounted on the building.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	

### G2020.06.04 Pavement Markings\*

Pavement marking are almost non-existent

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	

#### Event: Re-apply pavement markings

##### **Concern:**

Pavement lines, crosswalks and markings are almost non-existent

##### **Recommendation:**

Re-apply pavement markings

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Preventative Maintenance	2007	\$5,400	Low

*Updated: February 19 2005*

### G2030.02.01 Gravel Pedestrian Surfacing\*

Gravel walkway from 1965 link to internal exterior courtyard

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	10	



#### G2030.04 Rigid Pedestrian Pavement (Concrete)\*

Walkways at all entrances are concrete.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	

#### G2030.06 Exterior Steps and Ramps\*

The majority of entrances are fitted with concrete steps or landings. A concrete step from the upper west staff parking lot leads to the 1965 west link entrance. No exterior ramps are installed.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	

#### Event: Replace the west steps

##### **Concern:**

The west steps are chipped, spalling, cracked and sunken

##### **Recommendation:**

Replace the concrete steps and reinstall the handrail

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2006	\$4,860	Low

*Updated: February 19 2005*





### G2040.02 Fences and Gates\*

A painted wood fence is located on the north side of the west staff parking lot. A wire mesh fence mounted on a low concrete wall borders the north side of the south parking lot access road. Chainlink fences border the majority of the site.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	

**Event:** Replace the painted wood fence at the staff parking lot

**Concern:**

The painted wood fence at the west staff parking lot is rotting and slipping over

**Recommendation:**

Replace the wood fence with a chainlink fence and reattach the car plug-in receptacles

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2006	\$5,940	Low

*Updated: February 19 2005*



### G2040.03 Athletic and Recreational Surfaces\*

Grass playing fields for football and soccer are located on the south side of the building. A pea gravelled tot lot is located on the far south end of the site

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	

### G2040.05 Site and Street Furnishings\*

Painted metal bicycle racks are located adjacent to the north, west and south entrances.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	20	

### G2040.06 Exterior Signs\*

An illuminated plastic "Chinook Learning Services" sign is located on the building over the front entrance. Individual metal letters to indicate "Westmount Charter School" and "Viscount Bennett Centre" are located on the building at the northwest corner. Individual metal letters to indicate "Westmount Charter School" are located on the building at the southwest corner of the east classroom wing.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	

### G2040.08 Flagpoles\*

A painted +/-9m tall flag pole on a concrete base is located in the grass area adjacent to the front entrance.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	

### G2040.11 Retaining Walls\*

A concrete retaining wall the upper staff parking lot from the 1965 west link and another separates the northwest parking from the lower covered parking.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	

### G2050.01 Irrigation Systems\*

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
N/A	0	0	

### G2050.04 Lawns and Grasses\*

Mature lawns border the site and north and west sides of the building.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	

### G2050.05 Trees, Plants and Ground Covers\*

Various types of mature trees and shrubs are located on the north and west sides of the building.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	

### G3010.02 Site Domestic Water Distribution\*

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
N/A	0	0	

### G3010.03 Site Fire Protection Water Distribution\*

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
N/A	0	0	

### G3020.01 Sanitary Sewage Collection\*

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
N/A	0	0	

### G3020.02 Septic Systems\*

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
N/A	0	0	

### G3020.03 Sanitary Sewage Equipment\*

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
N/A	0	0	

### G3030.01 Storm Water Collection\*

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
N/A	0	0	

### G3030.02 Storm Water Equipment\*

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
N/A	0	0	

### G3030.03 Storm Water Ponds and Reservoirs\*

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
N/A	0	0	

### G3060.01 Gas Distribution\*

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
N/A	0	0	

### G3060.04 Fuel Storage Tanks\*

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
N/A	0	0	

### G3060.05 Fuel Dispensing Equipment\*

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
N/A	0	0	

### G3090 Other Site Mechanical Utilities\*

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
N/A	0	0	

### G4010.02 Electrical Power Distribution Lines\*

1992: 120/208 volt, 3 phase, 4 wire, 1800 amp underground service from padmount transformer

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	

#### G4010.03 Electrical Power Distribution Equipment\*

Utility padmount transformer

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	

#### G4010.04 Car Plugs-ins\*

Approximately 72 duplex receptacles, wall and rail mounted

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	

#### G4020.01 Area Lighting\*

A combination of 2-four head 400 watt mercury vapour poles in parking lot and wall mount HID mercury vapour and high pressure sodium around building

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	

#### G9090 Other Site Systems\*

2004: Underground fibre communication line

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	

## S8 FUNCTIONAL ASSESSMENT

### K40 Current Code Issues

Several areas of this facility need to be reviewed and code issues analyzed particularly with regard to building area, fire protection and suppression, exiting, separation and firerating of floors and buildings. At least one dead end corridor exists and one exit from the drama rooms is blocked.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	DEC-04

### K4010.01 Barrier Free Route: Parking to Entrance

The west 1965 link provides the best level entry to the building and is near the only lift (stair rail lift) in the building. No dedicated parking is provided at this location.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	DEC-04

**Event:** **Provide dedicated disabled parking near the 1965 west link entry.**

**Concern:**

Dedicated parking stalls are not provided.

**Recommendation:**

Provide minimum 2 dedicated asphalt or concrete parking stalls near the 1965 west link entry.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Barrier Free Access Upgrade	2005	\$10,260	Medium

*Updated: February 17 2005*

### K4010.02 Barrier Free Entrances

No barrier free door operators are provided.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	DEC-04

**Event:** **Install barrier free door operators**

**Concern:**

Barrier free automatic door operators are not installed at this facility

**Recommendation:**

Install barrier free automatic door operators at the 1965 west link entry.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Barrier Free Access Upgrade	2005	\$4,860	Medium

*Updated: February 17 2005*

**K4010.03 Barrier Free Interior Circulation**

Barrier free circulation is generally not provided within this facility

<b>Rating</b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
3 - Marginal	0	0	DEC-04

**Event:** **Provide greater barrier free access to all portions of the facility.**

**Concern:**

Only one stair rail lift is provided within this facility and this device is cumbersome, slow and difficult to use. There are numerous stairs and floor levels and access to all levels is not provided. The access ramps that are provided do not meet current accessibility or building code requirements. Few, if any, acceptable access to exit are provided.

**Recommendation:**

Install two elevators, one in each the 1954 and 1958 buildings to allow access to all floor levels. Remove existing interior wood ramps and construct new concrete ramps to meet current codes. At least 7 interior ramps would be required. Construct exterior concrete ramps to allow access to the main entrance and access to exit in an emergency situation. At least 5 exterior ramps would be required.



<b><u>Type</u></b>	<b><u>Year</u></b>	<b><u>Cost</u></b>	<b><u>Priority</u></b>
Barrier Free Access Upgrade	2005	\$950,400	Medium

*Updated: February 17 2005*

**K4010.04 Barrier Free Washrooms**

1965: Marginally acceptable barrier free washrooms are provided on both floors.

1954/1957: No barrier free washrooms are provided

<b>Rating</b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
3 - Marginal	0	0	DEC-04

**Event:** **Provide barrier free washrooms**

**Concern:**

1954/1957: No acceptable barrier free washrooms are provided.

**Recommendation:**

Install at least one barrier free washroom in each building

<b><u>Type</u></b>	<b><u>Year</u></b>	<b><u>Cost</u></b>	<b><u>Priority</u></b>
Barrier Free Access Upgrade	2005	\$43,200	Medium

*Updated: February 17 2005*