

School Facility Evaluation Project
Part I - Facility Profile and Summary

School Name: Glenbrook Elementary School
Location: 4725 33 Ave S.W.

School Code: 9122
Facility Code: 1448

Region: South
Jurisdiction: Calgary

Superintendent: Dr. Donna Micheals
Contact Person: Leanne Soligo
Telephone: 214-1121

Grades: K - 6

School Capacity: 700

Building Section	Year of Compl.	No. of Floors	Gross Bldg Area (Sq.M.)	Type of Construction (i.e., structure, roof, cladding)	Description of Mechanical Systems (incl. major upgrades)	Comments/Notes
Original Building	1959	1	2270.7	Wood frame, sloped and flat roofs, wood siding and stucco	low pressure steam boiler	
Additions/ Expansions	1963	1	635.4	Same as original	as above	
	1967	1	2427.6	Concrete block, flat roof, brick and stucco	as above	
Total			5333.7			

Evaluator's Name: Bob Passmore
& Company: Building Science Specialists

Upgrading/ Modernization (identify whether minor or major)				Minor upgrading of finishes in Staff Room and Administration Offices		
Portable Struct. (identify whether attached/perman. or free-standing/ relocatable)	NA					
List of Reports/ Supplementary Information	CBE Facility Asbestos Database, February 23, 1999.					

School Facility Evaluation Project
Part I - Facility Profile and Summary

	Evaluation Components	Summary Assessment	Estim. Cost
1	Site Conditions	- patch asphalt parking lot	
2	Building Exterior	- paint exterior of original building and perimeter of windows in addition - replace weather-stripping in windows of addition	\$120,700
3	Building Interior	- replace flooring in washrooms of addition. Install new carpet in Library - provide new toilet partitions in washrooms of addition - provide handicapped access throughout building and handicapped washroom.	\$179,000
4	Mechanical Systems	- provide two new hot water tanks - provide new boiler in original school - provide relief ventilation openings in both boiler rooms - provide two new expansion tanks - provide new components to ventilation unit - provide new corridor exhaust in addition	\$118,800
5	Electrical Systems	- provide addition exterior lighting - install new fire alarm system - provide new emergency lighting - new exit signs connected to emergency power - provide new lighting in tunnel and boiler room - provide ventilation to computer/telephone distribution hub upgrade to T-8 lamps throughout	\$180,000
6	Portable Buildings		\$0.00
7	Space Adequacy:		
	7.1 Classrooms	- slightly excessive	412.8
	7.2 Science Rooms/Labs	- deficient	-201.4
	7.3 Ancillary Areas	- deficient	-313.5
	7.4 Gymnasium	- deficient	-192.1
	7.5 Library/Resource Areas	- deficient	-99.8
	7.6 Administration/Staff Areas	- deficient	-143.8
	7.7 CTS Areas		0
	7.8 Other Non-Instructional Areas (incl. gross-up)	- slightly excessive	361.5
	Overall School Conditions & Estim. Costs		-176.3 \$598,500

School Facility Evaluation Project
Part I - Facility Profile and Summary

Section 1	Site Conditions	Rating	Comments/Concerns	Estim. Cost
1.1	General Site Conditions			
1.1.1	Overall site size.	4	2.52 hectares	
1.1.2	Outdoor athletic areas.	4	Two soccer pitches to south of school, Two P & R ball diamonds to east. Creative play area to SW. Basketball hoops on pavement to east.	
1.1.3	Outdoor playground areas, including condition of equipment and base.	4	Newer creative play area. Large concreted area in south courtyard and at ends of east and west wings. Some asphalt topping where concrete is worn, large area of asphalt to east with 3 outdoor basketball courts	
1.1.4	Site landscaping.	4	Mature	
1.1.5	Site accessories (i.e., perimeter and other fencing, guard rails, bike stands, flag poles).	4	Perimeter chain link fence to south &, west of site. East side from playgrounds enters into Parks & Recreation ball diamonds. The north side is bordered by street and parking lot.	
1.1.6	Surface drainage conditions (i.e., drains away from building, signs of ponding).	4	Drainage is away from building on all sides. Rather flat to west side, water ponds on grass area next to playground. Water sits on gravel to south.	
1.1.7	Evidence of sub-soil problems.	4	No evidence of problems noted.	
1.1.8	Safety and security concerns due to site conditions.	4	None noted.	
Other				

Section 1	Site Conditions	Rating	Comments/Concerns	Estim. Cost
1.2	Access/Drop-Off Areas/Roadways/Bus Lanes			
1.2.1	Vehicular and pedestrian access points (i.e., size, number, visibility, safety).	n/a	city streets	
1.2.2	Surfacing of on-site road network (note whether asphalt or gravel).	4	Teacher/visitor parking to north is paved.	
1.2.3	Bus lanes/drop-off areas (note whether on-site or off-site).	n/a	One bus parking spot on site in parking lot, gravel/paved. City streets	
1.2.4	Fire vehicle access.	4	City street, lane, parking lot to north, with fire access to west on concrete apron. Access to east side has been blocked by chain link fence.	
1.2.5	Signage.	4	Wall mounted sign on north elevation at main entry.	
Other				

School Facility Evaluation Project
Part I - Facility Profile and Summary

Section 1	Site Conditions	Rating	Comments/Concerns	Estim. Cost
1.3	Parking Lots and Sidewalks			
1.3.1	Number of parking spaces for staff, students and visitors (including stalls for disabled persons).	4	32 stalls, no designated handicapped stall. Provide handicapped stall.	\$3,000
1.3.2	Layout and safety of parking lots.	4	Fenced from play area. No pedestrian route through the parking area.	
1.3.3	Surfacing and drainage of parking lots (note whether asphalt or gravel).	3	Asphalt area is sloped to an area drain. Some cracking of asphalt noted. Seal asphalt cracks	\$2,000
1.3.4	Layout and safety of sidewalks.	4	Sidewalk from north avenue approaches the main entry (middle north side) and east end of east wing. Other walkways are city sidewalks.	
1.3.5	Surfacing and drainage of sidewalks (note type of material).	4	Concrete, slope well to east away from building	
1.3.6	Curb cuts and ramps for barrier free access.	4	Curb cut in city sidewalk, with one ramp to the main entry. It is a steep ramp, attendant would be required.	
Other				
Overall Site Conditions & Estimated Costs				\$5,000

Section 2	Building Exterior	Rating	Comments/Concerns		Estim. Cost
2.1	Overall Structure		Bldg. Section	Description/Condition	
2.1.1	Floor structure and beams (i.e., signs of bending, cracking, heaving, settlement, voids, rust, stains).	4	1960 - 1964	Minor cracking in terrazzo and tile floor finishes at washrooms and entry Classroom wood floors have shrunk relative to corridor concrete slabs.	
		4	1967	Minor cracks in slab on grade and suspended slabs, which have telegraphed through "poured linoleum" finish	
2.1.2	Wall structure and columns (i.e., signs of bending, cracking, settlement, voids, rust, stains).	4	1960 - 1964 1967	No evidence of problems.	
2.1.3	Roof structure (i.e., signs of bending, cracking, voids, rust, stains).	4	1960 - 1964 1967	No evidence of problems	
Other					
2.2	Roofing and Skylights		Description/Condition/Age		
	Identify the availability of an up-to-date inspection report or roofing program. Note if roof sections are of different ages and/or in varying states of repair.				
2.2.1	Based on the inspection report (and to the extent possible, direct observation), assess and rate roof conditions and estimate costs for required improvements (i.e., covering materials, membrane, insulation, other components).	FI	1960 - 1964 1967	Not reviewed, snow on roof.	
2.2.2	Roof accessories (i.e., ladders, stairs, hatches, masts, exhaust hoods, chimneys, gutters, downspouts, splashpads).	FI	1960 - 1964 1967		
2.2.3	Control of ice and snow falling from roof.	5	1960 - 1964	Roofs slope to inside and drain internally.	
		4	1968	Roof is flat with internal drains to municipal system	
2.2.4	Skylights (i.e., signs of distress, leaks, ice build-up, condensation, deteriorated materials/seals).	n/a	1960 - 1964 1968		
Other					

Section 2	Building Exterior	Rating	Comments/Concerns	Estim. Cost
2.3	Exterior Walls/Building Envelope		<u>Description/Condition</u>	
2.3.1	Exterior wall finishes (i.e., signs of deterioration, cracks, brick spalling, efflorescence, water stains).	3	1960 - Extensive cracking noted in painted finish on stucco. Lower perimeter of school is finished in horizontal wood siding. Nail heads are rusting. Painting of the exterior wood and stucco is recommended. Block firewalls penetrating through the roof show signs of cracking and paint peeling and splitting. 1964	\$18,500.00
		4	1967 Brick exterior, with stucco panels. Some minor cracking of the stucco finish	
2.3.2	Fascias, soffits, parapets (i.e., signs of looseness, stains, rust, peeling paint).	4	1960 - Fascia appears to be new break shaped metal. 1964 1967	
2.3.3	Building envelope (i.e., evidence of air infiltration/exfiltration through the exterior wall or ice build up on wall, eaves, canopy).	4	1960 - No evidence of problems 1964 1968	
2.3.4	Interface of roof drainage and ground drainage systems.	4	1960 - Roof drains internally into storm system 1964 1968	
2.3.5	Inside faces of exterior walls (i.e., signs of cracks, water stains, dust spots).	4	1960 - No evidence of problems 1964 1967	
Other		3	1960- Scope of work required for removal and replacement of boiler. Cash allowance for architectural repairs required for removal and replacement of boiler. 1964	\$100,000.00

9

Section 3	Building Interior - Overall Conditions	Rating	Comments/Concerns	Estim. Cost
3.1	Interior Structure		Bldg. Section Description/Condition	
3.1.1	Interior walls and partitions (i.e., signs of cracks, spalling, paint peeling).	4	1960 - Walls are wood frame with plaster finish or painted concrete block. No problems noted. 1964 1967	
3.1.2	Floors (i.e., signs of cracks, heaving, settlement).	4	1960- Floors are concrete in core, and corridors, wood frame in classrooms. Minor cracking noted in 1964 basement concrete floor.	
		4	1967 Floors are concrete slab on grade with tunnels running under the corridors. Minor cracking noted throughout with a substantial crack in the poured epoxy finish in the Boy's washroom on the upper level and in the corridor at the boiler room.	
	Other			
3.2	Materials and Finishes		Bldg. Section Description/Condition	
3.2.1	Floor materials and finishes.	4	1960- Floor finishes are 9" VAT in corridors, new sheet lino in classrooms with area carpets in some. 1964 Hardwood floor in Gymnasium. Staff areas are carpeted. Music room is carpeted Terrazzo floors in courtyard entries and science room. Ceramic tile floors in children's washrooms. Cracking noted in terrazzo and ceramic tile floors, but are maintainable.	
		3	1967 Floor finishes in corridors are poured epoxy (see 3.1.2 above). Office and Library are carpeted. Classrooms are VT with some area carpets. Replace epoxy flooring with sheet vinyl in washrooms. Replace carpet in Library and computer area	\$15,500
3.2.2	Wall materials and finishes.	4	1960- Walls are wood frame with painted plaster finish or painted concrete block. Walls in Gymnasium are 1964 finished with stipple (contains asbestos) Lower ten feet are protected with wood paneling.	
			1967 Walls are painted concrete with some demountable partitions in offices and Library	

School Facility Evaluation Project
Part I - Facility Profile and Summary

Section 3	Building Interior - Overall Conditions	Rating	Comments/Concerns	Estim. Cost
3.2	Materials and Finishes (cont'd)		Bldg. Section	
3.2.3	Ceiling materials and finishes.	4	1960-1964 Ceilings in classroom are sloped with 12 x 12 fibrous ceiling tiles. Gymnasium and corridors finished the same way. Library, lunch/science room, Shelter rooms have stippled finish (contains asbestos)	
		4	1967 Ceilings are suspended T-bar with 2 x 4 ceiling tiles	
3.2.4	Interior doors and hardware.	4	1960-1964 Doors are wood throughout, except for metal doors at fire separations. All appear to be original, except in office which have been upgraded to metal in HM frames.	
3.2.5	Millwork	4	1960-1964 Millwork is original, except for office and staffroom which have been upgraded	
3.2.6	Fixed/wall mounted equipment (i.e., writing boards, tackboards, display boards, signs).	3	1960-1964 All tackboards and chalkboards are original - adequate. Replace all chalkboards with white boards.	\$35,000
3.2.7	Any other fixed/mounted specialty items (i.e., CTS equipment, gymnasium equipment).	4	1960-1964 Gymnasium has fold out climbing wall.	
3.2.8	Washroom materials and finishes.	4	1960-1964 Sinks are wall hung, in good condition, partitions are original, but in good condition.	
		3	1967 Sinks are wall hung, in good condition, partitions are original, and require replacement.	\$3,500
Other				

Section 3	Building Interior - Overall Conditions	Rating	Comments/Concerns	Estim. Cost
3.3	Health and Safety Concerns --- <i>Intent is to identify renovations considered necessary to meet applicable codes, primarily due to safety concerns. Basis of evaluation should be an up-to-date inspection report from the authority having jurisdiction together with direct observations as appropriate. Evaluator should note if in his opinion a comprehensive code evaluation is required.</i>		Bldg. <u>Description/Condition</u> <u>Section</u>	
3.3.1	Building construction type - combustible or non-combustible, sprinklered or non-sprinklered.	4	1960-1964 Combination of combustible and non-combustible construction, Core area is mainly non-combustible, while classroom walls, floors and ceiling are combustible. Building is not sprinklered	
		4	1967 Non combustible construction, building is not sprinklered	
3.3.2	Fire separations (i.e., between buildings, wings, zones if non-sprinklered).	4	1960-1964 2 hour fire separations exists between west class wing and core.	
3.3.3	Fire resistance rating of materials (i.e., corridor walls and doors).	4	1960-1964 Walls are concrete block, doors are metal, Doors are not on hold devices, they are secured with hooks.	
3.3.4	Exiting distances and access to exits.	4	1960-1964 1967 Appear to be adequate.	
3.3.5	Barrier-free access.	2	1960-1964 1967 Facility is accessible, at front entry only. Ramp is short and steep with no continuous rails at proper height. There are no handicapped washroom facilities. There is no access between the upper and lower level. Extend ramp, provide automated handicapped access doors at entry, install unisex handicapped washroom (Nurses Office) and provide handicapped lift in same area.	\$125,000
3.3.6	Availability of hazardous materials audit (i.e., evidence of safety concerns with respect to asbestos, PCB's, chemicals).	4	1960-1964 1967 CBE Facility Asbestos database indicates the presence of asbestos in stipple finish on walls or ceiling in gymnasium, science/lunch room, library. Elbows on heating pipes in the lower level tunnels and storage and above ceiling tiles. The two boilers are wrapped in asbestos. The univent heaters contain asbestos transite board. Original fluorescent lights contain PCB ballasts. This must be a consideration as renovations are contemplated.	
3.3.7	Other health and safety concerns (i.e., evidence of excessive noise conditions, air quality problems)	4	1960-1964 No evidence of other problems	
Other				
Overall Bldg Interior Condition & Estim Costs				\$179,000

Section 4	Mechanical Systems	Rating		Comments/Concerns	Estim. Cost
4.1	Mechanical Site Services		Bldg. Section	Description/Condition	
4.1.1	Site drainage systems (i.e., surface and underground systems, catch basins).	4	1960 to 1964 to 1968	The parking lot and the play area to the east have catch basins draining to city storm mains.	
4.1.2	Exterior plumbing systems (i.e., irrigation systems, hose bibs).	4	1960 to 1964 to 1968	Hose bibbs are provided on the north and west sides of the building.	
4.1.3	Outside storage tanks.	N/A		none	
	Other				
4.2	Fire Suppression Systems		Bldg. Section	Description/Condition	
4.2.1	Fire hydrants and siamese connections.	N/A		None	
4.2.2	Fire suppression systems (i.e., pumps, sprinklers, piping, reservoirs, hoses, stand pipes, CO2 systems).	4	1960 to 1964 to 1968	The 1968 section has a standpipe system with fire hoses in cabinets. The rest of the school has standpipes with hoses on reels.	
4.2.3	Hand extinguishers, blankets and showers (i.e., in CTS areas).	4	1960 to 1964 to 1968	Hand extinguishers are provided in the hose cabinets, adjacent to the standpipes and in the service rooms. Type ABC dry chemical, pressurized water and carbon dioxide extinguishers are used.	
4.2.4	Other special situations (e.g., flammable storage areas, science labs, CTS areas).	N/A		None	
	Other				

School Facility Evaluation Project
Part I - Facility Profile and Summary

Section 4	Mechanical Systems	Rating		Comments/Concerns	Estim. Cost
4.3	Water Supply and Plumbing Systems			Bldg. <u>Description/Condition</u> <u>Section</u>	
4.3.1	Domestic water supply (i.e., pressure, volume, quality - note whether municipal or well supply).	4	1960 to 1964 to 1968	Water is supplied from city mains. Pressure volume and quality are good.	
4.3.2	Water treatment system(s).	N/A		None	
4.3.3	Pumps and valves (including backflow prevention valves).	4	1960 to 1964 to 1968	Backflow protection with required valving is provided on the fire line, domestic water supply, boiler feedwater and ice rink flooding line.	
4.3.4	Piping and fittings.	4	1960 to 1964 to 1968	Water piping is original galvanized iron or is copper with soldered fittings.	
4.3.5	Plumbing fixtures (i.e., toilets, urinals, sinks)	4	1960 to 1964 to 1968	Water closets are flush valve type. Urinals are flush tank type. Lavatories are wall hung. Classrooms in the 1960 and 1964 sections have countertop enameled steel sinks. Slop sinks are wall hung vitreous china. Single bubbler wall hung drinking fountains are provided in the corridors.. Condition is good.	
4.3.6	Domestic hot water system (i.e., heater, storage tanks, failure alarms, pressure, volume, recirculation).	3	1960 to 1964 to 1968	An old gas fired 33 gallon hot water tanks is provided in each boiler room. Capacities are adequate. Both heaters should be replaced.	\$800
4.3.7	Sanitary and storm sewers, including sumps and pits (note whether sewage system is municipal or septic).	4	1960 to 1964 to 1968	Storm and sanitary lines are connected to city mains. Storm and sanitary piping is hub and spigot cast iron. The boiler room for the 1960 to 1964 section has a submersible pump equipped sump for lower level floor drainage.	
Other					

School Facility Evaluation Project
Part I - Facility Profile and Summary

Section 4	Mechanical Systems	Rating		Comments/Concerns	Estim. Cost
4.4	Heating Systems		Bldg. Section	Description/Condition	
4.4.1	Heating capacity and reliability (including backup capacity).	3	1960 to 1964	A low pressure steam heating system is provided. The single low efficiency Lethbridge fire tube boiler is rated at 4,366 MBH. It is a coal fired unit converted to gas firing. Heating terminals are unit ventilators, radiation convectors and wall fin convectors. Capacity is adequate. There is no backup. The boiler should be replaced.	\$45,000
		3	1968	A single low pressure Cleaver Brooks steam boiler rated at, 2,345 MBH, provides steam to a heat exchanger and to a ventilation unit heating coil. The heat exchanger provides hot water used to heat the building. No back-up is provided. Capacity is adequate. The boiler and heat exchanger are nearing the end of their lives and will require replacement. The room is hot and requires ventilation.	\$40,000
4.4.2	Heating controls (including use of current energy management technology).	4	1960 to 1964 to 1968	All heating controls are pneumatic t'stats controlling motorized valves on heating terminals. Many convectors have manual control.	
4.4.3	Fresh air for combustion and condition of the combustion chimney.	3	1960 to 1964 to 1968	Both boiler rooms have had modifications to their combustion air ducts and they now do not comply with gas code requirements. Relief ventilation openings are not provided in either boiler room.	\$6,000
4.4.4	Treatment of water used in heating systems.	4	1960 to 1964 to 1968	Chemical treatment is applied to the water in both condensate tanks. A chemical feeder is provided for the 1968 hot water system.	
4.4.5	Low water cutoff/pressure relief valves and failure alarms (i.e., hot water heating).	4	1960 to 1964 to 1968	Low water level feeders and cutoffs are provided on both boilers. The condensate tanks have float operated water feeders. Pressure relief valves are provided on both boilers	
4.4.6	Heating air filtration systems and filters.	4	1960 to 1964 to 1968	Unit ventilators have filters installed.	
4.4.7	Heating humidification systems and components.	4	1960 to 1964	No humidification systems are provided.	

School Facility Evaluation Project
Part I - Facility Profile and Summary

Section 4	Mechanical Systems	Rating	Comments/Concerns	Estim. Cost
4.4	Heating Systems (cont'd)		Bldg. Description/Condition Section	
4.4.8	Heating distribution systems (i.e., piping, ductwork) and associated components (i.e., diffusers, radiators).	4	1960 to 1964 Steam at low pressure is distributed to the unit ventilators, wall fin convectors and convector radiators. Heating piping is black steel and is run in tunnels below the corridors.	
		4	1968 Hot water is pumped from the heat exchanger to wall fin radiators, convector radiators and fan cabinet units. Heating piping is black steel and is run in tunnels below the corridors.	
4.4.9	Heating piping, valve and/or duct insulation.	4	1960 to 1964 The steam mains are insulated with asbestos.	
		4	1968 The steam and hot water piping are insulated with fiberglass. The fresh air duct is insulated with interior fiberglass. The heat exchanger is insulated with fiberglass.	
4.4.10	Heat exchangers.	3	1968 A shell and tube heat exchanger is installed in the boiler room. It appears to be original and is nearing it's life expectancy. See 4.4.1	
4.4.11	Heating mixing boxes, dampers and linkages.	N/A	None	
4.4.12	Heating distribution/circulation in larger spaces (i.e., user comfort, temperature of outside wall surfaces).	4	1960 to 1964 Occupied areas have room T'stat control. No problems were reported.	
		4	1968 Occupied areas have room T'stat control. No problems were reported.	

School Facility Evaluation Project
Part I - Facility Profile and Summary

Section 4	Mechanical Systems	Rating	Comments/Concerns	Estim. Cost
4.4	Heating Systems (cont'd)		Bldg. <u>Description/Condition</u> Section	
4.4.13	Zone/unit heaters and controls.	4	1960 to 1964 to 1968 Pneumatic thermostats control the unit ventilators and convectors in occupied rooms. Electric Thermostats control the fan cabinet heater in the 1968 section	
Other	Condensate tank and pump	4	1960 to 1964 A replacement condensate and tank is provided. They are in good condition	
		3	1968 The condensate tank and pump will require replacement. See 4.4.1.	
Other	Expansion tanks	3	1968 Two standard expansion tanks with gauge glasses are installed. They are original and are nearing their life expectancy.	\$3,000
4.5	Ventilation Systems		Bldg. <u>Description/Condition</u> Section	
4.5.1	Air handling units capacity and condition.	N/A	1960 to 1964 None	
		3	1968 A built-up ventilation unit introduces fresh air mixes it with return air, tempers and supplies air to all occupied areas. Air changes in the rooms is not known. The motor, heating coil, motorized valve and fan bearings will require replacement.	\$9,000
4.5.2	Outside air for the occupant load (if possible, reference CFM/occupant).	3	1960 to 1964 Most occupied areas including the gym., use outside air entering through the unit ventilators. Actual amount is not known. The gym. also has motorized dampers on outside wall louvers for summer make-up for the air exhausted. The administration area has opening windows and requires a new HVAC system	\$12,000
		4	1968 The central ventilation unit can deliver tempered fresh air. Outside air per occupant is not known. It can be adjusted.	

School Facility Evaluation Project
Part I - Facility Profile and Summary

Section 4	Mechanical Systems	Rating		Comments/Concerns	Estim. Cost
4.5	Ventilation Systems (cont'd)		Bldg. Section	Description/Condition	
4.5.3	Air distribution system (if possible, reference number of air changes/hour).	3	1960 to 1964	Exhaust ventilation is provided for all areas. Make-up is provided by the unit ventilators. Air changes are not known but appear adequate. See 4.5.2	
		4	1968	Supply ductwork delivers ventilation air to all occupied areas. Air changes are approximately 10 per hour based on design parameters of the day.	
4.5.4	Exhaust systems capacity and condition.	4	1960 to 1964	Central roof exhaust fans exhaust air from all occupied areas. The washrooms have central roof exhausters. Capacity is judged to be adequate.	
		3	1968	Air is exhausted from the corridors and from the washrooms by roof exhaust fans. The corridor fan is noisy and will need replacement. Exhaust volumes are judged to be adequate.	\$3,000
4.5.5	Separation of out flow from air intakes.	N/A		None	
		5	1968	Good separation is provided.	
4.5.6	Special/dedicated ventilation and/or exhaust systems (i.e., kitchen, labs, CTS areas).	N/A	1960 to 1964 to 1968	None	
Other					

Section 4	Mechanical Systems	Rating	Comments/Concerns	Estim. Cost
4.5	Ventilation Systems (cont'd)		Bldg. <u>Description/Condition</u> <u>Section</u>	
	<i>Note: Only complete the following items if there are separate ventilation and heating systems.</i>			
4.5.7	Ventilation controls (including use of current energy management technology).	4	1960 to 1964 None. A chronotherm is used to lower building temperatures during unoccupied hours.	
		4	1968 The ventilation unit uses pneumatic controls to adjust outdoor volume, mixed air temperature and the discharge air temperature.	
4.5.8	Air filtration systems and filters.	4	1968 Filters are provided on the unit ventilators.	
		4	1968 A filter section is provided on the central ventilation unit with replaceable media.	
4.5.9	Humidification system and components.	N/A	1960 to 1964 None	
		4	1968 A water spray humidification system is controlled by a return air humidistat. Operation was normal.	
4.5.10	Heat exchangers.	N/A	None	
4.5.11	Ventilation distribution system and components (i.e., ductwork, diffusers, mixing boxes, dampers, linkages).	N/A	1960 to 1964 None	
		4	1968 A supply and return duct system is run in the tunnels to each occupied room. Corridor wall supply grilles and return grilles are used in all areas. Distribution in the rooms is adequate.	
Other				

Section 4	Mechanical Systems	Rating	Comments/Concerns	Estim. Cost
4.6	Cooling Systems		Bldg. <u>Description/Condition</u> <u>Section</u>	
4.6.1	Cooling system capacity and condition (i.e., chillers, cooling towers, condensers).	N/A	None	
4.6.2	Cooling distribution system and components (i.e., ductwork, diffusers, mixing boxes, dampers, linkages)	N/A	None	
4.6.3	Cooling system controls (including use of current energy management technology).	N/A	None	
4.6.4	Special/dedicated cooling systems (i.e., labs, CTS areas).	N/A	None	
Other				
4.7	Building Control Systems		Bldg. <u>Description/Condition</u> <u>Section</u>	
4.7.1	Building wide/system wide control systems and/or energy management systems.	4	1960 to 1964 to 1968 None. A chronotherm is used to lower building temperatures during unoccupied hours.	
	Overall Mech Systems Condition & Estim. Costs			\$118,800

Section 5	Electrical Systems	Rating	Comments /Concerns	Estim. Cost
5.1	Site Services		Bldg. Description/Condition Section	
5.1.1	Primary service capacity and reliability (i.e., access, location, components, installation, bus sizes - note whether overhead or underground).	4	1960 to 1964 to 1968 Underground service at 1 phase 120/240 volt to an 800 ampere main switch. The demand reading is 320 kva. Capacity is adequate.	
5.1.2	Site and building exterior lighting (i.e., safety concerns).	3	1960 to 1964 to 1968 Exterior is poorly lighted. Three HID fixtures are provided on the north side to illuminate the parking lot and main entry.	\$5,000
5.1.3	Vehicle plug-ins (i.e., number, capacity, condition).	4	1960 to 1964 to 1968 16 duplex plug-ins are provided on the sides of the parking lot. They do not operate above a set temperature. Condition is good. All parking spaces do not have a plug-in.	
	Other			
5.2	Life Safety Systems		Bldg. Description/Condition Section	
5.2.1	Fire and smoke alarm systems (i.e., safety concerns, up-to-date technology, regularly tested).	3	1960 to 1964 to 1968 Electrical circuits feed the fire alarm devices in all sections of the building. Fire drills are carried out. A new fire alarm system is require.	\$20,000
5.2.2	Emergency lighting systems (i.e., safety concerns, condition).	3	1960 to 1964 The corridors and the gymnasium have inadequately spaced emergency lights. The tunnels have no emergency lighting. The system should be replaced.	\$5,000
		3	1968 Emergency lights are provided in the corridors and the library. The tunnels do not have emergency lighting. Add emergency lights.	\$1,000
5.2.3	Exit lighting and signage (i.e., safety concerns, condition).	3	1960 to 1964 Illuminated exit signs are provided at some of the corridor exits and from the gymnasium exits. The corridor exit signs are not connected to emergency power. The signs should be replaced.	\$4,000
		4	1968 Illuminated exit signs are provided at all exits and are connected to emergency power.	
	Other			

School Facility Evaluation Project
Part I - Facility Profile and Summary

Section 5	Electrical Systems	Rating	Comments /Concerns	Estim. Cost
5.3	Power Supply and Distribution		Bldg. <u>Description/Condition</u> <u>Section</u>	
5.3.1	Power service surge protection.	4	1960 to 1964 to 1968 Only the recently installed computer system has surge protection.	
5.3.2	Panels and wireways capacity and condition.	4	1960 to 1964 to 1968 Most panelboards have spare circuits. Wiring is in good condition and of adequate capacity.	
5.3.3	Emergency generator capacity and condition and/or UPS (if applicable).	N/A	None	
5.3.4	General wiring devices and methods.	4	1960 to 1964 to 1968 Receptacles are grounded type and devices are in good condition.	
5.3.5	Motor controls.	4	1960 to 1964 to 1968 Magnetic motor starters are provided on larger motors. Exhaust fans in the 1960 to 1964 section have fused disconnects. Small motors are switched.	
Other				
5.4	Lighting Systems		Bldg. <u>Description/Condition</u> <u>Section</u>	
5.4.1	Interior lighting systems and components (i.e., illumination levels, conditions, controls).	3	1960 to 1964 to 1968 The occupied area and most service rooms are provided with fluorescent lighting. Incandescent lighting is provided in the storage rooms, tunnels and 1968 section vestibules .Light levels were recorded as follows: gymnasium - 430 lux, storage rooms - 215 lux, 1960 to 1964 classrooms - 646 lux, 1968 classrooms - 538 lux, 1960 to 1964 corridors - 323 lux, 1968 corridors - 215 lux, library - 430 lux, computer lab - 323 lux, office - 538 lux, The tunnel and boiler room lighting should be replaced. Included in 5.4.3.	
5.4.2	Replacement of ballasts (i.e., health and safety concerns).	3	1960 to 1964 to 1968 Most fluorescent fixtures have ballasts with P.C.Bs. Included in 5.4.3.	
5.4.3	Implementation of energy efficiency measures and recommendations.	3	1960 to 1964 to 1968 The car plug-ins have a temperature limit cutoff. Fluorescent fixtures have 34 watt lamps. All fluorescent fixtures should be upgraded to T-8 lamps.	\$144,000
Other				

Section 5	Electrical Systems	Rating	Comments /Concerns	Estim. Cost
5.5	Network and Communication Systems		Bldg. Description/Condition Section	
5.5.1	Telephone system and components (i.e., capacity, reliability, condition).	4	1960 to 1964 to 1968 The telephone system has adequate capacity and is reliable	
5.5.2	Other communication systems (i.e., public address, intercom, CCTV, satellite or cable TV).	4	1960 to 1964 to 1968 An telephone intercom is installed throughout the building. A public address system is installed with speakers in all locations	
5.5.3	Network cabling (if available, should be category 5 or better).	5	1960 to 1964 to 1968 A new computer system with internet access and outlets in all classrooms and a computer lab is provided.	
5.5.4	Network cabling installation (i.e., in conduit, secured to walls or tables).	5	1960 to 1964 to 1968 Cabling is in conduit and is concealed in walls and above ceilings.	
5.5.5	Wiring and telecommunication closets (i.e., size, security, ventilation/cooling, capacity for growth).	3	1960 to 1964 to 1968 Telephone and the computer network service and distribution hubs are located in a storage room. Ventilation is poor. Add ventilation.	\$1,000
5.5.6	Provision for dedicated circuits for network equipment (i.e., hubs, switches, computers).	5	1960 to 1964 to 1968 Dedicated circuits for the computer hub are provided. Computers are not on dedicated circuits.	
Other				

Section 5	Electrical Systems	Rating	Comments /Concerns	Estim. Cost
5.6	Miscellaneous Systems		Bldg. Description/Condition Section	
5.6.1	Site and building surveillance system (if applicable).	N/A	None	
5.6.2	Intrusion alarms (if applicable).	4	1960 to 1964 to 1968 A security system with motion detectors is installed in all areas. A central station connection is provided for unoccupied hours.	
5.6.3	Master clock system (if applicable).	4	1960 to 1964 to 1968 A controller for the master clock system is located in the general office.	
Other	Program co-ordinator	4	1960 to 1964 to 1968 A program controller is located in the general office to sound the call bells automatically.	
5.7	Elevators/Disabled Lifts (If applicable)			
5.7.1	Elevator/lift size, access and operating features (i.e., sensing devices, buttons, phones, detectors).	N/A	None	
5.7.2	Condition of elevators/lifts.	N/A	None	
5.7.3	Lighting and ventilation of elevators/lifts.	N/A	None	
Other				
Overall Elect. Systems Condition & Estim Costs				\$180,000

Section 6	Portable Buildings	Rating	Comments/Concerns	Estim. Cost
	<i>Note: Separate sheets can be completed, if necessary, for portable buildings of different ages and/or conditions.</i>	N/A	None	
6.1.1	Foundation and structure (i.e., signs of bending, cracking, settlement, rust, voids, stains).	N/A	None	
6.1.2	Roof materials and components (i.e., signs of deterioration, leaks, ice build-up).	N/A	None	
6.1.3	Exterior wall finishes (i.e., signs of deterioration, cracks, water stains).	N/A	None	
6.1.4	Doors and windows (i.e., signs of deterioration, rusting hardware, glass cracks, peeling paint, damaged seals).	N/A	None	
6.1.5	Interior finishes (i.e., floors, walls, ceiling).	N/A	None	
6.1.6	Millwork (i.e., counters, shelving, vanities, cabinets).	N/A	None	
6.1.7	Fixed/wall mounted equipment (i.e., writing boards, tackboards, display boards, signs)	N/A	None	
6.1.8	Heating system.	N/A	None	
6.1.9	Ventilation system.	N/A	None	
6.1.10	Electrical, communication and data network systems.	N/A	None	
6.1.11	Health and safety concerns (i.e., fire and smoke alarms, fire protection systems, exiting, fire resistance rating of materials).	N/A	None	
6.1.12	Barrier-free access.	N/A	None	
	Overall Portable Bldgs Condition & Estim Costs			\$0.00

School Facility Evaluation Project
Part I - Facility Profile and Summary

Section 7 Space Adequacy		This Facility			Equiv. New Facility			Surplus/ Deficiency	Comments/Concerns
		No.	Size	Total Area	No.	Size	Total Area		
7.1	Classrooms	23	83.6 111.5 79.8	2012.8	20	80	1600	412.8	
7.2	Science Rooms/Labs	1	83.6	83.6	3	95	285	-201.4	
7.3	Ancillary Areas (i.e., Art, Computer Labs, Drama, Music,)			216.5	3	90	270	-53.5	
	Ancillary	1	68.3		2	130	260	-260	
	Art	1	83.6						
	Music	1	64.6						
7.4	Gymnasium (incl. gym storage)			434.9			627	-192.1	
	Gymnasium		345.7						
	Storage		32.5						
	Stage		56.7						
7.5	Library/Resource Areas		200.2	200.2			300	-99.8	
7.6	Administration/Staff, Physical Education, Storage Areas			535.2			679	-143.8	
	Sub-Total			3483.2			4021	-537.8	
7.7	CTS Areas								
	7.7.1 Business Education							0	
	7.7.2 Home Economics							0	
	7.7.3 Industrial Arts							0	
	7.7.4 Other CTS Programs							0	
7.8	Other Non-Instructional Areas (i.e., circulation, wall area, crush space, wc area)			1850.5			1489	361.5	
	Overall Space Adequacy Assessment	27		5333.7	28		5510	-176.3	

[illegible]

Evaluation Component/ Sub-Component	Additional Notes and Comments

Evaluation Component/ Sub-Component	Additional Notes and Comments

Evaluation Component/ Sub-Component	Additional Notes and Comments

Evaluation Component/ Sub-Component	Additional Notes and Comments

Evaluation Component/ Sub-Component	Additional Notes and Comments