School: Glendale Elementary Date:April 13, 2000

			I			T	T
School	ol Name:	Janet Jol	hnstone	Elementary		School Code:	9270
Locat		224 Shav				Facility Code:	1512
Regio	on:	South				Superindendent:	Dr. Donna Michaels
Juriso	diction:	Calgary				Contact Person:	Leanne Soligo
						Telephone:	214-1121
Grade	es:	K-6				School Capacity:	500
Building Section	ion	Year of Compl.	No. of Floors	Gross Bldg Area (Sq.M.)	Type of Construction (i.e., structure, roof, cladding)	Description of Mechanical Systems (incl. major upgrades)	Comments/Notes
Original Buil		1982	1	795.26	Wood frame, with vertical metal siding, flat wood frame roof	Unit ventilators, piped to hot water boilers.	
Additions/ Expansions		1982	1		Concrete block with brick exterior, steel frame, OWSJ and metal deck, flat roofs.	Hot water boilers with central ventilation	
		Total		3903.73			
						Evaluator's Name:	Bob Passmore, M.A.A.A.
						& Company:	Building Science Specialists Ltd.

Upgrading/ Modernization (identify whether minor or major)					
Portable Struct. (identify whether attached/perman. or free-standing/ relocatable)					
List of Reports/ Supplementary Information	CBE Facili	ity Abes	tos Database, I	February 23, 1999	

Evaluation Components	Summary Assessment		Estim. Co
1 Site Conditions	- no work contemplated at this time.		\$0
2 Building Exterior	- replace glazing in skylight at front entry		\$8,000
3 Building Interior	- replace toilet partitions - repair fire separation		\$8,000
4 Mechanical Systems	- provide hose and standpipe system - provide backflow prevention to domestic and fire water lines - replace two hot water heaters & recirculators - replace controls compressor - provide relief air - upgrading required to HVAC units - replace exhaust fans - air balancing required in administration		\$96,200
5 Electrical Systems	- provide audio/visual alarms to fire alarm system - upgrade lighting to T-8's		\$85,000
6 Portable Buildings	- replace carpets in classes and corridors - upgrade fixtures to T-8's		\$52,000
7 Space Adequacy:			
7.1 Classrooms	- Deficient	-47.8	
7.2 Science Rooms/Labs	- Deficient	-61.05	
7.3 Ancillary Areas	- Slightly excessive	85	
7.4 Gymnasium	- Slightly excessive	21.8	
7.5 Library/Resource Areas	- Deficient	52.9	
7.6 Administration/Staff Areas	- Deficient	-230.4	
7.7 CTS Areas			
7.8 Other Non-Instructional Areas (incl. gross-up)	- Slightly excessive	100.25	
Overall School Conditions & Estim. Costs		-79.3	\$249,20

1.1.8 Safety and security concerns due to site conditions.

# School Facility Evaluation Project Part I - Facility Profile and Summary

### Section 1 Site Conditions Rating Estim. Cost Comments/Concerns 1.1 General Site Condions 1.1.1 Overall site size. 3.6 hectares Two small soccer pitches and one large, community ball diamond to south. 1.1.2 Outdoor athletic areas. New creative play area, to south east on gravel. 10 tetherball poles and four basketball hoops on pavement. 1.1.3 Outdoor playground areas, including condition of equipment and base. 1.1.4 Site landscaping. Maturing 1.1.5 Site accessories (i.e., perimeter and other fencing, Perimeter fenced to west side is wood post and cable. Play ground on west is fenced with chain link from guard rails, bike stands, flag poles). road to north. South is open to community playing fields. East side is fenced from alley. 1.1.6 Surface drainage conditions (i.e., drains away from Site is well drained, no sign of ponding. building, signs of ponding). 1.1.7 Evidence of sub-soil problems. None noted.

None noted.

Section 1	Site Conditions	Rating	Comments/Concerns	Estim. Cost
1.2	Access/Drop-Off Areas/Roadways/Bus Lanes			
1.2.1	Vehicular and pedestrian access points (i.e., size, number, visibility, safety).	4	Sidewalk approaches main entry and one sidewalk approaches west end of school. Bus and public drop off is on street to north. No problems noted.	
1.2.2	Surfacing of on-site road network (note whether asphalt or gravel).	4	Teacher/visitor parking to east is paved.	
1.2.3	Bus lanes/drop-off areas (note whether on-site or off-site).	N/A	On city street to north	
1.2.4	Fire vehicle access.	4	Fire access is through the parking lot onto graveled play area.	
1.2.5	Signage.	5	Wall mounted sign near main entry on north elevation.	
Other				
1.3	Parking Lots and Sidewalks			
1.3.1	Number of parking spaces for staff, students and visitors (including stalls for disabled persons).	4	32 staff stalls with two visitor stalls. There are no designated handicapped stalls.	
1.3.2	Layout and safety of parking lots.	4	On opposite side of school from play areas.	
1.3.3	Surfacing and drainage of parking lots (note whether asphalt or gravel).	4	Asphalt parking lot is sloped to an area drain.	
1.3.4	Layout and safety of sidewalks.	4	Sidewalks from north-side street approach the main entry, NE corner and North entry. Other walkways are city sidewalks.	
1.3.5	Surfacing and drainage of sidewalks (note type of material).	4	Concrete, slope away from building. Cracking noted at walk and east entry.	
1.3.6	Curb cuts and ramps for barrier free access.	5	Curb cut in city sidewalk.	
Other				
	Overall Site Conditions & Estimated Costs			\$0

Section 2	Building Exterior	Rating		Comments/Concerns	Estim. Cost
2.1	Overall Structure		Bldg. Section	Description/Condition	
2.1.1	Floor structure and beams (i.e., signs of bending, cracking, heaving, settlement, voids, rust, stains).	5	1982	No problems noted.	
2.1.2	Wall structure and columns (i.e., signs of bending, cracking, settlement, voids, rust, stains).	5	1982	No evidence of problems	
2.1.3	Roof structure (i.e., signs of bending, cracking, voids, rust, stains).	5	1982	No evidence of problems	
Other					
2.2	Roofing and Skylights Identify the availability of an up-to-date inspection report or roofing program. Note if roof sections are of different ages and/or in varying states of repair.			Description/Condition/Age	
	Based on the inspection report (and to the extent possible, direct observation), assess and rate roof conditions and estimate costs for required improvements (i.e., covering materials, membrane, insulation, other components).	FI	1982	No report available, not reviewed	
2.2.2	Roof accessories (i.e., ladders, stairs, hatches, masts, exhaust hoods, chimneys, gutters, downspouts, splashpads).	FI	1982	Not reviewed.	
2.2.3	Control of ice and snow falling from roof.	5	1982	Roofs slope to inside and drain internally.	
2.2.4	Skylights (i.e., signs of distress, leaks, ice build-up, condensation, deteriorated materials/seals).	3	1982	Three panes of sloped glazing at front entry require replacement	\$8,000
Other					

School: Glendale Elementary Date:April 13, 2000

Section 2	Building Exterior	Rating		Comments/Concerns	Estim. Cost
	Exterior Walls/Building Envelope		Bldg.	<u>Description/Condition</u>	
2.3.1	Exterior wall finishes (i.e., signs of deterioration, cracks, brick spalling, efflorescence, water stains).	FI	Section 1982	Brick exterior, efflorescence and brick cracking noted on NE elevation.	
2.3.2	Fascias, soffits, parapets (i.e., signs of looseness, stains, rust, peeling paint).	4	1982	Prefinished metal, no problems noted.	
2.3.3	Building envelope (i.e., evidence of air infiltration/ exfiltration through the exterior wall or ice build up on wall, eaves, canopy).	4	1982	No evidence of problems	
2.3.4	Interface of roof drainage and ground drainage systems.	4	1982	Roof drains internally into storm system	
2.3.5	Inside faces of exterior walls (i.e., signs of cracks, water stains, dust spots).	4	1982	No problems noted.	
Other					
2.4	Exterior Doors and Windows		Bldg.	Description/Condition	
2.4.1	Doors (i.e., signs of deterioration, rusting metal, glass cracks, peeling paint, damaged seals, sealed unit failure).	4	Section 1982	Insulated metal, no problems noted.	
2.4.2	Door accessories (i.e., latches, hardware, screens, locks, alarms, holders, closers, security devices).	4	1982	No evidence of problems, hardware is original.	
2.4.3	Exit door hardware (i.e., safety and/or code concerns).	4	1982	Hardware functions as required	
2.4.4	Windows (i.e., signs of deterioration, rusting metal, glass cracks, peeling paint, damaged seals, sealed unit failure).	4	1982	No problems noted.	
2.4.5	Window accessories (i.e., latches, hardware, screens, locks, alarms, holders, closers, security devices).	4	1982	No problems noted.	
2.4.6	Building envelope (i.e., signs of heavy condensation on doors or windows).	4	1982	No problems noted.	
Other	Replace boilers				
	Overall Bldg Exterior Condition & Estim Costs				\$8,000

Section 3	Building Interior - Overall Conditions	Rating		Comments/Concerns	Estim. Cos
3.1	Interior Structure		Bldg. Section	Description/Condition	
3.1.1	Interior walls and partitions (i.e., signs of cracks, spalling, paint peeling).	4	1982	No problems	
3.1.2	Floors (i.e., signs of cracks, heaving, settlement).	4	1982	Floors are concrete slab on grade, no problems noted.	
Other					
3.2	Materials and Finishes		Bldg.	Description/Condition	
3.2.1	Floor materials and finishes.	4	Section 1982	Floors are vinyl tile in corridors, classrooms a combination of VT and carpet, depending on use. Washroom (gang) are ceramic tile.	
3.2.2	Wall materials and finishes.	4	1982	Walls are painted concrete block. Gang washrooms have ceramic tile to 6 feet. Gym walls are painted concrete block. Demountable partitions in staff area and classrooms.	
3.2.3	Ceiling materials and finishes.	4	1982	Ceilings are suspended T-bar and gypsum board bulkheads. No problems noted.	
3.2.4	Interior doors and hardware.	4	1982	Doors are wood, in hollow metal frames Doors at library are hollow metal, on hold opens.	
3.2.5	Millwork	4	1982	Is original and adequate.	
	Fixed/wall mounted equipment (i.e., writing boards, tackboards, display boards, signs).	4	1982	All tackboards and blackboards are original - adequate. Some newer whiteboards .	
3.2.7	Any other fixed/mounted specialty items (i.e., CTS equipment, gymnasium equipment).	4	1982	Gymnasium has fold out climbing wall.	
3.2.8	Washroom materials and finishes.	3	1982	Laboratories are wall hung. Partitions require replacement. Walls and floors are ceramic tile.	\$7,000
Other					

ction 3	Building Interior - Overall Conditions	Rating		Comments/Concerns	Estim. Cost
ide me	Health and Safety Concerns Intent is to identify renovations considered necessary to meet applicable codes, primarily due to safety concerns. Basis of evaluation should be an up-to-		Bldg. <u>Section</u>	Description/Condition	
	date inspection report from the authority having jurisdiction together with direct observations as appropriate. Evaluator should note if in his opinion a comprehensive code evaluation is required.				
3.3.1	Building construction type - combustible or non- combustible, sprinklered or non-sprinklered.	4	1982	Building is of combustible and noncombustible construction.	
3.3.2	Fire separations (i.e., between buildings, wings, zones if non-sprinklered).	3	1982	2 hour fire separations exist between class wings and core. Fire separations between Telephone Room and Electrical room require repairs.	\$1,000
3.3.3	Fire resistance rating of materials (i.e., corridor walls and doors).	4	1982	Fire separations appear adequate.	
3.3.4	Exiting distances and access to exits.	4	1982	Appear to be adequate.	
3.3.5	Barrier-free access.	5	1982	Facility is fully accessible. Exterior access is at the main entry. There are handicapped accessible washrooms.	
3.3.6	Availability of hazardous materials audit (i.e., evidence of safety concerns with respect to asbestos, PCB's, chemicals).	5	1982	CBE Facility Asbestos database indicates no asbestos is present. No other hazardous materials are noted.	
3.3.7	Other health and safety concerns (i.e., evidence of excessive noise conditions, air quality problems)	5	1982	None noted.	
Other					
	Overall Bldg Interior Condition & Estim Costs				\$8,000

Section 4	Mechanical Systems	Rating		Comments/Concerns	Estim. Cost
4.1	Mechanical Site Services		Bldg. Section	Description/Condition	
4.1.1	Site drainage systems (i.e., surface and underground systems, catch basins).	4	1982	Catch basins are provided in the parking lot, north lawn, north west grass area and northeast(front) lawn. They are connected to the city storm system.	
	Exterior plumbing systems (i.e., irrigation systems, hose bibs).	4	1982	Hose bibs are provided on the northwest, southwest, southeast and northeast walls.	
4.1.3	Outside storage tanks.	NA		None	
Other					
4.2	Fire Suppression Systems		Bldg. Section	Description/Condition	
4.2.1	Fire hydrants and siamese connections.		1982	A fire hydrant is located on the southwest side.	
		4			
	Fire suppression systems (i.e., pumps, sprinklers, piping, reservoirs, hoses, stand pipes, CO2 systems).	3	1982	No fire protection system is provided. The building by code requires a hose and standpipe system.	\$27,500
4.2.3	Hand extinguishers, blankets and showers (i.e., in CTS areas).	4	1982	Type ABC dry chemical extinguishers are provided in cabinets in the main corridor near all exits and in the library. Type ABC dry chemical extinguishers are located in equipment rooms, former science room, copier room, staff room and stage.	
4.2.4	Other special situations (e.g., flammable storage areas, science labs, CTS areas).	NA		None	
Other					

Section 4	Mechanical Systems	Rating		Comments/Concerns	Estim. Cost
4.3	Water Supply and Plumbing Systems		Bldg.	<u>Description/Condition</u>	
4.3.1	Domestic water supply (i.e., pressure, volume, quality - note whether municipal or well supply).	4	Section 1982	A 6"dia. iron water supply is brought from city mains to a meter in the boiler room. Pressure, quality and capacity are good.	
4.3.2	Water treatment system(s).	NA		None	
4.3.3	Pumps and valves (including backflow prevention valves).	3	1982	A master control valve is and a valved bypass on the meter are provided. No backflow protection is provided on the domestic water supply. The boiler feedwater line has backflow protection. Provide backflow protection on the domestic water and fire lines.	\$6,000
4.3.4	Piping and fittings.	5	1982	Water piping is copper tubing with soldered joints.	
4.3.5	Plumbing fixtures (i.e., toilets, urinals, sinks)	3	1982	Water closets are regular rim, floor mounted with flush valves. Lavatories are wall hung. Urinals are stall type with flush valves. Countertop sinks are stainless steel. A wall hung janitors sink is provided, Single bubbler wall mounted drinking fountains are located in the corridors. A counter top lavatory requires replacing.	\$500
4.3.6	Domestic hot water system (i.e., heater, storage tanks, failure alarms, pressure, volume, recirculation).	3	1982	Twin tank type large capacity gas fired water heaters are located in the boiler room. Only one is used. They are much larger than required. An in-line recirculating pump is provided. These tanks will require replacement.	\$900
4.3.7	Sanitary and storm sewers, including sumps and pits (note whether sewage system is municipal or septic).	4	1982	Mechanical joint cast iron storm and sanitary lines are connected to city mains.	
Other					

Section 4	Mechanical Systems	Rating		Comments/Concerns	Estim. Cost
4.4	Heating Systems		Bldg.	<u>Description/Condition</u>	
4.4.1	Heating capacity and reliability (including backup capacity).	3	Section 1982	Twin compact packaged gas fired hot water boilers are installed in the boiler room. They each have an output of 1440 MBH. They have low water cutoffs, no flow shut down and pressure relief valves. They are replacements. Two heating circulators are installed. These will require replacement.	\$2,000
4.4.2	Heating controls (including use of current energy management technology.	3	1982	The heating system uses a system of pneumatic controls. A dual unit control air compressor c/w a dryer is provided. Boilers are lead-lag operation with indoor/outdoor temperature control. The compressors will require major work	\$5,000
4.4.3	Fresh air for combustion and condition of the combustion chimney.	3	1982	An insulated combustion air duct is brought from a wall louvre to 18" above the floor. A unit heater is used to add heat to the combustion air. It has a space t'stat controller. A gas code required relief air opening is not provided. Provide relief opening.	\$1,000
4.4.4	Treatment of water used in heating systems.	4	1982	A chemical pot feeder is piped across the supply and return heating mains.	
4.4.5	Low water cutoff/pressure relief valves and failure alarms (i.e., hot water heating).	5	1982	The boilers have low water cutoffs, no flow shut down and pressure relief valves.	
4.4.6	Heating air filtration systems and filters.	4	1982	See 4.5.1	
4.4.7	Heating humidification systems and components.	4	1982	See 4.5.9	

Section 4	Mechanical Systems	Rating		Comments/Concerns	Estim. Cost
4.4	Heating Systems (cont'd)		Bldg.	Description/Condition	
4.4.8	Heating distribution systems (i.e., piping, ductwork) and associated components (i.e., diffusers, radiators).	4	Section 1982	Heating distribution is a pumped system using threaded and screwed steel piping. Terminals are reheat coils, radiator convectors, wall fin convectors, a unit heater and fan cabinet heaters controlled by space t'stats.	
4.4.9	Heating piping, valve and/or duct insulation.	4	1982	Pipe insulation is canvas covered fiberglass.	
4.4.10	Heat exchangers.	5	1982	See 4.5.10	
4.4.11	Heating mixing boxes, dampers and linkages.	4	1982	There are no terminal mixing boxes.	
4.4.12	Heating distribution/circulation in larger spaces (i.e., user comfort, temperature of outside wall surfaces).	4	1982	No comfort problems were reported in the larger areas.	
4.4.13	Zone/unit heaters and controls.	4	1982	Fan cabinet heaters and the unit heater have their motors cycled by space t'stats.	
Other	Expansion tanks	3	1982	A standard type expansion tank is suspended from the ceiling. A gauge glass is provided. This tank will require replacement.	\$1,500
4.5	Ventilation Systems		Bldg.	Description/Condition	
4.5.1	Air handling units capacity and condition.	3	Section 1982	The main portion of the building uses two packaged HVAC units to temper and cool the air supply to all parts of the building. A separate packaged unit heats and ventilates the gymnasium. Return fans are not installed. Capacity is good. The motors, fans. heating coils and control valves will need major	\$28,000
4.5.2	Outside air for the occupant load (if possible, reference CFM/occupant).	4	1982	work. The amount of fresh air delivered by these units is adjustable. The CFM/occupant is not known.	
4.5.3	Air distribution system (if possible, reference number of air changes/hour).	4	1982	The two central units have supply main and return ducts. Air is supplied by branches to ceiling supply diffusers and return by ceiling grilles. Motorized fresh/return air dampers are provided. The gym. has a main supply duct with floor grilles and two large roof relief vents. Air changes are about 6/ hour.	
4.5.4	Exhaust systems capacity and condition.	3	1982	A central system exhaust is not provided. It is not known how relief for the system is provided. Central roof exhausters are used for the washrooms, These will require replacement.	\$1,800
4.5.5	Separation of out flow from air intakes.	4	1982	Separation is fair.	
4.5.6	Special/dedicated ventilation and/or exhaust systems (i.e., kitchen, labs, CTS areas).	NA		None	

ection 4	Mechanical Systems	Rating		Comments/Concerns	Estim. Cost
4.5	Ventilation Systems (cont'd)		Bldg. Section	Description/Condition	
	Note: Only complete the following items if there are separate ventilation and				
4.5.7	Ventilation controls (including use of current energy management technology).	4	1982	The ventilation units have discharge air temperature controllers. The return air and fresh air intakes have motorized dampers. There is no energy management system.	
4.5.8	Air filtration systems and filters.	4	1982	The ventilation units have filter sections with replaceable media filters.	
4.5.9	Humidification system and components.	3	1982	Each ventilation unit has a spray humidifier without pumps. Humidistat in the return air ducts operate solenoid water valves. Operation of the valves is erratic. Some repairs are required.	\$2,000
4.5.10	Heat exchangers.	3	1982	A replacement insulated shell and tube heat exchanger is used to transfer heat to the glycol mixture in the ventilation unit heating coil system. Three in-line circulators are installed for the ventilation unit heating coils. These will require replacement.	\$3,000
4.5.11	Ventilation distribution system and components (i.e., ductwork, diffusers, mixing boxes, dampers, linkages).	4	1982	See 4.5.3.	
Other					
4.6	Cooling Systems		Bldg.	Description/Condition	
4.6.1	Cooling system capacity and condition (i.e., chillers, cooling towers, condensers).	3	Section 1982	Direct expansion cooling coils are installed in the two main ventilation units. Two condensing units are located on the roof. Major repairs will be required on these units.	\$16,000
4.6.2	Cooling distribution system and components (i.e., ductwork, diffusers, mixing boxes, dampers, linkages)	3	1982	See 4.5.3 for distribution. General office staff complained about overheating and overcooling. The office area should have the air supply volumes rebalanced.	\$1,000
4.6.3	Cooling system controls (including use of current energy management technology).	4	1982	The condensing systems operate using electric controls cycled by the discharge duct sensors. Space t'stats add heat as required by operating control valves on reheat coils.	
4.6.4	Special/dedicated cooling systems (i.e., labs, CTS areas).	NA		None	
Other					
4.7	Building Control Systems		Bldg. Section	Description/Condition	
171	Building wide/system wide control systems		1982	A setback thermostat (chronotherm) ) is installed to lower building temperatures during unoccupied hours.	
4.7.1	and/or energy management systems.	4		nouis.	

#### School: Glendale Elementary Date:April 13, 2000

Section 5	Electrical Systems	Rating		Comments/Concerns	Estim. Cost
5.1	Site Services		Bldg. Section	<u>Description/Condition</u>	
5.1.1	Primary service capacity and reliability (i.e., access, location, components, installation, bus sizes - note whether overhead or underground).	4	1982	Service is underground from utility lines to a pad mounted transformer and then to a switchboard in the electrical room. The main switch is rated at 1600 amperes at 3 phase 115/208v. Demand is at 240 va.	
5.1.2	Site and building exterior lighting (i.e., safety concerns).	4	1982	HID fixtures are used on all exterior walls. The parking lot has two HIDs on the southeast wall of the school.	
5.1.3	Vehicle plug-ins (i.e., number, capacity, condition).	4	1982	The parking area has a total of 17 duplex plug-ins. They are installed on both sides of the lot. They are on a timer.	
Other					
5.2	Life Safety Systems		Bldg. Section	Description/Condition	
5.2.1	Fire and smoke alarm systems (i.e., safety concerns, up-to-date technology, regularly tested).	3	1982	An eight zone fire control panel is located in the main lobby. It has battery back-up and trouble supervision. Devices are located throughout the building. The system does not comply completely with current codes The system is tested annually. Provide audio/visual alarms.	\$2,000
5.2.2	Emergency lighting systems (i.e., safety concerns, condition).	4	1982	A single large emergency battery pack is used with remote heads in the corridors, library, gymnasium, washrooms, equipment rooms and main lobby/entry.	
5.2.3	Exit lighting and signage (i.e., safety concerns, condition).	4	1982	Illuminated exit lights are located at all building exits, gymnasium exits and library exits They are wired to the emergency battery pack.	
Other					

ction 5	Electrical Systems	Rating		Comments/Concerns	Estim. Cos
5.3	Power Supply and Distribution		Bldg. Section	<u>Description/Condition</u>	
5.3.1	Power service surge protection.	4	1982	Only the recently installed computer hub has surge protection.	
5.3.2	Panels and wireways capacity and condition.	4	1982	Wiring is in conduit and concealed. Panels have extra spaces.	
	Emergency generator capacity and condition and/or UPS (if applicable).	NA		None	
5.3.4	General wiring devices and methods.	4	1982	Receptacles are grounded type. Devices are in good condition.	
5.3.5	Motor controls.	5	1982	Larger motors have magnetic starters. Small motors have thermal switches.	
Other					
5.4	Lighting Systems		Bldg. Section	Description/Condition	
	Interior lighting systems and components (i.e., illumination levels, conditions, controls).	3	1982	Most of the building uses fluorescent fixtures. Lighting levels were recorded as follows: typical classrooms - 216 lux, library - 216 lux, conference room - 216 lux, copier room - 324 lux, general office - 324 lux, storage/reading room - 108 lux, gymnasium - 216 flux boiler room - 216 lux, electrical room - 324 lux. Fixtures and switching is good. Some exterior canopy fixtures do not have lamps. See 5.4.3. Most area should have lamps reinstalled.	\$2,000
	Replacement of ballasts (i.e., health and safety concerns).	3	1982	Many fixtures are expected to have ballasts with PCBs. See 5.4.3.	
	Implementation of energy efficiency measures and recommendations.	3	1982	Most of the fluorescent fixtures have been delamped by up to 50% and the lamps are 34 watt type. Replace all fluorescent fixtures with T-8 lamp equipped fixtures.	\$81,000
Other					

#### School: Glendale Elementary Date:April 13, 2000

Section 5	Electrical Systems	Rating		Comments/Concerns	Estim. Cost
5.5	Network and Communication Systems		Bldg. Section	Description/Condition	
5.5.1	Telephone system and components (i.e., capacity, reliability, condition).	4	1982	The telephone service is into the electrical room. Service is in good condition with adequate capacity.	
	Other communication systems (i.e., public address, intercom, CCTV, satellite or cable TV).	4	1982	A telephone intercom system has recently been installed with telephones in all classrooms and other occupied rooms. A public address system is provided with speakers throughout the building. A cable TV system is still in place in all areas.	
	Network cabling (if available, should be category 5 or better).	5	1982	A new computer system has recently been installed with internet access. Outlets are provided throughout the school.	
5.5.4	Network cabling installation (i.e., in conduit, secured to walls or tables).	5	1982	All computer cabling is run in conduit. Cabling is concealed in the building structure.	
5.5.5	Wiring and telecommunication closets (i.e., size, security, ventilation/cooling, capacity for growth).	4	1982	The computer hub is located in a change room with washroom facilities and showers that are not used. The room is called the resource room. It has exhaust ventilation. Security is questionable.	
	Provision for dedicated circuits for network equipment (i.e., hubs, switches, computers).	5	1982	The computer hub and computers in the computer area of the library are on dedicated circuits. Other computers are on general circuits.	
Other					

#### School: Glendale Elementary Date:April 13, 2000

Section 5	Electrical Systems	Rating		Comments/Concerns	Estim. Cost
5.6	Miscellaneous Systems		Bldg.	Description/Condition	
	Site and building surveillance system (if applicable).	NA	Section	None	
5.6.2	Intrusion alarms (if applicable).	5	1982	A security system with motion detectors is installed in all parts of the building. A central station connection is provided for unoccupied hours.	
5.6.3	Master clock system (if applicable).	4	1982	A master clock system is provided with a controller in the general office. The system does not have clocks throughout the building.	
Other	Program co-ordinator	5	1982	A program co-ordinator control panel is located in the general office. It automatically sounds the call bells.	
5.7	Elevators/Disabled Lifts (If applicable)		Bldg.	Description/Condition	
	Elevator/lift size, access and operating features (i.e., sensing devices, buttons, phones, detectors).	NA	Section	None	
5.7.2	Condition of elevators/lifts.	NA		Not applicable.	
5.7.3	Lighting and ventilation of elevators/lifts.	NA		Not applicable.	
Other					
	Overall Elect. Systems Condition & Estim Costs				\$85,000

Section 6	Portable Buildings	Rating	Comments/Concerns	Estim. Cost
	Note: Separate sheets can be completed, if necessary, for portable buildings of different ages and/or conditions.			
	Foundation and structure (i.e., signs of bending, cracking, settlement, rust, voids, stains).	4	Wood, no problems noted.	
6.1.2	Roof materials and components (i.e., signs of deterioration, leaks, ice build-up).	FI	Not reviewed	
6.1.3	Exterior wall finishes (i.e., signs of deterioration, cracks, water stains).	4	Vertical metal siding, no problems noted.	
	Doors and windows (i.e., signs of deterioration, rusting hardware, glass cracks, peeling paint, damaged seals).	4	No problems noted.	
6.1.5	Interior finishes (i.e., floors, walls, ceiling).	3	Walls are demountable and gypsum board partitions, ceiling are suspended T-bar, floors are VT and carpet. Carpet in rooms and corridor to be replaced.	\$31,000
6.1.6	Millwork (i.e., counters, shelving, vanities, cabinets).	4	Original, but functional	
6.1.7	Fixed/wall mounted equipment (i.e., writing boards, tackboards, display boards, signs)	4	Original, but functional	
6.1.8	Heating system.	4	Large unit ventilators with wall plenums are installed on the window wall. They use a hot water heating coil piped to the main heating system. These are in good condition.	
6.1.9	Ventilation system.	4	The unit ventilators bring in fresh air and mixes it with return air.	
6.1.10	Electrical, communication and data network systems.	3	The building telephone intercom system is provided in the portables. (8).The computer system is extended to the portables. Replace fluorescent fixtures with T-8 lamp equipped fixtures.	\$21,000
6.1.11	Health and safety concerns (i.e., fire and smoke alarms, fire protection systems, exiting, fire resistance rating of materials).	4	The fire alarm system is connected to the central system with alarms, pull stations and fire detectors. Emergency and exit lights are provided.	
6.1.12	Barrier-free access.	4	They are accessible from the main school	
	Overall Portable Bldgs Condition & Estim Costs			\$52,000

	Space Adequacy		This Fa	cility	Ec	quiv. Nev	w Facility	Surplus/	
Section 7		No.	Size	Total Area	No.	Size	Total Area	Deficiency	Comments/Concerns
7.1	Classrooms	14		1072.2	14	80	1120	-47.8	
			77						
			76.2						
			77.1						
			76						
			75.2						
7.2	Science Rooms/Labs	1	128.95	128.95	2	95	190	-61.05	
	Ancillary Areas (i.e., Art, Computer Labs, Drama, Music,)	4		485			400	85	
	Ancillary Areas		89.2		1	130			
	Ancillary Areas Ancillary Areas	1	107		-	100	1	<del> </del>	
	Ancillary Areas		106.3						
	Music		182.5		3	90			
	Gymnasium (incl. gym storage)		102.0	494.8	Ü	- 00	473	21.8	
	Gymnasium (incl. gym storage)		446.8			430			
	Storage		48			43			
	etorage		.0						
7.5	Library/Resource Areas			272.9			220	52.9	
	Library/Resource Areas		250.8						
	Conference		22.1						
7.6	Administration/Staff, Physical Education, Storage Areas			280.6			511	-230.4	
	Administration/Staff		188.9			357			
	Physical Education		15.8			70			
	Storage		75.9			84			
	Sub-Total			2734.45			2914	-179.55	
	CTS Areas								
	7.7.1 Business Education								
	7.7.2 Home Economics								
	7.7.3 Industrial Arts								
	7.7.4 Other CTS Programs								
	Other Non-Instructional Areas (i.e., circulation, wall area, crush space, wc area)			1169.25			1069	100.25	
	Overall Space Adequacy Assessment	19		3903.7	20		3983	-79.3	

Evaluation Component/ Sub-Component	Additional Notes and Comments

Evaluation Component/ Sub-Component	Additional Notes and Comments

Evaluation Component/ Sub-Component	Additional Notes and Comments

Evaluation Component/ Sub-Component	Additional Notes and Comments

Evaluation Component/ Sub-Component	Additional Notes and Comments

Evaluation Component/ Sub-Component	Additional Notes and Comments