

# RECAPP Facility Evaluation Report

## Edmonton School District No. 7



### Eastglen Composite High School

B3096A  
Edmonton

**Facility Details**

**Building Name:** Eastglen Composite High School  
**Address:** 11430 - 68 Street  
**Location:** Edmonton

**Building Id:** B3096A  
**Gross Area (sq. m):** 0.00  
**Replacement Cost:** \$25,964,709  
**Construction Year:** 0

**Evaluation Details**

**Evaluation Company:** Stephens Kozak Carr and Brown  
**Evaluation Date:** November 4 2005  
**Evaluator Name:** Mr. Eric Lumley

**Total Maintenance Events Next 5 years:** **\$8,858,530**  
**5 year Facility Condition Index (FCI):** **34.12%**

**General Summary:**

The building was constructed in 1953 with major additions in 1957 and 1961. The building is on two floors with basement areas under the main gymnasium and drama areas. There is an underground corridor providing access to the adjacent Eastglen Swimming Pool. The total area of the facility is 15,728sq.m.

The building is in acceptable structural condition but requires total window replacement, asbestos abatement, and interior refinishing to classroom floors and paint.

The building is generally in marginal condition.

**Structural Summary:**

The structure comprises cast-in-place concrete foundation and basement walls on strip footings. The concrete column sit on pad foundations. The two storey structure is cast-in-place concrete columns and beams with cast-in-place concrete floors.

The structure is generally in acceptable condition.

**Envelope Summary:**

The building skin is brick veneer with wood and steel windows. The windows are in need of replacement. The roof is SBS roofing and is in good condition. The exterior doors are the original wood doors or have been upgraded to metal insulated doors. The wood doors are in need of replacement.

The envelope, with the exception of the windows, is generally in acceptable condition.

**Interior Summary:**

The interior is plaster walls on clay tile, with asbestos spray on the ceilings in most classrooms. The corridors are terrazzo finish with cove base, and ceramic tile walls to dado height, then painted plaster walls to ceiling level. Gymnasiums have wood floors. Classrooms have upgraded sheet vinyl flooring or still have the original lino flooring. Doors are painted solid core wood in steel frames. Some areas have been upgraded with new flooring and T-bar ceilings.

The interior condition is generally marginal.

**Mechanical Summary:**

Original school built in 1953 with additions in 1957 and 1961. Heating system consists of three (3) low pressure steam boilers, distribution piping to air system coils and building terminal heat transfer units. Ten (10) low velocity air systems provide ventilation air throughout the building. Controls are pneumatic. BMCS not installed. Exhaust fans expel foul odors. Plumbing fixtures and brass are commercial quality. Fire protection consists of wet standpipe with fire hose cabinets, portion of building has wet sprinkler system, fire extinguishers.

Items found during review which should be addressed are:

- Replace janitor sinks.
- Install electric solenoid valve for science room.
- Install new heating plant.
- Install new hot water distribution system and terminal heat transfer units.
- Install fume hood make up units.
- Install air conditioning in computer rooms.

- Install air conditioning in server rooms.
- Install humidification.
- Install BMCS.
- Replace dated plumbing fixtures.

Mechanical systems and components are in marginal condition.

**Electrical Summary:**

In general, the electrical systems in the school are in acceptable condition. The marginal components are as follows and should be considered for upgrading:

- Install pad mounted, exterior transformer.
- Install new main distribution panel c/w TVSS.
- Upgrade branch circuit panels and provide additional receptacles.
- Replace motor starters.
- Provide additional emergency lighting.
- Replace T12 fluorescent fixtures with T8 type.

<b>Rating Guide</b>	
<b>Condition Rating</b>	<b>Performance</b>
1 - Critical	Unsafe, high risk of injury or critical system failure.
2 - Poor	Does not meet requirements, has significant deficiencies. May have high operating/maintenance costs.
3 - Marginal	Meets minimum requirements, has significant deficiencies. May have above average operating maintenance costs.
4 - Acceptable	Meets present requirements, minor deficiencies. Average operating/maintenance costs.
5 - Good	Meets all present requirements. No deficiencies.
6 - Excellent	As new/state of the art, meets present and foreseeable requirements.

**S1 STRUCTURAL****A1010 Standard Foundations\***

Concrete foundation walls and strip footings.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	100	NOV-05

**A1030 Slab on Grade\***

Basement floor slab.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	100	NOV-05

**A2020 Basement Walls (& Crawl Space)\***

Cast-in-place concrete basement walls and perimeter foundation walls.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	100	NOV-05

**B1010.01 Floor Structural Frame\*(Building Frame)**

Cast-in-place concrete columns and beams, with cast-in-place floor slabs.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	100	NOV-05

**B1010.02 Structural Interior Walls Supporting Floors\***

Cast-in-place concrete walls in basement and gym mezzanine.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	100	NOV-05

**B1010.03 Floor Decks, Slabs, and Toppings\***

Cast-in-place structural slabs at main and upper floors.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	100	NOV-05

**B1010.05 Mezzanine Construction\***

Gym mezzanine cast-in-place concrete.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	100	NOV-05

**B1010.06 Ramps: Exterior\*\***

Cast-in-place concrete ramps provided at all entrances above grade level.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	40	NOV-05

**B1010.07 Exterior Stairs\*\***

Cast-in-place concrete stairs at rear entrances.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	40	NOV-05

**B1020.01 Roof Structural Frame\***

Concrete Tees visible in auditorium. Main roof structure assumed to be similar. 1961 gym addition has gluelam beams, joists and wood deck.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	100	NOV-05

**B1020.04 Canopies\***

Concrete slab projection forms canopy at main entrance.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	100	NOV-05

**S2 ENVELOPE****B2010.01.02.01 Brick Masonry: Ext. Wall Skin\***

Brick veneer to entire perimeter.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	75	NOV-05

**B2010.01.03 Stone Assemblies: Exterior Wall Skin\***

Tyndal stone window surrounds and sills and vertical pilasters at the library.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	75	NOV-05

**B2010.01.03.04 Marble: Exterior Wall Skin**

Decorative marble finish adjacent to main entrance.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	NOV-05

**B2010.01.06.03 Metal Siding\*\***

Vertical metal siding on the west face of the original gymnasium and returning round the north and south corners.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	40	NOV-05

**B2010.01.11 Joint Sealers (caulking): Ext. Wall\*\***

Caulked construction joint between the 1953 original building and the 1957 addition.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	15	NOV-05

**B2010.02.03.04 Glass Masonry Units (Glass Block)**

Glass block above windows.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	NOV-05

**B2010.09 Exterior Soffits\***

Painted textured parging on concrete substrate.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	20	NOV-05

**B2020.01.01.01 Steel Windows (Glass & Frame)\*\***

Steel windows with single glazing at library and central entrance foyer / stair.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
2 - Poor	0	35	NOV-05

**Event:** **Replace steel windows with aluminum curtain wall sections.**

**Concern:**

Steel windows are deteriorated and offer no thermal insulation value.

**Recommendation:**

Replace steel windows with aluminum curtain wall section and double glazing. ( 20 M )

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2007	\$53,500	High

*Updated: February 15 2006*

**B2020.01.01.05 Wood Windows (Glass & Frame)\*\***

The majority of the windows are the original wood frame. Some windows have inset double glazing retained by a metal glazing stop.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
1 - Critical	0	35	NOV-05

**Event:** **Replace all windows with new fibreglass or PVC windows.**

**Concern:**

Existing windows are 53 years old and a significant number have rotted frames and sills.

**Recommendation:**

Remove the existing wood windows and glass block infill and replace with new fibreglass or PVC windows. Infill the wall opening with insulated steel stud construction, with a gypsum board interior finish and an acrylic stucco exterior finish. (140 window bays at \$11000 per bay).

Remove glass block and infill wall. (Part of window replacement event)

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2007	\$1,647,800	High

*Updated: February 15 2006*

**B2030.01.02 Steel-Framed Storefronts\*\***

Hollow metal doors and transom lites in steel frames at most entrances.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	15	NOV-05

**B2030.01.10 Wood Entrance Door\*\***

Main entrance and entrance to 1957 wing has varnished wood doors in wooden frames. original hardware is failing.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	NOV-05

**Event:** Replace exterior wooden doors and frames with insulated hollow metal doors and pressed steel frames.

**Concern:**

Existing wooden doors and frames are deteriorating and hardware is obsolete.

**Recommendation:**

Replace 8 wooden entrance doors and frames with hollow metal insulated doors and pressed steel frames.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2007	\$32,100	Medium

*Updated: February 15 2006*

**B2030.01.10 Wood Entrance Door\*\*Utility**

Painted wood doors to mechanical room, roof access and other locations.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	20	NOV-05

**Event:** Replace exterior painted wood doors with insulated hollow metal doors. Provide new hardware. (4 sets of double doors)

**Concern:**

Exterior painted wood doors are deteriorating.

**Recommendation:**

Replace 6 exterior painted wood doors with insulated hollow metal doors.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2007	\$6,420	Low

*Updated: February 15 2006*



**B2030.03 Large Exterior Special Doors\***

Manually operated wood sectional overhead doors with glazed panels in woodworking shop and automotive areas (4)

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	NOV-05

**Event:** Replace wood sectional overhead doors with insulated prefinished metal overhead doors, electrically operated.

**Concern:**

Overhead doors are wooden and in marginal condition. They provide little insulation value and are high maintenance items.

**Recommendation:**

Provide 4 new insulated metal sectional doors, electrically operated.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2007	\$25,680	Low

*Updated: February 15 2006*

**B3010.04.01 Built-up Bituminous Roofing (Asphalt & Gravel)\*\***

Small area of original tar and gravel roof over the boiler room. (280 sq.m.)

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	25	NOV-05

**B3010.04.04 Modified Bituminous Membrane Roofing (SBS)\*\***

Most areas have been reroofed between 1987 and 1991.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	25	NOV-05

**S3 INTERIOR****C1010.01 Interior Fixed Partitions\***

Plaster on clay tile substrate. Upgraded areas have gypsum board on steel studs.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	NOV-05

**C1010.05 Interior Windows\***

Individual interior glazing in several locations, typically laminated glass in steel frames.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	40	NOV-05

**C1020.01 Interior Swinging Doors\*\***

Painted wood doors in steel frames.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	NOV-05

**C1020.03 Interior Fire Doors\***

Wood doors to stairs and on storage rooms and mechanical rooms are not rated.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
2 - Poor	0	50	NOV-05

**Event:** Provide rated steel doors to stairs, storage rooms and mechanical rooms.  
**(80 doors)**

**Concern:**

Doors to stairs, storage rooms and mechanical rooms are not rated.

**Recommendation:**

Provide steel rated doors to stairs, storage rooms and mechanical rooms. 80 Doors

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Code Repair	2007	\$85,600	Low

*Updated: February 15 2006*

**C1020.04 Interior Sliding and Folding Doors\***

Wood gym divider in main gym.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	40	NOV-05

**C1030.01 Visual Display Boards\*\***

Combination of blackboards, whiteboards and display boards throughout classroom areas.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	10	NOV-05

**C1030.02 Fabricated Compartments(Toilets/Showers)\*\***

Metal toilet partitions, painted.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	20	NOV-05

**Event:** Replace painted toilet partitions with baked enamel finish toilet partitions.  
(28 stalls)

**Concern:**

Painted toilet partitions are scratched and bent.

**Recommendation:**

Replace painted toilet partitions with prefinished baked enamel toilet partitions.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2009	\$44,940	Low

*Updated: February 15 2006*

**C1030.06 Handrails\***

Painted pipe rail handrails and railings to mezzanine seating area.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	NOV-05

**C1030.08 Interior Identifying Devices\***

Cast aluminum and self adhesive plastic laminate signs on doors.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	10	NOV-05

**C1030.10 Lockers\*\***

1280 full height steel lockers, painted. Original.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	NOV-05

**C1030.12 Storage Shelving\***

Millwork storage units in storage rooms.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	20	NOV-05

**C1030.14 Toilet, Bath, and Laundry Accessories\***

Miscellaneous washroom accessories such as electric handryers, roller towel dispensers, soap dispensers, toilet roll holders, mirrors.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	20	NOV-05

**C2010 Stair Construction\***

Cast-in-place concrete stairs.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	100	NOV-05

**C2020.02 Terrazzo Stair Finishes\***

Terrazzo stair treads with carborundum strips on the nosings, integral coved terrazzo base.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	75	NOV-05

**C2020.08 Stair Railings and Balustrades\***

Stainless steel tubular handrails.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	50	NOV-05

**C3010.01 Concrete Wall Finishes\***

Painted concrete walls in basement and connecting passageway to swimming pool.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	100	NOV-05

**C3010.03 Plaster Wall Finishes\***

Plaster wall finish on clay tile substrate throughout.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	40	NOV-05

**C3010.04 Gypsum Board Wall Finishes\***

Upgraded areas have gypsum board finish on steel studs.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	40	NOV-05

**C3010.06 Tile Wall Finishes\*\***

Ceramic tile to dado height in corridors, stairs and washrooms.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	50	NOV-05

**C3010.06.02 Quarry Tile**

Quarry tile floor in main science classroom.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	0	NOV-05

**C3010.09 Acoustical Wall Treatment\*\***

12 x 12 perforated tile on acoustic matting in auditorium.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	20	NOV-05

**C3010.11 Interior Wall Painting\*\***

Interior of classrooms and corridors above tile dado.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	5	NOV-05

**Event:** Repaint interior of classrooms and corridors above tile dado. (20,250 sq.m.)

**Concern:**

Paint finish is dirty and blemished.

**Recommendation:**

Repaint interior of classrooms and corridors above dado height. (11,000 sq M)

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2007	\$233,260	Low

Updated: February 15 2006

**C3020.01 Concrete Floor Finishes (Paint)\***

Painted storage room and utility room floors.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	75	NOV-05

**C3020.02 Tile Floor Finishes\*\***

12 x 12 and 9 x 9 Vinyl asbestos tile in some classrooms and the entrance foyer to the auditorium.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	NOV-05

**C3020.02.01 Ceramic Tile**

Ceramic mosaic tile in washrooms.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	NOV-05

**Event:** Replace ceramic mosaic tile in washrooms with resilient sheet flooring.

**Concern:**

Ceramic mosaic tile in washrooms is patched and repaired in several locations.

**Recommendation:**

Remove ceramic mosaic tile and install sheet vinyl flooring. ( 200 sqM )

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2007	\$21,400	Low

Updated: February 15 2006

**C3020.03 Terrazzo Floor Finishes\***

Terrazzo flooring in corridors and main entrance, with coved terrazzo base.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	70	NOV-05

**C3020.04 Wood Flooring\*\***

Resilient wood flooring in both gymnasias. Wood strip flooring in I.A. woodworking area. New resilient wood flooring in dance studio.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	25	NOV-05

**C3020.07 Resilient Flooring\*\*Lino**

Original linoleum flooring in 60% of the classrooms.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
2 - Poor	0	20	NOV-05

**Event:** Replace original linoleum flooring with new resilient sheet vinyl flooring. (approximately 4400 sq.m.)

**Concern:**

Original linoleum is 53 years old and worn with open seams.

**Recommendation:**

Replace linoleum flooring in 60% of the classrooms with new resilient sheet vinyl flooring. (3800 sq M)

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2007	\$282,480	Medium

*Updated: February 15 2006*

**C3020.07.02 Resilient Sheet Flooring**

Resilient sheet vinyl flooring in upgraded areas.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	NOV-05

**C3020.08 Carpet Flooring\*\***

Carpet in general office and staff areas.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	10	NOV-05

**C3020.11 Floor Painting**

Painted concrete floors to some utility rooms and storage rooms.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	5	NOV-05

**C3020.14 Other Floor Finishes\*\***

Sealed concrete floor slab to mechanical rooms.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	5	NOV-05

**C3030.01 Concrete Ceiling Finishes\***

Painted concrete finish to basement areas and connecting underground passageway to the adjacent swimming pool.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	100	NOV-05

**C3030.03 Plaster Ceiling Finishes\***

Plaster ceilings in utility rooms, storage rooms, washrooms and change rooms.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	NOV-05

**C3030.06 Acoustic Ceiling Treatment (Susp.T-Bar)\*\***

Upgraded areas such as the Home Ec.area and the staff areas have T-bar ceilings with lay-in acoustic tile.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	25	NOV-05

**C3030.07 Interior Ceiling Painting\*\***

Painted ceilings throughout with the exception of upgraded areas which have T-bar ceilings.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	10	NOV-05

**Event:** **Repaint plaster ceilings in utility rooms, storage rooms, washrooms and change rooms.**

**Concern:**

Paint finish to plaster ceilings in utility rooms, storage rooms, washrooms and change rooms is damaged and discoloured.

**Recommendation:**

Repaint plaster ceilings in utility rooms and storage rooms. (1200 sq M)

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2007	\$26,750	Low

*Updated: February 15 2006*

**C3030.09 Other Ceiling Finishes\*Asbestos Acoustic Spray**

Asbestos acoustic spray finish to underside of concrete floor and roof slabs, in most classrooms. See Asbestos Building Material Survey Report dated March 21, 2000. This material was identified as requiring scheduled repair or removal.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
3 - Marginal	0	0	NOV-05

**Event:** **Remove asbestos acoustic ceiling spray throughout building. (6,800 sq.m.)**  
**Install T-bar ceilings.**

**Concern:**

Acoustic ceiling spray is subject to deterioration and impacts upgrading costs.

**Recommendation:**

Remove the asbestos ceiling spray and install T-bar ceilings with lay-in acoustic tiles. (7000 sq M)

<b><u>Type</u></b>	<b><u>Year</u></b>	<b><u>Cost</u></b>	<b><u>Priority</u></b>
Hazardous Materials Abatement	2007	\$1,018,640	Medium

*Updated: February 15 2006*

**C3030.09 Other Ceiling Finishes\*Tectum Acoustic Panels**

Main gymnasium has Tectum acoustic panel ceiling.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	0	NOV-05

**D1010.01.02 Hydraulic Passenger Elevators\*\***

Handicapped elevator providing access to both floor levels and the basement.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
5 - Good	0	30	NOV-05

**D1010.02 Lifts\*\***

Wheelchair stair lift providing access to Industrial Arts and Automotives wing.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
5 - Good	0	25	NOV-05



**S4 MECHANICAL****D2010.01 Water Closets\*\* - 1953**

1953: Floor mounted, elongated and regular bowl, flush tank, flush valve, open and closed front seats.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	NOV-05

**Event:** Install new water closets.

**Concern:**

Several water closets cracked. Fixtures dated. Water wastage.

**Recommendation:**

Install new water closets (20).

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Operating Efficiency Upgrade	2007	\$21,400	Medium

*Updated: February 15 2006*

**D2010.01 Water Closets\*\* - 1957**

1957: Floor mounted, elongated, flush tank, open front seat.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	NOV-05

**Event:** Install new water closets.

**Concern:**

Several water closets cracked, fixtures rated. Water wastage.

**Recommendation:**

Install new water closets (6).

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Operating Efficiency Upgrade	2007	\$6,420	Medium

*Updated: February 15 2006*

**D2010.01 Water Closets\*\* - 1961**

1961: Floor mounted elongated, open front, flush tank style.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	NOV-05

**Event:** Install new water closet.**Concern:**

Fixture dated. Water wastage.

**Recommendation:**

Install new water closet (1).

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Operating Efficiency Upgrade	2007	\$1,070	Medium

*Updated: February 15 2006***D2010.02 Urinals\*\* - 1953**

1953: Stall and wall hung, flush tank.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	NOV-05

**Event:** Install new flush valve urinals.**Concern:**

Several urinals are cracked. Fixtures dated. Water wastage.

**Recommendation:**

Install new flush valve urinals (7).

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2007	\$14,980	Medium

*Updated: February 15 2006***D2010.02 Urinals\*\* - 1957**

1957: Stall, flush tank.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	NOV-05

**Event:** Install new urinals.**Concern:**

Urinals dated. Water wastage.

**Recommendation:**

Install new flush valve urinals (3).

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Operating Efficiency Upgrade	2007	\$12,840	Medium

*Updated: February 15 2006*

**D2010.03 Lavatories\*\* - 1953**

1953: Vitreous china wall hung, stainless steel countertop with time delay brass.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	NOV-05

**Event:** Install new stainless steel countertop lavatories, time delay faucets and millwork.

**Concern:**

Wall hung lavatories have been vandalized.

**Recommendation:**

Install new stainless steel countertop lavatories (16).

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Operating Efficiency Upgrade	2007	\$40,660	Medium

*Updated: February 15 2006*

**D2010.03 Lavatories\*\* - 1957**

1957: Vitreous china, wall hung, on/off brass.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	NOV-05

**Event:** Install new stainless steel countertop lavatories, time delay faucets and millwork.

**Concern:**

Wall hung lavatories have been vandalized.

**Recommendation:**

Install new stainless steel countertop lavatories, time delay faucets and millwork.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Operating Efficiency Upgrade	2007	\$21,400	Medium

*Updated: February 15 2006*

**D2010.03 Lavatories\*\* - 1961**

1961: Vitreous china, wall mounted, on/off brass.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	NOV-05

**D2010.04 Sinks\*\***

Stainless steel counter sinks with swing spout, stainless steel sink, silk screen pressure wash sink, stainless steel lab sinks.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	NOV-05

**D2010.05 Showers\*\* - 1953**

1953: Institutional head, adjustable head, new central mix valves, time delay push button valve and on/off temperature adjustable valve. Female locker room shower renovated in 2003.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	NOV-05

**D2010.05 Showers\*\* - 1961**

1961: Stall, hot cold on/off brass, adjustable head. Physical education office.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	NOV-05

**D2010.08 Drinking Fountains / Coolers\*\***

Wall hung, vitreous china and stainless steel, non refrigerated and refrigerated.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	NOV-05

**D2010.09 Other Plumbing Fixtures\*\***

Raised janitor sink. No vacuum breaker on brass.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	NOV-05

**Event: Replace janitor sink.**

**Concern:**

Difficult to discharge waste from wash buckets into raised sink.  
No vacuum breaker on brass.

**Recommendation:**

Install floor mounted janitor sink and brass with vacuum breaker.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Operating Efficiency Upgrade	2006	\$3,210	Medium

*Updated: February 15 2006*

**D2010.09 Other Plumbing Fixtures\*\***

Gas turrets in science room.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	NOV-05

**Event:** Install electric solenoid valve and shut off activation button.

**Concern:**

Unable to locate central shut off.

**Recommendation:**

Install electric solenoid valve and shut off activation button.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Code Upgrade	2007	\$9,630	Medium

Updated: February 15 2006

**D2010.09 Other Plumbing Fixtures\*\***

Handicap water closets, Bradley wash fountains, dishwashers, washing machines, emergency wash showers, eye wash centers in labs, kitchens and mechanical rooms.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	NOV-05

**D2010.09 Other Plumbing Fixtures\*\* - 1957**

1957: Floor mounted janitor mop sink brass with vacuum breaker.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	NOV-05

**D2020.01.01 Pipes and Tubes: Domestic Water\***

Copper piping and fittings.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	40	NOV-05

**D2020.01.03 Piping Specialties (Backflow Preventors)\*\***

Exterior hose bibbs complete with vacuum breakers. Supervised backflow preventer installed on fire line.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	30	NOV-05

**D2020.02.02 Plumbing Pumps: Domestic Water\*\***

In line circulation pump installed between storage tank and heat exchanger. Two (2) inline system circulation pumps.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	20	NOV-05

**D2020.02.06 Domestic Water Heaters\*\***

Boiler room - one (1) A.O. Smith hot water heater, input 67,590 BTU/hr., one (1) State sandblaster hot water heater input 126,000 BTU/hr.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	20	NOV-05

**D2020.02.06 Domestic Water Heaters\*\***

Hot water storage room: Two (2) Bradford White hydrojet hot water heater (2005), input 125,000 BTU/hr, summer use only.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	20	NOV-05

**D2020.03 Water Supply Insulation\*: Domestic**

Majority of domestic hot, cold, recirculation piping insulated.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	NOV-05

**Event: Insulate domestic water lines.**

**Concern:**

Domestic piping is not fully insulated as there are sections throughout building without insulation.

**Recommendation:**

Insulate all domestic water lines where required.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Energy Efficiency Upgrade	2007	\$10,700	Medium

*Updated: February 15 2006*

**D2030.01 Waste and Vent Piping\***

Cast iron sanitary piping, galvanized drain lines and copper vent piping. Varies in age up to 53 years.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
2 - Poor	0	50	NOV-05

**Event: Install new drain piping.**

**Concern:**

Galvanized drain lines deteriorated.

**Recommendation:**

Install new piping.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2006	\$32,100	High

*Updated: February 15 2006*

**D2030.02 Waste Piping Specialties\***

Bottle trap on science room sinks.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
2 - Poor	0	50	NOV-05

**Event:** **Install new bottle traps on science lab sinks.**

**Concern:**

Bottle traps in science labs are leaking.

**Recommendation:**

Install new bottle traps.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2006	\$8,560	High

*Updated: February 15 2006*

**D2030.03 Waste Piping Equipment\***

Sewage lift pump provided for academic fan room.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	NOV-05

**D2030.03 Waste Piping Equipment\***

Sump pump provided for fan room 008, boiler room and academic fan room.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	NOV-05

**D2030.03 Waste Piping Equipment\***

Art room sinks and wash down hood in kitchen. Pot sink grease interceptor installed in kitchen.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
2 - Poor	0	30	NOV-05

**Event:** **Install interceptors on wash down hood in kitchen and on art room sinks.**

**Concern:**

No interceptors installed for kitchen wash down hood and art room sinks.

**Recommendation:**

Install interceptors on drains for wash down hood and art room sinks.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Code Upgrade	2007	\$9,630	Medium

*Updated: February 15 2006*

**D2040.01 Rain Water Drainage Piping Systems\***

Rain water leaders from roof hoppers connected to underground storm drainage and drainage in crawl space.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	NOV-05

**D2040.02.04 Roof Drains\*\***

Cast iron domes, full flow.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	40	NOV-05

**D2090.01 Compressed Air Systems\*\***

Two (2) simplex air compressors provide compressed air for shop wing.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	NOV-05

**D3010.02 Gas Supply Systems\***

Gas distribution piping to steam boilers, domestic hot water heaters, science rooms.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	NOV-05

**D3020.01.01 Heating Boilers & Accessories: Steam\*\***

Boiler #1 fire box low pressure steam boiler, original CRN: 789.2, capacity 3149 kg/hr.  
 Boiler #2 fire box low pressure steam heating boiler, original CRN: 789.2, capacity 3149 kg/hr.  
 Boiler #3 firetube low pressure steam boiler, original, CRN: C5729.52, capacity 1434 kg/hr.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	35	NOV-05

**Event: Install new heating plant.**

**Concern:**

Water leakage, energy inefficient, high maintenance, standing pilot.

**Recommendation:**

Install new heating plant. Install energy efficient coppertube boilers, fan assisted, low NOX, primary and secondary pumps.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Operating Efficiency Upgrade	2008	\$428,000	Medium

*Updated: February 15 2006*

**D3020.01.03 Chimneys (&Comb. Air) : Steam Boilers\*\***

Masonry chimney. Insulated combustion air.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	35	NOV-05



**D3020.01.04 Water Treatment: Steam Boilers\***

Chemical feed pumps.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	35	NOV-05

**D3040.01 Air Distribution Systems**

Auditorium ventilation is noisy.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	NOV-05

**Event:** Install acoustics to reduce noise.

**Concern:**

Auditorium ventilation is noisy.

**Recommendation:**

Install acoustics to reduce noise.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Indoor Air Quality Upgrade	2007	\$74,900	Medium

*Updated: February 15 2006*

**D3040.01.01 Air Handling Units: Air Distribution\*\***

Direct fired rooftop make up air unit. Purpose unknown.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	NOV-05

**D3040.01.01 Air Handling Units: Air Distribution\*\***

Six (6) air systems of similar configuration. Built up air systems consist of motorized fresh, return, exhaust air dampers, filter bank, steam tempering coil, steam reheat coil, supply fan, low velocity ductwork distribution, ducted return air, return air fan. Two academic wing systems, 24,000 cfm each; gymnasium north and south air system 10,000 cfm each; auditorium air system 16,000 cfm; west gymnasium 12,000 cfm.

Four (4) air systems of similar configuration. Built up air systems consist of motorized fresh air damper, filter bank, steam preheat coil, steam tempering coil, steam reheat coil, supply fan, low velocity ductwork distribution. Locker room air system, 7000 cfm; rifle range air system 6000 cfm; shop air system, 12,000 cfm; cafeteria air system, 12,000 cfm.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	NOV-05

**Event: Replace existing air systems.**

**Concern:**

Freeze up of steam coils has occurred. Air bypass occurring on filters. Damper bushings worn, no seal on dampers, loose and damaged internal insulation.

**Recommendation:**

Replace existing air systems with new units. Propose fourteen new air systems. Air systems could be rooftop or indoor units. Propose installation of gas fired custom units with supply fan, return fan, motorized fresh, return, exhaust dampers, indirect fired heat exchanger, high turn down burner, medium efficiency filter bank, medium velocity ductwork to terminal boxes, CO2 sensor to vary amount of fresh air, variable frequency drives, connect to BMCS, cooling coil section for future cooling.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2008	\$2,996,000	Medium

*Updated: February 15 2006*

**D3040.01.03 Air Cleaning Devices:Air Distribution\***

Air system filter sections complete with 50 mm throw away filters.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	NOV-05

**D3040.01.04 Ducts: Air Distribution\***

Low velocity ceiling mounted supply ductwork to air outlets.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	NOV-05

**D3040.01.07 Air Outlets & Inlets:Air Distribution\***

Air outlets vary as to type. Square and round diffusers, adjustable grilles, egg crate and linear return.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	NOV-05

**Event: Replace damaged supply and return grilles and diffusers.**

**Concern:**

Round diffusers in gym are damaged, adjustable wall mounted grilles in several classrooms are damaged. Return grilles in several classrooms are blocked off.

**Recommendation:**

Install new supply and return diffusers and grilles

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2007	\$4,280	Medium

*Updated: February 15 2006*

**D3040.02 Steam Distribution Systems: Piping/Pumps\*\***

Steam condensate pumps located in fan room (009) and in hot water storage tank room. Both are piped to drain. COST INCLUDED IN D3040.02.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	NOV-05

**D3040.02 Steam Distribution Systems: Piping/Pumps\*\***

Black iron piping to convectors, unit heaters. Condensate to three (3) steam boilers pumped from condensate receiver by two (2) condensate pumps. Condensate from shops, east and north west wings piped back to accumulator and then piped to condensate receiver by vacuum pumps. Remaining condensate piped directly to drains and condensate receiver.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	NOV-05

**Event: Install hot water heating piping and heating elements.**

**Concern:**

Steam lines cannot be isolated at mains as isolation valves have failed. The building must be shut down in order to perform repairs. Condensate lines leaking. High maintenance.

**Recommendation:**

Install hot water heating piping and heating elements.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2008	\$1,926,000	Medium

*Updated: February 15 2006*

**D3040.04 Special Exhaust Systems**

Cyclone dust collector related ductwork and hoods.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	NOV-05

**Event:** **Install make up air unit.**

**Concern:**

Dust collector is 100% exhaust air unit. No make up air.

**Recommendation:**

Install make up air unit.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Operating Efficiency Upgrade	2007	\$53,500	Medium

*Updated: February 15 2006*

**D3040.04 Special Exhaust Systems**

Science room (112) has four (4) fume hoods, science room (114) has one (1) fume hood.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	NOV-05

**Event:** **Install make up air units for science rooms.**

**Concern:**

No make up air to offset exhaust air requirements.

**Recommendation:**

Install make up air units.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Code Upgrade	2008	\$64,200	Medium

*Updated: February 15 2006*

**D3040.04.01 Fans: Exhaust\*\***

Roof mounted dome and centrifugal exhaust fans.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	NOV-05

**Event:** **Replace exhaust fans.**

**Concern:**

Fan housing rusting.

**Recommendation:**

Replace failing exhaust fans (4).

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2007	\$17,120	Medium

*Updated: February 15 2006*

**D3040.04.03 Ducts: Exhaust\***

Low velocity ductwork to exhaust air outlets and fans.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
N/A	0	0	NOV-05

**D3040.04.05 Air Outlets and Inlets: Exhaust\***

Egg crate and linear bar exhaust air grilles.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	NOV-05

**D3050.01.01 Computer Room Air Conditioning Units\*\***

Four (4) computer labs.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	NOV-05

**Event: Install air conditioning in computer labs.**

**Concern:**

No air conditioning in four (4) computer rooms. Rooms over heat.

**Recommendation:**

Install four (4) ductless air conditioning units with remote condensing unit.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Operating Efficiency Upgrade	2007	\$171,200	Medium

*Updated: February 15 2006*

**D3050.01.01 Computer Room Air Conditioning Units\*\* - Server Room**

Server Room: Two (2) server rooms.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	NOV-05

**Event: Install air conditioning in server rooms.**

**Concern:**

No air conditioning in two (2) server rooms. Rooms over heat.

**Recommendation:**

Install two (2) ductless air conditioning units with remote condensing units.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Operating Efficiency Upgrade	2007	\$53,500	Medium

*Updated: February 15 2006*

**D3050.01.04 Unit Air Conditioners\*\***

Water cooled recirculation unit in book depository.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	NOV-05

**D3050.01.04 Unit Air Conditioners\*\***

Window air conditioning unit in Office 224.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	NOV-05

**D3050.03 Humidifiers\*\***

No humidification.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	25	NOV-05

**Event:** Install gas fired humidifiers.

**Concern:**

No humidification. Alberta Infrastructure Design Guidelines recommends humidification.

**Recommendation:**

Install low maintenance gas fired humidifiers (14) with multiple grids for proposed new air systems. Install water softener.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Indoor Air Quality Upgrade	2008	\$599,200	Medium

*Updated: February 15 2006*

**D3050.05.01 Convectors\*\***

Exposed and recessed convectors. COST INCLUDED IN D3040.02.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	NOV-05

**D3050.05.02 Fan Coil Units\*\***

Recessed fan coil units installed in main entrance. COST INCLUDED IN D3040.02.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	NOV-05

**D3050.05.03 Finned Tube Radiation\*\***

Limited amount of wall fin radiation installed. COST INCLUDED IN D3040.02.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	40	NOV-05

**D3050.05.06 Unit Heaters\*\***

Vertical unit heaters installed in woods shop, automotive shop. Horizontal unit heater installed in various basement, main floor rooms, corridors, mechanical rooms. COST INCLUDED IN D3040.02.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	NOV-05

**D3060.02.01 Electric and Electronic Controls\*\***

Electric thermostats cycle unit heaters, fan coil units to maintain set point. COST INCLUDED IN D3060.02.05.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	NOV-05

**D3060.02.02 Pneumatic Controls\*\***

Two (2) Simplex air compressors, no refrigerated air dryer, pneumatic thermostats, dampers, control valve. COST INCLUDED IN D3060.02.05.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	40	NOV-05

**D3060.02.05 Building Systems Controls(BMCS, EMCS)\*\***

No BMCS.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	NOV-05

**Event: Install BMCS.**

**Concern:**

Current energy management technology not being utilized. Automatic control panels installed in 1989 are basically time clock control and do not provide temperature control of units. Majority of pneumatic controls are original and failure is imminent.

**Recommendation:**

Install BMCS to control equipment activation and provide global control in maintaining building environment. Replace existing pneumatic controls with digital controls throughout. Provide digital controls for proposed upgrades.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Energy Efficiency Upgrade	2008	\$749,000	Medium

*Updated: February 15 2006*

**D4010 Sprinklers: Fire Protection\***

Wet sprinklers located in Industrial Arts room (157) and Special Needs room (155). Test valve located in Special Needs room.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	NOV-05

**D4020 Standpipes\***

Wet standpipe fire hose cabinets complete with 65 mm angle valve, 40 mm hose valve, fire extinguisher.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	50	NOV-05

**D4030.01 Fire Extinguisher, Cabinets and Accessories\*\***

ABC fire extinguishers, pressurized water extinguishers, pump style extinguishers, installed in cabinets and on wall brackets.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	NOV-05

**Event:** Provide proper signage for all fire extinguishers and cabinets.

**Concern:**

Numerous fire extinguishers and cabinet locations not identified.

**Recommendation:**

Provide signage for fire extinguishers and cabinets to make location easily recognizable.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Code Upgrade	2007	\$2,140	Medium

*Updated: February 15 2006*

**D4030.01 Fire Extinguisher, Cabinets and Accessories\*\* - 1957**

1957: Fire hose cabinets located in stairwell.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	NOV-05

**Event:** Relocate fire hose cabinet.

**Concern:**

Fire hose cabinet located in stairwell. If hose was used for fire in corridor, it would prevent stairwell door from closing.

**Recommendation:**

Relocate fire hose cabinet into corridor.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Code Upgrade	2007	\$12,840	Medium

*Updated: February 15 2006*



**D4090 Other Fire Protection Systems\***

Fire blankets installed in labs, flammable wooden and metal storage cabinets installed in science rooms.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	NOV-05

**Event:** **Install metal flammable storage cabinets in place of wooden.**

**Concern:**

Flammable chemicals are stored in wooden cabinet.

**Recommendation:**

Install approved metal storage cabinet.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Operating Efficiency Upgrade	2006	\$12,840	Medium

*Updated: February 15 2006*

**Event:** **Provide new flammable resistant storage cabinets to accommodate chemicals currently stored in cupboards.**

**Concern:**

A large amount of chemicals were stored in regular cabinets.

**Recommendation:**

Install new flammable materials storage cabinets.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Indoor Air Quality Upgrade	2007	\$14,980	Medium

*Updated: February 15 2006*

**S5 ELECTRICAL****D5010.02 Secondary Electrical Transformers (Interior)\*\***

Three (3) interior Supreme Power Supplies transformers - 2.4kW, 120-240V - 3 Phase - 4 Wire rated 125kVA, located in basement high voltage room. 1952 Cemco main breaker, rated 5kW / 400A. The primary feeder is underground from an EPCOR source, west of the school in the ally across the field.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	40	NOV-05

**Event:** **Replace interior transformers with exterior pad mounted transformer.**

**Concern:**

Old original equipment, difficult to access and service.

**Recommendation:**

Install pad mounted transformer.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2007	\$42,800	Medium

*Updated: February 15 2006*

**D5010.03 Main Electrical Switchboards (Main Distribution)\*\***

1952 Westinghouse main distribution panel rated 600 Amps, 120/208 Volts - 3 Phase - 4 Wire, original MDP is full, no further spaces. A Cutler-Hammer 400 Amp MDP spliced into existing Westinghouse MDP. Maximum demand = 262 kVA (64 Amps - primary). No surge protection.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	40	NOV-05

**Event:** **Provide a new Main Distribution Panel c/w surge protection.**

**Concern:**

Original equipment is obsolete, no surge protection.

**Recommendation:**

Replace MDP with new. Provide TVSS device.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2007	\$53,500	Low

*Updated: February 15 2006*

**D5010.05 Electrical Branch Circuit Panelboards (Secondary Distribution)\*\***

120/208 Volts - 3 Phase - 4 Wire panelboards located in mechanical, storage rooms, electrical rooms throughout the school. Some panels are full.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	25	NOV-05

**Event:** **Provide additional electrical panels.**

**Concern:**

Panel are full, cannot add additional circuits.

**Recommendation:**

Provide 20 new branch circuit panels.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Program Functional Upgrade	2007	\$53,500	Low

*Updated: February 15 2006*

**D5010.07.02 Motor Starters and Accessories\*\***

Loose motor starters and manual switches in mechanical rooms. Original equipment becoming obsolete.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	NOV-05

**Event:** **Replace obsolete motor starters with new equipment.2007**

**Concern:**

Obsolete motor starters.

**Recommendation:**

Replace 15 motor starters with new equipment.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2007	\$16,050	Medium

*Updated: February 15 2006*

**D5020.01 Electrical Branch Wiring\***

Wiring installed in conduit. Lack of receptacles in classrooms throughout the school.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	50	NOV-05

**Event:** Increase the number or circuits and quantities of receptacles in classrooms and other areas affected.

**Concern:**

Insufficient quantity of duplex receptacles.

**Recommendation:**

Add circuits and receptacles in classrooms. Allow for 200 new receptacles.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Program Functional Upgrade	2007	\$53,500	Low

*Updated: February 15 2006*

**D5020.02.01 Lighting Accessories (Lighting Controls)\***

Local 120V line voltage switching throughout the school.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	30	NOV-05

**D5020.02.02 Interior Florescent Fixtures\*\***

Lighting consists of surface or suspended 1X4 wraparound type light fixtures. Second floor and main floor corridors, gymnasium and 2nd floor classrooms have T8 lamps and electronic ballasts. Remaining to be replaced.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	30	NOV-05

**Event:** Replace remaining lighting fixtures with T8 lamps and T8 electronic ballasts.

**Concern:**

Light fixtures are not energy efficient.

**Recommendation:**

Replace light fixtures with T8 lamps/ballasts. 1654 light fixtures to be replaced.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Energy Efficiency Upgrade	2007	\$224,700	Low

*Updated: February 15 2006*

**D5020.02.02.05 Other Interior Fixtures\***

EXIT lights are located throughout the school. Incandescent type EXIT lights, not tied into battery packs.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	NOV-05

**Event:** Provide LED type EXIT lights.

**Concern:**

Existing EXIT lights not energy efficient.

**Recommendation:**

Replace 30 existing lights with LED type and connect into battery packs.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Energy Efficiency Upgrade	2007	\$10,700	Medium

*Updated: February 15 2006*

**D5020.02.03 Emergency Lighting\***

Emergency lighting consists of battery packs c/w integral and remote heads. Insufficient quantity of emergency lighting.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	NOV-05

**Event:** Provide additional emergency battery packs.

**Concern:**

Insufficient emergency lighting.

**Recommendation:**

Provide 30 additional battery packs.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Code Upgrade	2007	\$32,100	Medium

*Updated: February 15 2006*

**D5020.03.01.04 Exterior H.P. Sodium Fixtures\***

High pressure sodium flood lights mounted on roof for exterior lighting.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	25	NOV-05

**D5020.03.02 Lighting Accessories (Lighting Controls)\***

Photo-electric control for exterior lighting.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	25	NOV-05

**D5030.01 Detection and Fire Alarm\*\***

There is an Edwards IRC-3 fire alarm control panel located in the general office, annunciator panel located at the main entrance. System installed in 1996. Manual and automatic addressable devices throughout the school.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	25	NOV-05

**D5030.02.02 Intrusion Detection\*\***

Intrusion alarm system is a MAX System control panel located in the general office electrical room. P.I.R.'s located throughout the school.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	25	NOV-05

**D5030.02.04 Video Surveillance\*\***

The video surveillance system consists of a National Electronics head-end cabinet in the general office electrical room. There are 16 colour cameras throughout the interior and exterior of the school. Viewing of the cameras are off the data network system, which is accessed by only authorized personnel with password access.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	25	NOV-05

**D5030.03 Clock and Program Systems\*\***

Simplex master program clock controls class change signals. Located in general office storage room. Battery clocks are located throughout the school.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	25	NOV-05

**D5030.04.01 Telephone Systems\*\***

Meridian telephone system head-end located in general office electrical room. Telephone sets in classrooms, staff areas, offices, general office, student services.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	25	NOV-05

**D5030.04.04 Data Systems\*\***

Main server and data closet located in 2nd floor library A.V. room. A sub data panel located in general office electrical room.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	25	NOV-05

**D5030.05 Public Address and Music Systems\*\***

Rauland Public Address system located in general office storage room. System is being used for all-call via TOA microphone. Surface speakers in classrooms and corridors.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	20	NOV-05

**S6 EQUIPMENT, FURNISHINGS AND SPECIAL CONSTRUCTION****E1020.02 Library Equipment\***

Security scanner at the library entrance.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	25	NOV-05

**E1020.03 Theater and Stage Equipment\***

The auditorium stage is equipped with stage drapery, spotlights and sound system. The stage is painted masonite finish on a wood stage platform.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	25	NOV-05

**E1020.07 Laboratory Equipment\***

The science rooms have a total of 5 fume hoods.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	25	NOV-05

**E1030.01 Vehicle Service Equipment\***

Automotives area has 2 hoists and a variety of small tools.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	25	NOV-05

**E1090.03 Food Service Equipment\***

Cafeteria kitchen is equipped with 2 deep fryers, convection oven, commercial gas range and griddle, 2 chest freezers, 1 upright freezer, 1 double width upright freezer, 1 walk-in cooler, hot food storage trays, slush machine and a reach-in cooler.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	25	NOV-05

**E1090.04 Residential Equipment\***

Staff areas have domestic kitchens with sink, fridge and microwave. Home Economics area has 11 electric ranges, dishwasher, laundry washer and dryer, electric range top, convection oven, 9 microwaves, 4 upright fridge/freezers and 3 upright freezers.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	25	NOV-05

**E1090.07 Athletic, Recreational, and Therapeutic Equipment\***

Each gymnasium is equipped with four sidcourt plywood basketball backstops and two glass basketball backstops, upswing in the main gym and sideswing in the smaller gym.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	15	NOV-05

**E2010.02.05 Educational Facility Casework\***

Classrooms typically have perimeter shelving units which house heating cabinets.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	35	NOV-05

**Event:** Replace perimeter shelving with new shelving.

**Concern:**

Perimeter shelving is in marginal condition, with overstressed shelves. Mechanical upgrading will necessitate the removal of this millwork.

**Recommendation:**

Replace perimeter millwork in conjunction with mechanical systems replacements.( 190 L M)

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2007	\$203,300	Low

*Updated: February 15 2006*

**E2010.02.07 Kitchen Casework\***

Cafeteria kitchen has base units with stainless steel tops, and upper storage cupboards.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	35	NOV-05

**E2010.02.08 Laboratory Casework\***

Science rooms have perimeter and island millwork units.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	35	NOV-05

**E2010.02.09 Library Casework\***

Millwork shelving units and main librarian charge desk.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	35	NOV-05



**E2010.03.01 Blinds\*\***

Roller blinds in classrooms, vertical blinds in staff areas and general office.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	35	NOV-05

**Event:** Replace roller blinds with perforated roller blinds throughout classroom areas.  
(380 blinds)

**Concern:**

Roller blinds are obsolete and mechanisms are worn.

**Recommendation:**

Replace existing roller blinds with new perforated roller blinds.  
(380 Blinds)

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2007	\$60,990	Low

*Updated: February 15 2006*

**E2010.03.06 Curtains and Drapes\*\***

Window drapery in classrooms. Stage drapery in auditorium.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	35	NOV-05

**Event:** Remove and dispose of drapery from classrooms.

**Concern:**

Window drapery is obsolete.

**Recommendation:**

Remove and dispose of drapery from classrooms.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2007	\$4,280	Low

*Updated: February 15 2006*

**E2010.05 Fixed Multiple Seating\*\***

Formed plywood seating on cast iron frames in auditorium. 1953 vintage.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	35	NOV-05

**E2020 Moveable Furnishings\***

Classroom and office furniture and equipment throughout.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	NOV-05

**F1010.02.05 Grandstands and Bleachers\*\***

Pull-out bleachers in main gymnasium for spectator seating. Cast-in-place concrete mezzanine with fixed platforms for spectator seating.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	50	NOV-05

**F1040.01 Aquatic Facilities\***

Adjacent swimming pool (City owned) is accessed through an underground passageway.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	40	NOV-05

**F2020.01 Asbestos\***

Asbestos materials throughout ceilings and mechanical systems. See Asbestos Building Materials Survey Report dated March 21, 2000.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	0	NOV-05

**F2020.02 PCBs\***

T12 lights with magnetic ballasts have PCB content. No sign of leakage.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	0	NOV-05

**F2020.03 Mercury\***

None identified

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	0	NOV-05

**F2020.04 Mould\***

None evident

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	0	NOV-05

**S8 FUNCTIONAL ASSESSMENT****K3010 Building Services**

Appear satisfactory.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	0	NOV-05

**K3020 Indoor Environment**

Poor indoor air quality due to obsolete mechanical system. See mechanical system replacement events.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
3 - Marginal	0	0	NOV-05

**K40 Current Code Issues**

Significant number of dead-end corridors in the basement area and lack of fire rated doors to stairs , storage rooms and mechanical rooms. Doors are identified in interior events.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
3 - Marginal	0	0	NOV-05

**K4010.01 Barrier Free Route: Parking to Entrance**

There are barrier free access routes to the car park area.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
5 - Good	0	0	NOV-05

**K4010.02 Barrier Free Entrances**

Barrier free entrances are provided.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
5 - Good	0	0	NOV-05

**K4010.03 Barrier Free Interior Circulation**

Barrier free interior circulation is provided.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
5 - Good	0	0	NOV-05

**K4010.04 Barrier Free Washrooms**

Barrier free washrooms are provided.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
5 - Good	0	0	NOV-05

# **RECAPP Facility Evaluation Report**

**Eastglen Composite High School**

S3096  
Edmonton

<b>Facility Details</b>	
<b>Building Name:</b>	Eastglen Composite High S
<b>Address:</b>	
<b>Location:</b>	Edmonton
<b>Building Id:</b>	S3096
<b>Gross Area (sq. m):</b>	0.00
<b>Replacement Cost:</b>	\$0
<b>Construction Year:</b>	0

<b>Evaluation Details</b>	
<b>Evaluation Company:</b>	
<b>Evaluation Date:</b>	November 4 2005
<b>Evaluator Name:</b>	

**Total Maintenance Events Next 5 years:                   \$375,570**  
**5 year Facility Condition Index (FCI):                         0%**

**General Summary:**

Shared site with Bellevue Elementary School. Relatively flat, grassed sports fields with cinder running track. Asphalt paved access roads and parking lots. Concrete sidewalks. Ornamental lawn area and mature trees at front of school. Chain link fence to the perimeter of the site, except for frontage to 68 Street.

**Structural Summary:**

**Envelope Summary:**

**Interior Summary:**

**Mechanical Summary:**

**Electrical Summary:**

<b>Rating Guide</b>	
<b>Condition Rating</b>	<b>Performance</b>
1 - Critical	Unsafe, high risk of injury or critical system failure.
2 - Poor	Does not meet requirements, has significant deficiencies. May have high operating/maintenance costs.
3 - Marginal	Meets minimum requirements, has significant deficiencies. May have above average operating maintenance costs.
4 - Acceptable	Meets present requirements, minor deficiencies. Average operating/maintenance costs.
5 - Good	Meets all present requirements. No deficiencies.
6 - Excellent	As new/state of the art, meets present and foreseeable requirements.

**S7 SITE****G2010.02.02 Flexible Pavement Roadway (Asphalt)\*\***

Asphalt access roads and and combined parking lots.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	NOV-05

**Event: Replace asphalt paving and sub-base.****Concern:**

Asphalt is cracked and heaving. Sub-base is likely deteriorated due to water penetration.

**Recommendation:**

Remove existing asphalt topping, repair or replace sub-base and provide new asphalt paving. 2600 sq.m.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2007	\$306,020	Medium

*Updated: February 22 2006*

**G2020.06.02 Parking Bumpers\***

Parking rail between parking rows. Tubular steel parking rail and posts.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	NOV-05

**G2020.06.03 Parking Lot Signs\***

Painted signs on parking rails.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	NOV-05

**G2020.06.04 Pavement Markings\***

Painted parking lines.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	NOV-05

**G2030.04 Rigid Pedestrian Pavement (Concrete)\*\***

Concrete sidewalks.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	NOV-05

**Event:** Replace cracked concrete sidewalks.**Concern:**

Concrete sidewalks are cracked and uneven.

**Recommendation:**

Replace 50% of concrete sidewalks. 450 sq.m.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2007	\$69,550	Medium

*Updated: February 22 2006***G2030.06 Exterior Steps and Ramps\***

Concrete stoops and ramps.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	NOV-05

**G2040.02 Fences and Gates\*\***

Chain closes off access road to rear of school.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	NOV-05

**G2040.03 Athletic and Recreational Surfaces\*\***

Grassed sports fields. Cinder running track.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	NOV-05

**G2040.05 Site and Street Furnishings\***

Concrete freestanding waste receptacles. Metal freestanding bicycle racks.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	NOV-05

**G2040.06 Exterior Signs\***

Freestanding building sign, wood structure with ability to post school events.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	NOV-05

**G2040.08 Flagpoles\***

Wall mounted aluminum flagpole.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	NOV-05

**G2050.04 Lawns and Grasses\***

Grassed sports fields and ornamental lawn.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	NOV-05

**G2050.05 Trees, Plants and Ground Covers\***

Mature deciduous and evergreen trees at front of school.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	NOV-05

**G3010.02 Site Domestic Water Distribution\***

150mm domestic line connected to city main.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	NOV-05

**G3010.03 Site Fire Protection Water Distribution\***

No fire hydrant within 45 m of main entrance.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
2 - Poor	0	0	NOV-05

**Event:** **Install fire hydrant within 45m of main entrance.**

**Concern:**

Code requires fire hydrant to be within 45m of main entrance.

**Recommendation:**

Install new fire hydrant close to main entrance, connected to 150mm domestic water line.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Code Upgrade	2006	\$21,400	High

*Updated: February 22 2006*

**G3020.01 Sanitary Sewage Collection\***

Combined sanitary /storm system.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	NOV-05

**G3030.01 Storm Water Collection\***

Catch basins in parking lot and landscaped areas. 200mm storm sewer from school to combined sanitary / storm system.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	0	NOV-05

**G3060.01 Gas Distribution\***

Natural gas line to interior meter.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	0	0	NOV-05



**G4010.04 Car Plugs-ins\***

There are a total of 31 duplex weatherproof receptacles. In the south parking lot there are 10 duplex receptacles in an angled boxes mounted to steel tubular rails. In the west parking lot there are 21 receptacles, 8 are wall mounted and 13 are mounted in angled boxes on steel tubular rails. Each receptacle serves two stalls. The receptacles are time-clock controlled.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	0	NOV-05

**G4020.01 Area Lighting\***

Area lighting consists of roof mounted high pressure sodium flood lights. There are HPS pole mounted luminaires.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	0	0	NOV-05