

School Name: W.R. Myers (Does Not Include D.A. Ferguson)  
 Location: Taber  
 Region: South  
 Jurisdiction: Horizon  
Div #67  
 Grades: 11&12

School Code: 6606  
 Facility Code: 162  
 Superintendent: Mr. Eric Johnson  
 Contact Person: Andy Tuveson  
 Telephone: 403-223-3547  
 School Capacity: 890

Building Section	Year of Compl.	No. of Floors	Gross Bldg Area (Sq.M.)	Type of Construction (i.e., structure, roof, cladding)	Description of Mechanical Systems (incl. major upgrades)	Comments/Notes
Original Building	1949	3	2798	Concrete foundation walls and footings. Concrete and brick walls. Wood frame floors & roof.	Two steel tube boilers @ 92kw output Two make up air units	Note: This evaluation covers W. R. Meyers only and does not include D.A.Ferguson.
	1960	1	1801	Concrete piles and grade beams. Precast concrete columns and beams. Wood deck, brick veneer.	Shelve A duct units	
	1965	1	1206	Concrete piles and grade beams, Precast concrete columns, steel joists and roof deck, brick veneer.	Shelv A duct units.	
	1967	2	2146	Concrete piles and grade beams. Precast concrete columns and floor beams, concrete floor, wood roof deck, brick veneer.	Shelv A duct units	
	1996	1	981	Concrete foundation, steel columns, beams, joists and roof deck, brick veneer walls		

Evaluator's Name: Ed Lehbauer  
 & Company: Hirano & Heaton Architects Lt

<b>Upgrading/ Modernization (identify whether minor or major)</b>	1997	3		Finishes upgrade to 1949 building and 1960 corridors.	
<b>Portable Struct. (identify whether attached/perman. or free-standing/ relocatable)</b>	N/A				
<b>List of Reports/ Supplementary Information</b>	N/A				

	Evaluation Components	Summary Assessment	Estim. Cost
1	Site Conditions	Poor drainage in athletic fields. Fence posts and rails in poor condition. Open drainage ditch should be covered. Costs are included in D.A. Ferguson evaluation	\$15,000.00
2	Building Exterior	Some minor cracking in fascia, repointing of bricks in 1949 level required. walls require additional insulation. All exterior doors and hardware should be replaced. Windows and frames to be replaced in 1965/67 sections.	\$105,000.00
3	Building Interior	Interior walls and partitions and floors are in reasonable condition. Materials and finishes for floors, walls and ceilings should be replaced in all areas. Interior doors are dated and worn out, will have to be replaced with rated doors and frames including hardware. All new millwork is required in sections 1965 and 1967. Washrooms to be upgraded with new ceramic tile floors and walls, stalls have to be replaced. 1967 section requires vertical lift.	\$765,000.00
4	Mechanical Systems	Being recently modernized, the mechanical system is in good condition, it should be expanded to handle the 5 remaining classrooms in the 1955 wing.	\$169,000.00
5	Electrical Systems	Main service is in good condition with space capacity. Additional exterior lighting is required. Vehicle plug-ins are required. Life safety in 1965. Addition requires upgrading. Classrooms require additional power and a lighting upgrade.	\$315,000.00
6	Portable Buildings	N/A	
7	Space Adequacy:		
	7.1 Classrooms	The classroom numbers are lower than required and size is under standard.	
	7.2 Science Rooms/Labs	The number of science classrooms is within standard size of the classrooms is under standard.	
	7.3 Ancillary Areas	2 rooms are presently supplied in the building. 4 additional is standard but because of oversupply in other areas the standards can be met.	
	7.4 Gymnasium	Gymnasium area sizes slightly under standard.	
	7.5 Library/Resource Areas	Library area is slightly under sized.	
	7.6 Administration/Staff Areas	Administration is 30% under sized.	
	7.7 CTS Areas	Spaces provided exceed requirements but in light of sharing spaces for shortcomings in classrooms etc. the usage works out.	
	7.8 Other Non-Instructional Areas (incl. gross-up)	Although at first glance area is excessive vs standard one has to keep in mind a large lunch room and associated facilities are provided thus skewing the area calculations for this area.	
	Overall School Conditions & Estim. Costs		\$1,369,000.00

Section 1	Site Conditions	Rating	Comments/Concerns	Estim. Cost
1.1	<b>General Site Conditions</b>			
1.1.1	Overall site size.	3	Inadequate due to an intensive school population as 2 schools share this city block. Site area = 6 acres	
1.1.2	Outdoor athletic areas.	3	Poor drainage, requires levelling, undersized for number of students. Costs included in D.A. Ferguson.	
1.1.3	Outdoor playground areas, including condition of equipment and base.	4	Baseball backstop, goal posts - under re-development	
1.1.4	Site landscaping.	4	West and south - Mixed trees O.K. East side - re-developed 1997/98 O.K.	
1.1.5	Site accessories (i.e., perimeter and other fencing, guard rails, bike stands, flag poles).	4	1 flagpole - Shared North side bike racks - capacity 40 bikes	
1.1.6	Surface drainage conditions (i.e., drains away from building, signs of ponding).	3	East side - Chain link fence in good condition South and west side 6 x 6 posts and rails - Poor condition; replace. Cost in D.A. Ferguson	\$10,000.00
1.1.7	Evidence of sub-soil problems.	4	1988 Weeping tile installed. 1949 and 1965 wing (Myers)	
1.1.8	Safety and security concerns due to site conditions.	3	Open drainage ditch - Town property - north side. Install culverts. Costs included in D. A. Ferguson	\$5,000.00
	Other			
1.2	<b>Access/Drop-Off Areas/Roadways/Bus Lanes</b>			
1.2.1	Vehicular and pedestrian access points (i.e., size, number, visibility, safety).	4	Access for buses only in turning loop in the main street.	
1.2.2	Surfacing of on-site road network (note whether asphalt or gravel).	N/A	None	
1.2.3	Bus lanes/drop-off areas (note whether on-site or off-site).	4	On site buses only. (Myers has some gravel staff parking on east side).	
1.2.4	Fire vehicle access.	4	North and west sides - Town roads adequate for access.	
1.2.5	Signage.	4	Large sign on main entrance.	
	Other			

Section 1	Site Conditions	Rating	Comments/Concerns	Estim. Cost
1.3	<b>Parking Lots and Sidewalks</b>			
1.3.1	Number of parking spaces for staff, students and visitors (including stalls for disabled persons).	4	No staff or student parking. All parking on streets - Town	
1.3.2	Layout and safety of parking lots.		N/A	
1.3.3	Surfacing and drainage of parking lots (note whether asphalt or gravel).	4	Roof drainage system runs to a swale connected to the Town storm drains. Gym roof runs to a dry well. Swale causes some grass deterioration. Proposal is in for drainage north to 56 Avenue storm system.	
1.3.4	Layout and safety of sidewalks.	4	OK - Curb cuts - Wheelchair access.	
1.3.5	Surfacing and drainage of sidewalks (note type of material).	4	Concrete - OK	
1.3.6	Curb cuts and ramps for barrier free access.	4	In place on East Side - Wheelchair accessible H/C parking stall on East Side.	
	Other			
	<b>Overall Site Conditions &amp; Estimated Costs</b>			\$15,000.00

Section 2	Building Exterior	Rating	Comments/Concerns		Estim. Cost
2.1	Overall Structure		<u>Bldg. Section</u>	<u>Description/Condition</u>	
2.1.1	Floor structure and beams (i.e., signs of bending, cracking, heaving, settlement, voids, rust, stains).	4	1949	Floor deflection due to wood floor joists.	\$18,000.00
2.1.2	Wall structure and columns (i.e., signs of bending, cracking, settlement, voids, rust, stains).	3	1960	1960 Section - D.A. Ferguson - Perimeter concrete cracking - Monitor (Costs in D.A. Ferguson report)	\$5,000.00
		3	1949	Re-pointing of on bricks at upper back required	\$5,000.00
2.1.3	Roof structure (i.e., signs of bending, cracking, voids, rust, stains).	4	all	No concerns indicated	
Other					

Section 2	Building Exterior	Rating	Comments/Concerns		Estim. Cost
2.2	<b>Roofing and Skylights</b> <i>Identify the availability of an up-to-date inspection report or roofing program. Note if roof sections are of different ages and/or in varying states of repair.</i>		<b>Bldg. Section or Roof Section</b>	<b>Description/Condition/Age</b>	
2.2.1	Based on the inspection report (and to the extent possible, direct observation), assess and rate roof conditions and estimate costs for required improvements (i.e., covering materials, membrane, insulation, other components).	4	1967	Roof membrane replaced 1989 2 ply SBS	
		5	1949	Replaced 1998 2 ply SBS	
		5	1996	2 ply torch on SBS - 1" fibreboard O.K.	
2.2.2		Roof accessories (i.e., ladders, stairs, hatches, masts, exhaust hoods, chimneys, gutters, downspouts, splashpads).	4	1949	Hatch access - 3rd floor adjacent to 303/304. "
	9		all	All other exterior ladders. - all exhausts are curbed. Downspouts external and internal. Internal drains from Gym areas under review for draining to north side storms.	
2.2.3	Control of ice and snow falling from roof.	4	1996	West side under review for installation of snow guards	
2.2.4	Skylights (i.e., signs of distress, leaks, ice build-up, condensation, deteriorated materials/seals).	4	All	All skylights removed. (200) with exception of 2 in 1996 Section performing well.	
Other					

Part II - Physical Condition

Section 2	Building Exterior	Rating	Comments/Concerns		Estim. Cost
2.3	<b>Exterior Walls/Building Envelope</b>		<b>Bldg. Section</b>	<b>Description/Condition</b>	
2.3.1	Exterior wall finishes (i.e., signs of deterioration, cracks, brick spalling, effluorescence, water stains).	4	1949	East face - water damage exterior. R38 Installed in walls. . R21 other areas	
		3	1965	Additional insulation.	\$5,000.00
		3	1967	Requires additional insulation	\$5,000.00
2.3.2	Fascias, soffits, parapets (i.e., signs of looseness, stains, rust, peeling paint).	4	1967	Plywood soffit No concerns	
2.3.3	Building envelope (i.e., evidence of air infiltration/exfiltration through the exterior wall or ice build up on wall, eaves, canopy).	N/A		None	
2.3.4	Interface of roof drainage and ground drainage systems.	4		See previous section Section 2.2.2	
2.3.5	Inside faces of exterior walls (i.e., signs of cracks, water stains, dust spots).	4		No concerns noted	
Other					
2.4	<b>Exterior Doors and Windows</b>		<b>Bldg. Section</b>	<b>Description/Condition</b>	
2.4.1	Doors (i.e., signs of deterioration, rusting metal, glass cracks, peeling paint, damaged seals, sealed unit failure).	3	1965	Require new exterior doors on all sides.	\$5,000.00
		3	1967	Require new exterior doorson all sides	\$5,000.00
2.4.2	Door accessories (i.e., latches, hardware, screens, locks, alarms, holders, closers, security devices).	3	All	All new hardware for above	\$16,000.00
2.4.3	Exit door hardware (i.e., safety and/or code concerns).	3	All	New panic hardware required.	\$6,000.00
2.4.4	Windows (i.e., signs of deterioration, rusting metal, glass cracks, peeling paint, damaged seals, sealed unit failure).	3	1965	1965 - Needs new windows - Aluminum framed	\$17,500.00
		3	1967	Needs new windows - aluminum framed	\$17,500.00
2.4.5	Window accessories (i.e., latches, hardware, screens, locks, alarms, holders, closers, security devices).	N/A		None	

Section 2	Building Exterior	Rating	Comments/Concerns		Estim. Cost
2.4.6	Building envelope (i.e., signs of heavy condensation on doors or windows).	N/A		None	
	Other				
<b>Overall Bldg Exterior Condition &amp; Estim Costs</b>					\$105,000.00

Section 3	Building Interior - Overall Conditions	Rating	Comments/Concerns		Estim. Cost
3.1	<b>Interior Structure</b>		<b>Bldg. Section</b>	<b>Description/Condition</b>	
3.1.1	Interior walls and partitions (i.e., signs of cracks, spalling, paint peeling).	4	All	No concerns noted.	
3.1.2	Floors (i.e., signs of cracks, heaving, settlement).	4	All	No concerns noted.	
Other					
3.2	<b>Materials and Finishes</b>		<b>Bldg. Section</b>	<b>Description/Condition</b>	
3.2.1	Floor materials and finishes.	3	1949	Upper 2 floors need new floor coverings	\$74,000.00
		3	1965	Needs new floor coverings	\$48,000.00
		3	1967	Needs new floor coverings	\$110,000.00
		3	1965/67	Classrooms need painting including doors and frames	\$24,000.00
		3	1967	Classrooms need painting including doors and frames	\$24,000.00
3.2.3	Ceiling materials and finishes.	4	All	No concerns noted.	
3.2	<b>Materials and Finishes (cont'd)</b>		<b>Bldg. Section</b>	<b>Description/Condition</b>	
3.2.4	Interior doors and hardware.	3	1965/67	All new rated doors and hardware to be replaced.	\$18,000.00
		3	1967	All new rated doors and hardware to be replaced.	\$18,000.00
3.2.5	Millwork	3	1965/67	All new millwork required. Existing dated and in poor condition	\$118,500.00
		3	1967	All new millwork required. Existing dated and in poor condition	\$118,500.00
3.2.6	Fixed/wall mounted equipment (i.e., writing boards, tackboards, display boards, signs).	3	1965	50% white boards and tackboards required.	\$11,000.00
		3	1967	50% white boards and tackboards required.	\$11,000.00
3.2.7	Any other fixed/mounted specialty items (i.e., CTS equipment, gymnasium equipment).	3		GYM, needs new bleachers	\$55,000.00
3.2.8	Washroom materials and finishes.	3	1949	Washrooms in poor condition. Upgrade - ceramic tils and new stalls	\$40,000.00
		3	1965	Washrooms in poor condition. Upgrade - ceramic tils and new stalls	\$40,000.00
Other					

Section 3	Building Interior - Overall Conditions	Rating	Comments/Concerns		Estim. Cost
3.3	<p><b>Health and Safety Concerns --- Intent is to identify renovations considered necessary to meet applicable codes, primarily due to safety concerns. Basis of evaluation should be an up-to-date inspection report from the authority having jurisdiction together with direct observations as appropriate. Evaluator should note if in his opinion a comprehensive code evaluation is required.</b></p>		<u>Bldg. Section</u>	<u>Description/Condition</u>	
3.3.1		4	All	Combustible, non sprinklered	
3.3.2		3	All	Fire rated doors required. See 3.2.4	
3.3.3		3	1965/67	Requires labelled doors, closures etc. See 3.2.4	
3.3.4		4	All	Acceptable	
3.3.5		3	1967	Upper floor - requires vertical lift	\$55,000.00
3.3.6		4	All	All asbestos removed, audit performed 1990/91	
3.3.7		3	All	Lack of conditioned air See 4.4.1	
Other					
<b>Overall Bldg Interior Condition &amp; Estim Costs</b>					\$765,000.00

Section 4	Mechanical Systems	Rating	Comments/Concerns		Estim. Cost
4.1	<b>Mechanical Site Services</b>				
4.1.1	Site drainage systems (i.e., surface and underground systems, catch basins).	2	All	Surface run-off, now town storm system. Spring thaw results in an icing condition on bus loop	\$100,000.00
4.1.2	Exterior plumbing systems (i.e., irrigation systems, hose bibs).	4	All	Irrigation on entire site fed from Town water system, meters located in school	
4.1.3	Outside storage tanks.	N/A			
Other					
4.2	<b>Fire Suppression Systems</b>		Bldg. Section	<u>Description/Condition</u>	
4.2.1	Fire hydrants and siamese connections.	4	All	1 Fire hydrant at south face of building within 90 meters. Building is not sprinklered and therefore no siamese connection exists.	
4.2.2	Fire suppression systems (i.e., pumps, sprinklers, piping, reservoirs, hoses, stand pipes, CO2 systems).	N/A			
4.2.3	Hand extinguishers, blankets and showers (i.e., in CTS areas).	5	All	Fire extinguishers located in cabinets throughout	
4.2.4	Other special situations (e.g., flammable storage areas, science labs, CTS areas).	4	All	Storage cabinets in science program	
Other					

Section 4	Mechanical Systems	Rating	Comments/Concerns		Estim. Cost
4.3	Water Supply and Plumbing Systems		Bldg. Section	Description/Condition	
4.3.1	Domestic water supply (i.e., pressure, volume, quality - note whether municipal or well supply).	3	All	Town water feeds 2 - 50mm services, cast iron, adjacent school has experienced leaks.	\$12,000.00
4.3.2	Water treatment system(s).	N/A		None	
4.3.3	Pumps and valves (including backflow prevention valves).	5	All	No backflow protection, acceptable to local municipality.	
4.3.4	Piping and fittings.	5	All	Water - copper above and below grade, most below grade piping was abandoned during upgrade. Sanitary - Cast iron above and below grade	
4.3.5	Plumbing fixtures (i.e., toilets, urinals, sinks)	3	1955	Fixtures have reached life expectancy.	\$17,000.00
		4	All Others	New fixtures throughout in good condition	
4.3.6	Domestic hot water system (i.e., heater, storage tanks, failure alarms, pressure, volume, recirculation).	5	All	265 L, 41 Kw commercial water heaters in new basement mechanical room.	
4.3.7	Sanitary and storm sewers, including sumps and pits (note whether sewage system is municipal or septic).	4	All	Sanitary ties into municipal system. Ground water sumps in 2 locations. Storm spills to grade	
Other					

Section 4	Mechanical Systems	Rating	Comments/Concerns		Estim. Cost
4.4	Heating Systems		<b>Bldg. Section</b>	<b>Description/Condition</b>	
4.4.1	Heating capacity and reliability (including backup capacity).	5	All	Boilers upgraded in recent modernization. Two steel tube boilers @ 92 KW of heating output each.	
4.4.2	Heating controls (including use of current energy management technology).	5	All	Digital controls through-out	
4.4.3	Fresh air for combustion and condition of the combustion chimney.	5	All	Acceptable	
4.4.4	Treatment of water used in heating systems.	5	All	Micron filter and pot feeder in place	
4.4.5	Low water cutoff/pressure relief valves and failure alarms (i.e., hot water heating).	5	All	All required failure alarms are in place	
4.4.6	Heating air filtration systems and filters.	N/A		None	
4.4.7	Heating humidification systems and components.	N/A		None	

Section 4	Mechanical Systems	Rating	Comments/Concerns		Estim. Cost
4.4	Heating Systems (cont'd)		<b>Bldg. Section</b>	<b>Description/Condition</b>	
4.4.8	Heating distribution systems (i.e., piping, ductwork) and associated components (i.e., diffusers, radiators).	5	All	Excellent condition	
4.4.9	Heating piping, valve and/or duct insulation.	5	All	Excellent condition	
4.4.10	Heat exchangers.	5	All	Shell and tube exchanger for high temp to heat pump loop.	
4.4.11	Heating mixing boxes, dampers and linkages.	N/A		N/A	
4.4.12	Heating distribution/circulation in larger spaces (i.e., user comfort, temperature of outside wall surfaces).	5	All	Excellent air distribution	
4.4.13	Zone/unit heaters and controls.	5	All	Digital controls throughout, individual controls throughout.	
Other		3	1965	Old wing has 5 classrooms with gas fired unit ventilators. They should be abandoned and tied into the heat pump system.	\$40,000.00

Section 4	Mechanical Systems	Rating	Comments/Concerns		Estim. Cost
4.5	<b>Ventilation Systems</b>		<b>Bldg. Section</b>	<b>Description/Condition</b>	
4.5.1	Air handling units capacity and condition.	5	All	Two gas fired make-up air units: MU-1 = 2648 L/S, MU-2 = 3304 L/S	
4.5.2	Outside air for the occupant load (if possible, reference CFM/occupant).	2	1965	Five classrooms with minimal O/A	
		5	All Others	Excellent conditin	
4.5.3	Air distribution system (if possible, reference number of air changes/hour).	5	All	Overhead duct distribution off heat pumps.	
4.5.4	Exhaust systems capacity and condition.	5	All	Acceptable	
4.5.5	Separation of out flow from air intakes.	5	All	Acceptable	
4.5.6	Special/dedicated ventilation and/or exhaust systems (i.e., kitchen, labs, CTS areas).	5	1997	Kitchen is non-commercial with residential range hoods. I.A. shop has been upgraded with dust collection, welding ex, paint booth, etc.	
		5	1965	I.A. shop has been upgraded with dust collection, welding, paint booth, etc.	
Other		2	1965	See 4.4. Other	
4.5	<b>Ventilation Systems (cont'd)</b>		<b>Bldg. Section</b>	<b>Description/Condition</b>	
	<b>Note: Only complete the following items if there are separate ventilation and heating systems.</b>				
4.5.7	Ventilation controls (including use of current energy management technology).	5	All	DDC system in place.	
4.5.8	Air filtration systems and filters.	5	All	H.P.'s 25mm thick thow away media. Make-up air units - 50 mm thick throw-away media	
4.5.9	Humidification system and components.	N/A		None	
4.5.10	Heat exchangers.	5	All	Make-up airs - Gas fired exchangers in acceptable condition.	
4.5.11	Ventilation distribution system and components (i.e., ductwork, diffusers, mixing boxes, dampers, linkages).	5		Excellent	
Other					

Section 4	Mechanical Systems	Rating	Comments/Concerns		Estim. Cost
4.6	<b>Cooling Systems</b>		<b>Bldg. Section</b>	<b>Description/Condition</b>	
4.6.1	Cooling system capacity and condition (i.e., chillers, cooling towers, condensers).	5	All	Dry cooler works in conjunction with H.P.'s Capacity is 423 KW heat rejected	
4.6.2	Cooling distribution system and components (i.e., ductwork, diffusers, mixing boxes, dampers, linkages)	5	All	H.P.'s piping loop for heating and cooling feeds interonnected water source heat pumps	
4.6.3	Cooling system controls (including use of current energy management technology).	5	All	DDC system throughout	
4.6.4	Special/dedicated cooling systems (i.e., labs, CTS areas).			None	
Other					
4.7	<b>Building Control Systems</b>		<b>Bldg. Section</b>	<b>Description/Condition</b>	
4.7.1	Building wide/system wide control systems and/or energy management systems.		All	DDC controls with load shedding and energy management is in place.	
<b>Overall Mech Systems Condition &amp; Estim. Costs</b>					\$169,000.00

Part II - Physical Condition

Section 5	Electrical Systems	Rating	Comments/Concerns		Estim. Cost
5.1	<b>Site Services</b>				
5.1.1	Primary service capacity and reliability (i.e., access, location, components, installation, bus sizes - note whether overhead or underground).	4		1200A 600V 3 φ 4W underground service is new and has adequate capacity for future expansion.	
5.1.2	Site and building exterior lighting (i.e., safety concerns).	3		Additional exterior lighting is required.	\$5,000.00
5.1.3	Vehicle plug-ins (i.e., number, capacity, condition).	3		No vehicle plug-ins exist. Approximately 45 are required for present staff.	\$5,500.00
Other					
5.2	<b>Life Safety Systems</b>		<b>Bldg. Section</b>	<u>Description/Condition</u>	
5.2.1	Fire and smoke alarm systems (i.e., safety concerns, up-to-date technology, regularly tested).	2	1965	Additional detectors are required in grade 10 wing.	\$1,000.00
		4	1949	Fire alarm is in good condition	
		4	1960	Fire alarm is in good condition	
		4	1987	Fire alarm is in good condition	
		4	1998	Fire alarm is in good condition	
5.2.2	Emergency lighting systems (i.e., safety concerns, condition).	2	1965	Additional emergency lighting is required in Shops and Art area.	\$2,000.00
		4	1949	Emergency lighting is in good condition	
		4	1960	Emergency lighting is in good condition	
		4	1987	Emergency lighting is in good condition	
		4	1998	Emergency lighting is in good condition	
5.2.3	Exit lighting and signage (i.e., safety concerns, condition).	2	1965	Proper exit lights are required in Shops and Art area.	\$1,500.00
		4	1949	Exit lighting and signage is in good condition and connected to emergency power	
		4	1960	Exit lighting and signage is in good condition and connected to emergency power	
		4	1987	Exit lighting and signage is in good condition and connected to emergency power	
		4	1998	Exit lighting and signage is in good condition and connected to emergency power	

Section 5	Electrical Systems	Rating	Comments/Concerns		Estim. Cost
Other					
<b>5.3</b>	<b>Power Supply and Distribution</b>		<u>Bldg. Section</u>	<u>Description/Condition</u>	
5.3.1	Power service surge protection.	3	1996	Most computer rooms have surge protection.	\$1,000.00
5.3.2	Panels and wireways capacity and condition.	3	1960	Panels are old and have no spare capacity	\$9,000.00
		3	1965	Panels are old and have no spare capacity	\$7,000.00
		5	1987	Panels are in good condition with spare capacity	
		5	1998	Panels are in good condition with spare capacity	
		N/A		None	
5.3.3	Emergency generator capacity and condition and/or UPS (if applicable).	N/A		None	
5.3.4	General wiring devices and methods.	3	1965	Insufficient power outlets in classrooms	\$2,500.00
		3	1987	Insufficient power outlets in classrooms	\$2,500.00
		4	1998	Adequate outlets in all rooms	
5.3.5	Motor controls.	4	All	Good condition	
Other					
<b>5.4</b>	<b>Lighting Systems</b>		<u>Bldg. Section</u>	<u>Description/Condition</u>	
5.4.1	Interior lighting systems and components (i.e., illumination levels, conditions, controls).	3	1965	Classrooms meet IES light level recommendations but light fixtures are in poor condition	\$135,000.00
		3	1987	Classrooms meet IES light level recommendations but light fixtures are in poor condition	
		5	1965	Corridor lighting is in good condition.	
		3	1987	Corridorlighting is poor and needs to be replaced.	
			1998	All lights are new and are in good condition.	
5.4.2	Replacement of ballasts (i.e., health and safety concerns).	3	1965	Light fixtures most likely contain ballasts with PCB's (Except 1965 corridor)	\$67,500.00
		3	1987	Light fixtures most likely contain ballasts with PCB's (Except 1965 corridor)	\$67,500.00

Part II - Physical Condition

Section 5	Electrical Systems	Rating	Comments/Concerns		Estim. Cost
5.4.3	Implementation of energy efficiency measures and recommendations.	4	1998	Light fixtures have T-8 lamps with electronic ballasts - no PCB's	
		3	1965	Replace old technology T-12 light fixtures with new technology T-8 lamps with electronic ballasts. See 5.4.1	\$2,400.00
		3	1987	Replace old technology T-12 light fixtures with new technology T-8 lamps with electronic ballasts. See 5.4.1	\$2,300.00
		3	All	Install occupancy sensors in classrooms and offices	\$2,300.00
Other					
<b>5.5</b>	<b>Network and Communication Systems</b>		<b>Bldg. Section</b>	<u>Description/Condition</u>	
5.5.1	Telephone system and components (i.e., capacity, reliability, condition).	4	All	Telephone system is in good condition	
5.5.2	Other communication systems (i.e., public address, intercom, CCTV, satellite or cable TV).	4	All	P.A. system is in good condition. No CCTV. Cable TV is good.	
5.5.3	Network cabling (if available, should be category 5 or better).	4	All	All network cabling is category 5.	
5.5.4	Network cabling installation (i.e., in conduit, secured to walls or tables).	3	All	Network cabling installation is only fair in classrooms.	\$1,000.00
5.5.5	Wiring and telecommunication closets (i.e., size, security, ventilation/cooling, capacity for growth).	4	All	Telecommunication closets have sufficient size and security. Cooling could be improved.	
5.5.6	Provision for dedicated circuits for network equipment (i.e., hubs, switches, computers).	4		Network equipments has dedicated circuits.	
Other					
<b>5.6</b>	<b>Miscellaneous Systems</b>		<b>Bldg. Section</b>	<u>Description/Condition</u>	
5.6.1	Site and building surveillance system (if applicable).	4	All	Surveillance system is new for interior and exterior of building	
5.6.2	Intrusion alarms (if applicable).	4	All	Intrusion alarms/detectors are installed throughout the facility.	
5.6.3	Master clock system (if applicable).	N/A		None	
Other					
<b>5.7</b>	<b>Elevators/Disabled Lifts (If applicable)</b>				
5.7.1	Elevator/lift size, access and operating features (i.e., sensing devices, buttons, phones, detectors).	4	1949	Elevator size and access is good	
5.7.2	Condition of elevators/lifts.	4	1949	Elevator appears in good condition	
5.7.3	Lighting and ventilation of elevators/lifts.	4	1949	Lighting and ventilation is good.	

Evaluator's Name: Bill Lay

Company: Wiebe Forest Engineering Ltd.

Section 5	Electrical Systems	Rating	Comments/Concerns		Estim. Cost
Other					
	Overall Elect. Systems Condition & Estim Costs				\$315,000.00

Section 6	Portable Buildings	Rating	Comments/Concerns	Estim. Cost
	<i>Note: Separate sheets can be completed, if necessary, for portable buildings of different ages and/or conditions.</i>	N/A		
6.1.1	Foundation and structure (i.e., signs of bending, cracking, settlement, rust, voids, stains).			
6.1.2	Roof materials and components (i.e., signs of deterioration, leaks, ice build-up).			
6.1.3	Exterior wall finishes (i.e., signs of deterioration, cracks, water stains).			
6.1.4	Doors and windows (i.e., signs of deterioration, rusting hardware, glass cracks, peeling paint, damaged seals).			
6.1.5	Interior finishes (i.e., floors, walls, ceiling).			
6.1.6	Millwork (i.e., counters, shelving, vanities, cabinets).			
6.1.7	Fixed/wall mounted equipment (i.e., writing boards, tackboards, display boards, signs)			
6.1.8	Heating system.			
6.1.9	Ventilation system.			
6.1.10	Electrical, communication and data network systems.			
6.1.11	Health and safety concerns (i.e., fire and smoke alarms, fire protection systems, exiting, fire resistance rating of materials).			
6.1.12	Barrier-free access.			
<b>Overall Portable Bldgs Condition &amp; Estim Costs</b>				

Section 7	Space Adequacy (Meyers Only)	This Facility			Equiv. New Facility			Surplus/ Deficiency	Comments/Concerns W. R. Meyers
		No.	Size	Total Area	No.	Size	Total Area		
7.1	Classrooms	14	65	1046	22	80	1760	-714	
7.2	Science Rooms/Labs	5	85	407	5	120	600	-193	
7.3	Ancillary Areas (i.e., Art, Computer Labs, Drama, Music,)	2	70	182	2	130	260	-78	
					4	90	360	-360	
7.4	Gymnasium (incl. gym storage)	1	976	976	1	1150	1150	-174	
7.5	Library/Resource Areas	1	351	351	1	445	445	-94	
7.6	Administration/Staff, Physical Education, Storage Areas			546			914	-368	
7.7	CTS Areas								
	7.7.1 Business Education	1	109	109	3	115	345	-236	
	7.7.2 Home Economics	1	100	100				100	
	7.7.3 Industrial Arts	4	150	691				691	
	7.7.4 Other CTS Programs	4	112	450				450	
7.8	Other Non-Instructional Areas (i.e., circulation, wall area, crush space, wc area)			4074			2145	1929	

Section 7	Space Adequacy (Meyers Only)	No.	Size	Total Area	No.	Size	Total Area	Surplus/ Deficiency	Comments/Concerns
									W. R. Meyers
	Overall Space Adequacy Assessment			8932			7979	953	

Evaluation Component/ Sub-Component	Additional Notes and Comments

Evaluation Component/ Sub-Component	Additional Notes and Comments

Evaluation Component/ Sub-Component	Additional Notes and Comments

Evaluation Component/ Sub-Component	Additional Notes and Comments

Evaluation Component/ Sub-Component	Additional Notes and Comments

Evaluation Component/ Sub-Component	Additional Notes and Comments