| School | | |
|--------|------|--|
| | Date | |

| School Name | : ALTERN | ATIVE H | IIGH (CLINTON | FORD SCHOOL) | School Code: | 9863 | |
|------------------------------------|----------------|------------------|----------------------------|--|---|---|--|
| Location: | 5003 - 20 | ST. SV | /, CALGARY AL | BERTA | Facility Code: | 1663 | |
| | | | | | | | |
| Region: | SOUTH | | | | Superindendent: | Dr. DONNA MICHAELS | |
| Jurisdiction: | CALGAR | RY SCHO | OOL DISTRICT | No. 19 | Contact Person: | Ms. LEANNE SOLIGO | |
| | | | | | Telephone: | (403) 214-1123 | |
| Grades: | 10 - 12 | | | | School Capacity: | 170 | |
| huilding Costion | Year of Compl. | No. of Floors | Gross Bldg Area (Sq.M.) | Type of Construction (i.e., structure, roof, cladding) | Description of Mechanical Systems (incl. major upgrades) | Comments/Notes | |
| Building Section Driginal Building | 1956 | 1 | 2159.3 | Masonary, Frame, Stucco, Lap | | | |
| original bullding | 1956 | ' | 2159.3 | siding and Brick accents. Flat | Steam Boiler for heating with perimeter baseboard radiation - | Elementary school converted to high school use. | |
| | | | | slope | ventalition by unit ventilators in | Modernization required | |
| | | | | slope | each classroom and central | iviodernization required | |
| | | | | | exhaust fan in basement/crawl | | |
| | | | | | | | |
| | | | | | space. | | |
| | | <u> </u> | | | | | |
| Additions/ | N/A | | | | | | |
| Expansions | | | Total | | | | |
| | | | 2159.2 | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | Evaluated Nove | MINISTON DZIVED | |
| | | | | | Evaluator's Name: | WINSTON DZIVER | |
| | | | | | & Company: | GOWLING and GIBB ARCHITECTS | |

| School_ | | |
|---------|------|--|
| | Date | |

| Upgrading/ Modernization (identify whether minor or major) | 1956 (?) | | Not determined | Same | | CR subdivided, Lib. Layout changed, Admin area changed. |
|--|-------------|----------|--|--|------|--|
| | | | | | | |
| Portable Struct. (identify whether attached/perman. or free-standing/ relocatable) | N/A | | | | | |
| | | | | | | |
| List of Reports/ Supplementary Information | Authority | having j | ot prepared. urisdiction repor als audit availal | rt(s) not prepared ble - "Manage in Place" policy in effe | ect. | |

| School | | |
|--------|------|--|
| | Date | |

| Evaluation Components | Summary Assessment | Estim. Cos |
|---|--|------------|
| 1 Site Conditions | Add Barrier Free Access ramp. | \$6,000 |
| 2 Building Exterior | Paint plywood soffits, replace exterior doors and replace windows with new aluminum and infill framing. (Cost includes allowance for boiler replacement) | \$215,000 |
| 3 Building Interior | Modernization - Floors, Doors, Millwork, Ceilings, Fitments and painting. | \$273,850 |
| 4 Mechanical Systems | Replace existing univent system throughout the building , New control system required, and Misc. plumbing items. | \$312,913 |
| 5 Electrical Systems | New light fixtures required, upgrade fire alarm, emergency and exit lighting system required, needs surge protection, upgrade electrical system, panels and wiring circuits. | \$168,872 |
| 6 Portable Buildings | N/A | \$0.00 |
| 7 Space Adequacy: 7.1 Classrooms | There is a sumble of 040.7 as we designed of feed by the second of the s | |
| 7.1 Classrooms | There is a surplus of 248.7 sq.m. of space designated for classrooms. | |
| 7.2 Science Rooms/Labs | The Science room includes 2/3 of a converted classroom. | |
| 7.3 Ancillary Areas | There is a slight deficiency of 26.4 sq.m. | |
| 7.4 Gymnasium | There is a deficiency of 332.6 sq.m. The gymnasium was originally designed as a gymnasium for an elementary school. This particular school has since been converted to a high school and its gymnasium requirements are considerably larger. | |
| 7.5 Library/Resource Areas | The library is also under sized by 42 sq.m. | |
| 7.6 Administration/Staff Areas | There is a surplus of 62.2 sq.m. in this area. The mechanical spaces have also been included in this area. | |
| 7.7 CTS Areas | There are no spaces designated for the CTS areas, a deficiency of 115 sq.m. NOTE: We had compared this school to a min. high school capacity of 200 students. | |
| 7.8 Other Non-Instructional Areas (inc gross-up) | There is a slight deficiency of 7.2 sq.m. | |
| Overall School Conditions & Estim. C | osts | \$976,63 |

| School | | |
|--------|------|--|
| | Date | |

| | Site Conditions | Rating | Comments/Concerns | Estim. Cost |
|-------|---|--------|--|-------------|
| 1.1 | General Site Conditions | • | | |
| 1.1.1 | Overall site size. | 4 | Site size appears adequate for functional and educational needs. | |
| 1.1.2 | Outdoor athletic areas. | 4 | Appear adequate - conditions not determined due to snow cover | |
| 1.1.3 | Outdoor playground areas, including condition of equipment and base. | 3 | Tire and timber structure on site - not required. Demolish | \$1,000 |
| 1.1.4 | Site landscaping. | 4 | Mature tress and shrubs | |
| 1.1.5 | Site accessories (i.e., perimeter and other fencing, guard rails, bike stands, flag poles). | 4 | Chain link and post & cable fence - acceptable flag pole - acceptable, pipe guard rails - acceptable | |
| 1.1.6 | Surface drainage conditions (i.e., drains away from building, signs of pending). | F.I | Not observed or determined due to snow cover. | |
| 1.1.7 | Evidence of sub-soil problems. | 4 | Seepage reported - sump pump handles flow. | |
| 1.1.8 | Safety and security concerns due to site conditions. | 4 | None noted/reported | |
| Other | | | | |

| School | | |
|--------|------|--|
| | Date | |

| Section 1 | Site Conditions | Rating | Comments/Concerns | Estim. Cost |
|-----------|--|--------|---|-------------|
| 1.2 | Access/Drop-Off Areas/Roadways/Bus Lanes | | | |
| 1.2.1 | Vehicular and pedestrian access points (i.e., size, number, visibility, safety). | 4 | One vehicle access point acceptable two pedestrian access points from street - Acceptable | |
| 1.2.2 | Surfacing of on-site road network (note whether asphalt or gravel). | F.I | Asphalt in poor condition reported - not viewed due to snow cover | |
| | Bus lanes/drop-off areas (note whether on-site or off- site). | 4 | Street drop-off | |
| 1.2.4 | Fire vehicle access. | 4 | Street access | |
| 1.2.5 | Signage. | 4 | Wording indicated "CLINTON FORD SCHOOL" with "ALTERNATE" Added - see photo. | |
| Other | | | | |

| School | | |
|--------|------|--|
| | Date | |

| ection 1 Site Conditions | Rating | Comments/Concerns | Estim. Cost |
|--|--------|--|-------------|
| 1.3 Parking Lots and Sidewalks | | | |
| 1.3.1 Number of parking spaces for staff, students and visitors (including stalls for disabled persons). | 4 | Approx. 38 stalls on site - 12 Energized Markings not confirmed due to snow cover. | |
| 1.3.2 Layout and safety of parking lots. | 4 | Appears acceptable | |
| 1.3.3 Surfacing and drainage of parking lots (note whether asphalt or gravel). | F.I | Not viewed or determined due to snow cover. Reported to be concrete and asphalt - poor condition | |
| 1.3.4 Layout and safety of sidewalks. | 4 | Layout appears acceptable | |
| Surfacing and drainage of sidewalks (note type of material). | F.I | Not viewed or determined due to snow cover | |
| 1.3.6 Curb cuts and ramps for barrier free access. | | No ramp present - Ramp at main entry. (Note: Substantial rise required) | \$5,000 |
| Other | | | |
| | | | |
| Overall Site Conditions & Estimated Costs | | | \$6,000 |

| School | | |
|--------|------|--|
| | Date | |

| Section 2 | Building Exterior | Rating | | Comments/Concerns | Estim. Cost |
|-----------|---|--------|-----------------|---|-------------|
| 2.1 | Overall Structure | | Bldg. | D 1 1 10 101 | |
| 2.1.1 | Floor structure and beams (i.e., signs of bending, cracking, heaving, settlement, voids, rust, stains). | 4 | Section 1956 | <u>Description/Condition</u> None Noted | |
| 2.1.2 | Wall structure and columns (i.e., signs of bending, | 4 | 1956 | None Noted | |
| 2.112 | cracking, settlement, voids, rust, stains). | | 1000 | | |
| 2.1.3 | Roof structure (i.e., signs of bending, cracking, voids, rust, stains). | 4 | 1956 | None Noted | |
| Other | | | | | |
| | | | | | |

| School | | |
|--------|------|--|
| | Date | |

| Section 2 | Building Exterior | Rating | | Comments/Concerns | Estim. Cost |
|-----------|--|--------|---------|---|-------------|
| | Roofing and Skylights | | Bldg. | | |
| | Identify the availability of an up-to-date | | Section | | |
| | inspection report or roofing program. Note if roof | | or Roof | | |
| | sections are of different ages and/or in varying | | Section | Description/Condition/Age | |
| | Based on the inspection report (and to the extent possible, direct observation), assess and rate roof conditions and estimate costs for required | F.I | 1956 | Roofing report has not been prepared and is not available from CBE. | |
| | improvements (i.e., covering materials, membrane, insulation, other components). | | | | |
| | Roof accessories (i.e., ladders, stairs, hatches, masts, exhaust hoods, chimneys, gutters, downspouts, splashpads). | F.I | 1956 | Reference 2.2.1 | |
| 2.2.3 | Control of ice and snow falling from roof. | N/A | 1956 | Flat roof | |
| | Skylights (i.e., signs of distress, leaks, ice build-up, condensation, deteriorated materials/seals). | F.I | 1956 | Reference 2.2.1 - Interior locations show staining | |
| Other | | | | | |

| School | | |
|--------|------|--|
| | Date | |

| 2.3.1 Exterior Walls/Building Envelope 2.3.1 Exterior wall finishes (i.e., signs of deterioration, cracks, brick spalling, efflorescence, water stains). Exterior wall finishes (i.e., signs of deterioration, cracks, brick spalling, efflorescence, water stains). F.I 1956 Section Description/Condition -Stucco - "spider cracks" and peeling paint - Review Re: repair feasibility - Wood lap siding at lower part of wall checked, weathered in poor condit with Stucco solution. | |
|---|----------------------------|
| 2.3.1 Exterior wall finishes (i.e., signs of deterioration, cracks, brick spalling, efflorescence, water stains). F.I. 1956 -Stucco - "spider cracks" and peeling paint - Review Re: repair feasibility - Wood lap siding at lower part of wall checked, weathered in poor condit | |
| cracks, brick spalling, efflorescence, water stains). - Wood lap siding at lower part of wall checked, weathered in poor condit | |
| | |
| | |
| | |
| | |
| | |
| 2.3.2 Fascias, soffits, parapets (i.e., signs of looseness, 3 1956 Stucco soffits acceptable | \$1,500 |
| stains, rust, peeling paint). Wood soffits - Repaint Flashing - pre-finished metal | |
| i lastility - pre-titisticu metai | |
| | |
| | |
| 2.3.3 Building envelope (i.e., evidence of air infiltration/ 4 1956 None noted | |
| exfiltration through the exterior wall or ice build up on | |
| wall, eaves, canopy). | |
| | |
| | |
| 2.3.4 Interface of roof drainage and ground drainage N/A 1956 Interior roof drainage to storm system | |
| systems. | |
| | |
| | |
| | |
| | |
| 2.3.5 Inside faces of exterior walls (i.e., signs of cracks, water stains, dust spots). 4 1956 None noted | |
| | |
| | |
| | |
| | |
| Other 3 1956 Scope of work required for mechanical equipment (boiler, etc.) removal or | r replacement not \$50,000 |
| determined - cost indicated is allowance only for on mechanical room. | |
| | |
| | |
| | |
| | |

| School | | |
|--------|------|--|
| | Date | |

| Section 2 | Building Exterior | Rating | | Comments/Concerns | Estim. Cost |
|-----------|---|--------|-----------------|---|-------------|
| 2.4 | Exterior Doors and Windows | | Bldg. | | |
| | Doors (i.e., signs of deterioration, rusting metal, glass cracks, peeling paint, damaged seals, sealed unit failure). | 2 | Section 1956 | <u>Description/Condition</u> Original panel doors with plywood added to exterior face (8 locations), replace all (11 total) | \$11,000 |
| | Door accessories (i.e., latches, hardware, screens, locks, alarms, holders, closers, security devices). | 2 | 1956 | Reference and cost in 2.4.1 | |
| 2.4.3 | Exit door hardware (i.e., safety and/or code concerns). | 2 | 1956 | Reference and cost in 2.4.1 | |
| | Windows (i.e., signs of deterioration, rusting metal, glass cracks, peeling paint, damaged seals, sealed unit failure). | 2 | 1956 | Original wood single glazed with storms - deteriorated condition - Replace all with aluminum windows and infill framing | \$152,500 |
| | Window accessories (i.e., latches, hardware, screens, locks, alarms, holders, closers, security devices). | 2 | 1956 | Reference and cost in 2.4.1 | |
| | Building envelope (i.e., signs of heavy condensation on doors or windows). | 2 | 1956 | Reference and cost in 2.4.1 | |
| Other | | | | | |
| | | | | | |
| | Overall Bldg Exterior Condition & Estim Costs | | | | \$215,000 |

| School | | |
|--------|------|--|
| | Date | |

| Section 3 | Building Interior - Overall Conditions | Rating | | Comments/Concerns | Estim. Cost |
|-----------|---|--------|------------------|--|-------------|
| 3.1 | Interior Structure | | Bldg. | | |
| | | | Section | <u>Description/Condition</u> | |
| 3.1.1 | Interior walls and partitions (i.e., signs of cracks, spalling, paint peeling). | 4 | 1956 | Minor plaster cracking | |
| 3.1.2 | Floors (i.e., signs of cracks, heaving, settlement). | F.I. | 1956 | Settlement SE corner of Gym Appears floor was "opened" by previous investigation. | |
| Other | | | | | |
| 3.2 | Materials and Finishes | | Bldg. Section | Description/Condition | |
| 3.2.1 | Floor materials and finishes. | 2 | 1956 | - Battleship linoleum & 9" x 9" VAT in fair to poor condition - Replace 1250 sq.m Other areas - conc, Terrazo, Quarry tile and new sheet vinyl okay | \$47,500 |
| | | 2 | 1956 | - Refinish gym & stage hardwood following settlement repair per 3.1.2 | \$8,800 |
| 3.2.2 | Wall materials and finishes. | 2 | 1956 | Walls masonry and plaster - repair minor plaster cracking - paint all | \$26,000 |
| | | 2 | 1956 | Gym Acoustic treatment above plywood wainscotting - provide new. Note: Possible Haz. Material abatement costs not included | \$13,300 |
| 3.2.3 | Ceiling materials and finishes. | 2 | 1956 | 12" x 12" Acoustic Glue-on-mis-match patched, nailed repair - other areas plaster - Provide T-Bar acoustic throught out to accommodate new lighting and ventilation (1920 sq.m.) - includes acoustic ceiling treatment in gym. | \$65,300 |

| School | | |
|--------|------|--|
| | Date | |

| Section 3 | Building Interior - Overall Conditions | Rating | | Comments/Concerns | Estim. Cost |
|-----------|---|--------|---------|---|-------------|
| 3.2 | Materials and Finishes (cont'd) | | Bldg. | | |
| | | | Section | | |
| 3.2.4 | Interior doors and hardware. | 2 | 1956 | Wood doors - damaged & non-rated | \$27,950 |
| | | | | Replace 43 - remainder acceptable | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| 225 | Millwork | 2 | 1956 | Classrooms orginal - outdated, worn - replace | \$46,000 |
| 3.2.5 | Willwork | 2 | 1956 | Science original - outdated, worn - replace | \$46,000 |
| | | | | Art original - outdated, worn - replace | |
| | | | | Lunch original - outdated, worn - replace | |
| | | | | Staff work room original - outdated, worn - replace | |
| | | | | Stail Work 19911 Original Statuted, World Topiaco | |
| | | | | | |
| 3.2.6 | Fixed/wall mounted equipment (i.e., writing boards, | 2 | 1956 | Original Blackboards - Replace | \$5,000 |
| | tackboards, display boards, signs). | | | 3 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 | **,*** |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| 3.2.7 | Any other fixed/mounted specialty items (i.e., CTS | 4 | 1956 | Gym. Equip. (Basketball Goals) - Acceptable | |
| | equipment, gymnasium equipment). | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| 3 2 8 | Washroom materials and finishes. | 4 | 1956 | Ceiling - Plaster - See 3.2.3 | |
| 3.2.0 | Washiooni materials and milishes. | 7 | 1930 | Walls - Conc. Blk. & Ceramic tile wainscotting - okay | |
| | | | | Floors - Quarry tile - okay | |
| | | | | Partitions - okay | |
| | | | | Showers added - okay | |
| | | | | · | |
| | | | | | |
| Other | | 2 | 1956 | Add lockers c/w bulkheads (170 units) | \$34,000 |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

| School | | |
|--------|------|--|
| | Date | |

| Section 3 | Building Interior - Overall Conditions | Rating | | Comments/Concerns | Estim. Cost |
|-----------|--|--------|--------------------------|--|-------------|
| 3.3 | Health and Safety Concerns Intent is to identify renovations considered necessary to meet applicable codes, primarily due to safety concerns. Basis of evaluation should be an up-to-date inspection report from the authority having jurisdiction together with direct observations as appropriate. Evaluator should note if in his | F.I. | Bldg. Section 1956 | Description/Condition Authority having jurisdiction report not prepared or available. | |
| 3.3.1 | opinion a comprehensive code evaluation is Building construction type - combustible or non- | 4 | 1956 | Combustible and non-combustible; no sprinklers | |
| | combustible, sprinklered or non-sprinklered. | | | | |
| 3.3.2 | Fire separations (i.e., between buildings, wings, zones if non-sprinklered). | 2 | 1956 | Fire seperations zones appear present except above ceiling construction not obseved (concealed) - zone doors not rated, other doors not rated - door costs part of 3.2.4 | |
| 3.3.3 | Fire resistance rating of materials (i.e., corridor walls and doors). | 2 | 1956 | Walls concrete block and frame with plaster finish. Doors not rated in all locations - Door costs part of 3.2.4 | |
| 3.3.4 | Exiting distances and access to exits. | 4 | 1956 | Acceptable | |
| 3.3.5 | Barrier-free access. | 2 | 1956 | Single storey - not accessible - see 1.3.6 for ramp. | |
| 3.3.6 | Availability of hazardous materials audit (i.e., evidence of safety concerns with respect to asbestos, PCB's, chemicals). | F.I. | 1956 | Audit available - "Manage in place" policy currently in effect Extent of Hazardous materials and abatement costs not determined. | |
| 3.3.7 | Other health and safety concerns (i.e., evidence of excessive noise conditions, air quality problems) | N/A | | | |
| Other | | | | | |
| | Overall Bldg Interior Condition & Estim Costs | | | | \$273,850 |

| School | | |
|--------|------|--|
| | Date | |

| Section 4 | Mechanical Systems | Rating | | Comments/Concerns | Estim. Cost |
|-----------|--|--------|---------|---|-------------|
| | Mechanical Site Services | | | | |
| 4.1.1 | Site drainage systems (i.e., surface and underground systems, catch basins). | 4 | | No catch basin, all surface drainage. | |
| | Exterior plumbing systems (i.e., irrigation systems, hose bibs). | 4 | | Several hose bibs around building. No irrigation system. | |
| 4.1.3 | Outside storage tanks. | N/A | | | |
| Other | | | | | |
| 4.2 | Fire Suppression Systems | | Bldg. | _ , , , , , , , , , , , , , , , , , , , | |
| 4.2.1 | Fire hydrants and Siamese connections. | 5 | Section | Description/Condition One fire hydrant across street. No Siamese connection. | |
| | Fire suppression systems (i.e., pumps, sprinklers, piping, reservoirs, hoses, stand pipes, CO2 systems). | 4 | | Standpipe and Fire hose (1-1/2") available inside the building. | |
| 4.2.3 | Hand extinguishers, blankets and showers (i.e., in CTS areas). | 4 | | Hand extinguishers throughout the building. | |
| | Other special situations (e.g., flammable storage areas, science labs, CTS areas). | N/A | | | |
| Other | | | | | |

| School | | |
|--------|------|--|
| | Date | |

| Section 4 | Mechanical Systems | Rating | | Comments/Concerns | Estim. Cost |
|-----------|---|--------|---------|--|--------------|
| 4.3 | Water Supply and Plumbing Systems | | Bldg. | 5 6 | |
| 4.3.1 | Domestic water supply (i.e., pressure, volume, quality note whether municipal or well supply). | 4 | Section | Description/Condition 4" municipal water supply. Spitted to a 2" domestic water service and 2" irrigation hose bibs system. | |
| 4.3.2 | Water treatment system(s). | N/A | | | |
| | Pumps and valves (including backflow prevention valves). | 4 | | 2" backflow prevention valves in main water supply and supply to hose bibs. Backflow prevention valves are installed to boiler make up water. | |
| 4.3.4 | Piping and fittings. | 4 | | Cast iron pipes for drainage and copper pipes for portable water system. All copper piping are relatively new and C.I. pipes appears to be in reasonable condition. | |
| 4.3.5 | Plumbing fixtures (i.e., toilets, urinals, sinks) | 3 | | Plumbing fixtures are quite old, most fixtures appears to be in good operating condition. cracks in some toilet base, replace toilets and flush valves (trouble getting replacement parts) | \$12, 000.00 |
| 4.3.6 | Domestic hot water system (i.e., heater, storage tanks, failure alarms, pressure, volume, recirculation). | 3 | | One residential size H.W. heater over 20 years old. | \$1,000.00 |
| 4.3.7 | Sanitary and storm sewers, including sumps and pits (note whether sewage system is municipal or septic). | 4 | | Sanitary and storm sewers appears to be in good operating condition. Ground water sump pump controls to be repaired with work order in place. Sewage system is municipal. | |
| Other | | 3 | | No insulation on domestic hot and cold water piping. | \$8,000.00 |

| School | | |
|--------|------|--|
| | Date | |

| Section 4 | Mechanical Systems | Rating | | Comments/Concerns | Estim. Cost |
|-----------|---|--------|---------|--|--------------|
| 4.4 | Heating Systems | | Bldg. | Description/Condition | |
| 4.4.1 | Heating capacity and reliability (including backup capacity). | 3 | Section | Original cast iron low pressure steam boiler appears to be in good operating condition. Reasonably well maintained. System has exceeded its service life. Condensate receiver tank have rust at bottom. Replace tank and pump. | \$102,169.00 |
| 4.4.2 | Heating controls (including use of current energy management technology. | 3 | | All heating controls are old pneumatic system. No energy management function. | \$64,779.00 |
| 4.4.3 | Fresh air for combustion and condition of the combustion chimney. | 4 | | Combustion air and chimney looks fine. No high level relief. | |
| 4.4.4 | Treatment of water used in heating systems. | 4 | | Routine water treatment required. | |
| 4.4.5 | Low water cutoff/pressure relief valves and failure alarms (i.e., hot water heating). | N/A | | N/A | |
| 4.4.6 | Heating air filtration systems and filters. | N/A | | N/A | |
| 4.4.7 | Heating humidification systems and components. | N/A | | N/A | |

| School | | |
|--------|------|--|
| | Date | |

| Section 4 | Mechanical Systems | Rating | | Comments/Concerns | Estim. Cost |
|-----------|---|--------|---------|---|-------------|
| | Heating Systems (cont'd) | | Bldg. | | |
| 4.40 | | | Section | <u>Description/Condition</u> | |
| | Heating distribution systems (i.e., piping, ductwork) and associated components (i.e., diffusers, radiators). | 4 | | Steam distributed to perimeter radiators and unit ventilators. Only general routine maintenance required. | |
| 4.4.9 | Heating piping, valve and/or duct insulation. | 4 | | Appears to be satisfactory. | |
| 4.4.10 | Heat exchangers. | N/A | | | |
| 4.4.11 | Heating mixing boxes, dampers and linkages. | N/A | | | |
| 4.4.12 | Heating distribution/circulation in larger spaces (i.e., user comfort, temperature of outside wall surfaces). | 4 | | Appears to be satisfactory. | |
| 4.4.13 | Zone/unit heaters and controls. | 4 | | Appears to be satisfactory. | |
| Other | | | | | |

| Section 4 | Mechanical Systems | Rating | | Comments/Concerns | Estim. Cost |
|-----------|--|-------------|---------|--|---------------------------|
| 4.5 | Ventilation Systems | | Bldg. | Description (Condition | |
| 4.5.1 | Air handling units capacity and condition. | 3 | Section | Description/Condition Unit ventilators in each classroom to bring in outside air with preheat. Equipment at end of life cycle, required special order on parts. Need new ventilation system or complete overhaul existing equipment | \$107,965.00 |
| 4.5.2 | Outside air for the occupant load (if possible, reference CFM/occupant). | F.I | | Equipment capacity unknown. | |
| 4.5.3 | Air distribution system (if possible, reference number of air changes/hour). | F.I | | Equipment capacity unknown. | |
| 4.5.4 | Exhaust systems capacity and condition. | F.I | | Common exhaust system to exhaust all classrooms through central exhaust fan located in basement /crawl space Exhaust capacity unknown. Exhaust fan condition appears to be satisfactory. | |
| 4.5.5 | Separation of out flow from air intakes. | 4 | | Good | |
| | Special/dedicated ventilation and/or exhaust systems (i.e., kitchen, labs, CTS areas). | 3 | | Art room exhaust hood leaks cold air into the room Add insulated motorized damper in exhaust duct with interlock. | \$1,000.00 |
| Other | | 3 3 3 | | Insufficient ventilation in Boy's washroom and Girl's washroom. No mechanical ventilation in Hallway. See part of 4.5.1. No fire dampers in exhaust grilles through Classroom walls and no fire dampers in ductwork through boiler room. | \$6,000.00 \$10,000.00 |

| School | | |
|--------|------|--|
| | Date | |

| Section 4 | Mechanical Systems | Rating | | Comments/Concerns | | |
|-----------|--|--------|---------|--|--|--|
| 4.5 | Ventilation Systems (cont'd) | | Bldg. | | | |
| | | | Section | <u>Description/Condition</u> | | |
| | Note: Only complete the following items if there | | | | | |
| | are separate ventilation and heating systems. | | | | | |
| | Ventilation controls (including use of current energy management technology). | | | | | |
| | | 3 | | Old pneumatic controls. See 4.7.1. | | |
| | | | | | | |
| 4.5.8 | Air filtration systems and filters. | | | | | |
| | | | | | | |
| | | 3 | | Filtration through unit ventilators in each classroom. New system required. Part of 4.5.1. | | |
| | | | | | | |
| 4.5.9 | Humidification system and components. | | | | | |
| | | N/A | | | | |
| | | | | | | |
| 4.5.10 | Heat exchangers. | | | | | |
| | | NI/A | | | | |
| | | N/A | | | | |
| 4544 | Manathatian distribution and assessment of the state of t | | | | | |
| | Ventilation distribution system and components (i.e., ductwork, diffusers, mixing boxes, dampers, | | | | | |
| | linkages). | N/A | | | | |
| | | | | | | |
| Other | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |

| School | | |
|--------|------|--|
| | Date | |

| Section 4 | Mechanical Systems | Rating | | Comments/Concerns | Estim. Cost |
|-----------|---|--------|------------------|--|--------------|
| 4.6 | Cooling Systems | | Bldg. | | |
| 4.6.1 | Cooling system capacity and condition (i.e., chillers, cooling towers, condensers). | N/A | Section | <u>Description/Condition</u> | |
| 4.6.2 | Cooling distribution system and components (i.e., ductwork, diffusers, mixing boxes, dampers, linkages) | N/A | | | |
| 4.6.3 | Cooling system controls (including use of current energy management technology). | N/A | | | |
| 4.6.4 | Special/dedicated cooling systems (i.e., labs, CTS areas). | N/A | | | |
| Other | | | | | |
| 4.7 | Building Control Systems | | Bldg. Section | Description/Condition | |
| 4.7.1 | Building wide/system wide control systems and/or energy management systems. | 3 | | Old pneumatic control system. Replace with energy management systems. See 4.4.2. | |
| | Overall Mech Systems Condition & Estim. Costs | | | | \$312,913.00 |

| School | | |
|--------|------|--|
| | Date | |

| Section 5 | Electrical Systems | Rating | | Comments/Concerns | Estim. Cost |
|-----------|--|--------|---------|--|-------------|
| | Site Services | | | | |
| | Primary service capacity and reliability (i.e., access, location, components, installation, bus sizes - note whether overhead or underground). | 3 | | Underground 200 amp 120/208V 3pH 4W main breaker. Had previous history of blackout due to overloading. Current peak consumption at 45 KVA. Upgrade to 400 amps 120/208 volts, 3pH is required. | \$30,000.00 |
| 5.1.2 | Site and building exterior lighting (i.e., safety concerns). | 4 | | Exterior lights on building side and rear controlled by photocell on and off. | |
| 5.1.3 | Vehicle plug-ins (i.e., number, capacity, condition). | 4 | | 18 car plugs are thermostatically controlled. No weather proof cover plates. | |
| Other | | | | | |
| 5.2 | Life Safety Systems | | Bldg. | | |
| 5.2.1 | Fire and smoke alarm systems (i.e., safety concerns, up-to-date technology, regularly tested). | 3 | Section | <u>Description/Condition</u> Fire alarm system was upgraded in the 1980's. No heat dectors in pipe tunnels. Simplex 4002 8 zone System. Add heat detectors in pipe tunnel, add strobe lights to F/A bells. | \$8,000.00 |
| 5.2.2 | Emergency lighting systems (i.e., safety concerns, condition). | 3 | | Emergency lighting system was partially upgraded. Additional upgrade is required. | \$6,000.00 |
| | Exit lighting and signage (i.e., safety concerns, condition). | 3 | | Exit lighting system was partially upgarded. Additional upgrade is required. | \$7,000.00 |
| Other | | | | | |

| School | | |
|--------|------|--|
| | Date | |

| Section 5 | Electrical Systems | Rating | | Comments/Concerns | Estim. Cost |
|-----------|--|--------|---------|--|-------------|
| 5.3 | Power Supply and Distribution | | Bldg. | Description (Condition | _ |
| 5.3.1 | Power service surge protection. | 2 | Section | Description/Condition No surge protection | \$1,500.00 |
| 5.3.2 | Panels and wireways capacity and condition. | 3 | | Existing panels, outlets and circuit wiring are in fair condition with insufficient spaces in panels for future. Concern too many receptacles are tied to same circuit. Upgrade existing panels to meet computer and convenience outlet requirements with space for future circuits overloaded due to change to high school program. | \$25,000.00 |
| | Emergency generator capacity and condition and/or UPS (if applicable). | N/A | | | |
| 5.3.4 | General wiring devices and methods. | 4 | | Generally satisfactory. | |
| 5.3.5 | Motor controls. | F.I. | | MCC replace on an as needed basis - Honeywell under contract to modify. | |
| Other | | | | | |

| Section 5 | Electrical Systems | Rating | | Comments/Concerns | Estim. Cost |
|-----------|---|--------|---------|--|-------------|
| 5.4 | Lighting Systems | | Bldg. | - 1 | |
| 5.4.1 | Interior lighting systems and components (i.e., illumination levels, conditions, controls). | 3 | Section | Fluorescent fixtures with T-12 lamps throughout. Lighting Level: 30-40 F.C. in Office, 20-25 F.C. in Hallway, 10-15 F.C. in Gym, 40-45 F.C. in Science Room, 40-45 F.C. in classrooms, 40-45 F.C. in Arts Room, 40-45 F.C. in Computer Lab, 10-20 F.c. in Washrooms. Ambient conditions has great impact on lighting level in space. Most room have 2 or 3 switches. New light fixtures with T-8 lamps and electronic ballasts are required. | \$86,372.00 |
| 5.4.2 | Replacement of ballasts (i.e., health and safety concerns). | 3 | | Original building fluorescent luminaires may contain PCB's in ballast. Estimate cost to dispose ballasts | \$4,000 |
| 5.4.3 | Implementation of energy efficiency measures and recommendations. | 3 | | Exterior lights are controlled by photocell only. Caretaker shut off lights manually after school is closed. Time clock is recommended. | \$500.00 |
| Other | | 1 | | New explosion proof type light fixture inside gas meter room. Explosion proof fixture is required. | \$500.00 |

| School | | |
|--------|------|--|
| | Date | |

| | Electrical Systems | Rating | | Comments/Concerns | Estim. Cost |
|-------|--|--------|---------|--|-------------|
| 5.5 | Network and Communication Systems | | Bldg. | Description (Constition | |
| 5.5.1 | Telephone system and components (i.e., capacity, reliability, condition). | 4 | Section | Description/Condition Telephone system upgraded. | |
| | Other communication systems (i.e., public address, intercom, CCTV, satellite or cable TV). | 4 | | Separate speaker system in classroom and telephone system can be used for paging. No CCTV, satellite or cable TV system. | |
| | Network cabling (if available, should be category 5 or better). | 4 | | Quad drops in classrooms, library and offices, all networked with conduit. Computer Lab fully networked. | |
| | Network cabling installation (i.e., in conduit, secured to walls or tables). | 4 | | Satisfactory. | |
| 5.5.5 | Wiring and telecommunication closets (i.e., size, security, ventilation/cooling, capacity for growth). | 4 | | Satisfactory. | |
| | Provision for dedicated circuits for network equipment (i.e., hubs, switches, computers). | 4 | | Satisfactory. | |
| Other | | | | | |

| School | | |
|--------|------|--|
| | Date | |

| | Electrical Systems | Rating | | Comments/Concerns | Estim. Cost |
|-------|--|--------|---------|---|--------------|
| | Miscellaneous Systems | | Bldg. | | |
| | | | Section | <u>Description/Condition</u> | |
| 5.6.1 | Site and building surveillance system (if applicable). | N/A | | | |
| 5.6.2 | Intrusion alarms (if applicable). | 4 | | Security system in place with motion detectors. | |
| 5.6.3 | Master clock system (if applicable). | N/A | | | |
| Other | | | | | |
| 5.7 | Elevators/Disabled Lifts (If applicable) | | | | |
| 5.7.1 | Elevator/lift size, access and operating features (i.e., sensing devices, buttons, phones, detectors). | N/A | | Single storey - see 1.3.6 Re: Exterior ramp | |
| 5.7.2 | Condition of elevators/lifts. | N/A | | | |
| 5.7.3 | Lighting and ventilation of elevators/lifts. | N/A | | | |
| Other | | | | | |
| | Overall Elect. Systems Condition & Estim Costs | | | | \$168,872.00 |

| School | | |
|--------|------|--|
| | Date | |

| ection 6 | Portable Buildings | Rating | Comments/Concerns | Estim. Cost |
|----------|--|--------|-------------------|-------------|
| | Note: Separate sheets can be completed, if necessary, for portable buildings of different ages and/or conditions. | N/A | None on this site | |
| 6.1.1 | Foundation and structure (i.e., signs of bending, cracking, settlement, rust, voids, stains). | N/A | | |
| 6.1.2 | Roof materials and components (i.e., signs of deterioration, leaks, ice build-up). | N/A | | |
| 6.1.3 | Exterior wall finishes (i.e., signs of deterioration, cracks, water stains). | N/A | | |
| 6.1.4 | Doors and windows (i.e., signs of deterioration, rusting hardware, glass cracks, peeling paint, damaged seals). | N/A | | |
| 6.1.5 | Interior finishes (i.e., floors, walls, ceiling). | N/A | | |
| 6.1.6 | Millwork (i.e., counters, shelving, vanities, cabinets). | N/A | | |
| 6.1.7 | Fixed/wall mounted equipment (i.e., writing boards, tackboards, display boards, signs) | N/A | | |
| 6.1.8 | Heating system. | N/A | | |
| 6.1.9 | Ventilation system. | N/A | | |
| 6.1.10 | Electrical, communication and data network systems. | N/A | | |
| 6.1.11 | Health and safety concerns (i.e., fire and smoke alarms, fire protection systems, exiting, fire resistance rating of materials). | N/A | | |
| 6.1.12 | Barrier-free access. | N/A | | |
| | Overall Portable Bldgs Condition & Estim Costs | | | \$0.00 |

| School | | |
|--------|------|--|
| | Date | |

| | | This Facility | | Equiv. New Facility | | Surplus/ | | | |
|-----------|--|---------------|--------------------------------|---------------------|-----|-----------|------------|------------|---|
| Section 7 | Space Adequacy | No. | Size | Total Area | No. | Size | Total Area | Deficiency | Comments/Concerns |
| 7.1 | Classrooms | 8 | 5@85.5 78.0 75.5 28.5 | 568.7 m2 | 4 | 80 | 320 m2 | 248.7 m2 | |
| 7.2 | Science Rooms/Labs | 2 | 94.8 57.0 | 141.6 m2 | 1 | 120 | 120 m2 | 21.6 m2 | Includes 2/3 of a converted classroom |
| 7.3 | Ancillary Areas (i.e., Art, Computer Labs, Drama, Music,) | 3 | 63.2 90.2 43.4 | 183.6 m2 | 2 | 130 90 | 210 m2 | (26.4 m2) | |
| 7.4 | Gymnasium (incl. gym storage) | 1 | 256.8 15.6 | 272.4 m2 | 1 | 550 55 | 605 m2 | (332.6 m2) | |
| 7.5 | Library/Resource Areas | 1 | 88 | 88 m2 | 1 | 130 | 130 m2 | (42.0 m2) | |
| 7.6 | Administration/Staff, Physical Education, Storage Areas | | Varies | 232.2 m2 | | 170 | 170 m2 | 62.2 m2 | |
| 7.7 | CTS Areas | | | | | | | | |
| | 7.7.1 Business Education | | | | 1 | 115 | 115 m2 | (115.0 m2) | |
| | 7.7.2 Home Economics | | | | | | | | |
| | 7.7.3 Industrial Arts | | | | | | | | |
| | 7.7.4 Other CTS Programs | | | | | | | | |
| | Other Non-Instructional Areas (i.e., circulation, wall area, crush space, wc area) | | Varies | 672.8 m2 | | 680 | 680 m2 | (7.2 m2) | Used min. criteria of 200 student high school equivalent. |
| | Overall Space Adequacy Assessment | 15 | | 2159.3 m2 | 10 | | 2350 m2 | (190.7 m2) | Alt High converted from Elem. School |

| School | | |
|--------|------|--|
| | Date | |

| Evaluation Component/ Sub-Component | Additional Notes and Comments |
|--|-------------------------------|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

| School | | |
|--------|------|--|
| | Date | |

| Evaluation Component/ Sub-Component | Additional Notes and Comments |
|--|-------------------------------|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

| School_ | | |
|---------|------|--|
| | Date | |

| Evaluation Component/ Sub-Component | Additional Notes and Comments |
|--|-------------------------------|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

| School | | |
|--------|------|--|
| | Date | |

| Evaluation Component/ Sub-Component | Additional Notes and Comments |
|--|-------------------------------|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

| School | | |
|--------|------|--|
| | Date | |

| Evaluation Component/ Sub-Component | Additional Notes and Comments |
|--|-------------------------------|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

| School | | |
|--------|------|--|
| | Date | |

| Evaluation Component/ Sub-Component | Additional Notes and Comments |
|--|-------------------------------|
| | |
| | |
| | |
| | |
| | |
| | |