# **EXECUTIVE SUMMARY**

## **Project Overview**

In February 2000 the Alberta Infrastructure School Facilities Branch engaged Carruthers & Associates Architects Inc. to investigate and report on the physical condition of 23 schools in Calgary under the jurisdiction of the Calgary Board of Education. We are now pleased to present the results of our investigations, in the form of charts as specified by Alberta Infrastructure.

## Construction History

Original: 1912, 1346.0 m.<sup>2</sup> 6 classrooms, washrooms,

offices,

Additions: 1961 552.8 m.<sup>2</sup> 1 classroom, gymnasium

Evaluation Date: March 13, 2000

# **Building Summary**

Masonry-brick perimeter walls, wood floors and interior partitions with plaster finish, shingled wood frame roof. with no sprinkler system. 1961 is concrete frame structure with concrete block in-fill walls, flat wood frame roof.

Boiler (1) was replaced in 1994-95 along with new pumps and heat exchanger for 1961 addition.

## Summary of Observations and Recommendations

Parking on-site does not exist but should be provided Exterior sidewalks need to be replaced All interiors to be repaired / replaced

Replace entire window system with new aluminum frame system including insulated spandral units in upper portion and double pane sealed units below.

#### Replace exterior doors.

Mechanical: New boiler has been installed, however steam distribution needs replacement and proper air systems and controls installed. Electrical: All electrical systems be upgraded in this facility.

#### **Estimated Costs:**

1.Site:	\$199,500
2.Building exterior:	\$729000
3.Building interior:	\$626,000
4.Mechanical:	\$258,000
5.Electrical:	143,500
6.Portables	\$0
TOTAL:	\$1,956.000

## Space Adequacy:

Total area this facility:	1898.0 m. <sup>2</sup>
Equivalent new facility requirements:	2078.0 m. <sup>2</sup>
Space Deficiency:	(179.2 m. <sup>2)</sup>

## Further Investigation:

Roof structure.

Roof & accessories-inspection required

Hazardous materials to be further investigated and priced.

Building Envelope. Fire & Building code study.

Asbestos costing.

## School Plan and Data Information

The plan information for the building was supplied by the school jurisdiction. Area information was provided by Alberta Infrastructure. The information generally appears to be up to date with some minor room function revisions.

# TABLE OF CONTENTS

Floor Plans

Site Plan - Not Available

Asbestos Report -- Not Available

Executive	Summary	
School Ev	aluation Report	1
Part I: Fa	acility Profile and Summary	1
Part II: .Pl	hysical Condition	2
1.	Site Conditions	2
2.	Building Exterior	7
3.	Building Interior	11
4.	Mechanical Systems	14
5.	Electrical Systems	21
6.	Portable Classrooms	26
7.	Space Adequacy	27
Photograp	ohs	