

| Alberta Infrastructure | | School Facilities Evaluation Project | | | | | | Champion School | | |
|--------------------------|--|--|--|--|--|--|--|-----------------|--|---|
| School Facilities Branch | | Executive Summary | | | | | | Champion, AB | | |
| | | | | | | | | March 15, 2000 | | |
| | | Executive Summary | | | | | | | | |
| | | <p>Alvin Reinhard Fritz Architect has been commissioned for architectural services to provide Alberta Infrastructure with a school facility evaluation for the Champion School in Champion, Alberta.</p> <p>The original school was constructed in 1952 with a classroom wing added in 1959. The original building is still in good structural condition as is the addition.</p> <p>Externally, some play equipment needs upgrading, and grading and perimeter drains are required to reduce ponding. Internally some upgrades to achieve reasonable code compliance is necessary.</p> | | | | | | | | |
| | | Mechanically, provide mechanical ventilation throughout school. Install a full DDC system. | | | | | | | | |
| | | Electrically, the electrical service must be upgraded to accommodate the additional loads that will be imposed by the ventilation upgrade. Replace lighting fixtures located in the hallways and offices with T8 lamps and ballast. | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | Alvin Reinhard Fritz Architect Inc. | | | | | | | | i |

| | | | | | | | | |
|--|-------------------------------------|--|--|--|--|--|-----|--|
| | Alvin Reinhard Fritz Architect Inc. | | | | | | iii | |
|--|-------------------------------------|--|--|--|--|--|-----|--|

| | | | | | | |
|-------------------------|---------------------------------------|----------------------|--------------------------------|--|--|-------------------------------------|
| School Name: | Champion Consolidated School | School Code: | 5404 | | | |
| Location: | Champion, AB | Facility Code: | 959 | | | |
| Region: | South | Superintendent: | Mr. John Bolton | | | |
| Jurisdiction: | Palliser Regional School Division #26 | Contact Person: | Mr. Bryan Kranzler | | | |
| | | Telephone: | (403) 328-4111 | | | |
| Grades: | 1-9 | School Capacity: | 300 | | | |
| Building Section | Year of Compl. | No. of Floors | Gross Bldg Area (Sq.M.) | Type of Construction (i.e., structure, roof, cladding) | Description of Mechanical Systems (incl. major upgrades) | Comments/Notes |
| Original Building | 1952 | 2 | 1257.7 | Concrete Frame, Masonry infill, brick cladding, joist floors. Built up roof. | Municipal water and sanitary service< hot water heating and distribution, no mechanical ventilation. | |
| Additions/ Expansions | 1959 | 2 | 836.8 | Concrete Frame, Masonry infill, brick cladding, joist floors. Built up roof. | As original. | |
| | | | | | | |
| | | | | | | |
| | Total | | 2094.5 | | | |
| | | | | | Evaluator's Name: | Bryan Norford |
| | | | | | & Company: | Alvin Reinhard Fritz Architect Inc. |

| | | | | | | |
|--|---|--|--|---|--|--|
| <p>Upgrading/ Modernization (identify whether minor or major)</p> | | | | <p>Upto 1979: Washrooms, windows, exit doors, library. 1998: Gym Ceiling, exit doors. 1989: Flooring.</p> | <p>Hot water heating and distribuion, lighting 1979 - 1988, fire alarm 1990.</p> | |
| <p>Portable Struct. (identify whether attached/perman. or free-standing/ relocatable)</p> | NA | | | | | |
| | | | | | | |
| <p>List of Reports/ Supplementary Information</p> | <p>Requires assessment report, November 1992.</p> | | | | | |

| | Evaluation Components | Summary Assessment | Estim. Cost |
|---|--|--|-------------|
| 1 | Site Conditions | Generally good. Some play equipment requires upgrading. Perimeter drains to eliminate ponding signage required. | 35,000.00 |
| 2 | Building Exterior | Satisfactory | 0.00 |
| 3 | Building Interior | Some fire separations recommended. Stair balustrades require replacement, fire rated door for furnace room, and lower corridors. | 42,000.00 |
| 4 | Mechanical Systems | Provide mechanical ventilation, provide exhaust fans for gym, kitchen, washrooms and LAN server room. Provide DDC system. | 107,500.00 |
| 5 | Electrical Systems | New service required to accommodate ventilation upgrade, upgrade lighting in hallways and office to T8 lamps. | 86,500.00 |
| 6 | Portable Buildings | NA | 0.00 |
| 7 | Space Adequacy: | | |
| | 7.1 Classrooms | Some extra classrooms. 91.2 | |
| | 7.2 Science Rooms/Labs | Only one Science room. -152 | |
| | 7.3 Ancillary Areas | Individual rooms each deficient. -98.5 | |
| | 7.4 Gymnasium | Sized for Elementary, major deficiency. -229 | |
| | 7.5 Library/Resource Areas | About right. -3.5 | |
| | 7.6 Administration/Staff Areas | Over 50% deficient. -234.2 | |
| | 7.7 CTS Areas | No Business Education. -115 | |
| | 7.8 Other Non-Instructional Areas (incl. gross-up) | Deficient. -103.5 | |
| | Overall School Conditions & Estim. Costs | Significantly deficient. -844.5 | 271,000.00 |

| Section 1 | Site Conditions | Rating | Comments/Concerns | Estim. Cost |
|-----------|---|--------|--|-------------|
| 1.1 | General Site Conditions | | | |
| 1.1.1 | Overall site size. | 4 | Adequate | |
| 1.1.2 | Outdoor athletic areas. | 4 | Track & Field areas, recently upgraded. | |
| 1.1.3 | Outdoor playground areas, including condition of equipment and base. | 1 | Some equipment requires replacement. Depth of pea gravel requires increasing. | 4,000.00 |
| 1.1.4 | Site landscaping. | 4 | Some landscaping, some prairie grass | |
| 1.1.5 | Site accessories (i.e., perimeter and other fencing, guard rails, bike stands, flag poles). | 4 | Adequate | |
| 1.1.6 | Surface drainage conditions (i.e., drains away from building, signs of ponding). | 1 | Some ponding along East and West sides of building. Insufficient space for grading. Provide perimeter drain to drypit. | 25,000.00 |
| 1.1.7 | Evidence of sub-soil problems. | | none | |
| 1.1.8 | Safety and security concerns due to site conditions. | | none | |
| | Other | | | |
| 1.2 | Access/Drop-Off Areas/Roadways/Bus Lanes | | | |

| Section 1 | Site Conditions | Rating | Comments/Concerns | Estim. Cost |
|-----------|--|--------|---|-------------|
| 1.2.1 | Vehicular and pedestrian access points (i.e., size, number, visibility, safety). | 4 | Two accesses to site - one for parking and one for drop off. Satisfactory | |
| 1.2.2 | Surfacing of on-site road network (note whether asphalt or gravel). | 4 | Gravel | |
| 1.2.3 | Bus lanes/drop-off areas (note whether on-site or off-site). | 4 | On site, along sidewalks | |
| 1.2.4 | Fire vehicle access. | 4 | Good gravel access, two sides | |
| 1.2.5 | Signage. | 2 | Poor. Adequate signage at road and on building required. Parking, fire lane signage required. | 2,000.00 |
| Other | | | | |

| Section 1 | Site Conditions | Rating | Comments/Concerns | Estim. Cost |
|-----------|--|--------|---|--------------------|
| | 1.3 Parking Lots and Sidewalks | | | |
| | 1.3.1 Number of parking spaces for staff, students and visitors (including stalls for disabled persons). | 4 | No specific layout, but adequate | |
| | 1.3.2 Layout and safety of parking lots. | 4 | Adequate | |
| | 1.3.3 Surfacing and drainage of parking lots (note whether asphalt or gravel). | 2 | Some ponding at west boundary. Regrade gravel as necessary. | 3,000.00 |
| | 1.3.4 Layout and safety of sidewalks. | 4 | Adequate | |
| | 1.3.5 Surfacing and drainage of sidewalks (note type of material). | 4 | Adequate concrete walks. | |
| | 1.3.6 Curb cuts and ramps for barrier free access. | 2 | None at present, no challenged students at present. 2 curb cuts required. | 1,000.00 |
| | Other | | | |
| | Overall Site Conditions & Estimated Costs | | | \$35,000.00 |

| Section 2 | Building Exterior | Rating | Comments/Concerns | | Estim. Cost |
|-----------|---|--------|----------------------|---|-------------|
| 2.1 | Overall Structure | | <u>Bldg. Section</u> | <u>Description/Condition</u> | |
| 2.1.1 | Floor structure and beams (i.e., signs of bending, cracking, heaving, settlement, voids, rust, stains). | 4 | | None apparent | |
| 2.1.2 | Wall structure and columns (i.e., signs of bending, cracking, settlement, voids, rust, stains). | F.I. | | Stress at one location - see 3.1.1 Remainder no apparent problem | |
| 2.1.3 | Roof structure (i.e., signs of bending, cracking, voids, rust, stains). | 4 | | None apparent | |
| Other | | | | | |

| Section 2 | Building Exterior | Rating | Comments/Concerns | | Estim. Cost |
|-----------|---|--------|--------------------------------------|---|-------------|
| | 2.2 Roofing and Skylights <i>Identify the availability of an up-to-date inspection report or roofing program. Note if roof sections are of different ages and/or in varying states of repair.</i> | | Bldg. Section or Roof Section | Description/Condition/Age | |
| | 2.2.1 Based on the inspection report (and to the extent possible, direct observation), assess and rate roof conditions and estimate costs for required improvements (i.e., covering materials, membrane, insulation, other components). | 5 | | New sloped metal roof recently installed over original flat build-up roofing. In good condition. Complete building. | |
| | 2.2.2 Roof accessories (i.e., ladders, stairs, hatches, masts, exhaust hoods, chimneys, gutters, downspouts, splashpads). | 4 | | Satisfactory | |
| | 2.2.3 Control of ice and snow falling from roof. | 4 | | No problem | |
| | 2.2.4 Skylights (i.e., signs of distress, leaks, ice build-up, condensation, deteriorated materials/seals). | NA | | No skylights | |
| Other | | | | | |

| Section 2 | Building Exterior | Rating | Comments/Concerns | | Estim. Cost |
|-----------|---|--------|----------------------|---|-------------|
| 2.3 | Exterior Walls/Building Envelope | | <u>Bldg. Section</u> | <u>Description/Condition</u> | |
| 2.3.1 | Exterior wall finishes (i.e., signs of deterioration, cracks, brick spalling, effluorescence, water stains). | 5 | Both | Exterior brick and siding in good condition | |
| 2.3.2 | Fascias, soffits, parapets (i.e., signs of looseness, stains, rust, peeling paint). | 5 | Both | Prefinished metal - good condition | |
| 2.3.3 | Building envelope (i.e., evidence of air infiltration/exfiltration through the exterior wall or ice build up on wall, eaves, canopy). | 4 | Both | none | |
| 2.3.4 | Interface of roof drainage and ground drainage systems. | 2 | Both | Down spouts - some ponding between building and sidewalk. Regrade where possible. See 1.1.6 | |
| 2.3.5 | Inside faces of exterior walls (i.e., signs of cracks, water stains, dust spots). | 4 | Both | None apparent | |
| | Other | | | | |
| 2.4 | Exterior Doors and Windows | | <u>Bldg. Section</u> | <u>Description/Condition</u> | |

| Section 2 | Building Exterior | Rating | Comments/Concerns | | Estim. Cost |
|--|---|--------|-------------------|-----------------------------------|-------------|
| 2.4.1 | Doors (i.e., signs of deterioration, rusting metal, glass cracks, peeling paint, damaged seals, sealed unit failure). | 4 | Both | Recent aluminum doors - adequate. | |
| 2.4.2 | Door accessories (i.e., latches, hardware, screens, locks, alarms, holders, closers, security devices). | 4 | Both | Adequate | |
| 2.4.3 | Exit door hardware (i.e., safety and/or code concerns). | 4 | Both | Older, but working satisfactorily | |
| 2.4.4 | Windows (i.e., signs of deterioration, rusting metal, glass cracks, peeling paint, damaged seals, sealed unit failure). | 5 | Both | Adequate. | |
| 2.4.5 | Window accessories (i.e., latches, hardware, screens, locks, alarms, holders, closers, security devices). | 5 | Both | Recent in good condition. | |
| 2.4.6 | Building envelope (i.e., signs of heavy condensation on doors or windows). | 4 | Both | None evident | |
| | Other | | | | |
| Overall Bldg Exterior Condition & Estim Costs | | | | | 0 |

| Section 3 | Building Interior - Overall Conditions | Rating | Comments/Concerns | | Estim. Cost |
|-----------|---|--------|----------------------|--|-------------|
| 3.1 | Interior Structure | | Bldg. Section | Description/Condition | |
| 3.1.1 | Interior walls and partitions (i.e., signs of cracks, spalling, paint peeling). | F.I. | 1952 | Generally good. However, some recent cracking at masonry junction with outside wall in stair/computer room and Gym office. Should be at least monitored. Requires Further Investigation. | |
| 3.1.2 | Floors (i.e., signs of cracks, heaving, settlement). | 4 | Both | None apparent | |
| | Other | | | | |
| 3.2 | Materials and Finishes | | Bldg. Section | | |
| 3.2.1 | Floor materials and finishes. | 1 | 1959 | Generally sheet vinyl and carpet in good condition throughout both sections. However, two classrooms and Science lab have vinyl tiles needing replacement or encapsulation. See 3.3.6. | |
| 3.2.2 | Wall materials and finishes. | 4 | Both | Mixture of giant brick and drywall, good condition. | |
| 3.2.3 | Ceiling materials and finishes. | 4 | Both | Some lay-in t-bar acoustic tile, some 12" square acoustic tile on drywall suspended ceiling. Metal slat ceiling in gym | |

| Section 3 | Building Interior - Overall Conditions | Rating | Comments/Concerns | | Estim. Cost |
|-----------|--|--------|----------------------|---|-------------|
| 3.2 | Materials and Finishes (cont'd) | | <u>Bldg. Section</u> | <u>Description/Condition</u> | |
| 3.2.4 | Interior doors and hardware. | 4 | Both | Adequate | |
| 3.2.5 | Millwork | 4 | Both | Mostly recent, in good order | |
| 3.2.6 | Fixed/wall mounted equipment (i.e., writing boards, tackboards, display boards, signs). | 4 | Both | Mostly recent, in good order | |
| 3.2.7 | Any other fixed/mounted specialty items (i.e., CTS equipment, gymnasium equipment). | 4 | Both | Fixed gym equipment, lockers in good condition | |
| 3.2.8 | Washroom materials and finishes. | 4 | Both | Floors: ceramic mosaic Walls: ceramic tiles to 7'0" Ceiling: drywall Toilet partitions in good shape | |
| Other | | | | | |
| 3.3 | Health and Safety Concerns --- <i>Intent is to identify renovations considered necessary to meet</i> | | <u>Bldg. Section</u> | | |

| Section 3 | Building Interior - Overall Conditions | Rating | Comments/Concerns | | Estim. Cost |
|--|--|--------|-------------------|--|--------------------|
| | <i>applicable codes, primarily due to safety concerns. Basis of evaluation should be an up-to-date inspection report from the authority having jurisdiction together with direct observations as appropriate. Evaluator should note if in his opinion a comprehensive code evaluation is required.</i> | NA | Both | No current report from Authorities having Jurisdiction. Comprehensive code evaluation not required at this time. See below for recommended code upgrades. | |
| 3.3.1 | Building construction type - combustible or non-combustible, sprinklered or non-sprinklered. | 4 | Both | Combustible, non-sprinklered. | |
| 3.3.2 | Fire separations (i.e., between buildings, wings, zones if non-sprinklered). | 1 | Both | Provide 1 hour separation at gym/south wing junction on both floors. | 4,000.00 |
| 3.3.3 | Fire resistance rating of materials (i.e., corridor walls and doors). | 1 | Both | Masonry walls provide corridor/classroom separation. Doors not rated, but solid on upper floor. Provide rated doors on lower floor to replace hollow doors. | 15,000.00 |
| 3.3.4 | Exiting distances and access to exits. | 4 | Both | Reasonable | |
| 3.3.5 | Barrier-free access. | 2 | Both | None at present. No challenged students at present. Requires handicap toilet for each sex. (Elevator/Chair Stair lift future considerations - not included.) | 6,000.00 |
| 3.3.6 | Availability of hazardous materials audit (i.e., evidence of safety concerns with respect to asbestos, PCB's, chemicals). | 3 | Both | Some vinyl asbestos tile in 3 rooms. Remove or encapsulate. Some asbestos pipe insulation. See Mechanical | 12,000.00 |
| 3.3.7 | Other health and safety concerns (i.e., evidence of excessive noise conditions, air quality problems) | 2 | Both | No artificial ventilation. See Mechanical | |
| Other | | 1 | Both | Balustrades to exit stairs not to code and hazardous. Replace. Provide 3/4 hour door, frame and hardware to Furnace Room | 5,000.00 |
| Overall Bldg Interior Condition & Estim Costs | | | | | \$42,000.00 |

| Section 4 | Mechanical Systems | Rating | Comments/Concerns | | Estim. Cost |
|-----------|--|--------|----------------------|--|-------------|
| | 4.1 Mechanical Site Services | | | | |
| | 4.1.1 Site drainage systems (i.e., surface and underground systems, catch basins). | 4 | Both | Drainage to surrounding surfaces. | |
| | 4.1.2 Exterior plumbing systems (i.e., irrigation systems, hose bibs). | 4 | Both | Underground irrigation for athaletic track; frost proof hose bibs. | |
| | 4.1.3 Outside storage tanks. | NA | Both | | |
| | Other | | | | |
| | 4.2 Fire Suppression Systems | | Bldg. Section | <u>Description/Condition</u> | |
| | 4.2.1 Fire hydrants and siamese connections. | NA | | | |
| | 4.2.2 Fire suppression systems (i.e., pumps, sprinklers, piping, reservoirs, hoses, stand pipes, CO2 systems). | NA | | | |
| | 4.2.3 Hand extinguishers, blankets and showers (i.e., in CTS areas). | 4 | Both | Hand fire extinguishers throughout | |
| | 4.2.4 Other special situations (e.g., flammable storage areas, science labs, CTS areas). | NA | | | |
| | Other | | | | |

| Section 4 | Mechanical Systems | Rating | Comments/Concerns | | Estim. Cost |
|-----------|---|--------|----------------------|---|-------------|
| | 4.3 Water Supply and Plumbing Systems | | Bldg. Section | <u>Description/Condition</u> | |
| | 4.3.1 Domestic water supply (i.e., pressure, volume, quality note whether municipal or well supply). | 4 | Both | Municipal treated water service | |
| | 4.3.2 Water treatment system(s). | 4 | Both | See 4.3.1 | |
| | 4.3.3 Pumps and valves (including backflow prevention valves). | NA | | | |
| | 4.3.4 Piping and fittings. | 4 | Both | copper pipe in good condition | |
| | 4.3.5 Plumbing fixtures (i.e., toilets, urinals, sinks) | 4 | Both | Plumbing fixtures replaced in approximately 1985. | |
| | 4.3.6 Domestic hot water system (i.e., heater, storage tanks, failure alarms, pressure, volume, recirculation). | 4 | Both | 240 volt electric domestic water heater, 6000 watt, 40 gallon capacity, installed in 1996. Has no recirculation system. | |
| | 4.3.7 Sanitary and storm sewers, including sumps and pits (note whether sewage system is municipal or septic). | 4 | Both | Municipal sanitary service. | |
| | Other | NA | | | |

| Section 4 | Mechanical Systems | Rating | Comments/Concerns | | Estim. Cost |
|-----------|---|--------|----------------------|---|-------------|
| | 4.4 Heating Systems | | <u>Bldg. Section</u> | <u>Description/Condition</u> | |
| | 4.4.1 Heating capacity and reliability (including backup capacity). | 4 | Both | 6 - Hydrotherm hot water boilers, MK 1800 BP, 168,000 input BTU each, installed in 1985. | |
| | 4.4.2 Heating controls (including use of current energy management technology). | 4 | Both | Controls replaced in 1985 with programable electric control, providing good zone control. Tie into BMS see cost 4.7.1 | |
| | 4.4.3 Fresh air for combustion and condition of the combustion chimney. | 4 | Both | Adequate. | |
| | 4.4.4 Treatment of water used in heating systems. | 4 | Both | Chemically treated by District forces. | |
| | 4.4.5 Low water cutoff/pressure relief valves and failure alarms (i.e., hot water heating). | 4 | Both | Boilers provided with low water cutoff and pressure relief valves. No alarms. | |
| | 4.4.6 Heating air filtration systems and filters. | NA | | | |
| | 4.4.7 Heating humidification systems and components. | NA | | | |

| Section 4 | Mechanical Systems | Rating | Comments/Concerns | | Estim. Cost |
|-----------|--|--------|----------------------|---|-------------|
| | 4.4 Heating Systems (cont'd) | | <u>Bldg. Section</u> | <u>Description/Condition</u> | |
| | 4.4.8 Heating distribution systems (i.e., piping, ductwork) and associated components (i.e., diffusers, radiators). | 4 | Both | hot water distribution piping and fin radiators replaced in 1985. | |
| | 4.4.9 Heating piping, valve and/or duct insulation. | 4 | Both | See 4.4.8 | |
| | 4.4.10 Heat exchangers. | NA | | | |
| | 4.4.11 Heating mixing boxes, dampers and linkages. | NA | | | |
| | 4.4.12 Heating distribution/circulation in larger spaces (i.e., user comfort, temperature of outside wall surfaces). | 4 | Both | Heat distribution for larger spaces is good. See 4.4.8 | |
| | 4.4.13 Zone/unit heaters and controls. | 4 | Both | Hot water entrance heaters. See 4.4.8 | |
| | Other | | | | |

| Section 4 | Mechanical Systems | Rating | Comments/Concerns | | Estim. Cost |
|-----------|---|--------|----------------------|--|-------------|
| 4.5 | Ventilation Systems | | <u>Bldg. Section</u> | <u>Description/Condition</u> | |
| 4.5.1 | Air handling units capacity and condition. | 2 | Both | No mechanical ventilation. | \$105,000 |
| 4.5.2 | Outside air for the occupant load (if possible, reference CFM/occupant). | 2 | Both | Cost included in 4.5.1. | |
| 4.5.3 | Air distribution system (if possible, reference number of air changes/hour). | 2 | Both | Cost included in 4.5.1. | |
| 4.5.4 | Exhaust systems capacity and condition. | 1 | Both | No exhaust systems for gymnasium or washrooms. Cost included in 4.5.1. | |
| 4.5.5 | Separation of out flow from air intakes. | 4 | Both | satisfactory | |
| 4.5.6 | Special/dedicated ventilation and/or exhaust systems (i.e., kitchen, labs, CTS areas). | 2 | Both | Kitchen requires exhaust system. Lab fume hood in good condition. | \$2,500 |
| Other | | | | | |
| 4.5 | Ventilation Systems (cont'd) | | <u>Bldg. Section</u> | <u>Description/Condition</u> | |
| | <i>Note: Only complete the following items if there are separate ventilation and heating systems.</i> | | | | |

| Section 4 | Mechanical Systems | Rating | Comments/Concerns | Estim. Cost |
|-----------|--|--------|----------------------------|-------------|
| 4.5.7 | Ventilation controls (including use of current energy management technology). | NA | No mechanical ventilation. | |
| 4.5.8 | Air filtration systems and filters. | NA | | |
| 4.5.9 | Humidification system and components. | NA | | |
| 4.5.10 | Heat exchangers. | NA | | |
| 4.5.11 | Ventilation distribution system and components (i.e., ductwork, diffusers, mixing boxes, dampers, linkages). | NA | | |
| Other | | | | |

| Section 4 | Mechanical Systems | Rating | Comments/Concerns | | Estim. Cost |
|-----------|---|--------|----------------------|--|--------------|
| 4.6 | Cooling Systems | | <u>Bldg. Section</u> | <u>Description/Condition</u> | |
| 4.6.1 | Cooling system capacity and condition (i.e., chillers, cooling towers, condensers). | NA | | No mechanical cooling systems. | |
| 4.6.2 | Cooling distribution system and components (i.e., ductwork, diffusers, mixing boxes, dampers, linkages) | NA | | | |
| 4.6.3 | Cooling system controls (including use of current energy management technology). | NA | | | |
| 4.6.4 | Special/dedicated cooling systems (i.e., labs, CTS areas). | NA | | | |
| Other | | | | | |
| 4.7 | Building Control Systems | | <u>Bldg. Section</u> | <u>Description/Condition</u> | |
| 4.7.1 | Building wide/system wide control systems and/or energy management systems. | 2 | Both | No building management system. Due to extent of ventilation upgrade provide DDC ventilation. | \$63,000 |
| | Overall Mech Systems Condition & Estim. Costs | | | | \$170,500.00 |

| Section 5 | Electrical Systems | Rating | Comments/Concerns | | Estim. Cost |
|-----------|--|--------|----------------------|--|-------------|
| 5.1 | Site Services | | | | |
| 5.1.1 | Primary service capacity and reliability (i.e., access, location, components, installation, bus sizes - note whether overhead or underground). | 3 | Both | 120/240v/1 phase/200 amp breaker/OH feed. Service upgrade required with ventilation upgraded. See 4.5.1. | \$25,000 |
| 5.1.2 | Site and building exterior lighting (i.e., safety concerns). | 4 | Both | Good HPS perimeter lighting | |
| 5.1.3 | Vehicle plug-ins (i.e., number, capacity, condition). | 4 | Both | Three duplex outlets on wooden rail in good condition. | |
| | Other | | | | |
| 5.2 | Life Safety Systems | | Bldg. Section | <u>Description/Condition</u> | |
| 5.2.1 | Fire and smoke alarm systems (i.e., safety concerns, up to-date technology, regularly tested). | 5 | Both | Edwards 6616 fire alarm panel. Tested regularly. | |
| 5.2.2 | Emergency lighting systems (i.e., safety concerns, condition). | 4 | Both | Adequate | |
| 5.2.3 | Exit lighting and signage (i.e., safety concerns, condition). | 4 | Both | Adequate | |
| | Other | | | | |

| Section 5 | Electrical Systems | Rating | Comments/Concerns | | Estim. Cost |
|-----------|--|--------|-------------------|---|-------------|
| | 5.3 Power Supply and Distribution | | Bldg. Section | Description/Condition | |
| | 5.3.1 Power service surge protection. | NA | | | |
| | 5.3.2 Panels and wireways capacity and condition. | 2 | Both | Two old original fuse panels accessible to students. Additional panel will be required to service ventilation upgrade. | \$3,000 |
| | 5.3.3 Emergency generator capacity and condition and/or UPS (if applicable). | NA | | | |
| | 5.3.4 General wiring devices and methods. | 4 | Both | Most devices have been upgraded within the last 10 years. Exterior lighting and receptacle panel requires fastening and a lock. | |
| | 5.3.5 Motor controls. | 4 | Both | Devices are older but still functional. Additional motor starters will be required during the ventilation upgrade. | \$2,500 |
| | Other | | | | |

| Section 5 | Electrical Systems | Rating | Comments/Concerns | | Estim. Cost |
|-----------|---|--------|----------------------|---|-------------|
| | 5.4 Lighting Systems | | <u>Bldg. Section</u> | <u>Description/Condition</u> | |
| | 5.4.1 Interior lighting systems and components (i.e., illumination levels, conditions, controls). | 3 | Both | 6-HPS lights provide yellow light and 100-200 lux. This is insufficient. T-12 lamps, located in hallways, 300-500 lux, T-12 lamps located in hallways and office. Classrooms, library and staff room have T-8 lamps. Cost shown provides for new lighting in gymnasium. | \$18,000 |
| | 5.4.2 Replacement of ballasts (i.e., health and safety concerns). | 4 | Both | Fixtures and ballast replaced by maintenance as required. | |
| | 5.4.3 Implementation of energy efficiency measures and recommendations. | 3 | Both | Upgrade hallways and office to T- 8 lighting. | \$18,000 |
| | Other | | | | |

| Section 5 | Electrical Systems | Rating | Comments/Concerns | | Estim. Cost |
|-----------|--|--------|----------------------|---|-------------|
| | 5.5 Network and Communication Systems | | Bldg. Section | <u>Description/Condition</u> | |
| | 5.5.1 Telephone system and components (i.e., capacity, reliability, condition). | 4 | Both | Meridian phone system approximately 8 years old. | |
| | 5.5.2 Other communication systems (i.e., public address, intercom, CCTV, satellite or cable TV). | 2 | Both | Original P.A. system Rauland. Malfunctioning, does not work in several classrooms. | \$20,000 |
| | 5.5.3 Network cabling (if available, should be category 5 or better). | 5 | Both | Cat 5 cable. | |
| | 5.5.4 Network cabling installation (i.e., in conduit, secured to walls or tables). | 5 | Both | Concealed in ceiling space or in conduit where exposed. | |
| | 5.5.5 Wiring and telecommunication closets (i.e., size, security, ventilation/cooling, capacity for growth). | 5 | Both | Network closet has capacity for growth. No equipment installed at present. Ventilation is required in cabinet (see 4.5.6) | |
| | 5.5.6 Provision for dedicated circuits for network equipment (i.e., hubs, switches, computers). | 3 | Both | No dedicated panel or circuits. Cost included in 5.3.2. | |
| | Other | | | | |

| Section 5 | Electrical Systems | Rating | Comments/Concerns | | Estim. Cost |
|-----------|--|--------|----------------------|---|-------------|
| | 5.6 Miscellaneous Systems | | Bldg. Section | <u>Description/Condition</u> | |
| | 5.6.1 Site and building surveillance system (if applicable). | NA | | | |
| | 5.6.2 Intrusion alarms (if applicable). | 4 | Both | AAA keypad security with motion detectors. Library requires a motion detector. No callout to alarm company. | |
| | 5.6.3 Master clock system (if applicable). | NA | | | |
| | Other | | | | |
| | 5.7 Elevators/Disabled Lifts (If applicable) | | | | |
| | 5.7.1 Elevator/lift size, access and operating features (i.e., sensing devices, buttons, phones, detectors). | NA | | No elevators. | |
| | 5.7.2 Condition of elevators/lifts. | NA | | | |
| | 5.7.3 Lighting and ventilation of elevators/lifts. | NA | | | |
| | Other | | | | |
| | Overall Elect. Systems Condition & Estim Costs | | | | \$86,500 |

| Section 6 | Portable Buildings | Rating | Comments/Concerns | Estim. Cost |
|---|--|--------|-------------------|-------------|
| | <i>Note: Separate sheets can be completed, if necessary, for portable buildings of different ages and/or conditions.</i> | NA | | |
| 6.1.1 | Foundation and structure (i.e., signs of bending, cracking, settlement, rust, voids, stains). | | | |
| 6.1.2 | Roof materials and components (i.e., signs of deterioration, leaks, ice build-up). | | | |
| 6.1.3 | Exterior wall finishes (i.e., signs of deterioration, cracks, water stains). | | | |
| 6.1.4 | Doors and windows (i.e., signs of deterioration, rusting hardware, glass cracks, peeling paint, damaged seals). | | | |
| 6.1.5 | Interior finishes (i.e., floors, walls, ceiling). | | | |
| 6.1.6 | Millwork (i.e., counters, shelving, vanities, cabinets). | | | |
| 6.1.7 | Fixed/wall mounted equipment (i.e., writing boards, tackboards, display boards, signs) | | | |
| 6.1.8 | Heating system. | | | |
| 6.1.9 | Ventilation system. | | | |
| 6.1.10 | Electrical, communication and data network systems. | | | |
| 6.1.11 | Health and safety concerns (i.e., fire and smoke alarms, fire protection systems, exiting, fire resistance rating of materials). | | | |
| 6.1.12 | Barrier-free access. | | | |
| Overall Portable Bldgs Condition & Estim Costs | | | | 0.00 |

| Section 7 | Space Adequacy | This Facility | | | Equiv. New Facility | | | Surplus/ Deficiency | Comments/Concerns |
|-----------|--|---------------|------------------------------|------------|---------------------|------------------------|------------|------------------------|--|
| | | No. | Size | Total Area | No. | Size | Total Area | | |
| 7.1 | Classrooms | 8 | varies | 571.12 | 6 | 80.0 | 480.0 | 91.1 | This is based on Assessed capacity of 300 and rated Junior High. Current enrollment is 100. Suggest reducing capacity to 200 Junior High rating. |
| 7.2 | Science Rooms/Labs | 1 | 88.0 | 88.0 | 2 | 120.0 | 240.0 | -152.0 | |
| 7.3 | Ancillary Areas (i.e., Art, Computer Labs, Drama, Music,) | 1 | 82.4 | 211.50 | 1 | 130.0 | 310.0 | -98.5 | |
| | | 1 | 89.7 | | 2 | 90.0 | | | |
| | | 1 | 69.4 | | | | | | |
| 7.4 | Gymnasium (incl. gym storage) | 1 | 244.0 | 244.0 | 1 | 473.0 | 473.0 | -229.0 | |
| 7.5 | Library/Resource Areas | 1 | 131.90 14.6 | 146.5 | 1 | 150.0 | 150.0 | -3.5 | |
| 7.6 | Administration/Staff, Physical Education, Storage Areas | | 67.5 19.4 36.0 51.9 | 174.8 | | 247.0 100.0 62.0 | 409.0 | -234.2 | |
| 7.7 | CTS Areas | | | | | | | | |
| | 7.7.1 Business Education | | | 0 | 1 | 115.0 | 115.0 | -115.0 | |
| | 7.7.2 Home Economics | | | | | | | | |
| | 7.7.3 Industrial Arts | | | | p | | | | |
| | 7.7.4 Other CTS Programs | | | | | | | | |
| 7.8 | Other Non-Instructional Areas (i.e., circulation, wall area, crush space, wc area) | | | 658.6 | | 442 212 72 36 | 762.0 | -103.4 | |
| | Overall Space Adequacy Assessment | 14 | | 2094.5 | 14 | | 2939.0 | -844.5 | |

| Evaluation Component/ Sub-Component | Additional Notes and Comments |
|--|-------------------------------|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

| Evaluation Component/ Sub-Component | Additional Notes and Comments |
|--|-------------------------------|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

| Evaluation Component/ Sub-Component | Additional Notes and Comments |
|--|-------------------------------|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

| Evaluation Component/ Sub-Component | Additional Notes and Comments |
|--|-------------------------------|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

| Evaluation Component/ Sub-Component | Additional Notes and Comments |
|--|-------------------------------|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

| Evaluation Component/ Sub-Component | Additional Notes and Comments |
|--|-------------------------------|
| | |
| | |