CHIEF JUSTICE MILVAIN ELEMENTARY SCHOOL CALGARY, ALBERTA

School Facility Evaluation Project Calgary School Board, District 19



Prepared For Alberta Infrastructure March 2000

Prepared By Bernbaum Architect Ltd. Rae Mclean & Associates

TABLE OF CONTENTS

	Page
Executive Summary	i
Facility Profile and Summary	1
Section 1 – Site Conditions	4
Section 2 – Building Exterior	7
Section 3 – Building Interior	11
Section 4 – Mechanical Systems	14
Section 5 – Electrical Systems	21
Section 6 – Portable Buildings	26
Section 7 – Space Adequacy	27
Mini Plans	Ai

Evaluation Team

Architectural
Bernbaum Architect Ltd.
511 Sonora Avenue S.W.
Calgary, Alberta T3C 2K1

Phone: (403) 244-5016 Fax: (403) 245-6958

Mechanical/Electrical Rae Mclean & Associates 207-6036-3rd St. S.W. Calgary, Alberta T2H 0H9

Phone: (403) 259-6716 Fax: (403) 252-0160

Chief Justice Milvain Elementary School Calgary South, District 19	School Facilities Evaluation Project March 2000
busibaum@home.com	rma@ab.imag.net

Chief Justice Milvain Elementary School Calgary South, District 19

School Facilities Evaluation Project March 2000

EXECUTIVE SUMMARY:

In January 2000, Alberta Infrastructure engaged Bernbaum Architect Ltd. to evaluate the condition of twenty one schools within the Calgary School Board District 19. A standardized form developed by Alberta Infrastructure and supplied to the evaluation team by the regional co-ordinator was used to document the condition and recommendations.

The original building for Chief Justice Milvain Elementary was constructed in 1981, and is a one storey building. The portables were added the same year, and are the only addition. The school is a well-maintained building and serves the students and staff quite efficiently. The architect has used upper clear story lighting to good advantage in the library area.

Summary of Observations and Recommendations

Architectural

The major concerns are related to maintenance items such as carpet, painting, caulking, etc. These should be done to keep the building in good condition. The school is close to being barrier free accessible in and out, with some modifications required to make the school fully accessible. Recommendations also include new windows and doors.

Mechanical

The mechanical system is typical of a 1980s school and in generally good condition. Some storage rooms have been converted to teaching areas and require attention, as they have no ventilation, otherwise only minor problems exist. We have recommended the scheduling for replacement of mechanical equipment.

Electrical

Electrically the system is of 1980s era and in good repair, although the exit lights should be upgraded. We recommend the upgrading of the technology.

Chief Justice Milvain Elementary School Calgary South, District 19

Costing

The estimated costs for the remedial work in the attached evaluation from has been based on the Costing Unit Rate Chart developed by Alberta Infrastructure. Where this data is incomplete or inappropriate to the recommended work, unit costs based on the local Calgary market were used.

1. 2.	Site Related Work Building Exterior	\$ \$	38,000. 240,900.
3.	Building Interior	\$	137,000.
4.	Mechanical Systems	\$	775,986.
5.	Electrical Systems	\$	157,600.
6.	Portables	\$	10,300.
	Total Estimated Costs	\$	1,359,786.

Space Adequacy

The existing area according to School Building Area Guidelines and Supplement – Maximum Gross Area of School Building Projects is slightly more than recommended.

Existing Total Gross Area	3,054.77 sm
Recommended total gross area	3,983.00 sm
Overage / (deficiency)	(928.23) sm

Chief Justice Milvain Elementary School Calgary South, District 19

School Facilities Evaluation Project March 2000

Further Investigation

Further Investigation is required to understand the following:

Investigate state of the roof as no report was available and the leaks are a continuing problem; investigate the hazardous materials in the school.

School Plan Data Information

The plan information was supplied by the school jurisdiction. Area information was provided by Alberta Infrastructure. The information generally appears to be up to date, with minor room function variations.