

School Name:		Eagle Butte High School				School Code:	5905
Location:		Dunmore				Facility Code:	222
Region:		South				Superintendent:	Keith Jones
Jurisdiction:		Prairie Rose Regional Div. #8				Contact Person:	Brian Frey
						Telephone:	403-527-5516
Grades:		10 to 12				School Capacity:	590
							1999 enrollment 422
Building Section		Year of Compl.	No. of Floors	Gross Bldg Area (Sq.M.)	Type of Construction (i.e., structure, roof, cladding)	Description of Mechanical Systems (incl. major upgrades)	Comments/Notes
Original Building							
		1995	1	4736	Wood frame, pitched roof, stucco exterior	Single boiler with radiant panels, force flows and unit heaters. Roof top units with DX cooling and gas fired heating.	Site landscaping is bermed up exterior walls to window sill height. This is a design feature of the school.
Additions/ Expansions							
						Part of above.	
				0	Portables		
				4736	Total Area		
						Evaluator's Name:	A. Benson
						& Company:	CJC Architects Inc.

Upgrading/ Modernization (identify whether minor or major)	N/A					
Portable Struct. (identify whether attached/perman. or free- standing/ relocatable)	N/A					
List of Reports/ Supplementary Information				Mini plans provided by Jurisdiction. No reports available. A metal storage shed (24m x 26m) is located at the south side of the building, same age as school.		

	Evaluation Components	Summary Assessment		Estim. Cost
1	Site Conditions	Additional sidewalk required at bus lane. Further investigation recommended concerning easy access to roof liability.		\$3,000
2	Building Exterior	Measures to control snow and ice falling from roof.		\$5,000
3	Building Interior	Some wall cracks. Further investigations recommended for code evaluation and hazardous materials audit.		\$5,000
4	Mechanical Systems	New mechanical systems, however classrooms are too noisy and system only has one boiler (no standby). Access to roof top units is poor and other problems exist. Further investigation required concerning sewer gas smell at east end of School.		\$59,550
5	Electrical Systems	New electric system, however lighting in several classrooms and library is poor and should be improved and ITS room is very warm.		\$28,700
6	Portable Buildings			\$0
7	Space Adequacy:			
	7.1 Classrooms	Sufficient classrooms.	6	
	7.2 Science Rooms/Labs	Deficient by one (1) lab.	-163	
	7.3 Ancillary Areas	Deficient by one (1) room.	-158	
	7.4 Gymnasium	51m ² surplus in gym, 31m ² storage deficiency	20	
	7.5 Library/Resource Areas	82m ² deficiency in library, but large lunch/study area.	61	
	7.6 Administration/Staff Areas	48m ² Phys. Ed deficiency, 48m ² storage deficiency, 155m ² Administration deficiency.	-251	
	7.7 CTS Areas	149m ² Bus. Ed deficiency, 11m ² Home Ec deficiency, 66m ² Ind. Art deficiency.	-226	
	7.8 Other Non-Instructional Areas (incl. gross-up)	General deficiency.	-416	
	Overall School Conditions & Estim. Costs			\$101,250

Section 1	Site Conditions	Rating	Comments/Concerns	Estim. Cost
1.1	General Site Conditions			
1.1.1	Overall site size.	4	There is limited site area for expansion.	
1.1.2	Outdoor athletic areas.	4	Play fields and running track satisfactory.	
1.1.3	Outdoor playground areas, including condition of equipment and base.	N/A		
1.1.4	Site landscaping.	4	Grass, irrigated, outdoor amphitheater.	
1.1.5	Site accessories (i.e., perimeter and other fencing, guard rails, bike stands, flag poles).	4	Barbed wire, fence a perimeter.	
1.1.6	Surface drainage conditions (i.e., drains away from building, signs of ponding).	4	The entire building has grass berming up to window sill line, an apparent design feature. It is reported that this caused seepage in the beginning, however, was rectified.	
1.1.7	Evidence of sub-soil problems.	4	None noted.	
1.1.8	Safety and security concerns due to site conditions.	F.I.	Easy unauthorized access to roof due to bermed wall design	
Other				

Section 1	Site Conditions	Rating	Comments/Concerns	Estim. Cost
1.2	Access/Drop-Off Areas/Roadways/Bus Lanes			
1.2.1	Vehicular and pedestrian access points (i.e., size, number, visibility, safety).	4	1 access point, adequate	
1.2.2	Surfacing of on-site road network (note whether asphalt or gravel).	4	Asphalt	
1.2.3	Bus lanes/drop-off areas (note whether on-site or off-site).	3	On-site, needs additional sidewalk to access full quota of buses	\$3,000
1.2.4	Fire vehicle access.	4	Access to building north face (front) and 1/4 of south face	
1.2.5	Signage.	4	On building, visible	
Other				

Section 1	Site Conditions	Rating	Comments/Concerns	Estim. Cost
1.3	Parking Lots and Sidewalks			
1.3.1	Number of parking spaces for staff, students and visitors (including stalls for disabled persons).	4	43 parking spaces	
1.3.2	Layout and safety of parking lots.	5		
1.3.3	Surfacing and drainage of parking lots (note whether asphalt or gravel).	4	Asphalt surface drainage, no apparent problems	
1.3.4	Layout and safety of sidewalks.	4	Refer to Item 1.2.3 above	
1.3.5	Surfacing and drainage of sidewalks (note type of material).	4	Concrete ok, drainage ok	
1.3.6	Curb cuts and ramps for barrier free access.	4	Access satisfactory	
Other				
	Overall Site Conditions & Estimated Costs			\$3,000

Section 2	Building Exterior	Rating	Comments/Concerns		Estim. Cost
2.1	Overall Structure		Bldg. Section	Description/Condition	
	2.1.1 Floor structure and beams (i.e., signs of bending, cracking, heaving, settlement, voids, rust, stains).	4	1995	Slab on grade, no apparent problems	
	2.1.2 Wall structure and columns (i.e., signs of bending, cracking, settlement, voids, rust, stains).	4	1995	Wood frame construction, no apparent problems	
	2.1.3 Roof structure (i.e., signs of bending, cracking, voids, rust, stains).	4	1995	Pitched roof, wood frame construction, no apparent problems	
	2.1.4 Control/expansion joints.	N/A			
Other					

Section 2	Building Exterior	Rating	Comments/Concerns		Estim. Cost
2.2	Roofing and Skylights <i>Identify the availability of an up-to-date inspection report or roofing program. Note if roof sections are of different ages and/or in varying states of repair.</i>		Bldg. Section or Roof Section	Description/Condition/Age	
2.2.1	Based on the inspection report (and to the extent possible, direct observation), assess and rate roof conditions and estimate costs for required improvements (i.e., covering materials, membrane, insulation, other components).	4	1995	Asphalt shingles 5 years old	
2.2.2	Roof accessories (i.e., ladders, stairs, hatches, masts, exhaust hoods, chimneys, gutters, downspouts, splashpads).	4	1995	Appear to be satisfactory except see Item 2.2.3 below	
2.2.3	Control of ice and snow falling from roof.	2	1995	Iceing problem at entrances, eaves trough length needs to be extended and heat-tracing added	\$5,000
2.2.4	Skylights (i.e., signs of distress, leaks, ice build-up, condensation, deteriorated materials/seals).	N/A	1995	None	
Other					

Section 2	Building Exterior	Rating	Comments/Concerns		Estim. Cost
2.3	Exterior Walls/Building Envelope		Bldg. Section	Description/Condition	
2.3.1	Exterior wall finishes (i.e., signs of deterioration, cracks, brick spalling, effluorescence, water stains).	4	1995	Stucco	
2.3.2	Fascias, soffits, parapets (i.e., signs of looseness, stains, rust, peeling paint).	4	1995	Metal	
2.3.3	Building envelope (i.e., evidence of air infiltration/exfiltration through the exterior wall or ice build up on wall, eaves, canopy).	4	1995	No apparent problems	
2.3.4	Interface of roof drainage and ground drainage systems.	4	1995	Rainwater leaders and splashpads	
2.3.5	Inside faces of exterior walls (i.e., signs of cracks, water stains, dust spots).	4	1995	No apparent problems	
Other					

Section 2	Building Exterior	Rating	Comments/Concerns		Estim. Cost
2.4	Exterior Doors and Windows		Bldg. Section	Description/Condition	
2.4.1	Doors (i.e., signs of deterioration, rusting metal, glass cracks, peeling paint, damaged seals, sealed unit failure).	4	1995	Metal doors and frames	
2.4.2	Door accessories (i.e., latches, hardware, screens, locks, alarms, holders, closers, security devices).	4	1995	No apparent problems	
2.4.3	Exit door hardware (i.e., safety and/or code concerns).	4	1995	Appropriate hardware	
2.4.4	Windows (i.e., signs of deterioration, rusting metal, glass cracks, peeling paint, damaged seals, sealed unit failure).	4	1995	Aluminum windows, no apparent problems	
2.4.5	Window accessories (i.e., latches, hardware, screens, locks, alarms, holders, closers, security devices).	4	1995	No apparent problems	
2.4.6	Building envelope (i.e., signs of heavy condensation on doors or windows).	4	1995	No problems noted	
Other					
	Overall Bldg Exterior Condition & Estim Costs				\$5,000

Section 3	Building Interior - Overall Conditions	Rating	Comments/Concerns		Estim. Cost
3.1	Interior Structure		<u>Bldg. Section</u>	<u>Description/Condition</u>	
	3.1.1 Interior walls and partitions (i.e., signs of cracks, spalling, paint peeling).	3	1995	Generally drywall, good condition. Gym: minor cracking in concrete block	\$5,000
	3.1.2 Floors (i.e., signs of cracks, heaving, settlement).	4	1995	Concrete slab on grade, no apparent problems	
	Other				
3.2	Materials and Finishes		<u>Bldg. Section</u>	<u>Description/Condition</u>	
	3.2.1 Floor materials and finishes.				
		4	1995	12 x 12 V.C. Tile typically, gym: hardwood c/w vented base	
	3.2.2 Wall materials and finishes.	4	1995	Drywall painted typically, P/LAM wainscott in corridors, concrete block in gym painted	
	3.2.3 Ceiling materials and finishes.				
		4	1995	Drywall typically, 2 x 4 acoustic tile in corridors, gym: exposed steel structure painted	

Section 3	Building Interior - Overall Conditions	Rating	Comments/Concerns		Estim. Cost
3.2	Materials and Finishes (cont'd)		<u>Bldg. Section</u>	<u>Description/Condition</u>	
3.2.4	Interior doors and hardware.	4	1995	Solid core wood door in P/S frames	
3.2.5	Millwork	4	1995	Millwork appears to be satisfactory	
3.2.6	Fixed/wall mounted equipment (i.e., writing boards, tackboards, display boards, signs).	4	1995	Appears to be satisfactory	
3.2.7	Any other fixed/mounted specialty items (i.e., CTS equipment, gymnasium equipment).	4	1995	Back stops in gym satisfactory	
3.2.8	Washroom materials and finishes.	4	1995	Marmoleum	
				C.T. walls & paint	
				Drywall ceilings painted	
				All materials appropriate	
Other					

Section 3	Building Interior - Overall Conditions	Rating	Comments/Concerns		Estim. Cost
3.3	Health and Safety Concerns --- Intent is to identify renovations considered necessary to meet applicable codes, primarily due to safety concerns. Basis of evaluation should be an up-to-date inspection report from the authority having jurisdiction together with direct observations as appropriate. Evaluator should note if in his opinion a comprehensive code evaluation is required.		Bldg. Section	Description/Condition	
		F.I.	1995	The building area appears to greatly exceed code limits for a non-sprinklered building. It may be that masonry firewalls are provided to separate the building into conforming areas, but this was not apparent.	
3.3.1	Building construction type - combustible or non-combustible, sprinklered or non-sprinklered.	4	1995	Combustible construction, non-sprinklered	
3.3.2	Fire separations (i.e., between buildings, wings, zones if non-sprinklered).	F.I.	1995	Refer to Item 3.3 above	
3.3.3	Fire resistance rating of materials (i.e., corridor walls and doors).	4	1995	Gypsum board walls and metal doors and frames would appear to be appropriate	
3.3.4	Exiting distances and access to exits.	F.I.	1995	Refer to Item 3.3 above	
3.3.5	Barrier-free access.	4	1995	H/C door operators at entrance has been provided.	
3.3.6	Availability of hazardous materials audit (i.e., evidence of safety concerns with respect to asbestos, PCB's, chemicals).	F.I.	1995	No information available	
3.3.7	Other health and safety concerns (i.e., evidence of excessive noise conditions, air quality problems)				
Other					
	Overall Bldg Interior Condition & Estim Costs				\$5,000

Section 4	Mechanical Systems	Rating	Comments/Concerns		Estim. Cost
4.1	Mechanical Site Services				
	4.1.1 Site drainage systems (i.e., surface and underground systems, catch basins).	4		Surface drainage. Need to improve water control at downspouts to prevent surface erosion and improve downspout at southwest corner.	
	4.1.2 Exterior plumbing systems (i.e., irrigation systems, hose bibs).	4		Two irrigation systems. Area adjacent to school from city water, areas farther away from St. Mary irrigation canal (Bullhead Creek).	
	4.1.3 Outside storage tanks.	N/A			
	Other	N/A			
4.2	Fire Suppression Systems		Bldg. Section	Description/Condition	
	4.2.1 Fire hydrants and siamese connections.	4		Fire hydrant (non-pressurized) from open reservoir located on property. Pump to fill reservoir is located on Bullhead Creek (several kilometers west of school).	
	4.2.2 Fire suppression systems (i.e., pumps, sprinklers, piping, reservoirs, hoses, stand pipes, CO2 systems).	N/A		No fire hose cabinets.	
	4.2.3 Hand extinguishers, blankets and showers (i.e., in CTS areas).	4		Fire extinguishers tested October 1999	
	4.2.4 Other special situations (e.g., flammable storage areas, science labs, CTS areas).	N/A			
	Other	N/A			

Section 4	Mechanical Systems	Rating	Comments/Concerns		Estim. Cost
4.3	Water Supply and Plumbing Systems		Bldg. Section	Description/Condition	
4.3.1	Domestic water supply (i.e., pressure, volume, quality - note whether municipal or well supply).	4		City of Medicine Hat	
4.3.2	Water treatment system(s).	4		By City of Medicine Hat	
4.3.3	Pumps and valves (including backflow prevention valves).	2		No back flow on two zones of irrigation (re-piping required), pump on reservoir (as well as at creek, see also 4.2.1 above)	\$1,000
4.3.4	Piping and fittings.	4		New school	
4.3.5	Plumbing fixtures (i.e., toilets, urinals, sinks)	4		New school	
4.3.6	Domestic hot water system (i.e., heater, storage tanks, failure alarms, pressure, volume, recirculation).	4		Two AO Smith 266,000 BTU/HR 80 gallon recirculation pump. North holding tank cannot be changed without shutting down hot water system.	
4.3.7	Sanitary and storm sewers, including sumps and pits (note whether sewage system is municipal or septic).	3		Septic field. Only one septic pump. Add additional pump.	\$2,500
Other		FI		Sewer gas smell in east end of school plumbing. Plumbing vent is adjacent to roof top unit.	

Section 4	Mechanical Systems	Rating	Comments/Concerns		Estim. Cost
4.4	Heating Systems		Bldg. Section	Description/Condition	
4.4.1	Heating capacity and reliability (including backup capacity).	3		One boiler Superhot 1,080,000 BTU/HR two pumps. Consider adding second boiler.	\$15,000
4.4.2	Heating controls (including use of current energy management technology).	4		Landis & Staefa DDC	
4.4.3	Fresh air for combustion and condition of the combustion chimney.	3		Combustion air with skirt no relief air	\$750
4.4.4	Treatment of water used in heating systems.	4		Pot feeder and micron filter	
4.4.5	Low water cut-off/pressure relief valves and failure alarms (i.e., hot water heating).	4		New school	
4.4.6	Heating air filtration systems and filters.	4		Filtering in roof top units	
4.4.7	Heating humidification systems and components.	4		Humidification only on gym system	

Section 4	Mechanical Systems	Rating	Comments/Concerns		Estim. Cost
4.4	Heating Systems (cont'd)		Bldg. Section	Description/Condition	
4.4.8	Heating distribution systems (i.e., piping, ductwork) and associated components (i.e., diffusers, radiators).	4		Radiant panels, force flows and unit heaters.	
4.4.9	Heating piping, valve and/or duct insulation.	4		New school	
4.4.10	Heat exchangers.	N/A			
4.4.11	Heating mixing boxes, dampers and linkages.	4		No noted problems	
4.4.12	Heating distribution/circulation in larger spaces (i.e., user comfort, temperature of outside wall surfaces).	4		Temperatures appear uniform	
4.4.13	Zone/unit heaters and controls.	4		Thermostat per classroom	
Other		N/A			

Section 4	Mechanical Systems	Rating	Comments/Concerns		Estim. Cost
4.5	Ventilation Systems		Bldg. Section	Description/Condition	
4.5.1	Air handling units capacity and condition.	4		Multiple new EngA heating/cooling units - access a problem five units do not have permanent access and two units are blocked by ductwork, parapets, etc.	
4.5.2	Outside air for the occupant load (if possible, reference CFM/occupant).	4		Appears okay	
4.5.3	Air distribution system (if possible, reference number of air changes/hour).	4		Appears okay	
4.5.4	Exhaust systems capacity and condition.	4		Appears okay	
4.5.5	Separation of out flow from air intakes.	4		Appears okay	
4.5.6	Special/dedicated ventilation and/or exhaust systems (i.e., kitchen, labs, CTS areas).	3		Need four kitchen hoods in CTS and one in kitchen	\$2,800
Other		3		Classrooms very noisy. Consider changing supply air grills to reduce air handling noise.	\$37,500

Section 4	Mechanical Systems	Rating	Comments/Concerns		Estim. Cost
4.5	Ventilation Systems (cont'd)		Bldg. Section	Description/Condition	
	<i>Note: Only complete the following items if there are separate ventilation and heating systems.</i>				
4.5.7	Ventilation controls (including use of current energy management technology).	N/A		Not separate system	
4.5.8	Air filtration systems and filters.	N/A		Not separate system	
4.5.9	Humidification system and components.	N/A		Not separate system	
4.5.10	Heat exchangers.	N/A		Not separate system	
4.5.11	Ventilation distribution system and components (i.e., ductwork, diffusers, mixing boxes, dampers, linkages).	N/A		Not separate system	
Other		N/A			

Section 4	Mechanical Systems	Rating	Comments/Concerns		Estim. Cost
4.6	Cooling Systems		Bldg. Section	Description/Condition	
4.6.1	Cooling system capacity and condition (i.e., chillers, cooling towers, condensers).	4		Part of above roof top unit system	
4.6.2	Cooling distribution system and components (i.e., ductwork, diffusers, mixing boxes, dampers, linkages)	4		Part of above roof top unit system	
4.6.3	Cooling system controls (including use of current energy management technology).	4		Landis & Staefa DDC	
4.6.4	Special/dedicated cooling systems (i.e., labs, CTS areas).	N/A			
Other		N/A			
4.7	Building Control Systems		Bldg. Section	Description/Condition	
4.7.1	Building wide/system wide control systems and/or energy management systems.	4		Landis & Staefa DDC	
	Overall Mech Systems Condition & Estim. Costs				\$59,550

Section 5	Electrical Systems	Rating	Comments/Concerns		Estim. Cost
5.1	Site Services				
5.1.1	Primary service capacity and reliability (i.e., access, location, components, installation, bus sizes - note whether overhead or underground).	4		400amp 347/600/60/3	
5.1.2	Site and building exterior lighting (i.e., safety concerns).	4		HID	
5.1.3	Vehicle plug-ins (i.e., number, capacity, condition).	3		27 duplex all in good condition except need one new post and new cap	\$1,200
Other		N/A			
5.2	Life Safety Systems		Bldg. Section	Description/Condition	
5.2.1	Fire and smoke alarm systems (i.e., safety concerns, up to-date technology, regularly tested).	5		Edwards add resuable	
5.2.2	Emergency lighting systems (i.e., safety concerns, condition).	4		Battery packs and remote heads	
5.2.3	Exit lighting and signage (i.e., safety concerns, condition).	4		Exit lights tied into battery packs	
Other		N/A			

Section 5	Electrical Systems	Rating	Comments/Concerns		Estim. Cost
5.3	Power Supply and Distribution		Bldg. Section	Description/Condition	
5.3.1	Power service surge protection.	4		Power bars	
5.3.2	Panels and wireways capacity and condition.	4		New school	
5.3.3	Emergency generator capacity and condition and/or UPS (if applicable).	N/A			
5.3.4	General wiring devices and methods.	4		New school	
5.3.5	Motor controls.	4		New school	
Other		N/A			

Section 5	Electrical Systems	Rating	Comments/Concerns		Estim. Cost
5.4	Lighting Systems		Bldg. Section	Description/Condition	
5.4.1	Interior lighting systems and components (i.e., illumination levels, conditions, controls).	3		Classroom 16-106FC (worst - fluorescent) (1), classroom 40-92FC (typical - fluorescent), office 40-80FC (fluorescent), gym 30-40FC (HID), library 11-60FC (fluorescent) (2). 1. Very high contrast in classrooms. 2. Library light poor in stack areas.	\$25,000
5.4.2	Replacement of ballasts (i.e., health and safety concerns).	5		T-8 technology except gym which is HID.	
5.4.3	Implementation of energy efficiency measures and recommendations.	5		T-8 technology except gym which is HID.	
Other		N/A			

Section 5	Electrical Systems	Rating	Comments/Concerns		Estim. Cost
5.5	Network and Communication Systems		Bldg. Section	Description/Condition	
5.5.1	Telephone system and components (i.e., capacity, reliability, condition).	4		Meridian. Telephone in each classroom	
5.5.2	Other communication systems (i.e., public address, intercom, CCTV, satellite or cable TV).	4		Satellite and intercom	
5.5.3	Network cabling (if available, should be category 5 or better).	4		Category 5	
5.5.4	Network cabling installation (i.e., in conduit, secured to walls or tables).	4		Neatly done	
5.5.5	Wiring and telecommunication closets (i.e., size, security, ventilation/cooling, capacity for growth).	2		Separate room contains telephone switchgear and information services equipment. Very warm	\$2,500
5.5.6	Provision for dedicated circuits for network equipment (i.e., hubs, switches, computers).	4		Appears good with space for growth.	
Other		N/A			

Section 5	Electrical Systems	Rating	Comments/Concerns		Estim. Cost
5.6	Miscellaneous Systems		Bldg. Section	Description/Condition	
5.6.1	Site and building surveillance system (if applicable).	N/A			
5.6.2	Intrusion alarms (if applicable).	4		DSC All Knight	
5.6.3	Master clock system (if applicable).	4		Simplex system, also does bells	
Other		N/A			
5.7	Elevators/Disabled Lifts (If applicable)				
5.7.1	Elevator/lift size, access and operating features (i.e., sensing devices, buttons, phones, detectors).	N/A			
5.7.2	Condition of elevators/lifts.	N/A			
5.7.3	Lighting and ventilation of elevators/lifts.	N/A			
Other		N/A			
	Overall Elect. Systems Condition & Estim Costs				\$28,700

Section 6	Portable Buildings	Rating	Comments/Concerns	Estim. Cost
	<i>Note: Separate sheets can be completed, if necessary, for portable buildings of different ages and/or conditions.</i>	N/A		
6.1.1	Foundation and structure (i.e., signs of bending, cracking, settlement, rust, voids, stains).	N/A		
6.1.2	Roof materials and components (i.e., signs of deterioration, leaks, ice build-up).	N/A		
6.1.3	Exterior wall finishes (i.e., signs of deterioration, cracks, water stains).	N/A		
6.1.4	Doors and windows (i.e., signs of deterioration, rusting hardware, glass cracks, peeling paint, damaged seals).	N/A		
6.1.5	Interior finishes (i.e., floors, walls, ceiling).	N/A		
6.1.6	Millwork (i.e., counters, shelving, vanities, cabinets).	N/A		
6.1.7	Fixed/wall mounted equipment (i.e., writing boards, tackboards, display boards, signs)	N/A		
6.1.8	Heating system.	N/A		
6.1.9	Ventilation system.	N/A		
6.1.10	Electrical, communication and data network systems.	N/A		
6.1.11	Health and safety concerns (i.e., fire and smoke alarms, fire protection systems, exiting, fire resistance rating of materials).	N/A		
6.1.12	Barrier-free access.	N/A		
	Overall Portable Bldgs Condition & Estim Costs			\$0

Section 7	Space Adequacy	This Facility			Equiv. New Facility			Surplus/ Deficiency	Comments/Concerns
		No.	Size	Total Area	No.	Size	Total Area		
7.1	Classrooms	16		1206	15	80	1200	6	
7.2	Science Rooms/Labs	2		197	3	120	360	-163	
7.3	Ancillary Areas (i.e., Art, Computer Labs, Drama, Music,)								
		3		242	4		400	-158	
7.4	Gymnasium (incl. gym storage)	1		780	1	760	760	20	
7.5	Library/Resource Areas	2		367	1	306	306	61	
7.6	Administration/Staff, Physical Education, Storage Areas			364			615	-251	
7.7	CTS Areas								
	7.7.1 Business Education	1		81	2	115	230	-149	
	7.7.2 Home Economics	1		149	1	160	160	-11	
	7.7.3 Industrial Arts	1		234	1	300	300	-66	
	7.7.4 Other CTS Programs								
7.8	Other Non-Instructional Areas (i.e., circulation, wall area, crush space, wc area)			1143			1559	-416	
	Overall Space Adequacy Assessment	27		4763	28		5890	-1127	

Evaluation Component/ Sub-Component	Additional Notes and Comments

Evaluation Component/ Sub-Component	Additional Notes and Comments

Evaluation Component/ Sub-Component	Additional Notes and Comments

Evaluation Component/ Sub-Component	Additional Notes and Comments

Evaluation Component/ Sub-Component	Additional Notes and Comments

Evaluation Component/ Sub-Component	Additional Notes and Comments