School Facilities Evaluation Project

Evaluation Team: Architectural Najfeldt Architect, Date of Tour: April 13, 2000

Mechanical Bacz Engineering Ltd.

Electrical Beaubien Glover Engineering Ltd.

School Name/City, Town: Elizabeth Seton Elementary and Junior High School, Edmonton, Ab.

Edmonton Roman Catholic Schools, Regional District No.40

Executive Summary:

ARCHITECTURAL This facility was constructed in 1977 of masonry construction, with flat roofs, with brick veneer exterior and metal panels to Gym

walls above the lower roof line. It was further expanded in 1994 of similar construction. At the same time portion of the original

building was modernized including upgrading of most interior finishes. A minor modernization took place in 1987.

Some site re-grading and catch basin s required, to improve drainage at north-east side of the building. Expansion of staff parking

lot is recommended. New sidewalks should be installed to replace existing paving slabs.

Roofing investigation is recommended to assess performance of existing inverted roofing, including roofing to portable Classrooms

to identify cause of leakage.

Building envelope appears in good condition, except for painting of stained front canopy soffit, no further action is required.

Generally, building interior is in good condition. Recommendations call for replacement of flooring in Washrooms and lowering

of urinals and vanities to accommodate elementary school children. Automatic entry should be provided.

Portable Classrooms are in reasonable condition and require only minor architectural upgrading.

MECHANICAL Mechanical system consists of central hot water heating and roof mounted air handling units. Ventilation is provided through

overhead ductwork system. Mechanical recommendations call for modifications to existing heating system, and replacement

of existing ventilation distribution system in the original building.

Furnaces in Portable Classrooms do not meet current Code and are recommended for replacement.

ELECTRICAL Electrical system is deemed in good condition. Electrical review recommends upgrading existing light fixtures to new energy

efficient luminaries, and upgrading of fire alarm system to current Code.