Part II - Physical Condition

School Name:	St. Edmi	ınd Elen	nentary and .lu	nior High School	School Code:	8215
Location:			nue, Edmonton		Facility Code:	2019
Location.	11721	OU AVOI	Lac, Lamonton	, Alberta	1 domey code.	2010
Region:	Central				Superindendent:	Mr. Garnet McKee
Jurisdiction:	Edmonto	on Roma	an Catholic Sch	nools Regional Division #40	Contact Person:	Mr. Ken Yakimovich
					Telephone:	(780) 453-4500
Grades:	K - IX				School Capacity:	96
Building Section	Year of Compl.	No. of Floors	Gross Bldg Area (Sq.M.)	Type of Construction (i.e., structure, roof, cladding)	Description of Mechanical Systems (incl. major upgrades)	Comments/Notes
Original Building	1956	2	2123.20	Masonry construction Flat roofs, brick exterior	steam system, served by two (2)	The Boiler Plant serving this section of the school is in good condition. The existing ventilation system (except of Gymnasium) can provide minimum fresh air, as is required by ASHRAE 62 1989 Standards and present ventilation codes.
Additions/ Expansions	1961 1966	2	1278.80 4962.30	Masonry construction Flat roofs, brick exterior  Masonry construction, flat roofs, brick exterior and painted block combination.	Consists of Hot Water Heating and steam system, served by two (2) Weil Mclain steam boilers, located in 1966 section of the school. The ventilation system consists of two (2) indoor mounted air handling units complete with coil and ductwork.	The Boiler Plant serving this section of the school is in good condition. The existing ventilation system can provide minimum fresh air, as is required by ASHRAE 62-1989 Standards and present ventilation codes.

School: St. Edmund

Date: April 19, 2000

& Company:

Najfeldt Architect

Part II - Physical Condition

Upgrading/ Modernization (identify whether minor or major)	1993		Reroofing completed.  Hallways and lockers repainted in 1956 and 1961 sections.	The modernization was a majnor modernization for the mechanical system. The new hot water heating boilers were installed	The new mechanical system meets present ventilation codes and ASHRAE 62-1989 standards.
Portable Struct. (identify whether attached/perman. or free-standing/ relocatable)			None		
		nducted in 1999 ompleted in 199			

#### Part II - Physical Condition

Evaluation Components							
Site Conditions							
Building Exterior	Replace fascias Provide weatherstripping and replace some exterior doors. Investigate further building envelope issues.						
Building Interior	Replace acoustic panels in music room.  Replace T-bar ceilings.  Replace gym lockers and toilet partitions.  Provide elevator, WC's and automatic opener.						
Mechanical Systems	The existing heating system can be reused. The ventilation system (with exception of the Gymnasium located in the original school) meets ASHRAE 62-1989 Standard and present ventilation code requirements. The existing heating and ventilation system requires modifications to the gymnasium area.						
Electrical Systems	The electrical distribution is in good condition. Retrofit all luminaires to new energy efficient T8 lamps and electronic ballast. Provide additional exterior lighting. Upgrade fire alarm system to current code.						
Portable Buildings	None						
Space Adequacy:							
7.1 Classrooms	Slightly Excessive 274.20	-					
7.2 Science Rooms/Labs	Deficient -237.80						
7.3 Ancillary Areas	Deficient -196.20						
7.4 Gymnasium	Somewhat Deficient -179.50						
7.5 Library/Resource Areas	Somewhat Deficient -161.10						
7.6 Administration/Staff Areas	Deficient -363.30						
7.7 CTS Areas	Deficient -157.00						
7.8 Other Non-Instructional Areas (incl. gross-up)	Excessive 1260.00						
Overall School Conditions & Estim. Costs		\$ 1,167,000					

#### Part II - Physical Condition

Section 1	Site Conditions	Rating	Comments/Concerns	Estim.	Cost
1.1	General Site Conditions				
1.1.1	Overall site size.	4	Adequate	\$	-
1.1.2	Outdoor athletic areas.	4	Soccer field, two baseball diamonds. Asphalt play area with five basketball hoops. Considered adequate.	\$	-
1.1.3	Outdoor playground areas, including condition of equipment and base.	2	Playground on sand base, equipment minimal and in poor condition. Replacement recommended.	\$ 95,00	00.00
1.1.4	Site landscaping.	4	Grass throughout, mature landscaping - adequate.	\$	-
1.1.5	Site accessories (i.e., perimeter and other fencing, guard rails, bike stands, flag poles).	4	Chain link fencing around entire site, piperails in front yard. Flagpole provided - no flag. Bikestands provided.	\$	-
1.1.6	Surface drainage conditions (i.e., drains away from building, signs of ponding).	3	Poor along south elevation of 1956 wing. Raise grade. Remainder of site has good drainage.	\$ 5,00	00.00
1.1.7	Evidence of sub-soil problems.	4	None	\$	-
1.1.8	Safety and security concerns due to site conditions.	4	None	\$	-
Other				\$	-

#### Part II - Physical Condition

	Site Conditions	Rating	Comments/Concerns	Estim. Cost
1.2	Access/Drop-Off Areas/Roadways/Bus Lanes			
	Vehicular and pedestrian access points (i.e., size, number, visibility, safety).	4	One vehicular access to parking lot. Visibility and safety - adequate. Wood rails around parking lot. Walkways to all access points - adequate.	\$ -
1.2.2	Surfacing of on-site road network (note whether asphalt or gravel).	N/A	No on-site roads.	\$ -
1.2.3	Bus lanes/drop-off areas (note whether on-site or off-site).	4	Off site from street across playfield.	\$ -
1.2.4	Fire vehicle access.	4	From back alley and surrounding streets. Considered adequate.	\$ -
1.2.5	Signage.	4	On the building - adequate.	\$ -
Other				\$ -

Schoo	l:	St.	Edr	nund
Date:	Α	pril	19,	2000

ction 1	Site Conditions	Rating	Comments/Concerns	Estim. Cost
1.3	Parking Lots and Sidewalks			
1.3.1	Number of parking spaces for staff, students and visitors (including stalls for disabled persons).	3	26 stalls for staff, 4 for visitors. (present staff 33, plus 8 after school care). Parking considered inadequate. Expand parking east of 1966 wing by 12 stalls.	\$ 54,000.00
1.3.2	Layout and safety of parking lots.	3	Issue with lack of parent drop-off area. Consider expanding parking and drop-off.	See 1.3.1
1.3.3	Surfacing and drainage of parking lots (note whether asphalt or gravel).	4	Asphalt paved - good drainage.	\$ -
1.3.4	Layout and safety of sidewalks.	4	Layout good.	\$ -
1.3.5	Surfacing and drainage of sidewalks (note type of material).	3	Combination of asphalt and concrete paved walks.  North walkways in poor condition, replace section.  Drainage good.	\$ 8,500.00
1.3.6	Curb cuts and ramps for barrier free access.	3	No ramps or curb cuts provided. Provide access ramp.	\$ 12,500.00
Other				\$ -
	Overall Site Conditions & Estimated Costs			\$ 175,000.00

#### Part II - Physical Condition

	Building Exterior	Rating		Comments/Concerns	Estim	ı. Cost
2.1	Overall Structure		Bldg. Section	Description/Condition		
2.1.1	Floor structure and beams (i.e., signs of bending, cracking, heaving, settlement, voids, rust, stains).	4	All	Concrete structure throughout, both for the main and second floors. No sign of bending or structural distress observed.	\$	-
	Wall structure and columns (i.e., signs of bending, cracking, settlement, voids, rust, stains).	4	All	Concrete block and brick veneer exterior walls. Exterior brick appears to be in good condition.	\$	-
2.1.3	Roof structure (i.e., signs of bending, cracking, voids, rust, stains).	4	All	Roof structure appears in good condition, no signs of structural distress, bending or cracks.	\$	-
Other					\$	-

#### Part II - Physical Condition

ection 2	Building Exterior	Rating		Comments/Concerns	Esti	m. Cost
2.2	Roofing and Skylights Identify the availability of an up-to-date inspection report or roofing program. Note if roof sections are of different ages and/or in varying		Bldg. Section or Roof Section	Description/Condition/Age		
2.2.1	Based on the inspection report (and to the extent possible, direct observation), assess and rate roof conditions and estimate costs for required improvements (i.e., covering materials, membrane, insulation, other components).	4	All	Tar and gravel roofs throughout. Appears in good condition.  No reports of recent roof leakage.	\$	-
2.2.2	Roof accessories (i.e., ladders, stairs, hatches, masts, exhaust hoods, chimneys, gutters, downspouts, splashpads).	4	All	Roof access from within building. Roof accessories appear in good condition.	\$	-
2.2.3	Control of ice and snow falling from roof.	4	All	No issues.	\$	-
2.2.4	Skylights (i.e., signs of distress, leaks, ice build-up, condensation, deteriorated materials/seals).	N/A			\$	-
Other					\$	-

School: St. Edmund

water stains, dust spots).

Other

# School Facility Evaluation Project

Section 2	Building Exterior	Rating		Comments/Concerns	Estim. Cost
2.3	Exterior Walls/Building Envelope		Bldg. Section	Description/Condition	
2.3.1	Exterior wall finishes (i.e., signs of deterioration, cracks, brick spalling, effluorescence, water stains).	4	All	Mostly brick, some painted block and painted pre-cast concrete beams.  Mostly in good condition.	\$ -
2.3.2	Fascias, soffits, parapets (i.e., signs of looseness, stains, rust, peeling paint).	3	All	Galvanized fascias, functioning, but of poor appearance, provide pre-finished metal fascias.	\$ 22,500.00
2.3.3	Building envelope (i.e., evidence of air infiltration/ exfiltration through the exterior wall or ice build up on wall, eaves, canopy).	3	1956	Air exfiltration in small gym.  Damage around windows in classrooms.  Complete building envelope study and effect repairs.	\$ 100,000.00
2.3.4	Interface of roof drainage and ground drainage systems.	4	All	No issues observed or reported. All roofs internally drained. Interface of drainage systems good.	\$ -
2.3.5	Inside faces of exterior walls (i.e., signs of cracks,	3	1956	Small gym - cracks in plaster finish, peeling paint. Evidence of air infiltration.	See 2.3.3

Cracks on inside faces of exterior walls.

1966

School: St. Edmund

#### Part II - Physical Condition

ection 2	Building Exterior	Rating		Comments/Concerns	Estim. Cost
2.4	Exterior Doors and Windows		Bldg. Section	Description/Condition	
	Doors (i.e., signs of deterioration, rusting metal, glass cracks, peeling paint, damaged seals, sealed unit failure).	3		Provide weatherstripping to all exterior doors, three sets in poor conditin. Replace three sets of exterior doors.	\$ 8,800.00
	Door accessories (i.e., latches, hardware, screens, locks, alarms, holders, closers, security devices).	4	All	Door hardware in reasonable condition, all in good working order.	\$ -
	Exit door hardware (i.e., safety and/or code concerns).	4		Adequate - no safety concerns. All panic hardware and closers appear in good working condition.	\$ -
	Windows (i.e., signs of deterioration, rusting metal, glass cracks, peeling paint, damaged seals, sealed unit failure).	4	1961	Metal clad wood window, metal panel above, aluminum sliders below, appears adequate.  Aluminum frame windows with venetian blinds. Adequate.	\$ -
	Window accessories (i.e., latches, hardware, screens, locks, alarms, holders, closers, security devices).	4		Sliding windows operational. Screens in place. No issues.	\$ -
	Building envelope (i.e., signs of heavy condensation on doors or windows).	3		Signs of movement and paint peeling around windows in classrooms.  Investigate cause and implement remedial work.	\$ 55,000.00
Other					
	Overall Bldg Exterior Condition & Estim Costs				\$ 186,300.00

,	School: St. Edmund Date: April 19, 2000
	Estim. Cost

Section 3	Building Interior - Overall Conditions	Rating		Comments/Concerns	Estim. Cost
3.1	Interior Structure		Bldg. <u>Section</u>	Description/Condition	
3.1.1	3.1.1 Interior walls and partitions (i.e., signs of cracks, spalling, paint peeling).			Some cracks in northwest wing and hallways walls. Cracks in gym walls. Movement cracks throughout in load bearing walls. Recommend structural and /or geotechnical investigation.	\$ 100,000.00
			1961	Some cracks in classroom walls. Complete study and implement repairs.	
3.1.2	Floors (i.e., signs of cracks, heaving, settlement).	4	All	None, all floors appear in good condition.	
Other		2		Replace acoustic panels in music room. Fabric worn badly, exposed fibreglass throughout. Unhealthy condition.	\$ 10,500.00
3.2	Materials and Finishes		Bldg.	2 1 1 2 10	
3.2.1	Floor materials and finishes.	2	Section   Description/Condition		\$ 6,800.00
			1966	VCT tile throughout - good condition. Carpet in music room - poor - replacement recommended.	
3.2.2	Wall materials and finishes.	4		Plywood dado painted plaster above - good condition.  Wood dado and plaster above - painted. Good condition.	\$ -
			1966	Concrete block painted - good condition.	
3.2.3	Ceiling materials and finishes.	2	1956	Stippled ceilings - good condition.	\$ 107,000.00
			1961	T-Bar in classrooms, plaster in hallways - good condition.	
			1966	T-Bar throughout in poor condition in hallways. Replace T-bar ceiling tiles in common areas.	

#### Part II - Physical Condition

Section 3	Building Interior - Overall Conditions	Rating		Comments/Concerns	Estim. Cost	
3.2	Materials and Finishes (cont'd)		Bldg.			_
224	Interior doors and hardware.		Section	<u>Description/Condition</u> Wood frames and wood doors - all painted. In reasonable condition.	\$	7,400.00
3.2.4	interior doors and nardware.	3	1956 1961	vvood frames and wood doors - all painted. In reasonable condition.	Þ	7,400.00
			1301			
			1966	Wood doors in metal frames - both painted.		
				Replace changerooms doors and WC doors. Doors dented and chipped		
				Repaint frames.		
3.2.5	Millwork	4	All	Painted plywood - older but acceptable.	\$	-
	Fixed/wall mounted equipment (i.e., writing boards,	4	All	Combination of chalkboards, whiteboards, and tackboards. All adequate.	\$	-
	tackboards, display boards, signs).					
	Any other fixed/mounted specialty items (i.e., CTS	3	All	Metal lockers in good condition.	\$	22,000.00
	equipment, gymnasium equipment).			Gym lockers in poor condition. Replace all.		
				Six basketball hoops in main gym and in small gym.		
3.2.8	Washroom materials and finishes.	2	All	Floor - Ceramic mosaic tile - good	\$	14,000.00
				Walls - Ceramic tile - good.	1	,000.00
				Ceilings - Drywall painted - good		
				Metal partitions - poor - replace all		
Oth					•	
Other					\$	-

Overall Bldg. Interior Condition & Estim Costs

# School Facility Evaluation Project

#### Part II - Physical Condition

ection 3	Building Interior - Overall Conditions	Rating		Comments/Concerns	Estim. Co
3.3	Health and Safety Concerns Intent is to identify renovations considered necessary to		Bldg. <u>Section</u>	Description/Condition	
	meet applicable codes, primarily due to safety concerns. Basis of evaluation should be an up-to-date inspection report from the authority having jurisdiction together with direct observations as appropriate. Evaluator should note if in his opinion a comprehensive code evaluation is				
3.3.1	Building construction type - combustible or non- combustible, sprinklered or non-sprinklered.	4	All	Non combustible construction, non-sprinklered.	\$
3.3.2	Fire separations (i.e., between buildings, wings, zones if non-sprinklered).	4	All	Appears adequate	\$
3.3.3	Fire resistance rating of materials (i.e., corridor walls and doors).	4	All	Good, block walls throughout.	\$
3.3.4	Exiting distances and access to exits.	4	All	Adequate.	\$
3.3.5	Barrier-free access.	3	All	Not provided, no elevator or ramps - provide both. No barrier free washrooms - provide WC. No automatic entry - provide automatic entry.	\$ 100,000
3.3.6	Availability of hazardous materials audit (i.e., evidence of safety concerns with respect to asbestos, PCB's, chemicals).	4	All	1980 Materials sampling conducted. 1999 Asbestos report provided.	\$
3.3.7	Other health and safety concerns (i.e., evidence of excessive noise conditions, air quality problems)	N/A			\$
Other					

\$ 367,700.00

School: St. Edmund

_	School: St. E Date: April 1	
	Estim. Cost	

Section 4	Mechanical Systems	Rating		Comments/Concerns		
4.1	Mechanical Site Services					
4.1.1	Site drainage systems (i.e., surface and underground systems, catch basins).	5	All sections	The site drainage system is surface type system and is in good condition. No water accumulation was identified around the building		
	Exterior plumbing systems (i.e., irrigation systems, hose bibs).	5	All sections	The irrigation system does not exist. The NFHB are in fair condition.		
4.1.3	Outside storage tanks.	N/A	All sections	None		
Other						
4.2	Fire Suppression Systems		Bldg.			
424	Fire hydrants and Siamese connections.		<u>Section</u>	<u>Description/Condition</u>		
4.2.1	The hydrants and Siamese connections.	N/A		None		
4.2.2	Fire suppression systems (i.e., pumps, sprinklers, piping, reservoirs, hoses, stand pipes, CO2 systems).	5		The standpipe system is in good condition.		
4.2.3	Hand extinguishers, blankets and showers (i.e., in CTS areas).	4	All sections	Fire extinguishers are in fair condition.		
4.2.4	Other special situations (e.g., flammable storage areas, science labs, CTS areas).	N/A	All section			
Other						

#### Part II - Physical Condition

ion 4	Mechanical Systems	Rating		Comments/Concerns	Estim. Cos
4.3	Water Supply and Plumbing Systems		Bldg. Section	Description/Condition	
4.3.1	Domestic water supply (i.e., pressure, volume, quality note whether municipal or well supply).	5	All sections	Domestic water supply is from the water main in the street (municipal water supply ). There is no problem with water pressure, volume and water quality.	
4.3.2	Water treatment system(s).	5	All sections	The domestic water supply is from the City Main. The water is treated and is in good condition.	
4.3.3	Pumps and valves (including Backflow prevention valves).	5	All sections	The domestic water circulation pumps and valves are in good condition.	
4.3.4	Piping and fittings.	5		All piping and fittings are not showing evidence of corrosion and are in fair condition.	
4.3.5	Plumbing fixtures (i.e., toilets, urinals, sinks)	4		All plumbing fixtures have individual isolation valves, meet all code requirements and are in fair condition.	
4.3.6	Domestic hot water system (i.e., heater, storage tanks, failure alarms, pressure, volume, recirculation).	5		The domestic hot water system consists of two (2) State, natural gas fired heaters. The capacity and conditions are good.	
4.3.7	Sanitary and storm sewers, including sumps and pits (note whether sewage system is municipal or septic).	5	All sections	The sanitary sewer system including sumps and pits is municipal type of system and is in fair condition. Storm system inside of the building is also in fair condition.	
Other					

School: St. Edmund

#### Part II - Physical Condition

ection 4	Mechanical Systems	Rating		Comments/Concerns	Estim. Cos
4.4	Heating Systems		Bldg. <u>Section</u>	Description/Condition	
4.4.1	Heating capacity and reliability (including backup capacity).	4	All sections	The existing heating boiler plant consist of four (4) natural gas fired Weil McClain steam boilers. The heating capacity and backup are fine.	
4.4.2	Heating controls (including use of current energy management technology.	4	All sections	The existing mechanical system is using pneumatic control system. DDC control system is applied to all components of mechanical system.	
4.4.3	Fresh air for combustion and condition of the combustion chimney.	5	All sections	The existing combustion air is sufficient and chimney is in good condition.	
4.4.4	Treatment of water used in heating systems.	N/A	All sections		
4.4.5	Low water cutoff/pressure relief valves and failure alarms (i.e., hot water heating).	4		Each boiler is complete with low water cutoff device and remote alarm system.  All are in fair condition.	
4.4.6	Heating air filtration systems and filters.	N/A	All sections		
4.4.7	Heating humidification systems and components.	4		Humidification system consist of steam boiler and steam distributors system.  The system is fine.	

School: St. Edmund

#### Part II - Physical Condition

Section 4	Mechanical Systems	Rating		Comments/Concerns	Estim. Cost
4.4	Heating Systems (cont'd)		Bldg. <u>Section</u>	Description/Condition	
4.4.8	Heating distribution systems (i.e., piping, ductwork) and associated components (i.e., diffusers, radiators).	4	All sections	The heating system consists of steam perimeter radiation system and univents. The system is in good condition. The ductwork serving entire school is in fine condition. No modification is required to the heating system. However, the new ductwork will be required for Gymnasium in the Original Section of the school.	
4.4.9	.4.9 Heating piping, valve and/or duct insulation.			The thermal insulation on the existing ductwork and piping system is in good condition.	
4.4.10	Heat exchangers.	4	All sections	All heat exchangers serving air handling units and boilers are in good condition.	
4.4.11	Heating mixing boxes, dampers and linkages.	4	All sections	All mixing boxes are located within Mechanical Room and are in good condition.	
4.4.12	Heating distribution/circulation in larger spaces (i.e., user comfort, temperature of outside wall surfaces).	3	All sections	The new hot water unit heaters are required in the large gymnasium. New ventilation system is required in the Gymnasium serving the Original School. Presently only gravity ventilation is provided to this Gymnasium.	\$50,000
4.4.13	Zone/unit heaters and controls.	5		All unit heaters and entrance forced flow heaters are complete with thermostats and are in good condition	
Other					

#### Part II - Physical Condition

Section 4	Mechanical Systems	Rating		Comments/Concerns	Estim. Cost
	Ventilation Systems		Bldg. Section	Description/Condition	
4.5.1	Air handling units capacity and condition.	4	All	Three (3) air handling units and Univents are serving the entire school. The air handling units and Univents can meet the present ventilation codes and the ASHRAE 62-1989 Standards.	
4.5.2	Outside air for the occupant load (if possible, reference CFM/occupant).	4	All sections	The air handling unit is capable to provide required minimum 15.0 CFM/student of outside air.	
4.5.3	Air distribution system (if possible, reference number of air changes/hour).	4	All sections	The air distribution system is via ceiling space. The air changes provided to each Classroom are set at 6 and can meet present codes.	
4.5.4	.5.4 Exhaust systems capacity and condition.		All sections	All exhaust fans have sufficient capacity and are in good condition.	
4.5.5	4.5.5 Separation of out flow from air intakes.		All sections	Are set at min. 10 Ft. which is acceptable	
4.5.6	Special/dedicated ventilation and/or exhaust systems (i.e., kitchen, labs, CTS areas).	4	All sections	The fume hoods serving Science Laboratories are fine.	
Other					

School: St. Edmund

#### Part II - Physical Condition

Section 4	Mechanical Systems	Rating		Comments/Concerns		
4.5	Ventilation Systems (cont'd)		Bldg.	D 11 (0 11)		
	Note: Only complete the following items if there are separate ventilation and heating systems.		Section	Description/Condition		
	4.5.7 Ventilation controls (including use of current energy management technology).			The ventilation system is using DDC pneumatic control system, which is current technology system and is in good condition.		
4.5.8	Air filtration systems and filters.	4		Air filtration system consists of med- efficiency replaceable filters, which are in fair condition.		
4.5.9	Humidification system and components.	4		The humidification system is steam type system. The entire system is fine, but not acitvated.		
4.5.10	Heat exchangers.	5	All sections	The water and gas heat exchanger is in good condition.		
4.5.11	Ventilation distribution system and components (i.e., ductwork, diffusers, mixing boxes, dampers, linkages).	4	All sections	The ventilation distribution system and components are in fine condition.		
Other						

#### Part II - Physical Condition

Section 4	Mechanical Systems	Rating		Comments/Concerns	Estim. Cost
4.6	Cooling Systems		Bldg. Section	Description/Condition	
	Cooling system capacity and condition (i.e., chillers, cooling towers, condensers).	N/A		None	
	Cooling distribution system and components (i.e., ductwork, diffusers, mixing boxes, dampers, linkages)	N/A			
4.6.3	Cooling system controls (including use of current energy management technology).	N/A			
	Special/dedicated cooling systems (i.e., labs, CTS areas).	N/A			
Other					
4.7	Building Control Systems	5			
4.7.1	Building wide/system wide control systems and/or energy management systems.	5		The existing control system is pneumatic DDC control sysytem and is using the current energy management technology.	
	Overall Mech Systems Condition & Estim. Costs				\$50,000

Schoo	l: St.	Edr	nund
Date:	April	19,	2000

Section 5	Electrical Systems	Rating		Comments/Concerns	Estim. Cost
5.1	Site Services				
5.1.1	Primary service capacity and reliability (i.e., access, location, components, installation, bus sizes - note whether overhead or underground).	4		Underground electrical service 1200A 120/208V 3 Phase 4 wire. Installed in 1967. The peak demand in the last 12 months was 194KVA = 540A. The service is original and in good condition. Federal pioneer distribution and sub panels.	
5.1.2	Site and building exterior lighting (i.e., safety concerns).	2		The Building Lighting is in good condition. HID wall packs located around perimeter. Requires two additional roof mounted flood lights in basketball court area. Insufficient lighting. Provide additional lighting in inner court. Presently no lighting in inner courtyard.	\$1,000.00
5.1.3	Vehicle plug-ins (i.e., number, capacity, condition).	3		Inadequate capacity to handle all staff and teachers. Total of 14 existing car plugs. Provide 5 new car plugs. Car parking note about new parking area.	\$3,000.00
Other					
	Life Safety Systems		Bldg. Section	Description/Condition	
5.2.1	Fire and smoke alarm systems (i.e., safety concerns, up-to-date technology, regularly tested).	3	1956	The fire alarm control panel is a Simplex 2001 and was installed in 1986. Tested on an annual basis. 16 zone panel. 1 spare zone. Provide new fire alarm panel. Existing cannot be upgraded to handle new code.	\$6,000.00
5.2.2	Emergency lighting systems (i.e., safety concerns, condition).	4	ALL	Emergency lighting, is in good condition. The battery packs and remote heads are mini style. Adequate lighting for path of egress.	
5.2.3	Exit lighting and signage (i.e., safety concerns, condition).	3	ALL	Exit signs are the old incandescent. Provide new energy efficient LED exits.	\$3,500.00
Other		2	ALL	There are 14 existing fire alarm bells. Provide 14 new strobe lights.	\$3,000.00

_	School: St. E Date: April 1	
	Estim. Cost	

Section 5	Electrical Systems	Rating		Comments/Concerns	Estim. Cost
5.3	Power Supply and Distribution		Bldg.	D	
5.3.1	Power service surge protection.	N/A	Section	<u>Description/Condition</u>	
5.3.2	Panels and wireways capacity and condition.	3	ALL	Panels are at 90% of capacity. Provide 4 new panels to accommodate new dedicated circuits. Existing panels are in good condition.	\$5,000.00
				dedicated circuits. Existing panels are in good condition.	
5.3.3	Emergency generator capacity and condition and/or	4	1956	The main computer server is on UPS backup. APC 1000.	
	UPS (if applicable).				
5.3.4	General wiring devices and methods.	4	ALL	Wiring is in good condition. Original to each section. All wiring is copper run in conduit.	
				Conduit.	
5.3.5	Motor controls.	4	ALL	Controls are in good condition. Andover AC 256M Plus DDC Control system.	
				Monitored by Catholic School Board in Central Edmonton.	
Other					
5.4	Lighting Systems		Bldg. Section	Description/Condition	
5.4.1	Interior lighting systems and components (i.e.,	2	1956	Computer Lab 630 Lux; Classroom 800 Lux; Office Area 480 Lux; Gym 430 Lux;	\$335,000.00
	illumination levels, conditions, controls).			Music 850 Lux; Staff Room 800 Lux. The existing lighting is T12 magnetic ballasts and lamps. Upgrade to T8 electronic ballasts and lamps.	
			1961	Classroom 1100 Lux; Science Lab 830 Lux. The existing lighting is T12 magnetic	
			1301	ballasts and lamps. Upgrade to T8 electronic ballasts and lamps.	
				Classroom 800 Lux; Reflection Room 1150 Lux; Gym 310 Lux; CTS 1400 Lux;	
				Mechanic Shop 1050 Lux; Lunch Room 1200 Lux; Corridors 500 Lux; Drama 850 Lux; Computer Lab 850 Lux; Home Economics 1000 Lux; Science 1250 Lux;	
5.4.2	Replacement of ballasts (i.e., health and safety	3	ALL	PCB Ballasts throughout all sections of the school. Remove and dispose of all	\$12,000.00
	concerns).			PCB Ballasts.	
5.4.3	Implementation of energy efficiency measures and	2	ALL	Upgrade all T12 magnetic ballasts and lamps to T8 electronic ballast and energy	See 5.4.1
	recommendations.			efficient lamps. Computerized energy management system was installed for	
0.1				mechanical and electrical energy savings.	
Other					

Part II - Physical Condition

Section 5	Electrical Systems	Rating		Comments/Concerns	Estim. Cost
	Network and Communication Systems	J	Bldg. Section	Description/Condition	
5.5.1	Telephone system and components (i.e., capacity, reliability, condition).	4	1956	There are 3 outside lines and 1 fax line. Nitsuko telephone system. Good condition.	
5.5.2	Other communication systems (i.e., public address, intercom, CCTV, satellite or cable TV).	4	ALL	P.A. System is in good condition. Dukane Petcom 2200. Cable TV. installed to each classroom. No CCTV or Satellite.	
5.5.3	Network cabling (if available, should be category 5 or better).	4	1956	Category 5 installed 1996. Installed to Library, office and computer lab only.	
5.5.4	Network cabling installation (i.e., in conduit, secured to walls or tables).	4	1956	Free aired, strapped to surface mounted conduit.	
5.5.5	Wiring and telecommunication closets (i.e., size, security, ventilation/cooling, capacity for growth).	2	1956	General Office Server Room, no capacity for growth. There is no ventilation. Room is hot. Provide new 24 port hub and patch panel. Provide exhaust fan. Hub storage room. Adequate capacity for growth. There is no ventilation. Room is very hot. Provide new exhaust fan. Existing 48 port hub is humming. 50% capacity.	\$16,500.00
			ALL	Provide data cabling to each classroom.	
			1966	2nd Floor Science Prep Room. There is no ventilation. 48 port hub. 55% capacity. Adequate capacity for growth. Provide new exhaust fan.	
5.5.6	Provision for dedicated circuits for network equipment (i.e., hubs, switches, computers).	3	All	No dedicated outlets. Provide dedicated outlets in each classroom. Provide dedicated outlets for server and hub.	\$3,000.00
Other					

School: St. Edmund

#### Part II - Physical Condition

Section 5	Electrical Systems	Rating		Comments/Concerns	Estim. Cost
5.6	Miscellaneous Systems		Bldg. Section	Description/Condition	
5.6.1	Site and building surveillance system (if applicable).	N/A			
5.6.2	Intrusion alarms (if applicable).	4		Telsco monitoring system with motion sensors corridors and office area. The system is in good condition. Controller located in 1956 Hub storage room.	
5.6.3	Master clock system (if applicable).	5		Master clock system is controlled from central branch. All clocks are digital. Installed in 1997. Excellent condition. Digital in corridors. 120V clocks in classrooms.	
Other					
5.7	Elevators/Disabled Lifts (If applicable)				
5.7.1	Elevator/lift size, access and operating features (i.e., sensing devices, buttons, phones, detectors).	N/A			
5.7.2	Condition of elevators/lifts.	N/A			
5.7.3	Lighting and ventilation of elevators/lifts.	N/A			
Other					
	Overall Elect. Systems Condition & Estim Costs				\$388,000.00

-	School: St. E Date: April 1	
	Estim. Cost	

Section 6	Portable Buildings	Rating	Comments/Concerns	Estim	ı. Cost
	Note: Separate sheets can be completed, if necessary, for portable buildings of different ages and/or conditions.		Not Applicable		
	Foundation and structure (i.e., signs of bending, cracking, settlement, rust, voids, stains).			\$	-
	Roof materials and components (i.e., signs of deterioration, leaks, ice build-up).			\$	-
	Exterior wall finishes (i.e., signs of deterioration, cracks, water stains).			\$	-
	Doors and windows (i.e., signs of deterioration, rusting hardware, glass cracks, peeling paint, damaged seals).			\$	-
6.1.5	Interior finishes (i.e., floors, walls, ceiling).			\$	-
6.1.6	Millwork (i.e., counters, shelving, vanities, cabinets).			\$	-
	Fixed/wall mounted equipment (i.e., writing boards, tackboards, display boards, signs)			\$	-
6.1.8	Heating system.				
6.1.9	Ventilation system.				
6.1.10	Electrical, communication and data network systems.				
	Health and safety concerns (i.e., fire and smoke alarms, fire protection systems, exiting, fire resistance rating of materials).			\$	-
6.1.12	Barrier-free access.			\$	-
	Overall Portable Bldgs Condition & Estim Costs			\$	-

# School Facility Evaluation Project Part II - Physical Condition

			This Fa	cility	Equiv. New Facility			Surplus/	
Section 7	Space Adequacy	No.	Size	Total Area	No.	Size	Total Area	Deficiency	Comments/Concerns
7.1	Classrooms	29	78.4	2274.2	25	80	2060	274.2	
7.2	Science Rooms/Labs	1 1 1	100.60 81.80 104.80	287.2	3 2	95 120	525	-237.8	
	Ancillary Areas (i.e., Art, Computer Labs, Drama, Music,)	2 2	82.70 79.20	323.8	2 4	130 90	620	-296.2	
7.4	Gymnasium (incl. gym storage)	1 1 1	305.8 445.9 16.30 25.50	793.5	1		973	-179.5	
7.5	Library/Resource Areas	1		288.9	1	280 170	450	-161.1	
	Administration/Staff, Physical Education, Storage Areas			503.73	1		867	-363.27	
7.7	CTS Areas								
	7.7.1 Business Education				1		115	-115	
	7.7.2 Home Economics	1		131.7	1	160	160	-28.3	
	7.7.3 Industrial Arts	1		266.3	1	280	280	-13.7	
	7.7.4 Other CTS Programs								
	Other Non-Instructional Areas (i.e., circulation, wall area, crush space, wc area)			3495			2235	1260	
	Overall Space Adequacy Assessment			8364.3			8225	139.3	

School: St. Edmund Date: April 19, 2000

Evaluation Component/ Sub-Component  Additional Notes and Comments	
	,