Part III - Space Adequacy

School: ST. PETER Date: April 7, 2000

| | School Name: | St. Peter | School | | | School Code: | 18 |
|------------------|---------------|----------------|------------------|----------------------------|---|--|--------------------|
| | Location: | Edmonto | n | | | Facility Code: | 1973 |
| | | 0 | | | | | |
| | Region: | Central | 5.0.0 | | "10 | Superintendent: | Mr. Garnet McKee |
| | Jurisdiction: | Edmonto | n R.C.S. | Regional Divisi | ion #40 | Contact Person: | Mr. Ken Yakimovich |
| | | | | | | Telephone: | (780) 453-4500 |
| | Grades: | Leased to | o Adult E | ducation Centre | 9 | School Capacity: | 150 |
| | | | | | | | |
| | g Section | Year of Compl. | No. of Floors | Gross Bldg Area (Sq.M.) | roof, cladding) | Description of Mechanical Systems (incl. major upgrades) | Comments/Notes |
| Origina | al Building | 1952 | 1 | 460.20 | Framed, shingles, built-up roof, wood siding, plaster. | Perimeter hot water radiation. | |
| Additic Expan | | 1955 | 1 | 1040.90 | Masonry, shingles, built-up roof, SBS torched on roofing, concrete block, wood siding, plaster. | Perimeter hot water radiation extended into additions. | |
| | | | | | | | |
| | | | | | | Evaluator's Name: | Francis Ng |

School: ST. PETER Date: April 7, 2000

Part III - Space Adequacy

| Upgrading/ Modernization | 1993 | | Upgrade | Partition changes involving duct / diffuser relocations and the | ? |
|-----------------------------|----------------|-------------|-----------------------|---|---|
| (identify whether | | | | installation of Rooftop HVAC units. | |
| minor or major) | 1996 | | Upgrade | | Gym. acoustic and band storage room |
| | | | | | |
| | 1997 | | Re-roofing (shingles) | | 1952 original and 1955 addition |
| | 1999 | | Upgrade | | Hot water heating, heating ventilation & air conditioning |
| | 1999 | | Re-roofing | | 1955 addition |
| | | | | | |
| | | | | | |
| Portable Struct. | N/A | | No Portables. | No Portable structures added to | |
| (identify whether | | | | this school. | |
| attached/perman. or | | | | | |
| free-standing/ | | | | | |
| relocatable) | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| List of Reports/ | None | | | | |
| Supplementary | | | | | |
| Information | Room no. based | on site no. | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

School Facility Evaluation Project Part III - Space Adequacy

| Evaluation Components | Summary Assessment | Estim. Cost |
|---|---|-------------|
| 1 Site Conditions | Repair sidewalks. Provide new grading. | \$18,250.0 |
| 2 Building Exterior | Install new built up roofs. Repair windows and accessories. Repair and repaint exit doors. | \$100,200.0 |
| Building Interior | Repair and repaint interior metal doors. Repair millwork. Repair interior floor and wall finishes. | \$31,400.0 |
| Mechanical Systems | An older building with components which may require replacement at any time. These include: new boilers. Vacuum breakers are also required on exterior hose bibbs and a new ventilation unit is needed for the Gymnasium. | \$80,500.0 |
| Electrical Systems | Electrical systems are in satisfactory condition. Provide surge suppression system and upgrade lighting in the Gymnasium. | \$63,500.0 |
| Portable Buildings | N/A | \$0.0 |
| Space Adequacy: | | |
| 7.1 Classrooms | 21.10 | |
| 7.2 Science Rooms/Labs | -120.00 | |
| 7.3 Ancillary Areas | -173.60 | |
| 7.4 Gymnasium | | |
| 7.5 Library/Resource Areas | -324.90 | |
| 7.6 Administration/Staff Areas | -55.70 | |
| 7.7 CTS Areas | -139.90 | |
| 7.8 Other Non-Instructional Areas (incl | 33.60 | |
| gross-up) | -49.50 | |
| Overall School Conditions & Estim. Co | -808.90 | \$293,850. |

Part III - Space Adequacy

| tion 1 | Site Conditions | Rating | Comments/Concerns | Estim. Cost |
|--------|---|--------|---|--------------|
| | General Site Conditions | | Description/Condition | |
| 1.1.1 | Overall site size. | 4 | Site facing 2 streets. (113 Street on the east; 114 Street on the west; services lanes on north and south) Adequate. | |
| 1.1.2 | Outdoor athletic areas. | 4 | 1 baseball backstop and 1 set of soccer goal posts maintained by the City of Edmonton. | |
| 1.1.3 | Outdoor playground areas, including condition of equipment and base. | 4 | No outdoor playground equipment. | |
| 1.1.4 | Site landscaping. | 4 | Trees and shrubs in the front lawn. | |
| | Site accessories (i.e., perimeter and other fencing, guard rails, bike stands, flag poles). | | No bike rack provided. One flag pole installed. | |
| | Surface drainage conditions (i.e., drains away from building, signs of ponding). | 3 | Ponding around the school especially along east sides of 1952 section. Need new grading around the building. | \$10,000 |
| 1.1.7 | Evidence of sub-soil problems. | | Settled and cracked sidewalk at all exits. Exposed concrete foundation walls near east and west sides of 1952 and 1955 sections. | Include 1 |
| 1.1.8 | Safety and security concerns due to site conditions. | 4 | No apparent problem. | |
| Other | | | | |
| | | | | |
| 1.2 | Access/Drop-Off Areas/Roadways/Bus Lanes | | Description/Condition | |

School: ST. PETER

Part III - Space Adequacy

| Section 1 | Site Conditions | Rating | Comments/Concerns | Estim. Cost |
|-----------|--|--------|--|-------------|
| | Vehicular and pedestrian access points (i.e., size, number, visibility, safety). | | One access for entry and exit from south lane for staff parking lot. One access for entry and exit from north lane for staff and visitor parking lot. | |
| 1.2.2 | Surfacing of on-site road network (note whether asphalt or gravel). | 4 | Gravel paving. | |
| 1.2.3 | Bus lanes/drop-off areas (note whether on-site or off-site). | 4 | Off-site bus loading and unloading areas along 113 Street. | |
| 1.2.4 | Fire vehicle access. | 4 | None. | |
| 1.2.5 | Signage. | | Building signage installed. Staff parking signage installed. Bus loading and unloading zone signage installed. Visitor parking signage installed. No handicapped stall signage installed. Install signage. | \$250.00 |
| Other | | | | |

School: ST. PETER

Part III - Space Adequacy

| Section 1 | Site Conditions | Rating | Comments/Concerns | Estim. Cost |
|-----------|--|--------|---|-------------|
| 1.3 | Parking Lots and Sidewalks | | Description/Condition | |
| 1.3.1 | Number of parking spaces for staff, students and visitors (including stalls for disabled persons). | | 21 staff parking stalls. 31 visitor parking stalls. Provide one handicapped parking stall. | \$3,000.00 |
| 1.3.2 | Layout and safety of parking lots. | 4 | No apparent problem. | |
| 1.3.3 | Surfacing and drainage of parking lots (note whether asphalt or gravel). | | Gravel paving. No catch basin was seen. | |
| 1.3.4 | Layout and safety of sidewalks. | | Sidewalks settled and cracked on north of 1955 section; east of 1952 section. Repair sidewalks. | \$5,000.00 |
| 1.3.5 | Surfacing and drainage of sidewalks (note type of material). | 4 | Concrete sidewalk. See 1.3.4. | |
| 1.3.6 | Curb cuts and ramps for barrier free access. | 4 | 1 gravel ramp for barrier free access at south entrance of 1952 section. | |
| Other | | | | |
| | Site Conditions Estimated Costs | | | \$18,250.00 |

School: ST. PETER

Part III - Space Adequacy

| on 2 | Building Exterior | Rating | | Comments/Concerns | Estim. Cos |
|-------|---|--------|------------------|---|------------|
| | Overall Structure | | Bldg. Section | Description/Condition | |
| 2.1.1 | Floor structure and beams (i.e., signs of bending, cracking, heaving, settlement, voids, rust, stains). | 4 | All | A minor crack on concrete foundation on east side of 1952 section. | |
| 2.1.2 | Wall structure and columns (i.e., signs of bending, cracking, settlement, voids, rust, stains). | 4 | All | Plaster paint peeled off e.g. west side of 1952 section. Stucco of Gymnasium cracked and dirty. | |
| | Roof structure (i.e., signs of bending, cracking, voids, rust, stains). | 4 | All | All areas were covered with T-Bar or mineral fibre ceiling tiles. | |
| | | | | | |
| Other | | | | | |

School: ST. PETER

Part III - Space Adequacy

| Section 2 | Building Exterior | Rating | | Comments/Concerns | Estim. Cost |
|-----------|--|--------|------|---|-------------------|
| 2.2 | Roofing and Skylights Identify the availability of an up-to-date inspection report or roofing program. Note if roof sections are of different ages and/or in varying Based on the inspection report (and to the extent possible, direct observation), assess and rate roof conditions and estimate costs for required improvements (i.e., covering materials, membrane, insulation, other components). | 3 | 1955 | Description/Condition/Age Built-up roof with blisters on lower roof. Repair roof. (area 80 sq.m.) Asphalt shingles in good condition. Built-up roof with blisters on upper roof of Gymnasium. Repair roof. (area 280 sq.m.) SBS torched on roofing on lower roof in good condition. Asphalt shingles in good condition. | \$25,200.00 |
| 2.2.2 | Roof accessories (i.e., ladders, stairs, hatches, masts, exhaust hoods, chimneys, gutters, downspouts, splashpads). | 3 | | No access to lower roofs. Use portable ladder from outside. Facing bricks of chimney need repointing. All metal flashing caps paint for upper roof peeled off. Repaint metal flashing caps. | \$8,000.00 |
| 2.2.3 | Control of ice and snow falling from roof. | 3 | All | Icicles built up near Men's and Women's washrooms. | Included in 2.3.3 |
| 2.2.4 | Skylights (i.e., signs of distress, leaks, ice build-up, condensation, deteriorated materials/seals). | N/A | | | |
| Other | | | | | |

School: ST. PETER

Part III - Space Adequacy

| | Building Exterior | Rating | _ | Comments/Concerns | Estim. Cost |
|-------|--|--------|------------------|--|-------------|
| 2.3 | Exterior Walls/Building Envelope | | Bldg. | | |
| 2.3.1 | Exterior wall finishes (i.e., signs of deterioration, cracks, brick spalling, effluorescence, water stains). | 3 | Section All | Description/Condition Wood panels paint peeled off. Repaint panels. Plaster paint peeled off e.g. west side of 1952 section. Repair and paint plaster. Stucco of Gymnasium cracked and dirty. Repaint stucco. | \$30,000.00 |
| 2.3.2 | Fascias, soffits, parapets (i.e., signs of looseness, stains, rust, peeling paint). | 3 | All | Plywood soffit damaged. Replace soffit with perforated metal panels. | \$8,000.00 |
| | Building envelope (i.e., evidence of air infiltration/ exfiltration through the exterior wall or ice build up on wall, eaves, canopy). | 3 | All | lcicles built up near Men and Women's Washrooms due to slope and size of eaves trough. Replace eaves troughs, downspouts and splashpads. | \$4,000.00 |
| 2.3.4 | Interface of roof drainage and ground drainage systems. | 3 | All | Exterior downspouts connected to underground drainage system. Ice built up inside the downspouts. Disconnect the downspouts at grade level and install concrete splashpads. | \$1,000.00 |
| 2.3.5 | Inside faces of exterior walls (i.e., signs of cracks, water stains, dust spots). | 3 | All | Gap between exterior walls and interior partitions. Repair partitions. Plaster is not smooth. | \$5,000.00 |
| Other | | | | | |
| 2.4 | Exterior Doors and Windows | | Bldg. Section | Description/Condition | |
| 2.4.1 | Doors (i.e., signs of deterioration, rusting metal, glass cracks, peeling paint, damaged seals, sealed unit failure). | 3 | All | Metal exit doors in good condition. Wood exit doors in good condition. Exit doors need new weatherstrips. South exit doors in Gymnasium need new weatherstrips. | \$1,000.00 |

School: ST. PETER

Part III - Space Adequacy

| ection 2 | Building Exterior | Rating | | Comments/Concerns | Estim. Cost |
|----------|---|--------|-----|---|------------------|
| | Door accessories (i.e., latches, hardware, screens, locks, alarms, holders, closers, security devices). | 3 | All | Door hinges and closers for all exterior doors to be readjusted. | \$500.00 |
| 2.4.3 | Exit door hardware (i.e., safety and/or code concerns). | 3 | All | Exit panic bars for Gymnasium need repair. | \$500.00 |
| 2.4.4 | Windows (i.e., signs of deterioration, rusting metal, glass cracks, peeling paint, damaged seals, sealed unit failure). | 3 | All | Dirt found between glazing typical. Gaskets need replacement for all rooms. Exterior wood window sills need repair and repaint. Caulking around some windows is required. | \$17,000.00 |
| 2.4.5 | Window accessories (i.e., latches, hardware, screens, locks, alarms, holders, closers, security devices). | 4 | All | Operable casement window latches in good condition. Horizontal aluminum blinds in good condition. | |
| 2.4.6 | Building envelope (i.e., signs of heavy condensation on doors or windows). | 3 | All | Condensation marks on window sills. | Included in 3.2. |
| Other | | | | | |
| | Building Exterior Estimated Costs | | | | \$100,200.00 |

School: ST. PETER

Part III - Space Adequacy

| Section 3 | Building Interior | Rating | | Comments/Concerns | Estim. Cost |
|-----------|---|--------|------------------|---|-------------|
| 3.1 | Interior Structure | | Bldg. Section | Description/Condition | |
| | Interior walls and partitions (i.e., signs of cracks, spalling, paint peeling). | 3 | All | Interior partitions cracked above door of Gymnasium. Repair partitions. Aluminum folding shutter between public classrooms and administration office in good condition. | \$1,000.00 |
| 3.1.2 | Floors (i.e., signs of cracks, heaving, settlement). | 4 | All | Floor covered with finishes. No visible cracks and settlement. | |
| Other | | | | | |
| 3.2 | Materials and Finishes | | Bldg. Section | Description/Condition | |
| 3.2.1 | Floor materials and finishes. | 3 | All | Carpet in good condition. Hardwood on ply and wood joists in Gymnasium needs refinish. Hardwood floor in Stage needs repair and refinish. Vinyl tiles scratched in Library. Replace tiles. Electrical room has plywood floor. | \$15,000.00 |
| 3.2.2 | Wall materials and finishes. | 3 | All | Drywall partitions need repair and repaint e.g. in Conference Room, Library. | \$4,000.00 |
| 3.2.3 | Ceiling materials and finishes. | 4 | All | Drywall ceiling in good condition. | |

School: ST. PETER

Part III - Space Adequacy

| ion 3 Building Interior | Rating | _ | Comments/Concerns | Estim. Cos |
|---|--------|---------|---|------------|
| 3.2 Materials and Finishes (cont'd) | | Bldg. | | |
| | | Section | | |
| 3.2.4 Interior doors and hardware. | 3 | All | Interior wood doors e.g. Library need repaint. | \$400. |
| 3.2.5 Millwork. | 3 | All | All wood window sills need repair. | \$6,000. |
| 3.2.6 Fixed/wall mounted equipment (i.e., writing boards, tackboards, display boards, signs). | 4 | All | Chalkboards in good condition. Tackboards in good condition. | |
| 3.2.7 Any other fixed/mounted specialty items (i.e., CTS equipment, gymnasium equipment). | 4 | All | Video equipment in Video/Conference Room. | |
| 3.2.8 Washroom materials and finishes. | 4 | All | Different types washroom finishes: Quartzite (Terrazzo) in Men's and Women's Washrooms in good condition. Drywall ceiling in Men's and Women's Washrooms in good condition. Drywall and terrazzo dado in Men's and Women's Washrooms in good condition. | |
| Other | | | Vinyl tiles in staff washroom in good condition. Drywall and drywall ceiling in Staff Washroom in good condition. | |
| | | | | |

School: ST. PETER

Part III - Space Adequacy

| Section 3 | Building Interior | Rating | | Comments/Concerns | Estim. Cost |
|-----------|--|--------|------------------|---|-------------|
| 3.3 | Health and Safety Concerns Intent is to identify renovations considered necessary to | | Bldg. Section | <u>Description/Condition</u> | |
| | meet applicable codes, primarily due to safety concerns. Basis of evaluation should be an up-to-date inspection report from the authority having jurisdiction together with direct observations as appropriate. Evaluator should note if in his opinion a comprehensive code evaluation is | | | | |
| 3.3.1 | Building construction type - combustible or non- combustible, sprinklered or non-sprinklered. | 4 | All | Combustible and non-sprinklered. | |
| 3.3.2 | Fire separations (i.e., between buildings, wings, zones if non-sprinklered). | 4 | All | Adequate. | |
| 3.3.3 | Fire resistance rating of materials (i.e., corridor walls and doors). | 4 | All | All rooms have 20 min. fire rated wood doors and metal frames. 3/4 hr. fire rated metal door and frame to electrical room. | |
| 3.3.4 | Exiting distances and access to exits. | 4 | All | Adequate. | |
| 3.3.5 | Barrier-free access. | 4 | All | Main Entrance allows barrier free access. Barrier free access to Gymnasium. 1 barrier free access to Staff Washroom. No barrier free access to Stage. | |
| | Availability of hazardous materials audit (i.e., evidence of safety concerns with respect to asbestos, PCB's, chemicals). | 3 | All | Complete hazardous materials audit. | \$5,000.00 |
| | Other health and safety concerns (i.e., evidence of excessive noise conditions, air quality problems). | 4 | All | No apparent problem. | |
| Other | | | | | |
| | Building Interior Estimated Costs | | | | \$31,400.00 |

School: ST. PETER

Part III - Space Adequacy

| Section 4 | Mechanical Systems | Rating | | Comments/Concerns | Estim. Cost |
|-----------|--|--------|------------------|---|-------------|
| 4.1 | Mechanical Site Services | | | Description/Condition | |
| 4.1.1 | Site drainage systems (i.e., surface and underground systems, catch basins). | 4 | All | Roof drainage splashed to grade. Sanitary connected to city mains. No known problems. | |
| 4.1.2 | Exterior plumbing systems (i.e., irrigation systems, hose bibbs). | 3 | All | No irrigation systems. There are some hose bibbs around the building. Require vacuum breakers. | \$500.00 |
| 4.1.3 | Outside storage tanks. | N/A | | There are no outside storage tanks at this school. | |
| Other | | | | | |
| | | | | | |
| 4.2 | Fire Suppression Systems | | Bldg. Section | Description/Condition | |
| 4.2.1 | Fire hydrants and siamese connections. | N/A | Section | There are no fire hydrants on school property. No siamese connections. | |
| 4.2.2 | Fire suppression systems (i.e., pumps, sprinklers, piping, reservoirs, hoses, stand pipes, CO2 systems). | N/A | | There are no sprinklers nor standpipe systems at this school. | |
| 4.2.3 | Hand extinguishers, blankets and showers (i.e., in CTS areas). | 4 | All | There are portable fire extinguishers throughout the building. These are checked once per year and are in good condition. | |
| 4.2.4 | Other special situations (e.g., flammable storage areas, science labs, CTS areas). | N/A | | There are no special fire suppression situations at this school. | |
| Other | | | | | |
| | | | | | |

School: ST. PETER

Part III - Space Adequacy

| ection 4 | Mechanical Systems | Rating | | Comments/Concerns | Estim. Cost |
|----------|---|--------|------------------|---|-------------|
| | Water Supply and Plumbing Systems | | Bldg. Section | Description/Condition | |
| 4.3.1 | Domestic water supply (i.e., pressure, volume, quality note whether municipal or well supply). | 4 | All | The domestic water supply and pressure appear to be good. No known problems. | |
| 4.3.2 | Water treatment system(s). | N/A | | There are no domestic water softeners nor other forms of water treatment at this school. | |
| 4.3.3 | Pumps and valves (including backflow prevention valves). | 4 | All | Backflow prevention valves on heating system make up water line. Appears to be in good condition. Other domestic water valves are repaired as problems arise. No current known problems. | |
| 4.3.4 | Piping and fittings. | 4 | All | Appear to be in good condition. No known problems. | |
| 4.3.5 | Plumbing fixtures (i.e., toilets, urinals, sinks) | 4 | All | Toilets, sinks, shower, urinals appear to be in good condition. No known problems. | |
| 4.3.6 | Domestic hot water system (i.e., heater, storage tanks, failure alarms, pressure, volume, recirculation). | 4 | All | Tank type water heater - John Wood model JW613402 NT35. No known problems. | |
| 4.3.7 | Sanitary and storm sewers, including sumps and pits (note whether sewage system is municipal or septic). | 4 | All | Sanitary and storm sewers within building appear to be in good condition. No known problems. | |
| Other | | | | | |
| | | | | | |

School: ST. PETER

Part III - Space Adequacy

| Section 4 | Mechanical Systems | Rating | | Comments/Concerns | Estim. Cost |
|-----------|---|--------|------------------|---|-------------|
| | Heating Systems | | Bldg. Section | Description/Condition | |
| 4.4.1 | Heating capacity and reliability (including backup capacity). | 3 | All | Heating capacity of heating plant appears to be adequate. Boilers are old. (converted coal fired boilers). It is not known how long these will continue to function. They should be replaced. | \$30,000.00 |
| 4.4.2 | Heating controls (including use of current energy management technology. | 4 | All | Heating controls: Andover. Electric thermostats in rooms. Pneumatic radiation control valves. No known problems. | |
| 4.4.3 | Fresh air for combustion and condition of the combustion chimney. | 4 | All | No known problems with Chimney nor combustion air ducts. | |
| 4.4.4 | Treatment of water used in heating systems. | 4 | All | Chemical pot feeder / manual feed into heating system. Chemical use is consistent. | |
| 4.4.5 | Low water cutoff/pressure relief valves and failure alarms (i.e., hot water heating). | 4 | All | No known problems. | |
| 4.4.6 | Heating air filtration systems and filters. | 4 | All | Filters in rooftop units are regularly changed. No known problems. | |
| 4.4.7 | Heating humidification systems and components. | N/A | | No humidification on heating system. | |
| | | | | | |

School: ST. PETER

Part III - Space Adequacy

| Section 4 | Mechanical Systems | Rating | | Comments/Concerns | Estim. Cost |
|-----------|---|--------|------------------|---|-------------|
| 4.4 | Heating Systems (cont'd) | | Bldg. Section | Description/Condition | |
| 4.4.8 | Heating distribution systems (i.e., piping, ductwork) and associated components (i.e., diffusers, radiators). | 4 | | No signs of excessive leaks. Circulation pumps (Viking, base mounted) are old but appear to be functioning well. No known problems. | |
| 4.4.9 | Heating piping, valve and/or duct insulation. | 4 | All | Insulation appears to be in good condition. Asbestos has either been removed or encapsulated. | |
| 4.4.10 | Heat exchangers. | N/A | | There are no heat exchangers on the heating system. | |
| 4.4.11 | Heating mixing boxes, dampers and linkages. | N/A | | There are no mixing boxes, dampers nor linkages in the heating system. | |
| 4.4.12 | Heating distribution/circulation in larger spaces (i.e., user comfort, temperature of outside wall surfaces). | 2 | | Heat distribution is generally good, although the computer room overheats regularly. Provide cooling for Computer room. | \$30,000.00 |
| 4.4.13 | Zone/unit heaters and controls. | 4 | | Unit heaters in service spaces. Force flow heaters in entrance ways. All appear to be in good condition and functioning well. | |
| Other | | | | | |
| | | | | | |

School: ST. PETER

Part III - Space Adequacy

| Section 4 | Mechanical Systems | Rating | | Comments/Concerns | Estim. Cost |
|-----------|--|--------|------------------|---|-------------|
| 4.5 | Ventilation Systems | | Bldg. Section | Description/Condition | |
| 4.5.1 | Air handling units capacity and condition. | 2 | All | Air handling units appear to be of adequate capacity and good condition in most areas, except the gymnasium. In this area, there is no mechanical ventilation, except for an exhaust fan. Air is stuffy. Provide new Air Handling unit for the gymnasium. | \$20,000.00 |
| 4.5.2 | Outside air for the occupant load (if possible, reference CFM/occupant). | 4 | All | System was likely designed for approx. 5 cfm of O/A per occupant. Detailed airflow quantities are unavailable. No reports of adverse conditions. | |
| 4.5.3 | Air distribution system (if possible, reference number of air changes/hour). | 4 | All | System was likely designed for approx. 1 cfm / sq.ft., total supply air. Detailed airflow quantities are unavailable. No reports of adverse conditions. | |
| 4.5.4 | Exhaust systems capacity and condition. | 4 | All | Gymnasium exhaust fan. Washroom exhaust fans. All appear to be in good working order. | |
| 4.5.5 | Separation of out flow from air intakes. | 4 | All | Separation of air outflows and intakes appears satisfactory. | |
| 4.5.6 | Special/dedicated ventilation and/or exhaust systems (i.e., kitchen, labs, CTS areas). | 4 | All | Staff kitchen range hood in good working order. | |
| Other | | | | | |
| | | | | | |

School: ST. PETER

Part III - Space Adequacy

| Section 4 | Mechanical Systems | Rating | | Comments/Concerns | Estim. Cost |
|-----------|--|--------|---------|--|-------------|
| 4.5 | Ventilation Systems (cont'd) | | Bldg. | Description (Constitute | |
| | Note: Only complete the following items if there | | Section | <u>Description/Condition</u> | |
| | are separate ventilation and heating systems. | | | | |
| 4.5.7 | Ventilation controls (including use of current energy management technology). | 4 | All | A combination of pneumatic & electric thermostats throughout. No known problems. | |
| 4.5.8 | Air filtration systems and filters. | 4 | All | Filters changed on a regular basis (3-4 times per year). Good condition. | |
| 4.5.9 | Humidification system and components. | N/A | | No humidification on ventilation system. | |
| 4.5.10 | Heat exchangers. | N/A | | No Heat exchangers on ventilation system. | |
| | Ventilation distribution system and components (i.e., ductwork, diffusers, mixing boxes, dampers, linkages). | 4 | All | Ductwork, diffusers appear to be in good condition. Dampers, linkage are part of Air handling units. No known problems. | |
| Other | | | | | |

School: ST. PETER

Part III - Space Adequacy

| ection 4 | Mechanical Systems | Rating | | Comments/Concerns | Estim. Cost |
|----------|---|--------|------------------|--|-------------|
| | Cooling Systems | | Bldg. Section | Description/Condition | |
| 4.6.1 | Cooling system capacity and condition (i.e., chillers, cooling towers, condensers). | 4 | All | Cooling systems appear to be adequately sized and seem to work well. No known problems. | |
| 4.6.2 | Cooling distribution system and components (i.e., ductwork, diffusers, mixing boxes, dampers, linkages) | 4 | All | Refer to item 4.5.11. | |
| 4.6.3 | Cooling system controls (including use of current energy management technology). | N/A | | No EMCS. | |
| 4.6.4 | Special/dedicated cooling systems (i.e., labs, CTS areas). | N/A | | No specialized / dedicated cooling systems. | |
| Other | | | | | |
| 4.7 | Building Control Systems | | Bldg. | | |
| 4.7.1 | Building wide/system wide control systems and/or energy management systems. | N/A | Section | Description/Condition No building wide / system wide control systems. All controls are local. | |
| | | | | | |
| | | | | | |
| | Mechanical Systems Estimated Costs | | | | \$80,500.00 |

School: ST. PETER

Part III - Space Adequacy

| Section 5 | Electrical Systems | Rating | Comments/Concerns | Estim. Cost |
|-----------|--|--------|--|-------------|
| 5.1 | Site Services | | Description/Condition | |
| 5.1.1 | Primary service capacity and reliability (i.e., access, location, components, installation, bus sizes - note whether overhead or underground). | 4 | Underground service from on-site pad mounted transformer. Installation is satisfactory. Main Switchboard: 600A, 120/208V, 3PH, 4W, c/w 600A main breaker. Service upgraded in 1997. Ample spare breaker capacity. | |
| 5.1.2 | Site and building exterior lighting (i.e., safety concerns). | 4 | Building mounted fixtures. Fixture are of the H.I.D. type. Coverage is adequate and no safety concerns expressed. | |
| 5.1.3 | Vehicle plug-ins (i.e., number, capacity, condition). | 4 | Approx. 6 energized parking stalls have been provided. Number provided appears adequate. Plug-ins are rail mounted and are in good condition. Vehicle plug-ins are timer and temperature controlled. | |
| Other | | | | |
| | | | | |
| 5.2 | Life Safety Systems | | Bldg. Section Description/Condition | |
| 5.2.1 | Fire and smoke alarm systems (i.e., safety concerns, up-to-date technology, regularly tested). | 4 | All Edwards 6616 system provided. Zoned, supervised and monitored. Condition is good and system is tested annually, and device coverage and location are satisfactory. Ample spare capacity in the system. | |
| 5.2.2 | Emergency lighting systems (i.e., safety concerns, condition). | 4 | All Emergency lighting is provided by battery packs and remote heads. Coverage is satisfactory. All packs operational. | |
| 5.2.3 | Exit lighting and signage (i.e., safety concerns, condition). | 4 | All Illuminated exit signs have been provided over each required exit as per the requirements of the building code. Exit signs are of the incandescent type and in satisfactory condition and all signs are provided DC power from the battery packs. | |
| Other | | | | |

School: ST. PETER

Part III - Space Adequacy

| Section 5 | Electrical Systems | Rating | | Comments/Concerns | Estim. Cost |
|-----------|--|--------|------------------|---|-------------|
| 5.3 | Power Supply and Distribution | | Bldg. Section | Description/Condition | |
| 5.3.1 | Power service surge protection. | 3 | All | None provided; concern expressed about power spikes. Provide surge suppression system. | \$3,500.00 |
| 5.3.2 | Panels and wireways capacity and condition. | 4 | All | Breaker panels have been provided throughout the school for utilization of power. All panels are in satisfactory condition, well identified, and c/w directories. All panels have spare breaker spaces. | |
| 5.3.3 | Emergency generator capacity and condition and/or UPS (if applicable). | N/A | | N/A | |
| 5.3.4 | General wiring devices and methods. | 4 | All | Receptacles of the duplex type have been provided throughout the school including classrooms. Receptacles are in satisfactory condition. Adequate number of receptacles have been provided. | |
| 5.3.5 | Motor controls. | 4 | Mech. Room | Wall mounted starters have been provided for motor control. Installation and operation satisfactory. | |
| Other | | | | | |
| | | | | | |

School: ST. PETER

Part III - Space Adequacy

| Section 5 | Electrical Systems | Rating | | Comments/Concerns | Estim. Cost |
|-----------|---|--------|------------------|--|----------------------|
| 5.4 | Lighting Systems | | Bldg. Section | Description/Condition | |
| 5.4.1 | Interior lighting systems and components (i.e., illumination levels, conditions, controls). | 3 | All | Fluorescent fixtures have been provided throughout the school. Fluorescent fixtures for the most part are c/w T12 lamps and standard ballast's. Fixtures are in generally good condition. Illumination levels are as follows: Classrooms: 65 to 75 fc Hallways: 30 to 40 fc Washrooms: 35 fc Staff Rooms: 65 fc Gymnasium: 20 to 25 fc (old incandescent fixtures) Administration:70 to 85 fc Computer Lab: 65 fc. Upgrade lighting in gymnasium. Recommend H.I.D. type lighting with metal halide fixtures and replace existing fluorescent fixtures with new ones utilizing T8 lamps and electronic ballast's. Refer to 5.4.3. | Included in 5.4.3 |
| 5.4.2 | Replacement of ballast's (i.e., health and safety concerns). | 4 | All | Standard ballast's. Unlikely that any ballast's contain PCB's. No safety concerns expressed. | |
| 5.4.3 | Implementation of energy efficiency measures and recommendations. | 3 | All | Recommend to replace existing fluorescent fixtures with new T8/electronic ballast fluorescent fixtures. As existing exit lights fail, and need replacing they should be replaced with LED type exit lights. | \$60,000.00 |
| Other | | | | | |

School: ST. PETER

Part III - Space Adequacy

| | Electrical Systems | Rating | | Comments/Concerns | Estim. Cost |
|-------|--|--------|-------|--|-------------|
| | Network and Communication Systems | | Bldg. | | |
| 5.5.1 | Telephone system and components (i.e., capacity, reliability, condition). | 4 | All | <u>Description/Condition</u> New telephone system has been provided. System is adequate, no concerns expressed. | |
| 5.5.2 | Other communication systems (i.e., public address, intercom, CCTV, satellite or cable TV). | N/A | | N/A | |
| 5.5.3 | Network cabling (if available, should be Category 5 or better). | 4 | All | Cat. 5 cabling has been provided; data outlets have been provided in classrooms. | |
| 5.5.4 | Network cabling installation (i.e., in conduit, secured to walls or tables). | 4 | All | Data cabling installation is satisfactory. Combination of open wiring and wiring in conduit. | |
| 5.5.5 | Wiring and telecommunication closets (i.e., size, security, ventilation/cooling, capacity for growth). | 4 | All | Installation is satisfactory. Data equipment installed in the general office area. Area is secure and well ventilated. | |
| 5.5.6 | Provision for dedicated circuits for network equipment (i.e., hubs, switches, computers). | 4 | All | Dedicated circuits have been provided for data equipment. | |
| Other | | | | | |
| | | | | | |

School: ST. PETER

Part III - Space Adequacy

| | Electrical Systems | Rating | | Comments/Concerns | Estim. Cost |
|-------|--|--------|---------|---|-------------|
| 5.6 | Miscellaneous Systems | | Bldg. | | |
| _ | | | Section | | |
| 5.6.1 | Site and building surveillance system (if applicable). | N/A | | N/A | |
| | | | | | |
| | | | | | |
| | | | | | |
| 5.6.2 | Intrusion alarms (if applicable). | 4 | All | Intrusion alarm has been provided. System consists of motion sensors, door contacts, etc. | |
| | | | | System is monitored and operation is satisfactory. | |
| | | | | | |
| | | | | | |
| 5.6.3 | Master clock system (if applicable). | 4 | All | No master clock system provided. Electric clocks have been provided in all areas. | |
| | | | | Electric clocks have been provided in all areas. | |
| | | | | | |
| | | | | | |
| Other | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| 5.7 | Elevators/Disabled Lifts (If applicable) | | Section | <u>Description/Condition</u> | |
| 5.7.1 | Elevator/lift size, access and operating features (i.e., | N/A | | N/A | |
| | sensing devices, buttons, phones, detectors). | | | | |
| | | | | | |
| | | | | | |
| 5.7.2 | Condition of elevators/lifts. | N/A | | N/A | |
| | | | | | |
| | | | | | |
| | | | | | |
| 5.7.3 | Lighting and ventilation of elevators/lifts. | N/A | | N/A | |
| | | | | | |
| | | | | | |
| | | | | | |
| Other | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | Floatrical Systems Estimated Costs | | | | ¢63 500 00 |
| | Electrical Systems Estimated Costs | | | | \$63,500.00 |

School: ST. PETER

Part III - Space Adequacy

| Section 6 | Portable Buildings | Rating | Comments/Concerns | Estim. Cost |
|-----------|--|--------|-------------------|-------------|
| | Note: Separate sheets can be completed, if necessary, for portable buildings of different ages and/or conditions. | | | |
| 6.1.1 | Foundation and structure (i.e., signs of bending, cracking, settlement, rust, voids, stains). | N/A | | |
| 6.1.2 | Roof materials and components (i.e., signs of deterioration, leaks, ice build-up). | N/A | | |
| 6.1.3 | Exterior wall finishes (i.e., signs of deterioration, cracks, water stains). | N/A | | |
| 6.1.4 | Doors and windows (i.e., signs of deterioration, rusting hardware, glass cracks, peeling paint, damaged seals). | N/A | | |
| 6.1.5 | Interior finishes (i.e., floors, walls, ceiling). | N/A | | |
| 6.1.6 | Millwork (i.e., counters, shelving, vanities, cabinets). | N/A | | |
| 6.1.7 | Fixed/wall mounted equipment (i.e., writing boards, tackboards, display boards, signs). | N/A | | |
| 6.1.8 | Heating system. | N/A | | |
| 6.1.9 | Ventilation system. | N/A | | |
| 6.1.10 | Electrical, communication and data network systems. | N/A | | |
| 6.1.11 | Health and safety concerns (i.e., fire and smoke alarms, fire protection systems, exiting, fire resistance rating of materials). | N/A | | |
| 6.1.12 | Barrier-free access. | N/A | | |
| | Portable Buildings Estimated Costs | | | \$0.00 |

School: ST. PETER

School Facility Evaluation Project Part III - Space Adequacy

| Section 7 | Space Adequacy | | This Fa | acility | E | quiv. Nev | v Facility | Surplus/ | |
|-----------|--|-----|--------------|------------|-----|------------------------|------------|------------|--|
| | | No. | Size | Total Area | No. | Size | Total Area | Deficiency | Comments/Concerns |
| 7.1 | Classrooms | 2 2 | 82.5 74.3 | 181.10 | 2 | 80 | 160.00 | 21.10 | No Adult Education Area Guidelines available for evaluation. Use Senior High Area Guidelines Capacity 200. |
| 7.2 | Science Rooms/Labs | | | | 1 | 120 | 120.00 | -120.00 | |
| 7.3 | Ancillary Areas (i.e., Art, Computer Labs, Drama, Music,) | | | 46.40 | 1 | 130 90 | 220.00 | -173.60 | |
| 7.4 | Gymnasium (incl. gym storage) | | | 280.10 | | 550.0 55 | 605.00 | -324.90 | |
| 7.5 | Library/Resource Areas | | | 74.30 | | | 130.00 | -55.70 | |
| 7.6 | Administration/Staff, Physical Education, Storage Areas | | | 193.10 | | 170 110 53 | 333.00 | -139.90 | |
| 7.7 | CTS Areas 7.7.1 Business Education | | | | 1 | 115 | 115.00 | -115.00 | |
| | 7.7.2 Home Economics | | | | | | | 0.00 | |
| | 7.7.3 Industrial Arts | | | | | | | 0.00 | |
| | 7.7.4 Other CTS Programs | 2 | 74.3 | 148.60 | | | | 148.60 | Computer & Video Lab. |
| 7.8 | Other Non-Instructional Areas (i.e., circulation, wall area, crush space, wc area) | | | 577.50 | | 375 180 48 24 | 627.00 | -49.50 | |
| | Overall Space Adequacy Assessment | | | 1501.10 | | | 2310.00 | -808.90 | |