	School Name: Lake Bonavista School			School Code:	9334		
Location: Lake Bonavista School Location: 1015 - 120 Avenue S.E.			ue S.E.		Facility Code:	1544	
	Region:	South				Superintendent:	Dr. Donna Michaels
	Jurisdiction:	Calgary -	- District	19		Contact Person:	Leanne Soligo
						Telephone:	(403) 214-1123
	Grades:	K - 6				School Capacity:	Total - 425
uildin	g Section	Year of Compl.	No. of Floors	Gross Bldg Area (Sq.M.)	Type of Construction (i.e., structure, roof, cladding)	Description of Mechanical Systems (incl. major upgrades)	Comments/Notes
rigin	al Building	1969	1	2802	Masonry block walls; slab on grade; steel roof deck on steel trusses.	Hot water heating and RTU for ventilation - good condition. Open area concept - divided and creating problems.	
	ons/ sions						
				None			
				2802 Total Gross Area			
	1						
						Evaluator's Name:	Harvey Bernbaum
						& Company:	Bernbaum Architect Ltd.

Upgrading/ Modernization (identify whether minor or major) Portable Struct.		None		
(identify whether attached/perman. or free-standing/ relocatable)				
		None		
List of Reports/ Supplementary Information		Asbestos report available and re	eviewed - March 15, 1999.	
		2. Assisted on site by:		
		Mrs. Marilyn King, Principal		

Evaluation Components	Summary Assessment	Estim. Cost					
1 Site Conditions	Provide disabled parking stall.						
2 Building Exterior	We have recommended replacement of windows and doors and their associated hardware, etc.						
3 Building Interior	We have recommended painting, upgrading to white boards, revising millwork and making school barrier free.						
4 Mechanical Systems	Older school complete with acceptable mechanical systems. Designed as open area concept with walls instal has created some heating and controls problems. We have recommended some upgrading.	led \$512,060					
5 Electrical Systems	Older school with acceptable electrical systems. Although a fire alarm panel should be installed. We have recommended upgrading the current technology.	\$112,280					
6 Portable Buildings	None.	\$0					
7 Space Adequacy:							
7.1 Classrooms	One classroom is used for storage at present.	33.5					
7.2 Science Rooms/Labs	Adequate.	-23					
7.3 Ancillary Areas	There are choices of which space to use for each function.	16.6					
7.4 Gymnasium	Adequate.	-240					
7.5 Library/Resource Areas	Adequate.	4.2					
7.6 Administration/Staff Areas	Small for its function.	-170					
7.7 CTS Areas							
7.8 Other Non-Instructional Areas (incl. gross-up)	Adequate.	11.1					
Overall School Conditions & Estim. Costs		\$939,440					

	Site Conditions	Rating	Comments/Concerns	Estim. Cost
1.1	General Site Conditions			
1.1.1	Overall site size.	4	Adequate.	
1.1.2	Outdoor athletic areas.	4	Adequate - not shared.	
113	Outdoor playground areas, including condition of	4	2 sets of creative.	
1.1.5	equipment and base.	7	2 Sets of Geative.	
1.1.4	Site landscaping.	4	Lack of shade on playground. Will put in a shaded seating area - Millennium project.	
1.1.5	Site accessories (i.e., perimeter and other fencing, guard rails, bike stands, flag poles).	4	Adequate.	
	guard rails, bike starids, riag poles).			
1.1.6	Surface drainage conditions (i.e., drains away from	4	No apparent problems.	
	building, signs of ponding).			
1.1.7	Evidence of sub-soil problems.	4	No apparent problems.	
1.1.8	Safety and security concerns due to site conditions.	4	No apparent problems.	
			The apparent presionic.	
O41				
Other				
1				

	Site Conditions	Rating	Comments/Concerns	Estim. Cost
1.2	Access/Drop-Off Areas/Roadways/Bus Lanes			
1.2.1	Vehicular and pedestrian access points (i.e., size, number, visibility, safety).	4	Adequate - streets and lanes.	
1.2.2	Surfacing of on-site road network (note whether asphalt or gravel).	n/a	None.	
1.2.3	Bus lanes/drop-off areas (note whether on-site or off-	4	City street in front of building.	
	site).			
1.2.4	Fire vehicle access.	4	Access to building through playground.	
1.2.5	Signage.	4	Adequate.	
Other				

	Site Conditions	Rating	Comments/Concerns	Estim. Cost
1.3	Parking Lots and Sidewalks			
1.3.1	Number of parking spaces for staff, students and visitors (including stalls for disabled persons).	3	Approximately 25 cars. Some staff use street for parking. Provide designated disabled persons stall c/w signage.	\$3,000
1.3.2	Layout and safety of parking lots.	4	Adequate.	
1.3.3	Surfacing and drainage of parking lots (note whether asphalt or gravel).	4	Adequate - asphalt.	
1.3.4	Layout and safety of sidewalks.	4	Adequate.	
1.3.5	Surfacing and drainage of sidewalks (note type of material).	4	Adequate.	
1.3.6	Curb cuts and ramps for barrier free access.	4	City Calgary - adequate.	
Other				
	Overall Site Conditions & Estimated Costs			\$3,000

Section 2	Building Exterior	Rating		Comments/Concerns	Estim. Cost
2.1	Overall Structure		Bldg.		
	L		Section	<u>Description/Condition</u>	
2.1.1	Floor structure and beams (i.e., signs of bending, cracking, heaving, settlement, voids, rust, stains).	4		No apparent problems.	
	cracking, neaving, settlement, voids, rust, stains).				
2.1.2	Wall structure and columns (i.e., signs of bending,	4		No apparent problems.	
	cracking, settlement, voids, rust, stains).				
242	Roof structure (i.e., signs of bending, cracking, voids,	4		No annual makilana	
2.1.3	rust, stains).	4		No apparent problems.	
	, , , , , ,				
2.1.4	Control/expansion joints.	4		No apparent problems.	
Other					

Section 2	Building Exterior	Rating		Comments/Concerns	Estim. Cost
	Roofing and Skylights Identify the availability of an up-to-date inspection report or roofing program. Note if roof sections are of different ages and/or in varying		Bldg. Section or Roof Section	Description/Condition/Age	
	Based on the inspection report (and to the extent possible, direct observation), assess and rate roof conditions and estimate costs for required improvements (i.e., covering materials, membrane, insulation, other components).	4		Roof is being totally redone in 2 weeks. No roofing report was available.	
2.2.2	Roof accessories (i.e., ladders, stairs, hatches, masts, exhaust hoods, chimneys, gutters, downspouts, splashpads).	4		No apparent problems.	
2.2.3	Control of ice and snow falling from roof.	4		Flat roof - no problems.	
2.2.4	Skylights (i.e., signs of distress, leaks, ice build-up, condensation, deteriorated materials/seals).	4		No skylights. Clerestory window in library - no apparent problem.	
Other					

Section 2	Building Exterior	Rating		Comments/Concerns	Estim. Cost
2.3	Exterior Walls/Building Envelope		Bldg.	D 14 10 101	
2.3.1	Exterior wall finishes (i.e., signs of deterioration, cracks, brick spalling, effluorescence, water stains).	4	Section	Description/Condition No apparent problem.	
2.3.2	Fascias, soffits, parapets (i.e., signs of looseness, stains, rust, peeling paint).	4		Metal fascia, stucco upper - no apparent problem.	
2.3.3	Building envelope (i.e., evidence of air infiltration/ exfiltration through the exterior wall or ice build up on wall, eaves, canopy).	4		No apparent problem.	
2.3.4	Interface of roof drainage and ground drainage systems.	4		Good drainage away from school from downspouts; internal drainage to city system is adequate.	
2.3.5	Inside faces of exterior walls (i.e., signs of cracks, water stains, dust spots).	4		No apparent problem.	
Other		3		Allowance for renovations related to mechanical upgrades	\$30,000

Section 2	Building Exterior	Rating		Comments/Concerns	Estim. Cost
2.4	Exterior Doors and Windows		Bldg.	- 1 d 25 mi	
2.4.1	Doors (i.e., signs of deterioration, rusting metal, glass cracks, peeling paint, damaged seals, sealed unit failure).	3	Section	<u>Description/Condition</u> No apparent problem at present, but reaching the end of their life cycle. Replace in next 5 years.	\$9,000
2.4.2	Door accessories (i.e., latches, hardware, screens, locks, alarms, holders, closers, security devices).	3		No apparent problem at present, but should be replaced when doors replaced.	\$6,000
2.4.3	Exit door hardware (i.e., safety and/or code concerns).	3		No indication of any problem at present, but should be replaced as above.	\$6,000
2.4.4	Windows (i.e., signs of deterioration, rusting metal, glass cracks, peeling paint, damaged seals, sealed unit failure).	3		No apparent problem at present, but are at the end of their life cycle. Internal blinds broken, etc. Replace all windows.	\$150,000
2.4.5	Window accessories (i.e., latches, hardware, screens, locks, alarms, holders, closers, security devices).	3		No apparent problem. As above - price included in 2.4.4.	
2.4.6	Building envelope (i.e., signs of heavy condensation on doors or windows).	4		No apparent problem.	
Other					
	Overall Bldg Exterior Condition & Estim Costs				\$201,000

Section 3	Building Interior - Overall Conditions	Rating		Comments/Concerns	Estim. Cost
3.1	Interior Structure		Bldg.		
			Section	<u>Description/Condition</u>	
3.1.1	Interior walls and partitions (i.e., signs of cracks, spalling, paint peeling).	4		No apparent problem.	
3.1.2	Floors (i.e., signs of cracks, heaving, settlement).	4		No apparent problem.	
Other					
Other					
3.2	Materials and Finishes		Bldg.		
			Section	Description/Condition	
3.2.1	Floor materials and finishes.	2		Rug in administration - loose and dangerous. Replace with proper area rug.	\$1,200
3.2.2	Wall materials and finishes.	3		No apparent problem. Painting should be scheduled for school in next 3 to 5 years. Allow	\$40,000
				painting 50% of the school.	4 10,000
3.2.3	Ceiling materials and finishes.	4		No apparent problem.	

	Building Interior - Overall Conditions	Rating		Comments/Concerns	Estim. Cost
3.2	Materials and Finishes (cont'd)		Bldg.	/	
3.2.4	Interior doors and hardware.	4	Section	Description/Condition No apparent problem.	
				The apparent presions	
3.2.5	Millwork	3		Millwork is somewhat dated, but functions well for its intended use. Allow to upgrade	\$30,000
				millwork to suit function of areas.	
0.00	Fired 6 and a surface and a su				#0.500
3.2.0	Fixed/wall mounted equipment (i.e., writing boards, tackboards, display boards, signs).	3		Upgrade to white boards.	\$8,500
3.2.7	Any other fixed/mounted specialty items (i.e., CTS	4		Gym equipment is adequate.	
	equipment, gymnasium equipment).				
3.2.8	Washroom materials and finishes.	4		Adequate.	
Other	1. Window blinds.	2		3 sets on south wall, classrooms 139 & 140 - broken - need repairs.	\$1,200

Section 3	Building Interior - Overall Conditions	Rating		Comments/Concerns	Estim. Cost
3.3	Health and Safety Concerns Intent is to identify renovations considered necessary to meet applicable codes, primarily due to safety concerns. Basis of evaluation should be an up-to-date inspection report from the authority having jurisdiction together with direct observations as		Bldg. <u>Section</u>	<u>Description/Condition</u>	
	appropriate. Evaluator should note if in his opinion a comprehensive code evaluation is				
3.3.1	Building construction type - combustible or non- combustible, sprinklered or non-sprinklered.	4		Non-combustible; non-sprinklered; building is adequate.	
3.3.2	Fire separations (i.e., between buildings, wings, zones if non-sprinklered).	4		Fire separations - no apparent problem.	
3.3.3	Fire resistance rating of materials (i.e., corridor walls and doors).	4		No apparent problems.	
3.3.4	Exiting distances and access to exits.	4		No apparent problems.	
3.3.5	Barrier-free access.	2		School is not barrier free, though wheelchair can access the building from outside. Need barrier free washrooms (2) and ramp to gymnasium level.	\$30,000
3.3.6	Availability of hazardous materials audit (i.e., evidence of safety concerns with respect to asbestos, PCB's, chemicals).	4		Audit reviewed - March 15, 1999 - mainly in ceilings and around piping.	
3.3.7	Other health and safety concerns (i.e., evidence of excessive noise conditions, air quality problems)	4		No problems noted or noticed.	
Other	Fan room - storage.	1		Remove storage and student access to fan room - to be implemented by school and school custodian.	\$200
	Overall Bldg Interior Condition & Estim Costs				\$111,100

Section 4	Mechanical Systems	Rating		Comments/Concerns	Estim. Cost
4.1	Mechanical Site Services				
4.1.1	Site drainage systems (i.e., surface and underground systems, catch basins).	4		Paved parking complete with catch basin to city, internal roof drainage.	
4.1.2	Exterior plumbing systems (i.e., irrigation systems, hose bibs).	4		Exterior irrigation exists complete with back flow prevention, two hose bibs require back flow prevention.	
4.1.3	Outside storage tanks.	n/a			
Other		n/a			
4.2	Fire Suppression Systems		Bldg.		
4.2	Fire Suppression Systems			Description/Condition	
4.2.1	Fire hydrants and siamese connections.	4		Siamese connection north east corner of school, hydrant on laneway.	
4.2.2	Fire suppression systems (i.e., pumps, sprinklers, piping, reservoirs, hoses, stand pipes, CO2 systems).	4		Fire hose cabinets, stage area is sprinklered.	
4.2.3	Hand extinguishers, blankets and showers (i.e., in CTS areas).	4		Inspected January 2000.	
4.2.4	Other special situations (e.g., flammable storage areas, science labs, CTS areas).	n/a			
Other		n/a			

Section 4	Mechanical Systems	Rating		Comments/Concerns	Estim. Cost
4.3	Water Supply and Plumbing Systems		Bldg.		
4.3.1	Domestic water supply (i.e., pressure, volume, quality note whether municipal or well supply).	4	Section	Description/Condition City of Calgary.	
4.3.2	Water treatment system(s).	4		City of Calgary.	
4.3.3	Pumps and valves (including backflow prevention valves).	3		Back flow prevention on main service, no ventilation in gas meter room.	\$3,000
4.3.4	Piping and fittings.	4		Copper piping.	
4.3.5	Plumbing fixtures (i.e., toilets, urinals, sinks)	4		Various lavatories chipped.	
4.3.6	Domestic hot water system (i.e., heater, storage tanks, failure alarms, pressure, volume, recirculation).	4		Domestic hot water - John Wood JWE502NA-D4/B5052 41.6 gallon - 38,000 BTU/HR complete with recirculation pump.	
4.3.7	Sanitary and storm sewers, including sumps and pits (note whether sewage system is municipal or septic).	4		City of Calgary.	
Other		n/a			

Section 4	Mechanical Systems	Rating		Comments/Concerns	Estim. Cost
4.4	Heating Systems		Bldg.		
4.4.1	Heating capacity and reliability (including backup capacity).	3	Section	<u>Description/Condition</u> Hot water heating - 2 Cleaver Brooks (Beaver) boilers Model #BG2-3000 input: 2,700,000 BTU/HR complete with expansion tank and three pumps. As system is reaching the end of its life cycle, we recommend a major mechanical upgrade.	\$175,000
4.4.2	Heating controls (including use of current energy management technology.	4		Pneumatic with air dryer conventional controls.	
4.4.3	Fresh air for combustion and condition of the combustion chimney.	F.I.		Combustion air - no relief air.	
4.4.4	Treatment of water used in heating systems.	4		Pot feeder and micron filter by CBE.	
4.4.5	Low water cutoff/pressure relief valves and failure alarms (i.e., hot water heating).	4		Adequate.	
4.4.6	Heating air filtration systems and filters.	4		Adequate.	
4.4.7	Heating humidification systems and components.	n/a			

Section 4	Mechanical Systems	Rating		Comments/Concerns	Estim. Cost
4.4	Heating Systems (cont'd)		Bldg.		
4.4.8	Heating distribution systems (i.e., piping, ductwork) and associated components (i.e., diffusers, radiators).	3	Section	<u>Description/Condition</u> Adequate. Allow for some upgrading in this area to coincide with other mechanical upgrades.	\$50,000
4.4.9	Heating piping, valve and/or duct insulation.	4		Adequate.	
4.4.10	Heat exchangers.	n/a			
4.4.11	Heating mixing boxes, dampers and linkages.	4		Adequate.	
4.4.12	Heating distribution/circulation in larger spaces (i.e., user comfort, temperature of outside wall surfaces).	4		Appears uniform. Building designed as open area concept and has been split-up with demountable partitions, not full heating (some only).	
4.4.13	Zone/unit heaters and controls.	4		Part of previous.	
Other		n/a			

Section 4	Mechanical Systems	Rating		Comments/Concerns	Estim. Cost
4.5	Ventilation Systems		Bldg.		
151	Air handling units capacity and condition.	3	Section	<u>Description/Condition</u> Appears in good condition RTU - EngA #DJ-60-0 550,000 maximum input BTUH. Nearing	\$198,000
4.5.1	All handling drifts capacity and condition.	3		end of its life cycle. Do a major ventilation upgrade at same time as 4.4.1 occurs.	\$198,000
4.5.2	Outside air for the occupant load (if possible, reference CFM/occupant).	4		Appears okay.	
	Air distribution system (if possible, reference number of air changes/hour).	4		Appears okay.	
4.5.4	Exhaust systems capacity and condition.	4		Appears okay.	
4.5.5	Separation of out flow from air intakes.	4		Appears okay.	
	Special/dedicated ventilation and/or exhaust systems (i.e., kitchen, labs, CTS areas).	3		Should have hood over staff room range ducted to outdoors.	\$2,000
Other		n/a			

Section 4	Mechanical Systems	Rating		Comments/Concerns	Estim. Cost
4.5	Ventilation Systems (cont'd)		Bldg.		
	Note: Only complete the following items if there		Section	<u>Description/Condition</u>	
	are separate ventilation and heating systems.				
4.5.7	Ventilation controls (including use of current energy	4		Pneumatic - part of previous.	
	management technology).				
4.5.8	Air filtration systems and filters.	4		Part of previous.	
4.5.9	Humidification system and components.	4		Spray coil type.	
4.5.10	Heat exchangers.	n/a			
4.5.11	Ventilation distribution system and components (i.e.,	4		Part of previous.	
	ductwork, diffusers, mixing boxes, dampers,				
	linkages).				
Other		n/a			

Section 4	Mechanical Systems	Rating		Comments/Concerns	Estim. Cost
4.6	Cooling Systems		Bldg.		
404			Section		
4.6.1	Cooling system capacity and condition (i.e., chillers, cooling towers, condensers).	4		Part of previous.	
	sooming towers, condenses of.				
4.6.0	Cooling distribution system and someone (i.e.			A J	
4.0.2	Cooling distribution system and components (i.e., ductwork, diffusers, mixing boxes, dampers, linkages)	4		Adequate.	
4.6.3	Cooling system controls (including use of current	4		Adequate.	
	energy management technology).				
4.6.4	Special/dedicated cooling systems (i.e., labs, CTS	n/a			
	areas).				
0.1		,			
Other		n/a			
4.7	Building Control Systems		Bldg.		
4.7	Building Control Systems		Section	Description/Condition	
4.7.1	Building wide/system wide control systems and/or	3		No building management or energy management systems. Add an energy management	\$84,060
	energy management systems.			system.	
	Overall Mech Systems Condition & Estim. Costs				\$512,060

Section 5	Electrical Systems	Rating		Comments/Concerns	Estim. Cost
5.1	Site Services				
	Primary service capacity and reliability (i.e., access, location, components, installation, bus sizes - note whether overhead or underground).	4		600A, 240V/3/4W underground.	
5.1.2	Site and building exterior lighting (i.e., safety concerns).	4		Incandescent and HID minimal exterior lighting.	
5.1.3	Vehicle plug-ins (i.e., number, capacity, condition).	3		9 duplex receptacles total (weatherproof), 2 require weatherproof covers.	\$200
Other		n/a			
5.2	Life Safety Systems		Bldg. Section	Description/Condition	
5.2.1	Fire and smoke alarm systems (i.e., safety concerns, up-to-date technology, regularly tested).	F.I.	000.001	Cannot locate fire alarm panel.	
5.2.2	Emergency lighting systems (i.e., safety concerns, condition).	4		Battery packs complete with remote emergency heads.	
5.2.3	Exit lighting and signage (i.e., safety concerns, condition).	4		Adequate.	
Other		n/a			

Section 5	Electrical Systems	Rating		Comments/Concerns	Estim. Cost
5.3	Power Supply and Distribution		Bldg.		
			Section	<u>Description/Condition</u>	
5.3.1	Power service surge protection.	4		Surge arrest power bars.	
5.3.2	Panels and wireways capacity and condition.	4		Limited spare capacity.	
5.3.3	Emergency generator capacity and condition and/or	n/a			
	UPS (if applicable).				
5.3.4	General wiring devices and methods.	4		Appear good.	
525	Motor controls.	4		Appear good.	
0.0.0	motor controls.	_		n ippour good.	
Other		n/a			
		,			

	Electrical Systems	Rating		Comments/Concerns	Estim. Cost
5.4	Lighting Systems		Bldg.		
5.4.1	Interior lighting systems and components (i.e., illumination levels, conditions, controls).	3		<u>Description/Condition</u> Corridors 10-40FC, classrooms 40-75FC, offices 55-110FC, gym 20-35FC (fluorescent). See Item 5.4.3 for upgrading and costs.	
	Replacement of ballasts (i.e., health and safety concerns).	4		Replaced on failure.	
5.4.3	Implementation of energy efficiency measures and recommendations.	3		T-12 technology. Do a lighting upgrade to T-8 lamps and energy efficient ballasts.	\$112,080
Other		n/a			

Section 5	Electrical Systems	Rating		Comments/Concerns	Estim. Cost
5.5	Network and Communication Systems		Bldg.		
5.5.1	Telephone system and components (i.e., capacity, reliability, condition).	4	Section	Description/Condition NT Meridian, telephone/classroom.	
5.5.2	Other communication systems (i.e., public address, intercom, CCTV, satellite or cable TV).	4		Public address system used for public address only as telephone system has intercom capability, cable television exists.	
5.5.3	Network cabling (if available, should be category 5 or better).	4		Category 5.	
5.5.4	Network cabling installation (i.e., in conduit, secured to walls or tables).	4		Installed by electrician.	
5.5.5	Wiring and telecommunication closets (i.e., size, security, ventilation/cooling, capacity for growth).	4		Storage room across hall from staff room, room is not ventilated.	
5.5.6	Provision for dedicated circuits for network equipment (i.e., hubs, switches, computers).	4		Appears okay.	
Other		n/a			

	Electrical Systems	Rating	Comments/Concerns		
5.6	Miscellaneous Systems		Bldg.		
			<u>Section</u>	<u>Description/Condition</u>	
5.6.1	Site and building surveillance system (if applicable).	n/a			
5.6.2	Intrusion alarms (if applicable).	4		CBE panel at entrance from parking lot.	
5.0.2	initiusion alarms (ii applicable).	4		CBE parier at entrance from parking lot.	
5.6.3	Master clock system (if applicable).	4		Controls a few clocks only, all others battery powered or electric.	
				,	
Other		n/a			
	Elevators/Disabled Lifts (If applicable)				
5.7.1	Elevator/lift size, access and operating features (i.e., sensing devices, buttons, phones, detectors).	n/a			
	sensing devices, buttons, priories, detectors).				
572	Condition of elevators/lifts.	n/a			
5.7.2	Condition of elevators/lints.	II/a			
5.7.3	Lighting and ventilation of elevators/lifts.	n/a			
Other		n/a			
	Overall Elect. Systems Condition & Estim Costs				\$112,280

Section 6	Portable Buildings	Rating	Comments/Concerns	Estim. Cost
	Note: Separate sheets can be completed, if necessary, for portable buildings of different ages and/or conditions.		No portables.	
	Foundation and structure (i.e., signs of bending, cracking, settlement, rust, voids, stains).	n/a		
	Roof materials and components (i.e., signs of deterioration, leaks, ice build-up).	n/a		
	Exterior wall finishes (i.e., signs of deterioration, cracks, water stains).	n/a		
	Doors and windows (i.e., signs of deterioration, rusting hardware, glass cracks, peeling paint, damaged seals).	n/a		
6.1.5	Interior finishes (i.e., floors, walls, ceiling).	n/a		
6.1.6	Millwork (i.e., counters, shelving, vanities, cabinets).	n/a		
	Fixed/wall mounted equipment (i.e., writing boards, tackboards, display boards, signs)	n/a		
6.1.8	Heating system.	n/a		
6.1.9	Ventilation system.	n/a		
6.1.10	Electrical, communication and data network systems.	n/a		
	Health and safety concerns (i.e., fire and smoke alarms, fire protection systems, exiting, fire resistance rating of materials).	n/a		
6.1.12	Barrier-free access.	n/a		
	Overall Portable Bldgs Condition & Estim Costs			\$0

Section 7 Space Adequacy - Capacity: 350

7.1	Classrooms		11		1133.5	10	80	800	333.5	Varies 72m ² to 111.5m ² . No portables.
7.2	Science Roo	ms/Labs	1		72	1	95	95	-23	Not used for Science - is now E.C.S.
	Ancillary Area Drama, Musi	as (i.e., Art, Computer Labs, ic) - Total	3		193.4	3		310	-116.6	
	Drama	Shared		74.2						Stage of gym is shared music/drama/lunch.
	Music									
	Computer	,		40						Actually part of library space.
	Art			79.2						
7.4	Gymnasium ((incl. gym storage) - Total	1		233	1		473	-240	
	Gym			223			430			
	Storage			10			43			
7.5	Library/Reso	urce Areas	1		164.2	1		160	4.2	Computer area deducted from total area of library.
	Administratio Storage Area	on/Staff, Physical Education, as			147			317	-170	
7.7	CTS Areas -	- N/A								
	7.7.1 Busines	ss Education								
	7.7.2 Home E	Economics								
	7.7.3 Industri	ial Arts								
	7.7.4 Other C	CTS Programs								
		nstructional Areas (i.e., vall area, crush space, wc			858.9			870	11.1	
	Overall Space	ce Adequacy Assessment	17		2,802	16		3,025	-200.8	

This Facility

Size

No.

School: Lake Bonavista School