School: Lakeview School Date: March 18, 2000

				T		T
School Name:	Lakeview	School			School Code:	9102
Location:	6304 Lar	kspur W	ay S.W.		Facility Code:	1431
Region:	South				Superintendent:	Dr. Donna Michaels
Jurisdiction:	Calgary -	- District	19		Contact Person:	Leanne Soligo
					Telephone:	(403) 214-1123
Grades:	K - 6				School Capacity:	Total - 450
	Year of	No. of	Gross Bldg Area	Type of Construction (i.e., structure,	Description of Mechanical Systems	
Building Section	Compl.	Floors	(Sq.M.)	roof, cladding)	(incl. major upgrades)	Comments/Notes
Original Building	1961	1	1219.4	Rolled roof, wood deck, concrete	Steam heating with unit ventilators.	
				structure, masonry and stucco		
				walls, part basement, slab on		
				grade.		
Additions/	1			grado.		
Expansions						
Expansions						
	1966	1	2734.6	Same - but no basement - all slab	Hot water heat exchangers using	
				on grade. Some steel trusses in	steam from original building. Uses	
				library area.	multi-zone for this wing.	
				libiaiv area.	muiti-zone for this wind.	
I			3954.0			This total shown as 3594 on standard
			0004.0			assessment and utilization report.
						Should be 3954 m ² .
					Evaluator's Name:	Harvey Bernbaum
	+				& Company:	Bernbaum Architect Ltd.
					& Company.	Dembaum Alchitect Eta.

Upgrading/ Modernization (identify whether minor or major)				None	
Portable Struct. (identify whether attached/perman. or free-standing/ relocatable)					
relocatable)	Approx. 1985	1	190m ² plus corridor	Wood frame.	Larger portables c/w toilet and sink and furnace area - not shown on plans or standard assessment and utilization
			$10m^2$ = $200m^2$		report.
			4154 Total Gross Area		
List of Reports/ Supplementary Information				No reports available. Assisted on site by: Linda Hoban, Custodian	

Evaluation Components	Summary Assessment	Estim. Cost					
1 Site Conditions	Additional landscaping to soften impact of Glenmore Trail; barrier free parking; resolving runoff problems in parking.						
2 Building Exterior	Deferred maintenance items; allowance for renovations related to boiler upgrade; replacing windows, doors.						
Building Interior	Mainly due to deferred maintenance. Upgrade floors and white boards; paint; cabinet upgrades; gym drapes.	\$181,30					
Mechanical Systems	Generally good condition 1960s school, maintenance is good, but systems need updating and replacement.	\$513,520					
Electrical Systems	Generally good condition, maintenance is good. Needs a new fire alarm system and new exit lights, and upgrading to new technology.	\$176,160					
Portable Buildings	Painting on skirting; barrier free accessibility ramps.	\$9,00					
7 Space Adequacy:							
7.1 Classrooms	They are lacking in other areas. 136.3						
7.2 Science Rooms/Labs	Insufficient science space101.3						
7.3 Ancillary Areas	-70.2						
7.4 Gymnasium	Gym is small for the size of the school196.7						
7.5 Library/Resource Areas	Library is small - if computers could be moved, size would be close92.4						
7.6 Administration/Staff Areas	Tight area, though well organized264						
7.7 CTS Areas							
7.8 Other Non-Instructional Areas (incl. gross-up)	Large corridor, etc. in addition. 830.3						
Overall School Conditions & Estim. Costs		\$1,161,48					

Section 1	Site Conditions	Rating	Comments/Concerns	Estim. Cost
1.1	General Site Conditions			
1.1.1	Overall site size.	4	Adequate.	
1.1.2	Outdoor athletic areas.	4	Adequate.	
1.1.3	Outdoor playground areas, including condition of equipment and base.	4	2 groups playground equipment - 1 old wood, 1 newer metal - adequate.	
1.1.4	Site landscaping.	3	Mature, but could use some against freeway to block view and soften impact.	\$10,000
1.1.5	Site accessories (i.e., perimeter and other fencing, guard rails, bike stands, flag poles).	4	Adequate - freeway on north side.	
1.1.6	Surface drainage conditions (i.e., drains away from building, signs of ponding).	3	Parking ponds at east end - both winter and summer - safety concerns - should be rectified by some repaving and redirection of runoff water. Allowance for this work.	\$10,000
1.1.7	Evidence of sub-soil problems.	4	Non-evident or known.	
1.1.8	Safety and security concerns due to site conditions.	2	Some teens drinking in parking lot - chain or similar measure, to block parking lot at night would stop this activity.	\$1,500
Other				

	Site Conditions	Rating	Comments/Concerns	Estim. Cost
1.2	Access/Drop-Off Areas/Roadways/Bus Lanes			
1.2.1	Vehicular and pedestrian access points (i.e., size, number, visibility, safety).	F.I.	Parent drop off happens in parking lot as street is so full of buses and other cars. This is a dangerous situation. Further investigate how to resolve this problem and determine alternatives.	
1.2.2	Surfacing of on-site road network (note whether asphalt or gravel).	4	Asphalt.	
1.2.3	Bus lanes/drop-off areas (note whether on-site or off-site).	4	In front of school.	
1.2.4	Fire vehicle access.	4	From street and parking lot.	
1.2.5	Signage.	4	Difficult to read, but adequate as it is a private school now.	
Other				

Section 1	Site Conditions	Rating	Comments/Concerns	Estim. Cost
1.3	Parking Lots and Sidewalks			
1.3.1	Number of parking spaces for staff, students and visitors (including stalls for disabled persons).	4	Adequate - approximately 31 stalls - with plug-ins for all teachers. No designated barrier free stall at present. Provide c/w signage.	\$1,500
1.3.2	Layout and safety of parking lots.	F.I.	Lot is used for dropping kids, turning around, and staff parking cars. This could present some unsafe conditions.	
	Surfacing and drainage of parking lots (note whether asphalt or gravel).	F.I.	Poorly drained - snow blocks water route to catch basin - slippery all winter.	
1.3.4	Layout and safety of sidewalks.	4	Adequate.	
	Surfacing and drainage of sidewalks (note type of material).	4	Adequate.	
1.3.6	Curb cuts and ramps for barrier free access.		Ramp required to allow access from site to the building. Should be sensitively worked into the landscape.	\$10,000
Other				
	Oursell City Constitution & Entire and City			¢22.000
	Overall Site Conditions & Estimated Costs			\$33,000

Section 2	Building Exterior	Rating		Comments/Concerns	Estim. Cost
2.1	Overall Structure		Bldg.		
	L		Section	<u>Description/Condition</u>	
2.1.1	Floor structure and beams (i.e., signs of bending, cracking, heaving, settlement, voids, rust, stains).	4		No apparent problems.	
	cracking, neaving, settlement, voids, rust, stains).				
2.1.2	Wall structure and columns (i.e., signs of bending,	4		No apparent problems.	
	cracking, settlement, voids, rust, stains).				
242	Roof structure (i.e., signs of bending, cracking, voids,	4		No annual makilana	
2.1.3	rust, stains).	4		No apparent problems.	
	, , , , , ,				
2.1.4	Control/expansion joints.	4		No apparent problems.	
Other					

Section 2	Building Exterior	Rating		Comments/Concerns	Estim. Cost
	Roofing and Skylights		Bldg.		
	Identify the availability of an up-to-date		Section		
	inspection report or roofing program. Note if roof		or Roof		
	sections are of different ages and/or in varying		Section	Description/Condition/Age	
2.2.1	Based on the inspection report (and to the extent	F.I.		No roof report. Many leaks reported. CBE has responded and fixed some. Appears as	
	possible, direct observation), assess and rate roof			though roof needs to be totally redone.	
	conditions and estimate costs for required				
	improvements (i.e., covering materials, membrane,				
	insulation, other components).				
222	Roof accessories (i.e., ladders, stairs, hatches,	F.I.		Could not review all items - should be investigated along with 2.2.1.	
2.2.2	masts, exhaust hoods, chimneys, gutters,	Г.1.		Could not review all items - should be investigated along with 2.2.1.	
	downspouts, splashpads).				
2.2.3	Control of ice and snow falling from roof.	4		Flat roof, no problems.	
					[]
2.2.4	Skylights (i.e., signs of distress, leaks, ice build-up,	F.I.		No skylights. Clerestory lights appear to be functioning well. Cracking and chipping of	
	condensation, deteriorated materials/seals).			plaster appears roof related and should be investigated along with 2.2.1.	
Other					
Other					
					1
					[

Section 2	Building Exterior	Rating		Comments/Concerns	Estim. Cost
2.3	Exterior Walls/Building Envelope		Bldg.		
2.3.1	Exterior wall finishes (i.e., signs of deterioration, cracks, brick spalling, effluorescence, water stains).	2	Section 1961	<u>Description/Condition</u> Paint all wood siding around old building.	\$20,000
2.3.2	Fascias, soffits, parapets (i.e., signs of looseness, stains, rust, peeling paint).	4		No apparent problems.	
2.3.3	Building envelope (i.e., evidence of air infiltration/ exfiltration through the exterior wall or ice build up on wall, eaves, canopy).	4		No apparent problems.	
2.3.4	Interface of roof drainage and ground drainage systems.	4		No apparent problems.	
2.3.5	Inside faces of exterior walls (i.e., signs of cracks, water stains, dust spots).	F.I.		Roof leakage evident. Appearance of water streaks and slight movement of concrete block due to moisture.	
Other		3	1961 1966	Allowance for renovations related to boiler and ventilation upgrade.	\$50,000

Section 2	Building Exterior	Rating		Comments/Concerns	Estim. Cost
2.4	Exterior Doors and Windows		Bldg.		
2.4.1	Doors (i.e., signs of deterioration, rusting metal, glass cracks, peeling paint, damaged seals, sealed unit failure).	3	Section	Description/Condition Doors original to building and should be scheduled for replacement in the next 5 years. New doors should be of similar style to the existing. Allowance for doors and associated repairs.	\$10,000
2.4.2	Door accessories (i.e., latches, hardware, screens, locks, alarms, holders, closers, security devices).	3		Allow for replacement at same time as 2.4.1.	\$10,000
2.4.3	Exit door hardware (i.e., safety and/or code concerns).	3		No apparent problems, but we recommend an allowance for some upgrading.	\$3,000
2.4.4	Windows (i.e., signs of deterioration, rusting metal, glass cracks, peeling paint, damaged seals, sealed unit failure).	2	1961	Sand and repaint windows facing south into "courtyard".	\$500
		3		Windows are in reasonable condition considering they are mostly original, but replacement should be scheduled. Should be replaced in style of original building within 5 years.	\$150,000
2.4.5	Window accessories (i.e., latches, hardware, screens, locks, alarms, holders, closers, security devices).		1961	Replace screens on small upper venting windows.	\$5,000
		3		Should be replaced when windows replaced. Replace inoperable hardware with appropriate pieces. See 2.4.4 for costs.	
2.4.6	Building envelope (i.e., signs of heavy condensation on doors or windows).	4		No apparent problems.	
Other					
	Overall Bldg Exterior Condition & Estim Costs				\$248,500

Section 3	Building Interior - Overall Conditions	Rating		Comments/Concerns	Estim. Cost
3.1	Interior Structure		Bldg.		
3.1.1	Interior walls and partitions (i.e., signs of cracks, spalling, paint peeling).	F.I.	1961	Description/Condition Water damage has already been reported to CBE. Not yet major in classification.	
3.1.2	Floors (i.e., signs of cracks, heaving, settlement).	4		Corridor floor in original building is concrete, and shows some telegraphing through floor tile, indicating movement shortly after building constructed. No longer is it moving.	
Other					
3.2	Materials and Finishes		Bldg.		
			Section	Description/Condition	
3.2.1	Floor materials and finishes.	2	1961	(a) Rug in classroom 1004 is very loose and worn out. (b) Vinyl tile in office area is worn out.	\$5,000
			1961	(c) Replace 2 nosing strips - stair to back stage.	
		3		V/A tile in corridor should be scheduled for replacement - original to building. Schedule in next 5 years.	\$30,000
3.2.2	Wall materials and finishes.			Paint: (a) Janitor room ceiling.	
		2	1961	(b) Wall at clear story windows in north corridor.	\$3,000
			1961	(c) Skylight frame and surround in art room.	
		3	1961 1966	Repaint 80% of interior in next 5 years.	\$40,000
3.2.3	Ceiling materials and finishes.	3	1961 1966	Water damaged tiles (see 2.2.1 for further investigation of roof and leaks). Replace water damaged tiles - allowance and begin upgrade to new tiles over next 5 years.	\$55,000

	Building Interior - Overall Conditions	Rating		Comments/Concerns	Estim. Cost
3.2	Materials and Finishes (cont'd)		Bldg.	- 1.1.15 m	
3.2.4	Interior doors and hardware.	3	Section 1961	Description/Condition Repair back plate on inside of door from girls washroom to mud room area.	\$100
3.2.5	Millwork	3	1961	Adequate - most original to building. Allowance for some upgrading of tops, door repairs.	\$10,000
3.2.6	Fixed/wall mounted equipment (i.e., writing boards, tackboards, display boards, signs).	3	1961 1966	Older black boards should be upgraded to current standard of white board.	\$8,000
3.2.7	Any other fixed/mounted specialty items (i.e., CTS equipment, gymnasium equipment).	3		Minimal, but apparently adequate. Drapes in gym should be replaced and are likely a fire hazard. Allowance for new stage curtains.	\$10,000
3.2.8	Washroom materials and finishes.	4		Adequate.	
Other	1. Roof drains through building.	F.I.		Evidence of leakage down drain pipes in building. Flashing on roof around drains, or drains themselves are not sealed properly. Check out while evaluating roof.	4000
	2. Fan room.	3	1961	Custodian should instruct teachers to not store tricycles in fan room, and move items to another more appropriate space.	\$200

	Building Interior - Overall Conditions	Rating		Comments/Concerns	Estim. Cost
3.3	Health and Safety Concerns Intent is to identify renovations considered necessary to		Bldg. Section	Description/Condition	
	meet applicable codes, primarily due to safety concerns. Basis of evaluation should be an up-to-date inspection report from the authority having jurisdiction together with direct observations as appropriate. Evaluator should note if in his opinion a comprehensive code evaluation is				
	Building construction type - combustible or non- combustible, sprinklered or non-sprinklered.	4		Non-combustible - not sprinklered.	
	Fire separations (i.e., between buildings, wings, zones if non-sprinklered).	4		Adequate for the age of building.	
	Fire resistance rating of materials (i.e., corridor walls and doors).	4		Adequate.	
3.3.4	Exiting distances and access to exits.	4		Adequate.	
3.3.5	Barrier-free access.	3		barrier free toilet exists in boys washroom, but is small and should be brought up to standard - size should be reviewed. Barrier free toilet to be added to girls washroom.	\$20,00
	Availability of hazardous materials audit (i.e., evidence of safety concerns with respect to asbestos, PCB's, chemicals).	4		In process with CBE having removed some around mechanical piping.	
	Other health and safety concerns (i.e., evidence of excessive noise conditions, air quality problems)	4		Noisy from Glenmore Trail in parking lot and playground. School north rooms are aware of the noise, but classrooms are still used.	
Other					
	Overall Bldg Interior Condition & Estim Costs				\$181,30

Section 4	Mechanical Systems	Rating		Comments/Concerns	Estim. Cost
4.1	Mechanical Site Services				
4.1.1	Site drainage systems (i.e., surface and underground systems, catch basins).	3		Catch basins in parking lot (slopes a problem) roof drains tied into internal piping (see 1.1.6). Catch basin rim may require lowering. Allowance for alterations.	
4.1.2	Exterior plumbing systems (i.e., irrigation systems, hose bibs).	3		They do not water grass, no irrigation, hose bibbs need back flow prevention.	\$10,000
4.1.3	Outside storage tanks.	n/a			
Other		n/a			
4.2	Fire Suppression Systems		Bldg. Section	Description/Condition	
4.2.1	Fire hydrants and siamese connections.	4	Section	Hydrant across playing field, second one about 1/4 block away by main entrance, no siamese connection.	
4.2.2	Fire suppression systems (i.e., pumps, sprinklers, piping, reservoirs, hoses, stand pipes, CO2 systems).	4		Fire hose cabinet.	
4.2.3	Hand extinguishers, blankets and showers (i.e., in CTS areas).	4		Fire extinguishers tested January 2000.	
4.2.4	Other special situations (e.g., flammable storage areas, science labs, CTS areas).	n/a			
Other		n/a			

	Mechanical Systems	Rating		Comments/Concerns	Estim. Cost
4.3	Water Supply and Plumbing Systems		Bldg.	Description (Our differen	
4.3.1	Domestic water supply (i.e., pressure, volume, quality note whether municipal or well supply).	4	Section	Description/Condition City of Calgary.	
4.3.2	Water treatment system(s).	4		By City of Calgary.	
4.3.3	Pumps and valves (including backflow prevention valves).	3		Back flow prevention on fire hose cabinet and boilers, not on main service.	\$6,000
4.3.4	Piping and fittings.	4		Adequate.	
4.3.5	Plumbing fixtures (i.e., toilets, urinals, sinks)	4		One bank of urinal runs continuously - repair.	
4.3.6	Domestic hot water system (i.e., heater, storage tanks, failure alarms, pressure, volume, recirculation).	4		John Wood 33.3 gallon 32,400 BTU/HR recirculation pump (leaking joints).	
4.3.7	Sanitary and storm sewers, including sumps and pits (note whether sewage system is municipal or septic).	4		City of Calgary - sump in boiler room for boiler room.	
Other		3		No ventilation in gas meter room.	\$2,500

Section 4	Mechanical Systems	Rating		Comments/Concerns	Estim. Cost
4.4	Heating Systems		Bldg.		
4.4.1	Heating capacity and reliability (including backup capacity).	3	1961	Description/Condition Older section is steam. Newer wing used hot water. Steam boiler is Dominion Bridge 97.8 sq. ft. Do a major mechanical upgrade.	\$177,930
4.4.2	Heating controls (including use of current energy management technology.	4		Pneumatic two compressors and tanks, no refrigerated after cooler.	
4.4.3	Fresh air for combustion and condition of the combustion chimney.	4		Combustion air and relief air.	
4.4.4	Treatment of water used in heating systems.	4		Pot feeder for steam boiler pot feeder and micron filter for hot water heat exchanger.	
4.4.5	Low water cutoff/pressure relief valves and failure alarms (i.e., hot water heating).	4		Adequate.	
4.4.6	Heating air filtration systems and filters.	4		Unit ventilators in older section, multi-zone unit in newer section.	
4.4.7	Heating humidification systems and components.	n/a			

Section 4	Mechanical Systems	Rating		Comments/Concerns	Estim. Cost
4.4	Heating Systems (cont'd)		Bldg.		
4.4.8	Heating distribution systems (i.e., piping, ductwork) and associated components (i.e., diffusers, radiators).	4	Section	<u>Description/Condition</u> Adequate.	
4.4.9	Heating piping, valve and/or duct insulation.	4		Adequate.	
4.4.10	Heat exchangers.	4		Steam to hot water heat exchange for new wing, two pumps.	
4.4.11	Heating mixing boxes, dampers and linkages.	4		On multizone.	
4.4.12	Heating distribution/circulation in larger spaces (i.e., user comfort, temperature of outside wall surfaces).	4		Temperature appears uniform.	
4.4.13	Zone/unit heaters and controls.	4		Thermostat/classroom.	
Other		n/a			

Section 4	Mechanical Systems	Rating		Comments/Concerns	Estim. Cost
4.5	Ventilation Systems		Bldg.		
4.5.1	Air handling units capacity and condition.	3	<u>Section</u> 1961 1966	<u>Description/Condition</u> Newer wing uses Trane Multizone T-17MZ 10 zones. Upgrade ventilation at same time as 4.4.1.	\$197,770
4.5.2	Outside air for the occupant load (if possible, reference CFM/occupant).	4		Appear okay except in portables.	
	Air distribution system (if possible, reference number of air changes/hour).	4		Appear okay except in portables.	
4.5.4	Exhaust systems capacity and condition.	4		Adequate.	
4.5.5	Separation of out flow from air intakes.	4		Adequate.	
4.5.6	Special/dedicated ventilation and/or exhaust systems (i.e., kitchen, labs, CTS areas).	3		Should add hood to stove.	\$700
Other		n/a			

Section 4	Mechanical Systems	Rating		Comments/Concerns	Estim. Cost
4.5	Ventilation Systems (cont'd)		Bldg.		
			Section	<u>Description/Condition</u>	
	Note: Only complete the following items if there are separate ventilation and heating systems.			Not separate.	
4.5.7	Ventilation controls (including use of current energy management technology).	4		No indication of problems.	
4.5.8	Air filtration systems and filters.	4		No indication of problems.	
4.5.9	Humidification system and components.	4		No indication of problems.	
4.5.10	Heat exchangers.	4		No indication of problems.	
4.5.11	Ventilation distribution system and components (i.e., ductwork, diffusers, mixing boxes, dampers, linkages).	4		No indication of problems.	
Other		n/a			

	Mechanical Systems	Rating		Comments/Concerns	Estim. Cost
4.6	Cooling Systems		Bldg.		
	Cooling system capacity and condition (i.e., chillers, cooling towers, condensers).	n/a	Section	<u>Description/Condition</u>	
	Cooling distribution system and components (i.e., ductwork, diffusers, mixing boxes, dampers, linkages)	n/a			
	Cooling system controls (including use of current energy management technology).	n/a			
	Special/dedicated cooling systems (i.e., labs, CTS areas).	n/a			
Other		n/a			
4.7	Building Control Systems		Bldg. Section	Description/Condition	
	Building wide/system wide control systems and/or energy management systems.	3	1961 1966	Upgrade controls at the same time as 4.4.1 and 4.5.1.	\$118,620
	Overall Mech Systems Condition & Estim. Costs				\$513,520

Section 5	Electrical Systems	Rating		Comments/Concerns	Estim. Cost
	Site Services				
5.1.1	Primary service capacity and reliability (i.e., access, location, components, installation, bus sizes - note whether overhead or underground).	4		350 amps 120/208/3.	
5.1.2	Site and building exterior lighting (i.e., safety concerns).	4		Minimal exterior lighting - not an issue to school.	
5.1.3	Vehicle plug-ins (i.e., number, capacity, condition).	4		16 duplex paint and replace weatherproof covers as required.	
Other		n/a			
5.2	Life Safety Systems		Bldg.		
5.2.1	Fire and smoke alarm systems (i.e., safety concerns, up-to-date technology, regularly tested).	3	1961 1966	Description/Condition 120 volt system, needs more pull station, change to supervised system.	\$10,000
5.2.2	Emergency lighting systems (i.e., safety concerns, condition).	4		Battery packs and remote heads.	
5.2.3	Exit lighting and signage (i.e., safety concerns, condition).	3	1961 1966	Exit lights should be replaced and tied into battery packs.	\$4,500
Other		n/a			

Section 5	Electrical Systems	Rating		Comments/Concerns	Estim. Cost
5.3	Power Supply and Distribution		Bldg.		
			Section		
5.3.	Power service surge protection.	4		Power bars on computers.	
5.3.3	Panels and wireways capacity and condition.	4		Panels are fairly full.	
0.0.2	Transis and wireways capacity and condition.	-		i anels are famy full.	
5.3.3	Emergency generator capacity and condition and/or	n/a			
	UPS (if applicable).				
5.3.4	General wiring devices and methods.	4		Adequate.	
5.3.5	Motor controls.	4		Parts may become a problem due to age of components.	
Othe	r	n/a			

Section 5	Electrical Systems	Rating		Comments/Concerns	Estim. Cost
5.4	Lighting Systems		Bldg.		
			Section	Description/Condition	
5.4.1	Interior lighting systems and components (i.e.,	3	1961	Gym 25-30FC(fluorescent), library 40-65FC(fluorescent), classrooms 40-	\$158,160
	illumination levels, conditions, controls).			95FC(fluorescent), corridor 10-40FC (fluorescent). Upgrade lighting to T-8 lamps and	
				energy efficient ballasts.	
5.4.0	Replacement of ballasts (i.e., health and safety	4		Only on fallows	
3.4.2	concerns).	4		Only on failure.	
	55.155.115/1				
5.4.3	Implementation of energy efficiency measures and	4		T-12 technology.	
	recommendations.				
Other		n/a			
Other		II/a			
					
					
					
					
					1

Section 5	Electrical Systems	Rating		Comments/Concerns	Estim. Cost
5.5	Network and Communication Systems		Bldg.		
5.5.1	Telephone system and components (i.e., capacity, reliability, condition).	4	Section	<u>Description/Condition</u> Nortel Meridian and Nortel Star Talk Flash.	
5.5.2	Other communication systems (i.e., public address, intercom, CCTV, satellite or cable TV).	4		Intercom.	
5.5.3	Network cabling (if available, should be category 5 or better).	4		Appears to be Category 5 but not labeled.	
5.5.4	Network cabling installation (i.e., in conduit, secured to walls or tables).	2	1961	Generally okay except center bank has wiring across floor - (trip hazard). These should be fed from pack poles.	\$3,500
5.5.5	Wiring and telecommunication closets (i.e., size, security, ventilation/cooling, capacity for growth).	4		None, switch gear for telephone in crawl space (tunnels).	
5.5.6	Provision for dedicated circuits for network equipment (i.e., hubs, switches, computers).	4		Appears adequate.	
Other		n/a			

	Electrical Systems	Rating		Comments/Concerns	Estim. Cost
5.6	Miscellaneous Systems		Bldg.		
			Section	<u>Description/Condition</u>	
5.6.1	Site and building surveillance system (if applicable).	n/a			
5.6.2	Intrusion alarms (if applicable).	4		By CBE.	
562	Master clock system (if applicable).	n/a		Bells only.	
5.0.5	iviaster clock system (ii applicable).	II/a		Beils Offly.	
Other		n/a			
		1,, a			
5.7	Elevators/Disabled Lifts (If applicable)				
	Elevator/lift size, access and operating features (i.e.,	n/a			
	sensing devices, buttons, phones, detectors).	.,,			
5.7.2	Condition of elevators/lifts.	n/a			
5.7.3	Lighting and ventilation of elevators/lifts.	n/a			
Other		n/a			
	Overall Elect. Systems Condition & Estim Costs				\$176,160

Section 6	Portable Buildings	Rating	Comments/Concerns	Estim. Cost
	Note: Separate sheets can be completed, if necessary, for portable buildings of different ages and/or conditions.		2 portables added in the 1980's.	
6.1.1	Foundation and structure (i.e., signs of bending, cracking, settlement, rust, voids, stains).	4	Wood structure - no apparent problems.	
6.1.2	Roof materials and components (i.e., signs of deterioration, leaks, ice build-up).	4	No apparent problems.	
6.1.3	Exterior wall finishes (i.e., signs of deterioration, cracks, water stains).	3	Skirting should be painted.	\$2,000
6.1.4	Doors and windows (i.e., signs of deterioration, rusting hardware, glass cracks, peeling paint, damaged seals).	4	No apparent problems.	
6.1.5	Interior finishes (i.e., floors, walls, ceiling).	4	No apparent problems.	
6.1.6	Millwork (i.e., counters, shelving, vanities, cabinets).	4	No apparent problems.	
6.1.7	Fixed/wall mounted equipment (i.e., writing boards, tackboards, display boards, signs)	4	No apparent problems.	
6.1.8	Heating system.	4	Furnaces - see below comments.	
6.1.9	Ventilation system.	3	Appears to run only on call for heat and rooms are stale smelling - should rework to allow for continuous ventilation.	\$2,000
6.1.10	Electrical, communication and data network systems.	4	Lighting levels okay, power okay.	
6.1.11	Health and safety concerns (i.e., fire and smoke alarms, fire protection systems, exiting, fire resistance rating of materials).		No apparent problems. No mechanical or electrical concerns.	
6.1.12	Barrier-free access.	3	Portable units are not accessible at present. Provide ramps from portables to grade for exiting.	\$5,000
	Overall Portable Bldgs Condition & Estim Costs			\$9,000

7.8 Other Non-Instructional Areas (i.e., circulation, wall area, crush space, wc

Overall Space Adequacy Assessment

Section 7	Space Adequacy - Capacity: 450	This Facility			Equiv. New Facility			Surplus/	
		No.	Size	Total Area	No.	Size	Total Area	Deficiency	Comments/Concerns
7.1	Classrooms	14		1,096.3	12	80	960	136.3	Portables not included.
7.2	Science Rooms/Labs	1		88.7	2	95	190	-101.3	
7.3	Ancillary Areas (i.e., Art, Computer Labs, Drama, Music) - Total	4		329.8	4		400	-70.2	
	Computers		60						Portion of library, but separate area.
	Music		111						
	Art		103.1						
	Drama (stage)		55.7						
7.4	Gymnasium (incl. gym storage)	1		276.3	1		473	-196.7	
7.5	Library/Resource Areas	1		127.6	1		220	-92.4	
7.6	Administration/Staff, Physical Education, Storage Areas			163			427	-264	
7.7	CTS Areas								N/A
	7.7.1 Business Education								
	7.7.2 Home Economics								
	7.7.3 Industrial Arts								
	7.7.4 Other CTS Programs								

1042

3,712

830.3

242

Excessive corridor and crush space with building addition.

1,872.3

3,954

20

21

School: Lakeview School

Date: March 18, 2000