

RECAPP Facility Evaluation Report

Lloydminster Pub Sch #1753



Martin Browne School

B3727A

Lloydminster (AB)

Facility Details

Building Name: Martin Browne School
Address: 4812 - 56 Avenue
Location: Lloydminster (AB)

Building Id: B3727A
Gross Area (sq. m): 1,097.08
Replacement Cost: \$3,768,000
Construction Year: 1958

Evaluation Details

Evaluation Company: KOLIGER SCHMIDT architect-engineer

Evaluation Date: September 6 2012

Evaluator Name: Steve Horvath KOLIGER SCHMIDT architect-engineer

Total Maintenance Events Next 5 years: **\$385,600**
5 year Facility Condition Index (FCI): **10.23%**

General Summary:

Martin Browne a K - 12 school was originally built in 1958 with an area of 570m². An addition was added in 1998 consisting of a storage room at the south west and classrooms and offices at the north with an area of 360m²; at this time the original building was also modernized. The total building area is 930m². The building is one storey in height. Two portables were added one in 2005 and the other in 2007 with a total area of 260m². The total area would be 1190m² for all areas. Currently there are 110 students administered by 16 staff.

Structural Summary:

The foundations consist of concrete foundation wall on concrete strip footing along perimeter for 1958 section, concrete grade beam on concrete piles for the 1998 section, concrete slab on grade in Crawl Spaces; wood joists for floor; wood studs for exterior and interior walls; roof has wood deck on wood trusses for both sections.

Overall structural system rating is acceptable.

Envelope Summary:

The exterior wall finish consists of painted facing brick and stucco for exterior walls for 1958 section; metal siding for the 1998 section. The windows are wood framed stationary sash for the south portion of the 1958 section and vinyl windows with stationary and operable sashes for the rest in both phases. Entries consist of metal framed storefront doors for all areas. The 1958 building has metal fascias with plywood soffits, the 1998 section has metal fascias with wood battens. The roofs are flat for both sections; consisting of built-up tar and gravel roofing for the 1958 section and EPDM roofing for the 1998. The roofs are drained with roof drains with internal downspouts for the 1958 area and scupper drains with downspouts spilling onto splash pads for the 1998 area.

Overall envelope system rating is acceptable.

Interior Summary:

The front entries lead to a spacious corridor (multi purpose area) which extends from from the north to the south end of the school. Adjacent to the north entry are the offices and library. A secondary entrance is located at the back of the building directly across from the north entry. The floor finishes consist of vinyl tiles for most areas, ceramic tiles for the boys and girls washrooms, carpet for the administration area, library and parts of some classrooms. The ceilings consist of suspended T-bar acoustic ceiling tiles for the majority of the ceilings, painted gypsum board for the washrooms, fiberboard ceiling tiles for the multi purpose area. The walls are painted gypsum board for all areas. Interior glazing in steel frames is located by the office area. The interior doors consist of solid wood in steel frames for all areas. The classrooms are equipped with chalkboards, white boards, tackboards, projection screens. The 1958 area of the building was modernized in 1998.

Overall interior system rating is acceptable.

Mechanical Summary:

The school is heated with an gas fired, hot water boiler that supplies finned tube radiation, convectors, heating coils and entrance force flows. The kindergarten area of the school has a furnace that provides heating, ventilation and cooling. The domestic water heater is gas fired. There are both flush valve and flush tank water closets. The urinals are flush tank with timers. There are wall hung lavatories in the washrooms and stainless steel sinks in the classrooms.

The mechanical systems are in acceptable condition.

Electrical Summary:

Martin Browne School is fed from a 120/240V1PH/3W residential power service. 400A-120/240V/1PH/3W main distribution switchboard, branch circuit panelboards located throughout school, manual motor starters, incandescent light fixtures, surface and recess mounted fluorescent light fixtures with T8 lamps and electronic ballasts, DC emergency lighting, wall mounted high pressure sodium light fixtures located along building perimeter and entry vestibules, fire alarm system, intrusion detection system, wall mounted DC clocks, Toshiba telephone system, and Cat 5E data system.

Electrical in acceptable condition.

| Rating Guide | |
|-------------------------|---|
| Condition Rating | Performance |
| 1 - Critical | Unsafe, high risk of injury or critical system failure. |
| 2 - Poor | Does not meet requirements, has significant deficiencies. May have high operating/maintenance costs. |
| 3 - Marginal | Meets minimum requirements, has significant deficiencies. May have above average operating maintenance costs. |
| 4 - Acceptable | Meets present requirements, minor deficiencies. Average operating/maintenance costs. |
| 5 - Good | Meets all present requirements. No deficiencies. |
| 6 - Excellent | As new/state of the art, meets present and foreseeable requirements. |

S1 STRUCTURAL**A1010 Standard Foundations***

Concrete foundation walls on continuous concrete strip footings for 1958, Concrete grade beams on concrete piles for 1998

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------------|-------------------------|---------------------------|-----------------------|
| 4 - Acceptable | 1958 | 0 | JAN-13 |

A1030 Slab on Grade*

Concrete slab for crawl space and mechanical room

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------------|-------------------------|---------------------------|-----------------------|
| 4 - Acceptable | 1958 | 0 | JAN-13 |

A2020 Basement Walls (& Crawl Space)*

Concrete walls in crawl space for both sections.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------------|-------------------------|---------------------------|-----------------------|
| 4 - Acceptable | 1958 | 0 | JAN-13 |

B1010.01 Floor Structural Frame (Building Frame)* -

Wood joist on concrete walls for 1958 and 1998 sections.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------------|-------------------------|---------------------------|-----------------------|
| 4 - Acceptable | 1958 | 0 | JAN-13 |

B1010.02 Structural Interior Walls Supporting Floors (or Roof)*

Wood studs for 1958 and 1998 sections

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------------|-------------------------|---------------------------|-----------------------|
| 4 - Acceptable | 1958 | 0 | JAN-13 |

B1010.03 Floor Decks, Slabs, and Toppings*

Wood joists with plywood deck for 1958 and 1998 sections.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------------|-------------------------|---------------------------|-----------------------|
| 4 - Acceptable | 1958 | 0 | JAN-13 |

B1010.06 Ramps: Exterior*

Southeast Entrance - has a concrete ramp.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|---------------|------------------|--------------------|----------------|
| 3 - Marginal | 1958 | 0 | JAN-13 |

Event: Install 3m of railing on wall and wheel guard at 50mm from ramp surface on existing railing

Concern:

Ramp does not have a railing on both sides. No wheel guard at bottom of existing rail

Recommendation:

Provide steel tube railing on exterior wall and a wheel guard at 50mm above ramp on existing rail.



Ramp does not have a railing on both sides. No wheel guard at bottom of existing rail.

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------------|-------------|-------------|-----------------|
| Barrier Free Access Upgrade | 2013 | \$1,400 | High |

Updated: JAN-13

B1010.09 Floor Construction Fireproofing*

No fireproofing required as crawl spaces are divided into areas not exceeding 5000m²

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 0 | JAN-13 |

B1010.10 Floor Construction Firestopping*

No firestopping required as crawl spaces are divided into areas not exceeding 5000m²

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 0 | JAN-13 |

B1020.01 Roof Structural Frame*

Wood deck on wood roof joists for 1958 and 1998 Sections.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 0 | JAN-13 |

B1020.06 Roof Construction Fireproofing*

Combination of gypsum board and acoustic suspended ceiling tiles.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 0 | JAN-13 |

B1020.07 Roof Construction Firestopping*

Plaster around conduits and pipes piercing fire separation.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 0 | JAN-13 |

S2 ENVELOPE**B2010.01.02.01 Brick Masonry: Ext. Wall Skin* - 1958 Section**

Exterior walls from top of foundation to window sills - have facing bricks.
Chimney above flat roof - has facing bricks.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 0 | JAN-13 |

B2010.01.06.03 Metal Siding**

Addition attached to Northwest corner of the original building - has metal siding.
Addition attached to the Southwest corner of the original building -.Storage 119 - has metal siding.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 40 | JAN-13 |

Event: Replace 160m² metal siding.

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2038 | \$25,200 | Unassigned |

Updated: JAN-13

B2010.01.08 Cement Plaster (Stucco): Ext. Wall* - 1958 Section

Upper portion of exterior walls from window sills to fascia - have stucco finish.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 0 | JAN-13 |

B2010.01.11 Joint Sealers (caulking): Ext. Wall**

Caulked joints at junction of exterior cladding with door and window frames.1958 section recaulked at this time.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 20 | JAN-13 |

Event: Replace 210m Caulking

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2018 | \$7,400 | Unassigned |

Updated: JAN-13

B2010.01.13 Paints (& Stains): Ext. Wall**

Painted exterior bricks and soffits for 1958 section, repainted in 1998.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 15 | JAN-13 |

Event: Repaint 200m² exterior walls and soffits.

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2016 | \$4,900 | Unassigned |

Updated: JAN-13

B2010.02.05 Wood Framing: Ext. Wall Const.*

Wood studs with plywood sheathing on exterior and painted gypsum board on interior for 1958 and 1998 sections.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 0 | JAN-13 |

B2010.03 Exterior Wall Vapour Retarders, Air Barriers, and Insulation*

Polyethylene vapour barrier and batt insulation in stud cavities for 1958 and 1998 sections.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 0 | JAN-13 |

B2010.09 Exterior Soffits* - 1958

Painted wood soffits with painted metal fascias.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 0 | JAN-13 |

B2010.09 Exterior Soffits* - 1998

Prefinished metal fascias, entries have prefinished metal soffits.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 0 | JAN-13 |

B2020.01.01.05 Wood Windows (Glass & Frame) - 1958 Section**

Wood casement windows on upper portion of South walls

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 35 | JAN-13 |

Event: Replace 15m² Vinyl Windows.

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2016 | \$15,600 | Unassigned |

Updated: JAN-13

B2020.01.01.06 Vinyl, Fibreglass & Plastic Windows - 1998 Section**

PVC windows with fixed and operating sash for 1998 section, 1958 Section classroom windows replaced in 2004.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 2001 | 40 | JAN-13 |

Event: Replace 30m² Vinyl windows.

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2041 | \$33,000 | Unassigned |

Updated: JAN-13

B2030.01.02 Steel-Framed Storefronts: Doors**

Entries to school have steel framed storefront doors with glazed panels. 1958 Section entries were replaced at this time.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 30 | JAN-13 |

Event: Replace 10 steel framed storefront doors.

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2038 | \$28,900 | Unassigned |

Updated: JAN-13

B2030.02 Exterior Utility Doors**

Storage 119, Mechanical Room 110 - have metal door and metal frame.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 40 | JAN-13 |

Event: Replace 2 exterior utility doors.

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2038 | \$2,100 | Unassigned |

Updated: JAN-13

B3010.01 Deck Vapour Retarder and Insulation* - 1958 Section

Mopped on tar with rigid insulation for all phases.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 0 | JAN-13 |

B3010.04.01 Built-up Bituminous Roofing (Asphalt & Gravel)**

Built-up roofing with gravel.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|---------------|------------------|--------------------|----------------|
| 3 - Marginal | 1958 | 25 | JAN-13 |

Event: Replace 570m² built-up roofing.

Concern:

Original built-up roofing has blisters, ponding and poor drainage to roof drains.

Recommendation:

Replace built-up roofing and provide proper slopes to roof drains.

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|---------------------|-------------|-------------|-----------------|
| Failure Replacement | 2013 | \$119,500 | High |

Updated: JAN-13

B3010.04.05 Membrane Roofing (Single Ply, EPDM, PVC, TPO)**

EPDM roofing.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 25 | JAN-13 |

Event: Replace 360m² EPDM roofing.

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2023 | \$84,900 | Unassigned |

Updated: JAN-13

B3010.08.02 Metal Gutters and Downspouts**

Scuppers with downspouts utilized, also one integral roof drain above demising corridor.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 30 | JAN-13 |

Event: Install 30m of downspouts and extension with 4 scuppers.

Concern:

Downspouts do not have sufficient extensions away from building. One area does not have any scuppers or downspouts.

Recommendation:

Install downspout extension for a minimum of 1.2m away from building. Install four scuppers with downspouts and proper extensions.

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|------------------------------|-------------|-------------|-----------------|
| Operating Efficiency Upgrade | 2013 | \$5,500 | High |

Updated: JAN-13

Event: Replace 25m scuppers and downspouts.

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2028 | \$5,500 | Unassigned |

Updated: JAN-13

S3 INTERIOR

C1010.01 Interior Fixed Partitions*

Wood stud walls clad with gypsum board for all phases.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 0 | JAN-13 |

C1010.02 Interior Demountable Partitions*

Resource Room 115, Principal 116, Administration 117, Library 118, Circulation 120 - have interior demountable partitions.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 0 | JAN-13 |

C1010.05 Interior Windows*

Principal 116, Resource Room 115 - have clear glass in steel frames

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|---------------|------------------|--------------------|----------------|
| 3 - Marginal | 1958 | 0 | JAN-13 |

Event: Install 10m² of wired glass in steel frames.

Concern:

Interior windows at corridor do not have wired glass.

Recommendation:

Install wired glass to replace regular glazing.

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-------------|-------------|-------------|-----------------|
| Code Repair | 2013 | \$11,500 | High |

Updated: JAN-13

C1020.01 Interior Swinging Doors (& Hardware)*

Painted wood doors in metal frames. 1958 section replaced at this time.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 0 | JAN-13 |

C1020.03 Interior Fire Doors*

Mechanical room door is metal clad wood door in steel frame.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|---------------|------------------|--------------------|----------------|
| 3 - Marginal | 1998 | 0 | JAN-13 |

Event: Install 3/4 hr. rated door in mechanical room.

Concern:

Mechanical room door is steel clad wood door and does not have a fire door label. A 3/4hr rating is required.

Recommendation:

Install a 3/4 fire rated door with an automatic closer.

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-------------|-------------|-------------|-----------------|
| Code Repair | 2012 | \$1,000 | High |

Updated: JAN-13

C1030.01 Visual Display Boards**

Classrooms - have tack boards, green chalkboards, projection screens and white boards. 1958 section replaced in 1998.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 20 | JAN-13 |

Event: Replace 20 visual display boards.

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2018 | \$15,800 | Unassigned |

Updated: JAN-13

C1030.02 Fabricated Compartments (Toilets/Showers)**

Boys and girls Washrooms have prefinished metal toilet partitions. 1958 section replaced in 1998.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 30 | JAN-13 |

Event: Replace 8 fabricated compartments (toilets)

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2028 | \$11,300 | Unassigned |

Updated: JAN-13

C1030.08 Interior Identifying Devices*

All rooms have engraved plastic identifying signs.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 0 | JAN-13 |

C1030.10 Lockers**

Metal lockers located in several classrooms

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 30 | JAN-13 |

Event: Replace 40 Metal Lockers

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2018 | \$23,100 | Unassigned |

Updated: JAN-13

C1030.12 Storage Shelving*

Storage areas have wood shelves.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 0 | JAN-13 |

C1030.14 Toilet, Bath, and Laundry Accessories*

Boys and Girls Washrooms, Staff Washroom - have paper towel, soap dispensers and mirrors over vanities. 1958 section replaced in 1998.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 0 | JAN-13 |

C1030.17 Other Fittings*

Wood and metal boot racks provide at secondary entry.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 0 | JAN-13 |

C3010.03 Plaster Wall Finishes (Unpainted)*

Mechanical room has unpainted wall and ceiling finishes.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 0 | JAN-13 |

C3010.11 Interior Wall Painting*

All walls - have painted finish, 1958 section repainted in 1998.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 0 | JAN-13 |

C3020.01.02 Painted Concrete Floor Finishes*

Boiler Room 108 - has painted concrete floor.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|---------------|------------------|--------------------|----------------|
| 3 - Marginal | 1958 | 0 | JAN-13 |

Event: Repaint 28m² concrete floor.

Concern:

Boiler Room - paint on concrete floor has faded.

Recommendation:

Repaint concrete floor

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|---------------------|-------------|-------------|-----------------|
| Failure Replacement | 2012 | \$1,500 | Low |

Updated: JAN-13

C3020.02 Tile Floor Finishes**

Boys and Girls Washrooms, Staff Washroom 122 - have ceramic floor tiles. 1958 section installed in 1998.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 50 | JAN-13 |

Event: Replace 42m² ceramic floor tiles.

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2048 | \$8,500 | Unassigned |

Updated: JAN-13

C3020.07 Resilient Flooring**

Corridors, Classrooms, Multipurpose Room, Storage have vinyl floor tiles, 1958 section replaced at this time.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 20 | JAN-13 |

Event: Replace 630m² sheet vinyl flooring.

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2018 | \$60,500 | Unassigned |

Updated: JAN-13

C3020.08 Carpet Flooring**

Staff Room, Resource Room, Principal, Administration, Library and kindergarten have carpet. 1958 areas replaced in 1998.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 15 | JAN-13 |

Event: Replace 230m² carpet.

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2016 | \$20,100 | Unassigned |

Updated: JAN-13

C3030.06 Acoustic Ceiling Treatment (Susp. T-Bar)**

All areas except main corridor, Boys and Girls Washrooms, Staff Washroom , Boiler Room and storage room.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 25 | JAN-13 |

Event: Replace 660m² acoustic ceiling treatment (Susp.T-Bar).

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2023 | \$36,900 | Unassigned |

Updated: JAN-13

C3030.07 Interior Ceiling Painting*

Boys and Girls Washrooms, Staff Washroom , Boiler Room and storage room - have painted drywall ceiling. 1958 section painted in 1998.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 0 | JAN-13 |

C3030.09 Other Ceiling Finishes*

Fiberboard ceiling tiles adhered to roof joist in main corridor.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 0 | JAN-13 |

S4 MECHANICAL

D2010.04 Sinks**

There are stainless steel single compartment sinks in the staff room and the classrooms There is a floor mounted service sink in the mechanical room.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 30 | JAN-13 |

Event: Add a Vacuum Breaker (1)

Concern:

Service Sink in Mechanical Room has no vacuum breaker and soap dispenser is connected directly into the supply.

Recommendation:

Add a vacuum breaker or backflow device.

Consequences of Deferral:

Soap and chemicals can be drawn into the domestic water system.

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-------------|-------------|-------------|-----------------|
| Repair | 2013 | \$1,200 | High |

Updated: JAN-13



Service Sink in Mechanical Room.

Event: Replace Stainless Steel Sinks (6) and Service Sink (1)

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2028 | \$14,000 | Unassigned |

Updated: JAN-13

D2010.08 Drinking Fountains/Coolers**

There is a vitreous china single bubbler in the corridor and a double cast iron drinking fountain.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 35 | JAN-13 |

Event: Replace Drinking Fountain (1)

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2016 | \$2,000 | Unassigned |

Updated: JAN-13

Event: Replace Drinking Fountain (1)

Concern:

Drinking fountain is rusting and unsightly.

Recommendation:

Replace drinking fountain.

Consequences of Deferral:

Unattractive and unsanitary drinking fountain.

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|---------------------|-------------|-------------|-----------------|
| Failure Replacement | 2013 | \$2,000 | Low |

Updated: JAN-13



Double Bubbler drinking fountain is rusting.

D2010.10 Washroom Fixtures (WC, Lav, Urnl)**

There are two flush tank water closets and the rest are flush valve. Three of the urinals are floor mounted stall type and one is a wall hung urinal. Both types have flush tanks with timers. The lavatories are wall hung with varying types of trim.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 35 | JAN-13 |

Event: Replace Water Closets (8), Lavatories (10) and Urinals (4)

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2033 | \$45,000 | Unassigned |

Updated: JAN-13

D2020.01.01 Pipes and Tubes: Domestic Water*

The domestic water lines are copper.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 0 | JAN-13 |

D2020.01.02 Valves: Domestic Water**

There are main shut off valves for the domestic water service.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 40 | JAN-13 |

Event: Replace Shut-off Valves (2)

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2016 | \$2,800 | Unassigned |

Updated: JAN-13

D2020.02.06 Domestic Water Heaters**

The domestic water heater is a John Wood, model JW 402 NA-04 natural gas fired water heater with a storage capacity of 151 litres and a recovery rate of 130 litres/hour.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1984 | 20 | JAN-13 |

Event: Replace Domestic Water Heater (1)

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2016 | \$2,300 | Unassigned |

Updated: JAN-13

D2020.03 Water Supply Insulation: Domestic*

The domestic water supply lines are insulated.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 0 | JAN-13 |

D2030.01 Waste and Vent Piping*

The waste and vent piping is cast iron with some copper and PVC.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 0 | JAN-13 |

D2030.02.04 Floor Drains*

There are floor drains located in the washrooms and mechanical room.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 0 | JAN-13 |

D2040.01 Rain Water Drainage Piping Systems*

There are cast iron rain water leaders that run in the walls and discharge to grade.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 0 | JAN-13 |

D2040.02.04 Roof Drains*

There are domed cast iron roof drains.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 0 | JAN-13 |

D3010.02 Gas Supply Systems*

Natural gas is supplied to the boiler, water heater and furnace.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 0 | JAN-13 |

D3020.02.01 Heating Boilers and Accessories: H.W.**

The natural gas hot water heating boiler is a Volcano model G-20-507. The boiler has been well maintained and was inspected in 2011. Bell and Gosset heating pumps circulate the heating water.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 35 | JAN-13 |

Event: Replace Heating Boiler (1)

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2016 | \$32,000 | Unassigned |

Updated: JAN-13

D3020.02.02 Chimneys (& Comb. Air): H.W. Boiler**

The insulated metal chimney runs to a brick chimney and terminates with a weather cap on the roof. Combustion air is provided to the mechanical room.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 35 | JAN-13 |

Event: Replace Chimney (4m)

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2016 | \$3,500 | Unassigned |

Updated: JAN-13

D3020.02.03 Water Treatment: H. W. Boiler*

Chemical pot feeder located in the heating system hydronic loop.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 0 | JAN-13 |

D3020.03.01 Furnaces**

There is a furnace located in a small furnace room with access from the outside. The furnace has an cooling coil and a hot water heating coil.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 25 | JAN-13 |

Event: Replace the Furnace (1)

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2023 | \$4,700 | Unassigned |

Updated: JAN-13

D3020.03.02 Chimneys (& Comb. Air): Furnace*

Furnace is provided with venting and combustion air.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 0 | JAN-13 |

D3030.06.02 Refrigerant Condensing Units**

There is a Lennox HS23-311-5P roof mounted condensing unit for the cooling coil in the furnace.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 25 | JAN-13 |

Event: Replace Condensing Unit (1)

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2023 | \$7,200 | Unassigned |

Updated: JAN-13

D3040.01.04 Ducts: Air Distribution*

The supply air ductwork is galvanized sheet metal.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 0 | JAN-13 |

D3040.01.07 Air Outlets & Inlets: Air Distribution*

There are square ceiling supply diffusers and egg crate return grilles.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 0 | JAN-13 |

D3040.03.01 Hot Water Distribution Systems - 1958**

Hot water for heating is supplied to entrance force flow heaters, finned tube radiation, and convectors through copper piping.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 40 | JAN-13 |

Event: Replace Hot Water Heating Distribution System (570 m²)

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2016 | \$65,000 | Unassigned |

Updated: JAN-13

D3040.03.01 Hot Water Distribution Systems - 1998**

Hot water for heating is supplied to heating coils through copper piping.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 40 | JAN-13 |

Event: Replace Hot Water Heating Distribution System (360 m²)

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2038 | \$41,000 | Unassigned |

Updated: JAN-13

D3040.04.01 Fans: Exhaust**

There are cabinet exhaust fans on the roof and an exhaust fan located in the mechanical room as well as a ceiling fan in the staff washroom.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 30 | JAN-13 |

Event: Replace Exhaust Fans (5)

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2016 | \$9,500 | Unassigned |

Updated: JAN-13

D3040.04.03 Ducts: Exhaust*

The exhaust ductwork is galvanized sheet metal.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 0 | JAN-13 |

D3040.04.05 Air Outlets and Inlets: Exhaust*

There are egg crate and integral exhaust air grilles.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 0 | JAN-13 |

D3050.02 Air Coils**

There is a cooling coil in the furnace supply air ductwork.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 30 | JAN-13 |

Event: Replace Cooling Coil (1)

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2028 | \$1,000 | Unassigned |

Updated: JAN-13

D3050.05.01 Convectors**

There are convector units located in the multipurpose room.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 40 | JAN-13 |

Event: Replace Convectors (5)

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2016 | \$4,500 | Unassigned |

Updated: JAN-13

D3050.05.02 Fan Coil Units - Classrooms**

Fan coil units with heating coils serving individual classrooms are mounted in ceiling space.(not accessible at the time of site visit) Information received from site personnel is they are Price model SEV 8000 units.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 30 | JAN-13 |

Event: Replace Fan Coil Units (5)

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2028 | \$30,000 | Unassigned |

Updated: JAN-13

D3050.05.02 Fan Coil Units - Force Flow Units**

Wall mounted force flow heaters in entrance vestibules and in the storage room.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 30 | JAN-13 |

Event: Replace Force Flow Units (4)

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2016 | \$24,000 | Unassigned |

Updated: JAN-13

D3050.05.03 Finned Tube Radiation**

There is perimeter finned tube radiation located in sloped top radiation cabinets.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 40 | JAN-13 |

Event: Replace Finned Tube Radiation (570 m²/gfa)

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2038 | \$32,000 | Unassigned |

Updated: JAN-13

D3060.02.01 Electric and Electronic Controls**

Electric controls of entrance force flow units, convectors finned tube radiation and furnace.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 30 | JAN-13 |

Event: Replace Controls (930m²/gfa)

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2028 | \$3,500 | Unassigned |

Updated: JAN-13

D4030.01 Fire Extinguisher, Cabinets and Accessories*

Portable dry chemical fire extinguishers are located throughout building.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 0 | JAN-13 |

S5 ELECTRICAL**D5010.03 Main Electrical Switchboards (Main Distribution)****

400A-120/240V/1PH/3W main distribution switchboard as manufactured by Amalgamated Electric. Switchboard located in mechanical room.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 40 | JAN-13 |

Event: Replace main distribution switchboard (1)

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2016 | \$37,000 | Unassigned |

Updated: JAN-13

D5010.05 Electrical Branch Circuit Panelboards (Secondary Distribution) - 1958**

Amalgamated Electric panelboards located in mechanical room and throughout 1958 section of school.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 30 | JAN-13 |

Event: Replace branch circuit panelboards (3)

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2016 | \$17,500 | Unassigned |

Updated: JAN-13

D5010.05 Electrical Branch Circuit Panelboards (Secondary Distribution) - 1983**

Sylvania panelboard located in Room 114.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1983 | 30 | JAN-13 |

Event: Replace branch circuit panelboard (1)

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2016 | \$5,700 | Unassigned |

Updated: JAN-13

D5010.05 Electrical Branch Circuit Panelboards (Secondary Distribution) - 1998**

Square D panelboards located in mechanical room and 1998 school addition.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|---------------|------------------|--------------------|----------------|
| 5 - Good | 1998 | 30 | JAN-13 |

Event: Replace branch circuit panelboards (4)

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2028 | \$23,000 | Unassigned |

Updated: JAN-13

D5010.07.02 Motor Starters and Accessories**

4 manual motor starters to small motor loads.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 30 | JAN-13 |

Event: Replace motor starters (4)

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2016 | \$2,500 | Unassigned |

Updated: JAN-13

D5020.01 Electrical Branch Wiring*

Copper wiring installed in conduit.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 0 | JAN-13 |

D5020.02.01 Lighting Accessories: Interior (Lighting Controls)*

Lighting control is provided by line voltage switches in classrooms, corridors, and offices. Occupancy sensors provide lighting control in staff room and washrooms. Each classroom has own switches to control lights.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 0 | JAN-13 |

D5020.02.02.01 Interior Incandescent Fixtures*

Incandescent potlights re-lamped with compact fluorescent screw-in bulbs located in entry vestibule of 1958 section of school.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 0 | JAN-13 |

D5020.02.02.02 Interior Fluorescent Fixtures**

Mixture of surface mounted and recess mounted fluorescent fixtures complete with T8 lamps and electronic ballasts.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 30 | JAN-13 |

Event: Replace fluorescent fixtures (190 fixtures)

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2028 | \$90,000 | Unassigned |

Updated: JAN-13

D5020.02.03.02 Emergency Lighting Battery Packs**

DC emergency lighting system with battery packs and remote heads installed to illuminate exit paths.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 20 | JAN-13 |

Event: Replace emergency lighting battery pack (4)

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2018 | \$5,600 | Unassigned |

Updated: JAN-13

D5020.02.03.03 Exit Signs*

LED exit signs at exit doors and to identify paths to exit.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 0 | JAN-13 |

D5020.03.01.04 Exterior H.P. Sodium Fixtures*

Wall mounted high pressure sodium light fixtures installed to illuminate entry vestibule and installed along building perimeter.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 0 | JAN-13 |

D5020.03.02 Lighting Accessories: Exterior (Lighting Controls)*

Exterior lighting controlled by a photo cell with a manual override.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 0 | JAN-13 |

D5030.01 Detection and Fire Alarm**

Notifier fire alarm system with Notifier AFP-200 fire alarm panel, horn/strobes, and fire detection devices. Fire alarm panel located at main front entrance.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 25 | JAN-13 |

Event: Replace fire alarm system (919 square meters/GFA)

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2023 | \$36,000 | Unassigned |

Updated: JAN-13

D5030.02.02 Intrusion Detection**

DSC security system complete with keypad, motion detectors, and door contacts. System is monitored.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|---------------|------------------|--------------------|----------------|
| 5 - Good | 2005 | 25 | JAN-13 |

Event: Replace intrusion detection (919 square meters/GFA)

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2030 | \$32,500 | Unassigned |

Updated: JAN-13

D5030.03 Clock and Program Systems*

Wall mounted DC clocks located in classrooms and office areas.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 0 | JAN-13 |

D5030.04.01 Telephone Systems*

Toshiba telephone system with telephones in general office and each classroom.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1990 | 0 | JAN-13 |

D5030.04.04 Data Systems*

Cat 5E data system with outlets located throughout school.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 0 | JAN-13 |

S6 EQUIPMENT, FURNISHINGS AND SPECIAL CONSTRUCTION**E1020.02 Library Equipment***

Library - has book shelves.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 0 | JAN-13 |

E1090.04 Residential Equipment*

Staff Room has microwave, refrigerator.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 0 | JAN-13 |

E2010.02 Fixed Casework**

Reception desk, classrooms have counter height open shelving units. 1958 areas replaced in 1998.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 35 | JAN-13 |

Event: Replace 390m²/gfa fixed casework.

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2033 | \$44,300 | Unassigned |

Updated: JAN-13**E2010.03.01 Blinds****

Horizontal blinds for classroom windows.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 30 | JAN-13 |

Event: Replace 45m² blinds

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------|-------------|-------------|-----------------|
| Lifecycle Replacement | 2028 | \$5,900 | Unassigned |

Updated: JAN-13

S8 SPECIAL ASSESSMENT**K4010.01 Barrier Free Route: Parking to Entrance***

Sloped level walks to entries

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 0 | JAN-13 |

K4010.02 Barrier Free Entrances*

No barrier free doors at entrance.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 0 | JAN-13 |

Event: **Install two automatic doors at south entry.****Concern:**

No automatic doors for barrier free access at south entry.

Recommendation:

Install automatic doors at south entrance.

| <u>Type</u> | <u>Year</u> | <u>Cost</u> | <u>Priority</u> |
|-----------------------------|-------------|-------------|-----------------|
| Barrier Free Access Upgrade | 2013 | \$32,600 | Medium |

Updated: JAN-13**K4010.03 Barrier Free Interior Circulation***

Building - Corridors are of sufficient width for wheelchairs.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 0 | JAN-13 |

K4010.04 Barrier Free Washrooms*

Barrier free cubicles for washrooms

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 0 | JAN-13 |

K4030.01 Asbestos*

None observed or identified by staff.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 0 | JAN-13 |

K4030.04 Mould*

None observed or identified by staff.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 0 | JAN-13 |

K4030.07 Ozone Depleting Substances (CFC's, HCFC's, Halon)*

There is R-22 in the refrigeration systems.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1998 | 0 | JAN-13 |

K4030.09 Other Hazardous Materials*

None observed or identified by staff.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 1958 | 0 | JAN-13 |

K5010.01 Site Documentation*

Site- Google maps Martin Browne School
Viewed by: KOLIGER SCHMIDT architect-engineer on September 6, 2012

Martin Browne School is located west side of 56th Avenue and South of 51st Street. School bus loading and unloading zone is along 56th Avenue. Paved parking lot at the east side is accessed by a paved access road which continues to the back (west side of the school as well as access to the city lane at the south of the property. Concrete walks are located on the east side of the school which connect each of the entries on that side to the city walk. A walk is also provided from the west entry to the city walk at the junction of 56 Ave. and 51 Street. Grassed landscaping is provided adjacent to the building on the north and east side enclosing a cluster of mature trees. The west side of the property houses the play structures and grassed out door play areas. A chain link fence is located at the south west and north sides of the property.

| <u>Rating</u> | <u>Installed</u> | <u>Design Life</u> | <u>Updated</u> |
|----------------|------------------|--------------------|----------------|
| 4 - Acceptable | 2012 | 0 | JAN-13 |



Site- google maps Martin Browne School
Viewed by: KOLIGER SCHMIDT architect-engineer on September 6, 2012

K5010.02 Building Documentation*

Floor Plan Martin Browne School

Viewed by: KOLIGER SCHMIDT architect-engineer on September 6, 2012

The school was originally built in 1958 with an area of 570m². An addition was added in 1998 consisting of a storage room at the south west and classrooms and offices at the north with an area of 360m²; at this time the original building was also modernized. The total building area is 930m². Two portables were added one in 2005 and the other in 2007 with a total area of 260m². The total area would be 1190m² for all areas.

Rating

4 - Acceptable

Installed

2012



Design Life

0

Updated

JAN-13

| SCHOOL DATA | | | | |
|------------------------|------|-------|------|------|
| NEW FRAME CONSTRUCTION | | | | |
| PLAN NO. | 343 | | | |
| CROSS AREA CITY SCHOOL | | | | |
| CAPACITY | 100 | | | |
| RM NO. | COOR | AREA | TYPE | DATE |
| 101 | CR | 68.40 | 112 | |
| 102 | CR | 55.30 | 112 | |
| 103 | CR | 68.40 | 115 | |
| 104 | CR | 68.40 | 115 | |
| 105 | CR | 68.40 | 115 | |
| 106 | CR | 68.40 | 115 | |
| 107 | CR | 68.40 | 115 | |
| 108 | CR | 68.40 | 115 | |
| 109 | CR | 68.40 | 115 | |
| 110 | CR | 68.40 | 115 | |
| 111 | CR | 68.40 | 115 | |
| 112 | CR | 68.40 | 115 | |
| 113 | CR | 68.40 | 115 | |
| 114 | CR | 68.40 | 115 | |
| 115 | CR | 68.40 | 115 | |
| 116 | CR | 68.40 | 115 | |
| 117 | CR | 68.40 | 115 | |
| 118 | CR | 68.40 | 115 | |
| 119 | CR | 68.40 | 115 | |
| 120 | CR | 68.40 | 115 | |
| 121 | CR | 68.40 | 115 | |
| 122 | CR | 68.40 | 115 | |
| 123 | CR | 68.40 | 115 | |
| 124 | CR | 68.40 | 115 | |
| 125 | CR | 68.40 | 115 | |
| 126 | CR | 68.40 | 115 | |
| 127 | CR | 68.40 | 115 | |
| 128 | CR | 68.40 | 115 | |
| 129 | CR | 68.40 | 115 | |
| 130 | CR | 68.40 | 115 | |
| 131 | CR | 68.40 | 115 | |
| 132 | CR | 68.40 | 115 | |
| 133 | CR | 68.40 | 115 | |
| 134 | CR | 68.40 | 115 | |
| 135 | CR | 68.40 | 115 | |
| 136 | CR | 68.40 | 115 | |
| 137 | CR | 68.40 | 115 | |
| 138 | CR | 68.40 | 115 | |
| 139 | CR | 68.40 | 115 | |
| 140 | CR | 68.40 | 115 | |
| 141 | CR | 68.40 | 115 | |
| 142 | CR | 68.40 | 115 | |
| 143 | CR | 68.40 | 115 | |
| 144 | CR | 68.40 | 115 | |
| 145 | CR | 68.40 | 115 | |
| 146 | CR | 68.40 | 115 | |
| 147 | CR | 68.40 | 115 | |
| 148 | CR | 68.40 | 115 | |
| 149 | CR | 68.40 | 115 | |
| 150 | CR | 68.40 | 115 | |
| 151 | CR | 68.40 | 115 | |
| 152 | CR | 68.40 | 115 | |
| 153 | CR | 68.40 | 115 | |
| 154 | CR | 68.40 | 115 | |
| 155 | CR | 68.40 | 115 | |
| 156 | CR | 68.40 | 115 | |
| 157 | CR | 68.40 | 115 | |
| 158 | CR | 68.40 | 115 | |
| 159 | CR | 68.40 | 115 | |
| 160 | CR | 68.40 | 115 | |
| 161 | CR | 68.40 | 115 | |
| 162 | CR | 68.40 | 115 | |
| 163 | CR | 68.40 | 115 | |
| 164 | CR | 68.40 | 115 | |
| 165 | CR | 68.40 | 115 | |
| 166 | CR | 68.40 | 115 | |
| 167 | CR | 68.40 | 115 | |
| 168 | CR | 68.40 | 115 | |
| 169 | CR | 68.40 | 115 | |
| 170 | CR | 68.40 | 115 | |
| 171 | CR | 68.40 | 115 | |
| 172 | CR | 68.40 | 115 | |
| 173 | CR | 68.40 | 115 | |
| 174 | CR | 68.40 | 115 | |
| 175 | CR | 68.40 | 115 | |
| 176 | CR | 68.40 | 115 | |
| 177 | CR | 68.40 | 115 | |
| 178 | CR | 68.40 | 115 | |
| 179 | CR | 68.40 | 115 | |
| 180 | CR | 68.40 | 115 | |
| 181 | CR | 68.40 | 115 | |
| 182 | CR | 68.40 | 115 | |
| 183 | CR | 68.40 | 115 | |
| 184 | CR | 68.40 | 115 | |
| 185 | CR | 68.40 | 115 | |
| 186 | CR | 68.40 | 115 | |
| 187 | CR | 68.40 | 115 | |
| 188 | CR | 68.40 | 115 | |
| 189 | CR | 68.40 | 115 | |
| 190 | CR | 68.40 | 115 | |
| 191 | CR | 68.40 | 115 | |
| 192 | CR | 68.40 | 115 | |
| 193 | CR | 68.40 | 115 | |
| 194 | CR | 68.40 | 115 | |
| 195 | CR | 68.40 | 115 | |
| 196 | CR | 68.40 | 115 | |
| 197 | CR | 68.40 | 115 | |
| 198 | CR | 68.40 | 115 | |
| 199 | CR | 68.40 | 115 | |
| 200 | CR | 68.40 | 115 | |



Floor Plan Martin Browne School

Viewed by: KOLIGER SCHMIDT architect-engineer on September 6, 2012