

**Listing of Events**  
**Elk Island Catholic Separate Regional Division**  
**St. Mary's School**

<b>Building Events</b>		<b>2004</b>	<b>2005</b>	<b>2006</b>	<b>2007</b>	<b>2008</b>	<b>Total</b>
Lifecycle Replacement	Replace Aluminum-Framed main entrance doors and side panels.	\$ 15,000.00	\$ -	\$ -	\$ -	\$ -	\$ 15,000.00
Lifecycle Replacement	Replace ceramic tile in room 102.	\$ -	\$ 5,000.00	\$ -	\$ -	\$ -	\$ 5,000.00
Lifecycle Replacement	Replace Kitchen cabinets.	\$ -	\$ 15,000.00	\$ -	\$ -	\$ -	\$ 15,000.00
Lifecycle Replacement	Replace the make-up air unit.	\$ -	\$ -	\$ 12,000.00	\$ -	\$ -	\$ 12,000.00
Lifecycle Replacement	Replace the original roofotp exhaust fans.	\$ -	\$ 7,500.00	\$ -	\$ -	\$ -	\$ 7,500.00
Lifecycle Replacement	Replace the Simplex fire alarm control panel.	\$ -	\$ 6,500.00	\$ -	\$ -	\$ -	\$ 6,500.00
Lifecycle Replacement	Sheet flooring in the Change Rooms & Room 125.	\$ 20,000.00	\$ -	\$ -	\$ -	\$ -	\$ 20,000.00
Repair	Repair cracks in the Terrazzo flooring.	\$ 5,000.00	\$ -	\$ -	\$ -	\$ -	\$ 5,000.00
Repair	Repair damaged insulation around the perimeter of the building - East elevation.	\$ 2,500.00	\$ -	\$ -	\$ -	\$ -	\$ 2,500.00
Repair	Repair floating wood floors in rooms 128, 129 and 130.	\$ -	\$ 15,000.00	\$ -	\$ -	\$ -	\$ 15,000.00
Repair	Repair mortar between split face concrete blocks	\$ 1,500.00	\$ -	\$ -	\$ -	\$ -	\$ 1,500.00
<b>Total of Maintenance Events</b>		<b>\$ 44,000.00</b>	<b>\$ 49,000.00</b>	<b>\$ 12,000.00</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ 105,000.00</b>
Operating Efficiency Upgrade	Install internal ladder to access roof area.	\$ 2,000.00	\$ -	\$ -	\$ -	\$ -	\$ 2,000.00
<b>Total of Upgrading Events</b>		<b>\$ 2,000.00</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ 2,000.00</b>
<b>Building Events Total</b>		<b>\$ 46,000.00</b>	<b>\$ 49,000.00</b>	<b>\$ 12,000.00</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ 107,000.00</b>
<b>Site Events</b>							
Repair	Repair walkway cracks.	\$ 2,500.00	\$ -	\$ -	\$ -	\$ -	\$ 2,500.00
Upgrading	Pave bus turn-around at the south end of the school.	\$ 80,000.00	\$ -	\$ -	\$ -	\$ -	\$ 80,000.00
<b>Site Events Total</b>		<b>\$ 82,500.00</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ 82,500.00</b>
<b>St. Mary's School Total</b>		<b>\$ 128,500.00</b>	<b>\$ 49,000.00</b>	<b>\$ 12,000.00</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ 189,500.00</b>

## Elk Island Catholic Separate Regional Division No.41 Listing of Events

Archbishop Jordan High School B4003A			2006	2007	2008	2009	2010	Total
<b>Building Events</b>								
<b>Maintenance Events</b>								
B3020.02 Other Roofing Openings (Hatch,Vent, etc)*	Failure Replacement	Replace caps on curbed roof openings in the original building.	\$ -	\$ -	\$ 1,000.00	\$ -	\$ -	\$ 1,000.00
C3020.08 Carpet Flooring*	Failure Replacement	Replace carpet in Cafeteria (of 1991 addition) and in classrooms of the original building.	\$ -	\$ -	\$ -	\$ 150,000.00	\$ -	\$ 150,000.00
D3030.06.02 Refrigerant Condensing Units*	Failure Replacement	Replace condensing unit.	\$ -	\$ 40,000.00	\$ -	\$ -	\$ -	\$ 40,000.00
B2030.02 Exterior Utility Doors*	Failure Replacement	Replace doors to roof in the original building.	\$ -	\$ -	\$ 3,000.00	\$ -	\$ -	\$ 3,000.00
B2010.06 Exterior Louvers, Grilles, and Screens*	Failure Replacement	Replace metal louvres in the original building.	\$ -	\$ -	\$ -	\$ -	\$ 20,000.00	\$ 20,000.00
C3020.07 Resilient Flooring*	Failure Replacement	Replace sheet vinyl flooring in Arts Room.	\$ -	\$ -	\$ -	\$ 10,000.00	\$ -	\$ 10,000.00
D3020.02.01 Heating Boilers and Accessories: H.W.*	Lifecycle Replacement	Replace 1969 boiler	\$ -	\$ -	\$ -	\$ 50,000.00	\$ -	\$ 50,000.00
B3010.04.01 Built-up Bituminous Roofing (Asphalt & Gravel)*	Lifecycle Replacement	Replace built-up roofing with SBS in original building.	\$ -	\$ -	\$ 245,000.00	\$ -	\$ -	\$ 245,000.00
D3060.02.02 Pneumatic Controls*	Lifecycle Replacement	Replace control valves & actuators	\$ -	\$ -	\$ -	\$ 20,000.00	\$ -	\$ 20,000.00
D3050.03 Humidifiers*	Lifecycle Replacement	Replace humidifier	\$ -	\$ -	\$ -	\$ 5,000.00	\$ -	\$ 5,000.00
B2010.09 Exterior Soffits*	Preventative Maintenance	Refinish soffits in original building.	\$ -	\$ 3,000.00	\$ -	\$ -	\$ -	\$ 3,000.00
C1020.01 Interior Swinging Doors*	Preventative Maintenance	Repaint doors and frames in classrooms of original building.	\$ -	\$ -	\$ 8,000.00	\$ -	\$ -	\$ 8,000.00
C3010.12 Wall Coverings*	Repair	Paint vinyl fabric wall surfaces in Arts Room.	\$ -	\$ -	\$ 5,000.00	\$ -	\$ -	\$ 5,000.00
B3020.02.03 Roof Windows (Clearstory)	Repair	Replace broken sealed units and re-caulk perimeter in clearstory windows of original building.	\$ -	\$ -	\$ 5,000.00	\$ -	\$ -	\$ 5,000.00
E2010.02.05 Educational Facility Casework*	Repair	Replace countertop in paint spray area and refinish cabinet doors and drawer fronts in Arts Room.	\$ -	\$ -	\$ 5,000.00	\$ -	\$ -	\$ 5,000.00
B2010.01.02.01 Brick Masonry: Ext. Wall Repair Skin*		Replace damaged bricks in north side of the original building.	\$ -	\$ -	\$ 3,500.00	\$ -	\$ -	\$ 3,500.00
B2010.01.09 Expansion Control: Exterior Repair Wall Skin*		Replace rod and caulking in control joints of the original building.	\$ -	\$ -	\$ 3,500.00	\$ -	\$ -	\$ 3,500.00
<b>Total of Maintenance Events</b>			<b>\$ -</b>	<b>\$ 43,000.00</b>	<b>\$ 279,000.00</b>	<b>\$ 235,000.00</b>	<b>\$ 20,000.00</b>	<b>\$ 577,000.00</b>

### Upgrading Events

## Elk Island Catholic Separate Regional Division No.41 Listing of Events

Archbishop Jordan High School B4003A			2006	2007	2008	2009	2010	Total
D4010 Sprinklers: Fire Protection*	Code Upgrade	Add wet pipe sprinkler system to 1969 (unsprinklered) portion of building.	\$ -	\$ 75,000.00	\$ -	\$ -	\$ -	\$ 75,000.00
D5020.03.03 Emergency Lighting*	Energy Efficiency Upgrade	Replace existing exit lights with new.	\$ -	\$ 15,000.00	\$ -	\$ -	\$ -	\$ 15,000.00
D2010.05 Showers*	Program Functional Upgrade	Replace group showers with individual stall showers	\$ -	\$ 10,000.00	\$ -	\$ -	\$ -	\$ 10,000.00
D2010.03 Lavatories*	Program Functional Upgrade	Replace vitreous china lavatories with new stainless steel type to suit washroom upgrades.	\$ -	\$ 5,000.00	\$ -	\$ -	\$ -	\$ 5,000.00
<b>Total of Upgrading Events</b>			\$ -	\$ 105,000.00	\$ -	\$ -	\$ -	\$ 105,000.00
<b>Total of Building Events</b>			\$ -	\$ 148,000.00	\$ 279,000.00	\$ 235,000.00	\$ 20,000.00	\$ 682,000.00
<b>Site Events</b>								
G2020.02.02 Flexible Paving Parking Lots(Asphalt)*	Preventative Maintenance	Provide seal coats to paved parking lot surfaces.	\$ -	\$ -	\$ -	\$ -	\$ 112,000.00	\$ 112,000.00
G2030.04 Rigid Pedestrian Pavement (Concrete)*	Preventative Maintenance	Re-build the north concrete sidewalk.	\$ -	\$ -	\$ 68,000.00	\$ -	\$ -	\$ 68,000.00
G2030.03 Pedestrian Unit Pavers*	Repair	Re-build unistone paver surfaces adjacent to concrete pads at front (south) and west entrances.	\$ -	\$ -	\$ 6,000.00	\$ -	\$ -	\$ 6,000.00
<b>Total of Site Events</b>			\$ -	\$ -	\$ 74,000.00	\$ -	\$ 112,000.00	\$ 186,000.00

## Elk Island Catholic Separate Regional Division No.41 Listing of Events

Elk Island Catholic Separate Regional Division No. 41 B5429A			2006	2007	2008	2009	2010	Total
<b>Building Events</b>								
<b>Maintenance Events</b>								
D5020.02.03 Emergency Lighting*	Code Repair	No emergency or exit lighting has been provided which is a violation of the building code.	\$ 7,500.00	\$ -	\$ -	\$ -	\$ -	\$ 7,500.00
C3020.01 Concrete Floor Finishes (Paint)*	Failure Replacement	Repaint concrete floor.	\$ -	\$ -	\$ 1,000.00	\$ -	\$ -	\$ 1,000.00
C3030.04 Gypsum Board Ceiling Finishes*	Failure Replacement	Repair gypsum board ceiling and provide firestopping.	\$ 1,000.00	\$ -	\$ -	\$ -	\$ -	\$ 1,000.00
C3030.06 Acoustic Ceiling Treatment (Susp.T-Bar)*	Failure Replacement	Replace with new acoustic ceiling tiles.	\$ 3,000.00	\$ -	\$ -	\$ -	\$ -	\$ 3,000.00
B2020.01.01.05 Wood Windows (Glass & Frame)*	Failure Replacement	Replace with new aluminum windows.	\$ -	\$ -	\$ 54,000.00	\$ -	\$ -	\$ 54,000.00
B3010.04.01 Built-up Bituminous Roofing (Asphalt & Gravel)*	Failure Replacement	Replace with new SBS roofing system.	\$ 81,750.00	\$ -	\$ -	\$ -	\$ -	\$ 81,750.00
C2020.06 Carpet Stair Finishes*	Failure Replacement	Replace with new sheet carpet.	\$ 500.00	\$ -	\$ -	\$ -	\$ -	\$ 500.00
C3020.08.02 Sheet Carpet	Failure Replacement	Replace with new sheet carpet.	\$ 37,500.00	\$ -	\$ -	\$ -	\$ -	\$ 37,500.00
C3020.07.01 Resilient Tile Flooring	Failure Replacement	Replace with vinyl sheet.	\$ 15,000.00	\$ -	\$ -	\$ -	\$ -	\$ 15,000.00
F2020.01 Asbestos*	Hazardous Materials Abatement	Provide new vinyl sheet flooring.	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -
C3010.11 Interior Wall Painting*	Repair	Repaint walls.	\$ -	\$ -	\$ 1,000.00	\$ -	\$ -	\$ 1,000.00
B2030.02.02 Wood and Plastic Doors	Repair	Replace with new hardware.	\$ 2,000.00	\$ -	\$ -	\$ -	\$ -	\$ 2,000.00
<b>Total of Maintenance Events</b>			<b>\$ 148,250.00</b>	<b>\$ -</b>	<b>\$ 56,000.00</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ 204,250.00</b>
<b>Upgrading Events</b>								
K4010.02 Barrier Free Entrances	Barrier Free Access Upgrade	Provide automatic door for handicapped.	\$ 10,000.00	\$ -	\$ -	\$ -	\$ -	\$ 10,000.00
K4010.04 Barrier Free Washrooms	Barrier Free Access Upgrade	Provide barrier free washrooms with accessories for visitors and staff.	\$ 20,000.00	\$ -	\$ -	\$ -	\$ -	\$ 20,000.00
D2020.01.03 Piping Specialties (Backflow Preventors)* - Main Domestic Water Service	Code Upgrade	Provide backflow prevention device on building main domestic water service.	\$ 5,000.00	\$ -	\$ -	\$ -	\$ -	\$ 5,000.00
E1090.04 Residential Equipment*	Indoor Air Quality Upgrade	Provide exhaust hood and ducting to outside.	\$ 1,000.00	\$ -	\$ -	\$ -	\$ -	\$ 1,000.00
<b>Total of Upgrading Events</b>			<b>\$ 36,000.00</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ 36,000.00</b>
<b>Total of Building Events</b>			<b>\$ 184,250.00</b>	<b>\$ -</b>	<b>\$ 56,000.00</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ 240,250.00</b>

## Elk Island Catholic Separate Regional Division No.41 Listing of Events

Elk Island Catholic Separate Regional Division No. 41 B5429A	2006	2007	2008	2009	2010	Total
<b>Site Events</b>						
G1030.04 Slope Protection and Erosion Failure Replacement Control Provide new grade around the building.	\$ 10,000.00	\$ -	\$ -	\$ -	\$ -	\$ 10,000.00
<b>Total of Site Events</b>	<b>\$ 10,000.00</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ 10,000.00</b>

**Elk Island Catholic Separate Regional Division No.41  
Listing of Events**

Father Kenneth Kearns School B4011A			2006	2007	2008	2009	2010	Total
<b>Building Events</b>								
<b>Maintenance Events</b>								
C3020.01 Concrete Floor Finishes (Paint)*	Failure Replacement	Repaint concrete floor.	\$ 3,150.00	\$ -	\$ -	\$ -	\$ -	\$ 3,150.00
C3030.07 Interior Ceiling Painting*	Failure Replacement	Repaint gypsum board ceiling.	\$ -	\$ -	\$ 2,500.00	\$ -	\$ -	\$ 2,500.00
B3010.08.02 Metal Gutters and Downspouts*	Failure Replacement	Replace all concrete splashpads.	\$ 3,000.00	\$ -	\$ -	\$ -	\$ -	\$ 3,000.00
D2020.01.03 Piping Specialties (Backflow Preventors)* - Heating Water Make-Up	Failure Replacement	Replace boiler water make-up backflow preventor.	\$ 1,000.00	\$ -	\$ -	\$ -	\$ -	\$ 1,000.00
D2010.08 Drinking Fountains / Coolers*	Failure Replacement	Replace non-refrigerated drinking fountains.	\$ 2,000.00	\$ -	\$ -	\$ -	\$ -	\$ 2,000.00
C3030.06 Acoustic Ceiling Treatment (Susp.T-Bar)*	Failure Replacement	Replace with new acoustic ceiling tiles.	\$ 3,000.00	\$ -	\$ -	\$ -	\$ -	\$ 3,000.00
B2020.01.01.02 Aluminum Windows (Glass & Frame)*	Failure Replacement	Replace with new aluminum widow with double glazed panels.	\$ 2,000.00	\$ -	\$ -	\$ -	\$ -	\$ 2,000.00
C1010.03 Interior Operable Folding Panel Partitions*	Failure Replacement	Replace with new folding partition and hardware.	\$ -	\$ -	\$ 4,000.00	\$ -	\$ -	\$ 4,000.00
E2010.02.05 Educational Facility Casework*	Failure Replacement	Replace with new millwork.	\$ -	\$ -	\$ 32,500.00	\$ -	\$ -	\$ 32,500.00
B3010.04.01 Built-up Bituminous Roofing (Asphalt & Gravel) 1967*	Failure Replacement	Replace with new SBS roofing.	\$ -	\$ -	\$ 169,650.00	\$ -	\$ -	\$ 169,650.00
C3020.08.02 Sheet Carpet	Failure Replacement	Replace with new sheet carpet.	\$ 15,200.00	\$ -	\$ -	\$ -	\$ -	\$ 15,200.00
E2010.03.01 Blinds*	Failure Replacement	Replace with new vertical blinds.	\$ 1,650.00	\$ -	\$ -	\$ -	\$ -	\$ 1,650.00
C3020.07.01 Resilient Tile Flooring	Failure Replacement	Replace with new vinyl sheet flooring.	\$ 100,000.00	\$ -	\$ -	\$ -	\$ -	\$ 100,000.00
B2020.01.01.02 Aluminum Windows (Glass & Frame)*	Failure Replacement	Replace with new window gaskets.	\$ 1,950.00	\$ -	\$ -	\$ -	\$ -	\$ 1,950.00
F2020.01 Asbestos*	Hazardous Materials Abatement	Provide new vinyl sheet flooring.	\$ -	\$ -	\$ -	\$ -	\$ -	\$ -
C3010.11 Interior Wall Painting*	Lifecycle Replacement	Repaint all walls.	\$ -	\$ -	\$ 20,000.00	\$ -	\$ -	\$ 20,000.00
D3040.01.01 Air Handling Units: Air Distribution*	Lifecycle Replacement	Replace air handling units.	\$ 200,000.00	\$ -	\$ -	\$ -	\$ -	\$ 200,000.00
D3020.02.02 Chimneys (&Comb. Air): H.W. Boiler*	Lifecycle Replacement	Replace boiler chimney.	\$ 5,000.00	\$ -	\$ -	\$ -	\$ -	\$ 5,000.00
D3040.01.02 Fans: Air Distribution*	Lifecycle Replacement	Replace exhaust fans.	\$ -	\$ -	\$ 3,500.00	\$ -	\$ -	\$ 3,500.00

**Elk Island Catholic Separate Regional Division No.41  
Listing of Events**

<b>Father Kenneth Kearns School B4011A</b>			<b>2006</b>	<b>2007</b>	<b>2008</b>	<b>2009</b>	<b>2010</b>	<b>Total</b>
D5030.01 Detection and Fire Alarm*	Lifecycle Replacement	Replace fire alarm system	\$ -	\$ 30,000.00	\$ -	\$ -	\$ -	\$ 30,000.00
D3020.02.01 Heating Boilers and Accessories: H.W.*	Lifecycle Replacement	Replace heating boilers.	\$ -	\$ -	\$ 200,000.00	\$ -	\$ -	\$ 200,000.00
D3060.02.02 Pneumatic Controls*	Lifecycle Replacement	Replace pneumatic controls.	\$ -	\$ -	\$ 200,000.00	\$ -	\$ -	\$ 200,000.00
B2010.01.08 Cement Plaster (Stucco): Ext. Wall*	Repair	Repair stucco.	\$ 1,000.00	\$ -	\$ -	\$ -	\$ -	\$ 1,000.00
B2030.01.10 Wood Entrance Door*	Repair	Repair wood doors and replace with new hardware.	\$ 4,500.00	\$ -	\$ -	\$ -	\$ -	\$ 4,500.00
F1010.02.04 Portable and Mobile Buildings (1993)	Repair	Replace vinyl flooring, acoustic ceiling tiles.	\$ 12,000.00	\$ -	\$ -	\$ -	\$ -	\$ 12,000.00
C2020.01 Tile Stair Finishes*	Repair	Replace with new vinyl sheet and nosings.	\$ 1,000.00	\$ -	\$ -	\$ -	\$ -	\$ 1,000.00
<b>Total of Maintenance Events</b>			<b>\$ 356,450.00</b>	<b>\$ 30,000.00</b>	<b>\$ 632,150.00</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ 1,018,600.00</b>
<b>Upgrading Events</b>								
K4010.02 Barrier Free Entrances	Barrier Free Access Upgrade	Provide automatic doors for handicapped.	\$ 10,000.00	\$ -	\$ -	\$ -	\$ -	\$ 10,000.00
K4010.01 Barrier Free Route: Parking to Entrance	Barrier Free Access Upgrade	Provide handicapped ramp.	\$ 5,000.00	\$ -	\$ -	\$ -	\$ -	\$ 5,000.00
K4010.04 Barrier Free Washrooms	Barrier Free Access Upgrade	Provide new handicapped washrooms with barrier free accessories.	\$ 8,000.00	\$ -	\$ -	\$ -	\$ -	\$ 8,000.00
D2020.01.03 Piping Specialties (Backflow Preventors)* - Main Domestic Water Service	Code Upgrade	Provide backflow prevention device on building main domestic water service.	\$ 5,000.00	\$ -	\$ -	\$ -	\$ -	\$ 5,000.00
E2010.02.07 Kitchen Casework*	Indoor Air Quality Upgrade	Provide exhaust hood and ducting to outside.	\$ 1,000.00	\$ -	\$ -	\$ -	\$ -	\$ 1,000.00
<b>Total of Upgrading Events</b>			<b>\$ 29,000.00</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ 29,000.00</b>
<b>Total of Building Events</b>			<b>\$ 385,450.00</b>	<b>\$ 30,000.00</b>	<b>\$ 632,150.00</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ 1,047,600.00</b>
<b>Site Events</b>								
G2020.06.04 Pavement Markings*	Failure Replacement	Repaint all parking stall lines and handicapped logo.	\$ 5,000.00	\$ -	\$ -	\$ -	\$ -	\$ 5,000.00
G2010.02.02 Flexible Pavement Roadway (Asphalt)*	Study	Study of bus drop-off and pick-up area.	\$ 5,000.00	\$ -	\$ -	\$ -	\$ -	\$ 5,000.00
<b>Total of Site Events</b>			<b>\$ 10,000.00</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ 10,000.00</b>

**Elk Island Catholic Separate Regional Division No.41  
Listing of Events**

Jean Vanier School B4014A			2006	2007	2008	2009	2010	Total
<b>Building Events</b>								
<b>Maintenance Events</b>								
C1020.03 Interior Fire Doors*	Code Repair	Replace solid core wood doors in fire separations.	\$ -	\$ 43,000.00	\$ -	\$ -	\$ -	\$ 43,000.00
C1010.03 Interior Operable Folding Panel Partitions*(Sliding Partitions)	Failure Replacement	Replace both sliding wood panel partitions in Stage.	\$ -	\$ -	\$ 125,000.00	\$ -	\$ -	\$ 125,000.00
F1010.02.04 Portable and Mobile Buildings*(Portable No.7)	Failure Replacement	Replace carpet flooring.	\$ -	\$ -	\$ 9,000.00	\$ -	\$ -	\$ 9,000.00
F1010.02.04 Portable and Mobile Buildings*(Portable No.8)	Failure Replacement	Replace carpet flooring.	\$ -	\$ -	\$ 9,000.00	\$ -	\$ -	\$ 9,000.00
C3020.08 Carpet Flooring*	Failure Replacement	Replace carpet in Staff Work Room and Library.	\$ -	\$ -	\$ 22,000.00	\$ -	\$ -	\$ 22,000.00
D2020.02.06 Domestic Water Heaters*	Failure Replacement	Replace domestic water heater.	\$ -	\$ 3,000.00	\$ -	\$ -	\$ -	\$ 3,000.00
F1010.02.04 Portable and Mobile Buildings*(Portable No.1)	Failure Replacement	Replace exterior cladding and skirting. Replace window.	\$ -	\$ -	\$ 10,000.00	\$ -	\$ -	\$ 10,000.00
F1010.02.04 Portable and Mobile Buildings*(Portable No.2)	Failure Replacement	Replace exterior cladding and skirting. Replace window.	\$ -	\$ -	\$ 10,000.00	\$ -	\$ -	\$ 10,000.00
F1010.02.04 Portable and Mobile Buildings*(Portable No.3)	Failure Replacement	Replace exterior cladding and skirting. Replace window.	\$ -	\$ -	\$ 10,000.00	\$ -	\$ -	\$ 10,000.00
F1010.02.04 Portable and Mobile Buildings*(Portable No.4)	Failure Replacement	Replace exterior cladding and skirting. Replace window.	\$ -	\$ -	\$ 10,000.00	\$ -	\$ -	\$ 10,000.00
F1010.02.04 Portable and Mobile Buildings*(Portable No.5)	Failure Replacement	Replace exterior cladding and skirting. Replace window.	\$ -	\$ -	\$ 10,000.00	\$ -	\$ -	\$ 10,000.00
F1010.02.04 Portable and Mobile Buildings*(Portable No.6)	Failure Replacement	Replace exterior cladding and skirting. Replace window.	\$ -	\$ -	\$ 10,000.00	\$ -	\$ -	\$ 10,000.00
F1010.02.04 Portable and Mobile Buildings*(Portable No.7)	Failure Replacement	Replace exterior cladding and skirting. Replace window.	\$ -	\$ -	\$ 10,000.00	\$ -	\$ -	\$ 10,000.00
F1010.02.04 Portable and Mobile Buildings*(Portable No.8)	Failure Replacement	Replace exterior cladding and skirting. Replace windows.	\$ -	\$ -	\$ 12,000.00	\$ -	\$ -	\$ 12,000.00
D5030.01 Detection and Fire Alarm*	Failure Replacement	Replace Fire Alarm System.	\$ -	\$ 80,000.00	\$ -	\$ -	\$ -	\$ 80,000.00
C1030.02 Fabricated Compartments(Toilets/Showers)*	Failure Replacement	Replace toilet partitions in Boys' and Girls' Washrooms in the 1973 portion of the building.	\$ -	\$ -	\$ 9,000.00	\$ -	\$ -	\$ 9,000.00
F1010.02.04 Portable and Mobile Buildings*(Portable No.1)	Failure Replacement	Replace vinyl tile flooring.	\$ -	\$ -	\$ 11,000.00	\$ -	\$ -	\$ 11,000.00
F1010.02.04 Portable and Mobile Buildings*(Portable No.2)	Failure Replacement	Replace vinyl tile flooring.	\$ -	\$ -	\$ 11,000.00	\$ -	\$ -	\$ 11,000.00



## Elk Island Catholic Separate Regional Division No.41 Listing of Events

Jean Vanier School B4014A			2006	2007	2008	2009	2010	Total
F1010.02.04 Portable and Mobile Buildings*(Portable No.3)	Failure Replacement	Replace vinyl tile flooring.	\$ -	\$ -	\$ 11,000.00	\$ -	\$ -	\$ 11,000.00
F1010.02.04 Portable and Mobile Buildings*(Portable No.4)	Failure Replacement	Replace vinyl tile flooring.	\$ -	\$ -	\$ 11,000.00	\$ -	\$ -	\$ 11,000.00
F1010.02.04 Portable and Mobile Buildings*(Portable No.6)	Failure Replacement	Replace vinyl tile flooring.	\$ -	\$ -	\$ 11,000.00	\$ -	\$ -	\$ 11,000.00
B3010.04.01 Built-up Bituminous Roofing (Asphalt & Gravel)*	Failure Replacement	Re-roof all asphalt and gravel roof areas with two ply SBS roofing.	\$ -	\$ -	\$ -	\$ -	\$ 235,000.00	\$ 235,000.00
D3030.06.02 Refrigerant Condensing Units*	Lifecycle Replacement	Replace condensing units.	\$ -	\$ -	\$ -	\$ 40,000.00	\$ -	\$ 40,000.00
C3020.07 Resilient Flooring*	Lifecycle Replacement	Replace vinyl asbestos tile flooring in all Washrooms and Gym Stage.	\$ -	\$ 28,000.00	\$ -	\$ -	\$ -	\$ 28,000.00
C3030.06 Acoustic Ceiling Treatment (Acoustic Textured Spray)*	Repair	Repair surfaces of acoustic spray coating on the ceiling of Gymnasium.	\$ -	\$ -	\$ -	\$ 3,000.00	\$ -	\$ 3,000.00
C3010.09 Acoustical Wall Treatment*	Repair	Repair surfaces of acoustic spray coatings on the walls of Gymnasium.	\$ -	\$ -	\$ -	\$ 2,000.00	\$ -	\$ 2,000.00
D2040.02.04 Roof Drains*	Repair	Replace roof drain strainers.	\$ -	\$ 6,000.00	\$ -	\$ -	\$ -	\$ 6,000.00
B2020.01.01.02 Aluminum Windows (Glass & Frame)*	Repair	Replace venetian blinds between glass panes and replace weather seal on hopper sections of windows.	\$ -	\$ 8,000.00	\$ -	\$ -	\$ -	\$ 8,000.00
<b>Total of Maintenance Events</b>			<b>\$ -</b>	<b>\$ 168,000.00</b>	<b>\$ 311,000.00</b>	<b>\$ 45,000.00</b>	<b>\$ 235,000.00</b>	<b>\$ 759,000.00</b>
<b>Upgrading Events</b>								
K4010.02 Barrier Free Entrances	Barrier Free Access Upgrade	Provide an automatic door opener at the front entrance.	\$ -	\$ 10,000.00	\$ -	\$ -	\$ -	\$ 10,000.00
K4010.03 Barrier Free Interior Circulation	Barrier Free Access Upgrade	Re-build two wood interior ramps to access portable areas.	\$ -	\$ 20,000.00	\$ -	\$ -	\$ -	\$ 20,000.00
D2020.01.03 Piping Specialties (Backflow Preventors)*	Code Upgrade	Install backflow prevention device on fire line, at incoming water service.	\$ -	\$ 4,000.00	\$ -	\$ -	\$ -	\$ 4,000.00
D3040.01.01 Air Handling Units: Air Distribution*	Code Upgrade	Replace Multizone air handling units	\$ -	\$ -	\$ 100,000.00	\$ -	\$ -	\$ 100,000.00
D2010.05 Showers*	Program Functional Upgrade	Replace group showers with individual stall showers.	\$ -	\$ -	\$ -	\$ 10,000.00	\$ -	\$ 10,000.00
D2010.03 Lavatories*	Program Functional Upgrade	Replace vitreous china lavatories with new stainless steel type.	\$ -	\$ -	\$ 4,000.00	\$ -	\$ -	\$ 4,000.00
F2020.01 Asbestos*	Study	Prepare inventory of asbestos containing materials.	\$ -	\$ 5,000.00	\$ -	\$ -	\$ -	\$ 5,000.00
<b>Total of Upgrading Events</b>			<b>\$ -</b>	<b>\$ 39,000.00</b>	<b>\$ 104,000.00</b>	<b>\$ 10,000.00</b>	<b>\$ -</b>	<b>\$ 153,000.00</b>
<b>Total of Building Events</b>			<b>\$ -</b>	<b>\$ 207,000.00</b>	<b>\$ 415,000.00</b>	<b>\$ 55,000.00</b>	<b>\$ 235,000.00</b>	<b>\$ 912,000.00</b>

**Elk Island Catholic Separate Regional Division No.41  
Listing of Events**

Jean Vanier School B4014A			2006	2007	2008	2009	2010	Total
<b>Site Events</b>								
G2020.02.02 Flexible Paving Parking Lots(Asphalt)*	Program Functional Upgrade	Build a student drop-off area on the NE corner of the property.	\$ -	\$ -	\$ -	\$ 186,000.00	\$ -	\$ <b>186,000.00</b>
G2020.02.02 Flexible Paving Parking Lots(Asphalt)*	Program Functional Upgrade	Expand the existing parking lot.	\$ -	\$ -	\$ 44,000.00	\$ -	\$ -	\$ <b>44,000.00</b>
G4010.04 Car Plugs-ins*	Program Functional Upgrade	Install new car plug-ins for approximately 14 stalls.	\$ -	\$ 4,500.00	\$ -	\$ -	\$ -	\$ <b>4,500.00</b>
G2020.02.02 Flexible Paving Parking Lots(Asphalt)*	Repair	Provide asphalt overlay in existing parking lot.	\$ -	\$ -	\$ 24,000.00	\$ -	\$ -	\$ <b>24,000.00</b>
G1030 Site Earthwork (Back Slopes)	Repair	Regrade along the west and south building perimeters for positive back slopes.	\$ -	\$ -	\$ -	\$ 70,000.00	\$ -	\$ <b>70,000.00</b>
<b>Total of Site Events</b>			<b>\$ -</b>	<b>\$ 4,500.00</b>	<b>\$ 68,000.00</b>	<b>\$ 256,000.00</b>	<b>\$ -</b>	<b>\$ 328,500.00</b>

**Elk Island Catholic Separate Regional Division No.41  
Listing of Events**

Madonna School B4015A			2006	2007	2008	2009	2010	Total
<b>Building Events</b>								
<b>Maintenance Events</b>								
C3030.09 Other Ceiling Finishes Spray-on Materials*	Failure Replacement	Provide new acoustical ceiling treatment.	\$ 20,250.00	\$ -	\$ -	\$ -	\$ -	\$ 20,250.00
B3010.08.02 Metal Gutters and Downspouts*	Failure Replacement	Provide new concrete splashpads.	\$ 1,000.00	\$ -	\$ -	\$ -	\$ -	\$ 1,000.00
E2010.02.99 Other Casework (Vanities)	Failure Replacement	Provide new plastic laminated handicapped vanities.	\$ 2,500.00	\$ -	\$ -	\$ -	\$ -	\$ 2,500.00
C3020.01 Concrete Floor Finishes (Paint)*	Failure Replacement	Repaint concrete floor.	\$ -	\$ -	\$ 1,000.00	\$ -	\$ -	\$ 1,000.00
F1010.02.04 Portable and Mobile Buildings (1994)*	Failure Replacement	Replace carpet and panel ceiling tiles.	\$ 13,250.00	\$ -	\$ -	\$ -	\$ -	\$ 13,250.00
D2010.08 Drinking Fountains / Coolers*	Failure Replacement	Replace non-refrigerated drinking fountains.	\$ 2,000.00	\$ -	\$ -	\$ -	\$ -	\$ 2,000.00
C2020.11 Other Stair Finishes (Stepped Floor)*	Failure Replacement	Replace with new carpet.	\$ 6,500.00	\$ -	\$ -	\$ -	\$ -	\$ 6,500.00
E2010.02.05 Educational Facility Casework*	Failure Replacement	Replace with new millwork.	\$ -	\$ -	\$ 32,500.00	\$ -	\$ -	\$ 32,500.00
B3010.04.01 Built-up Bituminous Roofing (Asphalt & Gravel)*	Failure Replacement	Replace with new SBS.	\$ -	\$ -	\$ 220,000.00	\$ -	\$ -	\$ 220,000.00
C3020.08.02 Sheet Carpet	Failure Replacement	Replace with new sheet carpet.	\$ 15,000.00	\$ -	\$ -	\$ -	\$ -	\$ 15,000.00
B2020.01.01.02 Aluminum Windows (Glass & Frame)*	Failure Replacement	Replace with new window gaskets.	\$ 2,550.00	\$ -	\$ -	\$ -	\$ -	\$ 2,550.00
C3020.07.01 Resilient Tile Flooring	Failure Replacement	Replace with vinyl sheet.	\$ 100,000.00	\$ -	\$ -	\$ -	\$ -	\$ 100,000.00
D3040.01.02 Fans: Air Distribution*	Lifecycle Replacement	Replace exhaust fans.	\$ -	\$ 5,000.00	\$ -	\$ -	\$ -	\$ 5,000.00
D3040.01.04 Ducts: Air Distribution*	Lifecycle Replacement	Replace fibreglass ductwork.	\$ -	\$ 500,000.00	\$ -	\$ -	\$ -	\$ 500,000.00
D5030.01 Detection and Fire Alarm*	Lifecycle Replacement	Replace fire alarm system	\$ -	\$ -	\$ 30,000.00	\$ -	\$ -	\$ 30,000.00
D3040.01.01 Air Handling Units: Air Distribution*	Lifecycle Replacement	Replace multizone air handling units.	\$ -	\$ 1,000,000.00	\$ -	\$ -	\$ -	\$ 1,000,000.00
D3020.03.01 Furnaces*	Lifecycle Replacement	Replace Penthouse Mechanical Rooms furnaces.	\$ -	\$ 3,000.00	\$ -	\$ -	\$ -	\$ 3,000.00
D3030.06.02 Refrigerant Condensing Units*	Lifecycle Replacement	Replace refrigerant condensing units.	\$ -	\$ 100,000.00	\$ -	\$ -	\$ -	\$ 100,000.00
D3020.03.02 Chimneys (&Comb. Air): Furnace*	Lifecycle Replacement	Replace Roof Mechanical Rooms furnaces chimneys.	\$ -	\$ 1,000.00	\$ -	\$ -	\$ -	\$ 1,000.00

**Elk Island Catholic Separate Regional Division No.41  
Listing of Events**

<b>Madonna School B4015A</b>			<b>2006</b>	<b>2007</b>	<b>2008</b>	<b>2009</b>	<b>2010</b>	<b>Total</b>
B3010.09 Roof Specialties and Accessories	Repair	Repaint all metal cat ladders.	\$ 1,000.00	\$ -	\$ -	\$ -	\$ -	\$ 1,000.00
C1020.01.07 Wood Doors	Repair	Repaint door frames.	\$ -	\$ -	\$ 1,600.00	\$ -	\$ -	\$ 1,600.00
C1020.03 Interior Fire Doors*	Repair	Repaint doors and frames.	\$ -	\$ -	\$ 1,000.00	\$ -	\$ -	\$ 1,000.00
B2030.01.10 Wood Entrance Door*	Repair	Repair solid wood door and hardware.	\$ 1,600.00	\$ -	\$ -	\$ -	\$ -	\$ 1,600.00
F1010.02.04 Portable and Mobile Buildings (1992)	Repair	Replace carpet, vinyl flooring and acoustic ceiling tiles.	\$ 26,000.00	\$ -	\$ -	\$ -	\$ -	\$ 26,000.00
F1010.02.04 Portable and Mobile Buildings (1976)	Repair	Replace vinyl flooring, acoustic ceiling tiles.	\$ 14,500.00	\$ -	\$ -	\$ -	\$ -	\$ 14,500.00
C3030.06 Acoustic Ceiling Treatment (Susp.T-Bar)*	Repair	Replace with new acoustic ceiling tiles.	\$ 3,000.00	\$ -	\$ -	\$ -	\$ -	\$ 3,000.00
<b>Total of Maintenance Events</b>			<b>\$ 209,150.00</b>	<b>\$ 1,609,000.00</b>	<b>\$ 286,100.00</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ 2,104,250.00</b>
<b>Upgrading Events</b>								
K4010.02 Barrier Free Entrances	Barrier Free Access Upgrade	Provide automatic door for handicapped.	\$ 10,000.00	\$ -	\$ -	\$ -	\$ -	\$ 10,000.00
K4010.04 Barrier Free Washrooms	Barrier Free Access Upgrade	Provide grab bars and tilted mirrors.	\$ 1,000.00	\$ -	\$ -	\$ -	\$ -	\$ 1,000.00
K4010.01 Barrier Free Route: Parking to Entrance	Barrier Free Access Upgrade	Provide handicapped ramp.	\$ 5,000.00	\$ -	\$ -	\$ -	\$ -	\$ 5,000.00
D2020.01.03 Piping Specialties (Backflow Preventors)* - Main Domestic Water Service	Code Upgrade	Provide backflow prevention device on building main domestic water service.	\$ 5,000.00	\$ -	\$ -	\$ -	\$ -	\$ 5,000.00
<b>Total of Upgrading Events</b>			<b>\$ 21,000.00</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ 21,000.00</b>
<b>Total of Building Events</b>			<b>\$ 230,150.00</b>	<b>\$ 1,609,000.00</b>	<b>\$ 286,100.00</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ 2,125,250.00</b>
<b>Site Events</b>								
G2010.02.02 Flexible Pavement Roadway (Asphalt)*	Study	Study of bus drop-off and pick-up area.	\$ 5,000.00	\$ -	\$ -	\$ -	\$ -	\$ 5,000.00
<b>Total of Site Events</b>			<b>\$ 5,000.00</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ 5,000.00</b>

**Elk Island Catholic Separate Regional Division No.41  
Listing of Events**

Maintenance Shop B5785A			2006	2007	2008	2009	2010	Total
<b>Building Events</b>								
<b>Maintenance Events</b>								
C3020.08.02 Sheet Carpet	Failure Replacement	Caulk cracks with new concrete filler.	\$ 3,750.00	\$ -	\$ -	\$ -	\$ -	\$ 3,750.00
C3030.07 Interior Ceiling Painting*	Failure Replacement	Paint gypsum board ceiling.	\$ 1,000.00	\$ -	\$ -	\$ -	\$ -	\$ 1,000.00
C1020.01.07 Wood Doors	Failure Replacement	Provide new wood doors, door frame and hardware.	\$ 1,500.00	\$ -	\$ -	\$ -	\$ -	\$ 1,500.00
C3030.06 Acoustic Ceiling Treatment (Susp.T-Bar)*	Failure Replacement	Replace with new acoustic ceiling tiles.	\$ 1,000.00	\$ -	\$ -	\$ -	\$ -	\$ 1,000.00
B2030.03.02 Sectional Overhead Doors	Failure Replacement	Replace with new insulated metal overhead sectional doors c/w hardware and tracks.	\$ 12,000.00	\$ -	\$ -	\$ -	\$ -	\$ 12,000.00
B2030.02 Exterior Utility Doors*	Failure Replacement	Replace with new metal insulated exterior doors c/w hardware.	\$ 2,500.00	\$ -	\$ -	\$ -	\$ -	\$ 2,500.00
C3020.07.01 Resilient Tile Flooring	Failure Replacement	Replace with new sheet vinyl.	\$ 2,250.00	\$ -	\$ -	\$ -	\$ -	\$ 2,250.00
C3010.11 Interior Wall Painting*	Failure Replacement	Repaint all gypsum board walls.	\$ 3,000.00	\$ -	\$ -	\$ -	\$ -	\$ 3,000.00
F1040.06 Other Special Facilities*	Preventative Maintenance	Provide enough fire extinguishers, fire suppression canopy over any welding or painting areas.	\$ 5,000.00	\$ -	\$ -	\$ -	\$ -	\$ 5,000.00
C3020.14 Other Floor Finishes Concrete Floor)*	Repair	Caulk cracks with new concrete filler.	\$ 1,000.00	\$ -	\$ -	\$ -	\$ -	\$ 1,000.00
B2010.02.03 Masonry Units: Ext. Wall Const.*	Repair	Provide additional insulation on the inner surface of concrete blocks.	\$ 10,000.00	\$ -	\$ -	\$ -	\$ -	\$ 10,000.00
<b>Total of Maintenance Events</b>			<b>\$ 43,000.00</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ 43,000.00</b>
<b>Upgrading Events</b>								
D2020.01.03 Piping Specialties (Backflow Preventors)* - Main Domestic Water Service	Code Upgrade	Provide backflow prevention device on building main domestic water service.	\$ 5,000.00	\$ -	\$ -	\$ -	\$ -	\$ 5,000.00
D3040.01.03 Air Cleaning Devices:Air Distribution*	Indoor Air Quality Upgrade	Install higher efficiency furnace filter.	\$ 1,000.00	\$ -	\$ -	\$ -	\$ -	\$ 1,000.00
<b>Total of Upgrading Events</b>			<b>\$ 6,000.00</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ 6,000.00</b>
<b>Total of Building Events</b>			<b>\$ 49,000.00</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ 49,000.00</b>

## Elk Island Catholic Separate Regional Division No.41 Listing of Events

St. Theresa School B4026A			2006	2007	2008	2009	2010	Total
<b>Building Events</b>								
<b>Maintenance Events</b>								
D3040.01.04 Ducts: Air Distribution*	Code Repair	Replace all plastic ducts with sheet metal ducts.	\$ 60,000.00	\$ -	\$ -	\$ -	\$ -	\$ 60,000.00
D2020.01.03 Piping Specialties (Backflow Preventors)*	Code Repair	Provide cross-contamination control device.	\$ 5,000.00	\$ -	\$ -	\$ -	\$ -	\$ 5,000.00
D3040.04.01 Fans: Exhaust*	Code Repair	Replace the exhaust fans in 2 staff washrooms.	\$ 3,000.00	\$ -	\$ -	\$ -	\$ -	\$ 3,000.00
D3040.01.01 Air Handling Units: Air Distribution*	Failure Replacement	Replace 4 air handling units with new ones.	\$ 200,000.00	\$ -	\$ -	\$ -	\$ -	\$ 200,000.00
D2020.03 Water Supply Insulation*: Domestic	Failure Replacement	Replace the insulation of the domestic water supply piping.	\$ 6,000.00	\$ -	\$ -	\$ -	\$ -	\$ 6,000.00
D3030.06.02 Refrigerant Condensing Units*	Failure Replacement	Replace the refrigerant condensing units with new ones.	\$ 60,000.00	\$ -	\$ -	\$ -	\$ -	\$ 60,000.00
D3020.03.01 Furnaces*	Failure Replacement	Replace two 30 year old furnaces with new furnaces.	\$ 6,000.00	\$ -	\$ -	\$ -	\$ -	\$ 6,000.00
D2020.01.01 Pipes and Tubes: Domestic Water*	Preventative Maintenance	Replace all domestic piping.	\$ 30,000.00	\$ -	\$ -	\$ -	\$ -	\$ 30,000.00
D3010.02 Gas Supply Systems*	Repair	Repaint the gas pipes on the roof.	\$ 2,000.00	\$ -	\$ -	\$ -	\$ -	\$ 2,000.00
C3030.06 Acoustic Ceiling Treatment (Susp.T-Bar)*	Repair	Replace defective tiles and suspension system with new.	\$ 26,500.00	\$ -	\$ -	\$ -	\$ -	\$ 26,500.00
F1010.02.04 Portable and Mobile Buildings*	Repair	Replace broken metal downspouts with new.	\$ 2,500.00	\$ -	\$ -	\$ -	\$ -	\$ 2,500.00
C3020.07 Resilient Flooring*--VCT	Repair	Some vinyl composite tiles (VCT) in the corridors are delaminating.	\$ 18,000.00	\$ -	\$ -	\$ -	\$ -	\$ 18,000.00
F1010.02.04 Portable and Mobile Buildings*	Repair	Provide reinforcement to the floor structure of the 1976 portables.	\$ 25,000.00	\$ -	\$ -	\$ -	\$ -	\$ 25,000.00
C3020.04 Wood Flooring*	Repair	The gymnasium has wood flooring which needs re-finishing.	\$ 5,000.00	\$ -	\$ -	\$ -	\$ -	\$ 5,000.00
<b>Total of Maintenance Events</b>			<b>\$ 449,000.00</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ 449,000.00</b>
<b>Upgrading Events</b>								
K4010.02 Barrier Free Entrances	Barrier Free Access Upgrade	Install barrier free push paddles on the entrance door.	\$ 4,000.00	\$ -	\$ -	\$ -	\$ -	\$ 4,000.00
K40 Current Code Issues	Code Upgrade	Conduct a code review on the fire separation requirement between the core school and the portables.	\$ 15,000.00	\$ -	\$ -	\$ -	\$ -	\$ 15,000.00
K4010.04 Barrier Free Washrooms	Code Upgrade	Modify the existing washrooms to provide barrier free facilities.	\$ 25,000.00	\$ -	\$ -	\$ -	\$ -	\$ 25,000.00

**Elk Island Catholic Separate Regional Division No.41  
Listing of Events**

<b>St. Theresa School B4026A</b>			<b>2006</b>	<b>2007</b>	<b>2008</b>	<b>2009</b>	<b>2010</b>	<b>Total</b>
D3040.01.03 Air Cleaning Devices:Air Distribution*	Indoor Air Quality Upgrade	Install a higher efficiency air filtration system in the ventilation system.	\$ 8,000.00	\$ -	\$ -	\$ -	\$ -	\$ 8,000.00
E2010.02.05 Educational Facility Casework*	Program Functional Upgrade	Replace and provide additional casework to the classrooms and music room.	\$ 45,000.00	\$ -	\$ -	\$ -	\$ -	\$ 45,000.00
E2010.02.08 Laboratory Casework*	Program Functional Upgrade	Redesign a new layout for the Science room, with new millwork, and install additional locked storage.	\$ 25,000.00	\$ -	\$ -	\$ -	\$ -	\$ 25,000.00
C1030.10 Lockers*	Program Functional Upgrade	Replace the 6-tier metal lockers in the school.	\$ 31,500.00	\$ -	\$ -	\$ -	\$ -	\$ 31,500.00
<b>Total of Upgrading Events</b>			<b>\$ 153,500.00</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ 153,500.00</b>
<b>Total of Building Events</b>			<b>\$ 602,500.00</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ 602,500.00</b>
<b>Site Events</b>								
G2020.02.02 Flexible Paving Parking Lots(Asphalt)--Ponding*	Failure Replacement	Ponding in west parking lot.	\$ 15,000.00	\$ -	\$ -	\$ -	\$ -	\$ 15,000.00
G9090 Other Site Systems*--Parents drop off	Program Functional Upgrade	Parents drop students off in the bus zone, staff parking lot and along the street.	\$ 28,000.00	\$ -	\$ -	\$ -	\$ -	\$ 28,000.00
G2020.02.02 Flexible Paving Parking Lots(Asphalt)*-Add stalls	Program Functional Upgrade	The school has a staff of 40 and currently has 28 parking stalls. There is no visitors' parking.	\$ 30,000.00	\$ -	\$ -	\$ -	\$ -	\$ 30,000.00
G2020.06.03 Parking Lot Signs*	Program Functional Upgrade	There are no signs to identify staff parking and for other information.	\$ 2,000.00	\$ -	\$ -	\$ -	\$ -	\$ 2,000.00
G2010.06 Roadway Appurtenances*	Program Functional Upgrade	There is no signage on the roadways for direction and identification.	\$ 1,500.00	\$ -	\$ -	\$ -	\$ -	\$ 1,500.00
<b>Total of Site Events</b>			<b>\$ 76,500.00</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ -</b>	<b>\$ 76,500.00</b>